

ASS. REC. BY:

REF:

CS/INC19019563/Nvd3

Special Instruction:

Surveyor: NAZASSIGNMENT (Office)From (Person): Hazalya Bt Ibrahim of INC Date/Time: 5/11/19 @ 10:01am

Estimated Cost: _____ Bill to: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐ CSTo Inspect Vehicle No: SMJ 9789S Insured: SH 2763Bat Workshop m/s JWG International Tel: 6909 8882 / 82996103of 10 Amk Ind. Park 2A #03-08Policy No: _____ Claim No: MT/1069712-002

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 2/11/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 10:37am 5/11/19 Person Contacted: Kalvin Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction	Estimate
	<u>SMJ 9789S - NA / FWD 19019 367 / M</u>	<u>DOA: 2/11/2019</u>
<u>21/11/19</u>	<u>@ 215pm</u>	<u>Kalvin will check</u>
<u>11/12/19</u>	<u>@ 434pm</u>	<u>Kalvin will forward us the estimate</u>
<u>31/3/20</u>	<u>@ 1203pm</u>	<u>Pending for LTA letter</u>

Signature: Naz

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

ODI/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s JWG INTERNATIONAL

at AMK IND PARK RA #03-08

Insurance: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Name of Veh: _____

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.

Est. or Market Value: 180K

UDAC Accident Report: _____ Consistent? : Yes or No

GR / PR Sheet: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lump Sum: _____ % J Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMP 97895 Yr Regn: JUN 2018

Type: (M) Car / (M) Cycle / (B) S / Van / Lorry / Taxi / Prime Mover /

Truck / Trolley or

Make: MERCEDES BENZ C.G. 1,991

Colour: WHITE A/C: (Insured) Sid / Nil / NA

Sp. Reading: 28,851 T/Radio: (Insured) Sid / Nil / NA

Engl/No: _____

C.No: WDD2130422A398568

Gon. Cond: Good / Fair / Poor / Burnt

Steering: (Inorder) / Jammed / Leaked / Burnt or

Brake: (Inorder) / Jammed / Leaked / Burnt or

Modl: III (SIR) / STD AIR / m or

Tyre Size: F: 245 / 40 R19

R: 11

BS / DUN / EXHOVA / GY / FS / LIZA / MIC / OHTSU / (PIR) SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bnl. 5 mm R/Bnl. 5 mm

U/Bnl. 5 mm U/Bnl. 5 mm

D.O.A. 2/11/19 U.O.A. 5/11/19

Survey held at JWG INTERNATIONAL

Des. of Damages: (Fr) / (Rear) / OIS / NIS / UIC / Roadtop or

The UIC / Chassis frame / Body Structure affected due to collision

INC

Date / Time	Action / Instruction
	COE Estimate \$79,190.00
	Repair Limit \$95K
21/3/2020	FINALIZED LUMP SUM REPAIR \$38,100.00 / 10 REPAIR DAYS
	(Recd 98,151.28, 72%)

Date/Time, File Pass 1st? ☐ : Prelim Report

1) ☐ : Final Report

Date/Time, File Return 1st?

2) 22/4 - typist

Report Format: TP
Lump Sum / I.B.I. (\$) 38,100/2

Days Of Repair: 10

Resurvey No. of Trip: 2

Survey Fee:

Transportation

Add Fee: ☐ : Site Insp (\$ _____) ☐ : S + HS (\$ _____)

☐ : Interview (\$ _____) ☐ : Photos

☐ : Tech. Invs (\$ _____) ☐ : Others

☐ : Weekend (\$ _____)

Total

Nivitha (LKK Auto)

From: Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>
Sent: Wednesday, 6 November 2019 9:13 AM
To: Admin-D (LKKAuto); assignments
Cc: Hazalysa Binte Ibrahim
Subject: FW: TP CASES FARMED OUT TO LKK ON 05/11/2019

Dear LKK,

RE-send with details.

Thank you.

Warmest Regards

Hazalysa Bte Ibrahim
Admin Assistant
Motor Department
www.income.com.sg

Income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 5 November 2019 10:49 AM
To: Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>; assignments <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 05/11/2019

Dear Hazalysa,

Thank you for the assignment.

Please be informed that SJN6248X (HUI YANG MOTOR) the vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hazalya Binte Ibrahim [mailto:hazalya.ibrahim@income.com.sg]

Sent: Tuesday, 5 November 2019 10:01 AM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments<assignments@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>

Subject: TP CASES FARMED OUT TO LKK ON 05/11/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	David Phua	MT/1069328-002	SMA1928H	AUTOMOTIVE REPAIR CENTRE PTE. LTD.	38 WOODLANDS INDUSTRIAL PARK E1 #05-18 SINGAPORE 757700	Lin Shu Juan / 6468 8834	10:00-16:00	SJN695A	30/10/19	
2	Eric Tang	MT/1069802-002	SMG3831H	JWG INTERNATIONAL PTE. LTD	10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT	/ 6909 8882		SHB8339R	04/11/19	

					SINGAPORE 568047				
3	Fiona Shen	MT/1069712- 002	SMI97895	JWG INTERNATIONAL PTE. LTD	10 ANG MO KIO INDUSTRIAL PARK 2A #03- 08 AMK AUTOPOINT SINGAPORE 568047	/ 6909 8882		SH27638	02/11/19
4	Jared Liu	MT/1068817- 002	PC81K	SERVE YOU MOTOR SERVICE	BLK 5033 #01- 265 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569536	Elaine Chia / 9239 3188	10:00- 12:00	SIG7545T	22/10/19
5	David Phua	MT/1069721- 002	SDE2368C	SMART AUTOMOTIVE SERVICES PTE LTD	WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	Peh Eng Hock / 88583566	10:00- 12:00	SKG8799I	02/11/19
6	Fiona Shen	MT/1065847- 003	SJNG248X	HUI YANG MOTOR SERVICE	176 SIN MING DRIVE #04- 02/03 SIN MING AUTOCARE SINGAPORE 575721	Bel / 64515752		SIVA202Z	05/10/19
7	Charlotte Chew	MT/1067762- 002	SUV3347Y	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		SHC6277T	20/10/19
8	Helena Tan	MT/1067921- 002	SMK7021G	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		SJUB146G	22/10/19
9	Chryllis Quah	MT/1069704- 002	SLG5075U	TTS EUROCARS PTE LTD	383 SIN MING DRIVE TTS CENTRE SINGAPORE 575717	Ms. Kavi / 97637000	15:00- 16:00	SLC2471C	02/11/19

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
T +65 6430 7902
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.


Find out more at Income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

< All Inboxes LTA e-Receipt - SM...

copy of the e-receipt for your records.

Visit www.onemotoring.com.sg for more information, or go to www.lta.gov.sg/feedback if you have any feedback. This email is auto-generated, please do not reply to this email.

Thank you for using LTA's digital services.

If you are not the intended recipient of this communication, please delete it.

As it may contain confidential or official information, do not retain it or disclose the contents to any person as it may be an offence under the Official Secrets Act.

Land Transport Authority

Land Transport Authority

Land Transport Authority
10, Sin Ming Drive
Singapore 575701

GST Registration No. MM 0006529-2

Print Date/Time 11 Dec 2019 / 17:20:12

Receipt Date/Time 11 Dec 2019 / 17:20:11

Tax Invoice/Receipt

Receipt No. ITNET-00000-191211-002770

Previous Receipt No.

S/N Item Description/
Business Transaction Reference
No.

Replaced Vehicle No. SMU97895

1 Replacement of Veh Reg No - SMP6688C
Replacement Fee
20191211171909794108

Amount Before GST (\$S)	GST Amount (\$S)	Amount After GST (\$S)
-------------------------------	------------------------	------------------------------

300.00	21.00	321.00
--------	-------	--------

Sub-Total	300.00	21.00	321.00
------------------	--------	-------	--------

Total Before Rounding	300.00	21.00	321.00
------------------------------	--------	-------	--------

Rounding Difference			0.00
----------------------------	--	--	------

Total Amount Payable			321.00
-----------------------------	--	--	--------

Paid By

XXXXXXXXXXXX8940	Credit Card: Visa MasterCard	321.00
------------------	---------------------------------	--------

Total			321.00
--------------	--	--	--------

Cash Change			0.00
--------------------	--	--	------

Tendered Amount			321.00
------------------------	--	--	--------

Excess Refundable Amount			0.00
---------------------------------	--	--	------

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



10 Sin Ming Drive Singapore 575701
www.lta.gov.sg

11 Dec 2019

Our ref 1112190203N061010102

GAN HONG CHENG, NIGEL
APT BLK 439 HOUGANG AVENUE 8
#15-1549
SINGAPORE 530439

Dear Sir/Madam

**You Have Successfully Replaced Vehicle Registration No. SMJ9789S
With SMR6688C**

You have successfully replaced your vehicle registration number. The vehicle, whose previous number was SMJ9789S, now has the number SMR6688C.

The vehicle details after the transaction are:

Transaction No.	: 20191211171909794108
Vehicle Registration No.	: SMR6688C (Previously SMJ9789S)
Vehicle Make	: MERCEDES BENZ
Vehicle Model	: E200 AVG AUTO
Chassis No.	: WDD2130422A398568
Engine No./ Motor No.	: 27492031341652 / -

What You Need To Do:

- You must show the new number SMR6688C on your vehicle by 14 Dec 2019.

Please change the number plates on this vehicle to show SMR6688C by 14 Dec 2019. Otherwise, it is an offence and the penalty is a fine of up to \$2,000 or imprisonment of up to 6 months, or both.

JWG INTERNATIONAL PTE. LTD.

Co. & GST Reg. No.: 201837488H

Blk 10, Ang Mo Kio Ind Park 2A,

#03-08 AMK AutoPoint,

Singapore 568047

H/P: 9069 7882 Fax: 6909 9592

E-Mail: jwg.claims@yahoo.com

DATE : 4/11/2019

VEHICLE NO : SMJ 9789 S
MODEL : MERCEDES E200
CHASSIS NO :

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BOOTLID / DD	1	\$ -	\$3145.00
2	REAR BOOTLID CENTER CHROME X SVL	1	\$ -	\$240.00 -
3	REAR BOOTLID NUMBER PLATE LAMP X SVL	2	\$ 49.50 -	\$ 99.00 -
4	REAR BOOTLID EMBLEM E200 / NEL	1	\$ -	\$157.50 -
5	REAR BOOTLID LOGO / NEL	1	\$ -	\$90.00 -
6	REAR BOOTLID LOCK / BT	1	\$ -	\$445.00
7	REAR BOOTLID CATCH X SVL	1	\$ -	\$795.00 -
8	REAR BOOTLID HINGE X SVL	2	\$ 457.50 -	\$915.00 -
9	REAR BOOTLID HINGE GARNISH X SVL	2	\$ 42.00 -	\$84.00 -
10	REAR BOOTLID VACUUM LOCK COMPLETE	1	\$ -	\$1688.70
11	REAR BOOTLID INNER LOCK X SVL	1	\$ -	\$562.00 -
12	REAR BOOTLID LOCK X SVL	1	\$ -	\$388.00 -
13	REAR BOOTLID STOPPER X SVL	2	\$ 48.00 -	\$96.00 -
14	REAR BOOTLID SEAL X SVL	2	\$ 585.00 -	\$1170.00 -
15	REAR BOOTLID OPERNER X SVL	1	\$ -	\$645.00 -
16	REAR BOOTLID WEATHERSTRIP / DEF	1	\$ -	\$540.00
17	REAR BOOTLID INNER TRIM X SVL	1	\$ -	\$525.00 -
19	REAR BUMPER SIDE RETAINER X SVL	2	\$ 142.50	\$285.00 -
20	REAR BUMPER BRACKET X SVL	2	\$ 112.50	\$225.00 -
21	REAR BUMPER REFLECTOR X LH SVL / RH X SVL	2	\$ 52.50 -	\$105.00 -
22	REAR BUMPER TOW COVER / DEF	1	\$ -	\$114.00 -
23	REAR BUMPER REVERSE SENSOR / MIS	2	\$ 442.50 -	\$1890.00
24	REAR BUMPER REVERSE SENSOR HOLDER / MIS	2	\$ 88.00 -	\$352.00
25	REVERSE SENSOR WIREHARNESS / NEL	1	\$ -	\$2480.00
26	REAR BUMPER CARRIER / DEF	1	\$ -	\$139.50 -
27	REAR BUMPER SPONGE X SVL	1	\$ -	\$550.00 -
28	REAR BUMPER REINFORCEMENT / BT	1	\$ -	\$465.00 -
29	REAR END PANEL X X / DEF	1	\$ -	\$2440.00

2,293 (2293/DD)

157.50 / NEL

90 / NEL

200 / BT

800 / not working

300 / DEF

\$52.50 / LH SCR

147 / DEF

500 / MIS

80 / NEL

1,000 / NEL

\$139.50 / DEF

465 / BT

1,300 / DEF

21,698.70 \$7524.50

not working

21/4 NGZ ✓

21/4 NGZ ✓

XSVL
XSVL
XSVL
XSVL
XSVL
DEF

30	REAR END PANEL INNER SUPPORT	2 XSVL	1	\$ -	\$ 645.00 -
31	REAR END PANEL TOP GARNISH	2 / CRK	1	\$ -	\$ 144.00 -
32	REAR SPARE WHEEL PANEL	2	1	\$ -	\$ 292.50 -
33	REAR SPARE WHEEL QUARTER PANEL LH	2	1	\$ -	\$ 523.50 -
34	REAR SPARE WHEEL CONTAINER BOX	2	1	\$ -	\$ 655.00 -
35	REAR SPARE WHEEL TOP BOARD	2	1	\$ -	\$ 840.00 -
36	REAR SPARE WHEEL BOOTLID MOTOR	2	1	\$ -	\$ 1430.00 -
37	REAR BUMPER UNDERCOVER	1 / CRK	1	\$ -	\$ 445.00 -
38	REAR BUMPER SENSOR DETECTOR	2	1	\$ -	\$ 195.00 -
39	REAR BUMPER SENSOR DETECTOR WIREHARN	2	1	\$ -	\$ 210.00 -
40	REAR FENDER	XSVL Y LHKR 2 X SVL	1 2	\$ 3825.00	\$ 7650.00 -
41	REAR FENDER COWLING	XSVL	2	\$ 342.00	\$ 684.00 -
42	REAR FENDER INNER TRIM	XSVL	2	\$ 322.50 -	\$ 645.00 -
43	REAR FENDER AIR DUCT	XSVL	2	\$ 45.00 -	\$ 90.00 -
44	WINDSCREEN COMPLETE WITH MOULDING	XSVL	1	\$ -	\$ 225.00 -
45	TAILLAMP	2 / CRK	2	\$ 1350.00	\$ 2700.00 -
46	TAILLAMP PANEL	2 XSVL	2	\$ 322.50 -	\$ 645.00 -
47	TAILLAMP CLIPS	2 / NEC	2	\$ 20.00 -	\$ 40.00 -
48	TAILLAMP GARNISH	2 X SVL	2	\$ 98.00 -	\$ 196.00 -
49	BOOTLID INNER SIDE GARNISH	2 XSVL	2	\$ 82.50 -	\$ 165.00 -
50	REAR EXHAUST PIPE COMPLETE	2 XSVL	1	\$ -	\$ 3225.00 -
51	REAR EXHAUST PIPE GASKET	2 XSVL	1	\$ -	\$ 39.00 -
52	REAR EXHAUST PIPE HEAT SHEID	2 / DEF	1	\$ -	\$ 515.00 -
53	REAR EXHAUST PIPE MOUNTING	2 XSVL	1	\$ -	\$ 67.50 -
54	DRIVER HEADREST COMPLETE SET	1 / NEC	1	\$ -	\$ 885.00 -
55	PASSANGER HEADREST COMPLETE SET	1 / NEC	1	\$ -	\$ 885.00 -
56	DRIVER SEAT BELT	1 / JAM 750	1	\$ -	\$ 2505.00 -
57	DRIVER SEAT BELT BUCKET	XSVL	1	\$ -	\$ 240.00 -
58	PASSANGER SEAT BELT	1 / JAM 750	1	\$ -	\$ 2505.00 -
59	PASSANGER SEAT BELT BUCKET	XSVL	1	\$ -	\$ 240.00 -
60	REAR SEAT BELT	1 / JAM 650	1 2	\$ 2230.00	\$ 4460.00 -
61	REAR SEAT BELT BUCKET	XSVL	2	\$ 180.00 -	\$ 360.00 -
62	CENTER SEAT BELT	X SVL	1	\$ -	\$ 615.00 -
63	CENTER SEAT BELT BUCKET	XSVL	1	\$ -	\$ 180.00 -
64	SRS CONTROL MODULE	1 / NEC	1	\$ -	\$ 2650.00 -
65	FRONT BONNET	1 / DD	1	\$ -	\$ 3975.00 -
66	FRONT BONNET SEAL	2 / NEC	1	\$ -	\$ 122.00 -
67	FRONT BONNET LOGO	1 / NEC	1	\$ -	\$ 135.00 -
68	FRONT BONNET ISOLATOR	2 XSVL	1	\$ -	\$ 480.00 -
69	FRONT BONNET HINGE	2 XSVL	2	\$ 327.50 -	\$ 655.00 -
70	FRONT BONNET LOCK	2 XSVL	2	\$ 120.00 -	\$ 240.00 -

144 / CRK

465 / CRK
195 / DEF

XSVL
1700 X R

1,600 / CRK

40 / NEC

300 / DEF

X R
X R
1,000 / JAM

1,000 / JAM

2,000 / JAM

800 / NEC

2,500 / DD

122 / NEC

135 / NEC

43,288.50

10,301

71	FRONT BONNET WEATHERSTRIP	9 XSL	1	\$ -	\$ 148.00 -
72	FRONT BUMPER SIDE RETAINER	2 XSVL	2	\$ 112.50 -	\$ 225.00 -
73	FRONT BUMPER BRACKET	2 XSVL	2	\$ 68.00 -	\$ 136.00 -
74	FRONT BUMPER TOW COVER	1 / DEF	1	\$ -	\$ 112.50 -
75	FRONT GRILLE TRIM	1 / DEF	1	\$ -	\$ 292.50 -
76	FRONT GRILLE CENTER AIR GUIDE	1 / BR	1	\$ -	\$ 440.00 -
77	FRONT GRILLE SIDE AIR GUIDE	2 / DEF	2	\$ 289.00 -	\$ 578.00 -
78	FRONT BUMPER NUMBER PLATE GARNISH	1 / MS	1	\$ -	\$ 202.50 -
79	FRONT BUMPER AIR DUCT	XSVL	1	\$ -	\$ 240.00 -
80	FRONT BUMPER SPONGE	2 XSVL	1	\$ -	\$ 279.00 -
81	FRONT BUMPER SIDE SPONGE	1 XSVL	2	\$ 223.00 -	\$ 446.00 -
82	FRONT BUMPER REINFORCEMENT	1 / BT	1	\$ -	\$ 967.50 -
83	FRONT BUMPER CARRIER	1 / DEF	1	\$ -	\$ 187.50 -
84	FRONT BUMPER PARKING SENSOR	XSVL	2 6	\$ 487.50 -	\$ 2925.00 -
85	FRONT BUMPER PARKING SENSOR HOLDER	2 6	2 6	\$ 89.00 -	\$ 534.00 -
86	FRONT BUMPER PARKING SENSOR WIREHARN	XSVL	1	\$ -	\$ 810.00 -
87	FRONT SUPPORT PANEL	1 / DEF	1	\$ -	\$ 570.00 -
88	FRONT SUPPORT SIDE PANEL	2 XSVL	2	\$ 285.00 -	\$ 570.00 -
89	TEMPERATURE SENSOR	2 XSVL	1	\$ -	\$ 97.50 -
90	HEADLAMP	2 / CRK	2	\$ 480.00 -	\$ 960.00 -
91	HEADLAMP PANEL	XSVL	2	\$ 238.00 -	\$ 476.00 -
92	HEADLAMP SIDE BRACKET	XSVL	2	\$ 303.00 -	\$ 606.00 -
93	HEADLAMP PANEL LOWER SUPPORT	XSVL	2	\$ 218.00 -	\$ 436.00 -
94	HEADLAMP SEAL	XSVL	2	\$ 150.00 -	\$ 300.00 -
95	FRONT FENDER	2 4 / BT 1 4 XSVL	1 2	\$ 1725.00 -	\$ 3450.00 -
96	FRONT FENDER COWLING	1 XSVL	2	\$ 345.00 -	\$ 690.00 -
97	FRONT FENDER INNER TRIM	2 XSVL	2	\$ 337.50 -	\$ 675.00 -
98	TURBO INTERCOOLER	2 XSVL	1	\$ -	\$ 3818.00 -
99	TURBO INTERCOOLER SUPPORT	2 XSVL	1	\$ -	\$ 240.00 -
100	AUTO TRANSMISSION OIL COOLER	1 / DEF	1	\$ -	\$ 975.00 -
101	A/C CONDENSOR	1 / DEF	1	\$ -	\$ 2512.50 -
102	A/C HIGH PRESSURE PIPE	2 XSVL	1	\$ -	\$ 210.00 -
103	A/C LOW PRESSURE PIPE	2 XSVL	1	\$ -	\$ 225.00 -
104	A/C DISCHARGE PIPE	2 XSVL	1	\$ -	\$ 480.00 -
105	RADIATOR ASSY	1 / DEF	1	\$ 900 -	\$ 1171.50 -
106	RADIATOR FAN MOTOR COMPLETE	1 / CRK	1	\$ -	\$ 945.00 -

TOTAL PRICE \$ -
LESS 10% \$ -
SUB TOTAL PRICE \$ -

12,290.50

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE	1	\$ 180.00	\$ 180.00

30

3/NET

CRK

2	REAR NUMBER PLATE	NEC X SVL	1	\$ 180.00	\$ 180.00	X SVL X Δ
3	FRONT BUMPER	/ CRK	1	\$ 3,800.00	\$ 3,800.00	2,000 / CRK
4	FRONT GRILLE COMPLETE	/ CRK	1	\$ 2,600.00	\$ 2,600.00	Come together Δ
5	FRONT GRILLE LOGO	/ MIS	1	\$ 450.00	\$ 450.00	2,500
6	FRONT GRILLE BASE	/ MJ	1	\$ 1,000.00	\$ 1,000.00	
7	FRONT GRILLE EMBLEM	NEC X RPT	1	\$ 250.00	\$ 250.00	X RPT Δ
8	FRONT LOWER GRILLE COMPLETE	? X SVL	1	\$ 1,200.00	\$ 1,200.00	
9	FRONT LOWER GRILLE CARBON FIBRE MOULD		1	\$ 900.00	\$ 900.00	600 / CRK
10	FRONT BUMPER CARBON FIBRE LIPS	/ CRK	1	\$ 2,800.00	\$ 2,800.00	1,000 / CRK
11	CARBON FIBRE FOG LAMP PROTECTOR	/ CRK	2	\$ 800.00	\$ 1,600.00	1,000 / CRK
12	CARBON FIBRE FOG LAMP MOULDING - TOP	/ CRK	2	\$ 450.00	\$ 900.00	600 / CRK
13	CARBON FIBRE FOG LAMP MOULDING - BTM	/ CRK	2	\$ 450.00	\$ 900.00	600 / CRK
14	FOG LAMP COVER	RH X SVL LH X SVL	2	\$ 380.00	\$ 760.00	X RPT Δ
15	REAR BOOTLID LIPS	NEC X SVL	1	\$ 1,600.00	\$ 1,600.00	X SVL Δ
16	REAR BUMPER LOWER DIFFUSER - CARBON	/ CRK	1	\$ 2,800.00	\$ 2,800.00	1,200 / CRK
17	DIFFUSER LAMP	/ CRK	1	\$ 600.00	\$ 600.00	600 / CRK
18	REAR BUMPER	/ CRK	1	\$ 3,600.00	\$ 3,600.00	2,000 / CRK
19	REAR EXHAUST DIFFUSER	2 / DEF	2	\$ 800.00	\$ 1,600.00	900 / DEF
20	BODY STICKER - COMPLETE	/ NEC	1	\$ 2,600.00	\$ 2,600.00	2,000 / NEC
21	REAR END PANEL SEALANT	2 / NEC	1	\$ 100.00	\$ 100.00	100 / NEC
22	SPARE WHEEL PANEL SEALANT	2 X NN	1	\$ 100.00	\$ 100.00	
23	RADIATOR COOLANT	2 / NEC X NN	1	\$ 200.00	\$ 200.00	X NN Δ
24	SPARE WHEEL INSULATOR	2 X SVL	1	\$ 400.00	\$ 400.00	
25	FRONT BUMPER CLIPS	/ NEC	1	\$ 100.00	\$ 100.00	100 / NEC
26	FRONT BONNET ISOLATOR CLIPS	2 / NEC	1	\$ 100.00	\$ 100.00	100 / NEC
27	FRONT FENDER COWLING CLIPS	2 X NN	1	\$ 100.00	\$ 100.00	
28	REAR BUMPER CLIPS	/ NEC	1	\$ 100.00	\$ 100.00	100 / NEC
29	REAR FENDER COWLING CLIPS	2 X NN	1	\$ 100.00	\$ 100.00	
30	REAR FENDER INNER TRIM CLIPS	X NN	1	\$ 100.00	\$ 100.00	
31	BOOTLID INNER TRIM CLIPS	2 / NEC	1	\$ 100.00	\$ 100.00	100 / NEC
32	REAR END PANEL TOP GARNISH CLIPS	2 / NEC	1	\$ 100.00	\$ 100.00	100 / NEC

TOTAL \$ 31,920.00

16,600

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS - FRONT	1,400 \$ 2,000.00	800 1,000 600 Δ
1	PANEL BEATING, REMOVAL AND REPLACING PARTS - REAR	\$ 2,800.00	800 1,000 800 Δ
2	TO SPRAY PAINT AFFECTED AREA - FRONT	\$ 1,800.00	1,400 1,000 Δ

2	TO SPRAY PAINT AFFECTED AREA - REAR	\$ 2,000.00	1,000 800 Δ
3	TUFF COAT	\$ 250.00	150
4	WIRING CHECK	\$ 180.00	100 30 Δ
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 600.00	X NN
6	CONDUCT WATER LEAKAGE TEST	\$ 100.00	50 X NN Δ
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	40
12	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD	\$ 200.00	? / 60 Δ
13	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	\$ 250.00	? / 50 X NN Δ
14	TO RNR UNDERCARRIAGE SYSTEM	\$ 350.00	? X NN Δ
15	TO CHECK WHEEL ALIGNMENT	\$ 150.00	X NN Δ
16	TO RNR A/C CONDENSOR ASSY AND REFILL GAS	\$ 150.00	? / 100 Δ
17	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	\$ 80.00	30 Δ
19	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	\$ 150.00	? / 100 80 Δ
20	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	\$ 100.00	? / 40 X RLT
22	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 800.00	? / 800 200 Δ

TOTAL

\$ 12,640.00

3,890

ESTIMATE REPORT

136, 251. 28

TOTAL PARTS COST : \$ 31,920.00
TOTAL LABOUR COST : \$ 12,640.00
TOTAL REPAIR COST : \$ 44,560.00

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

KELVIN WO

NA 2 CLK
5/11/19 1700
LIS
10 DAYS
DATE 11/11/19 1700

KELVIN WO
HP 9069 7882

JWG INTERNATIONAL PTE. LTD.

Co. & GST Reg. No.: 201837488H

Blk 10, Ang Mo Kio Ind Park 2A,

#03-08 AMK AutoPoint,

Singapore 568047

H/P: 9069 7882 Fax: 6909 9592

E-Mail: jwg.claims@yahoo.com

DATE : 4/11/2019

VEHICLE NO : SMJ 9789 S
MODEL : MERCEDES E200
CHASSIS NO :

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER SUPPORT BAR	1	\$ -	\$ 1480.70
2	FRONT BUMPER SUPPORT BAR BRACKET	1	\$ -	\$ 988.00
3	REAR SENSOR DETECTOR CONTROL MODULE	2	\$ 1475.00	\$ 2950.00

/ BT

/ DEF

/ not working

TOTAL PRICE \$ -
LESS 10% \$ -
SUB TOTAL PRICE \$ -

P \$ 61,686.40
Less 10% \$ 55,517.76

S/N \$ 30,740.00

L \$ 5,530.00

T \$ 91,787.76

LS \$ 73,430.20

≈ \$ 73,400.00

10 working days

PARTS : \$ 30,116.00

LESS 10% : \$ 27,104.40

S/NETT : \$ 16,600.00

LABOUR \$ 3,890.00

TOTAL \$ 47,594.40

LESS LIS 20% \$ 38,075.52

\$ 38,100.00 / 10 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: