

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/11/2019 15:51
Date Of Accident	02/11/2019 06:25
Exact Location Of Accident	CTE TWDS SLE @ AMK CENTRAL FLYOVER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMJ9789S
Insured/Policyholder	
Name Of Registered Owner	GAN HONG CHENG NIGEL
NRIC No	S8303437H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-87288884
Alternative Phone No	OFFICE-87288884

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2019-00009669
Cover Note Number	

Driver

Name of Driver	GAN HONG CHENG NIGEL
NRIC No	S8303437H
Date Of Birth	17/02/1983
Occupation	INDOOR
Date Of Driving Pass	13/09/2018
Driving Experience	1 YEAR AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-87288884
Fax Number	
Contact Number	OFFICE-87288884
EMail Address	NOEMAIL

Address	BLK 439 HOUGANG AVE 8 #15-1549
Postcode	530439
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH2763B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJB1610D
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

GAN HONG CHENG NIGEL

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

SMJ9789S

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN

VEHICLE NO.: SMT 9789S

INSURER : FLND Insurance

DATE & TIME: 02/11/2019 0625 hrs

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

(TE TWDS SLE @ Ang Mo Kio Central Flyover



Vehicle A : SMJ 9789S

Vehicle B : SH 2763B

Vehicle C : SJB 1610D


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I, Vehicle A (SMJ 9789S) was travelling along the stated venue at the first lane. As the vehicle in front, Vehicle C (SJB 1610D) slowed down and came to a stop, I followed suit. Suddenly, Vehicle B (SH 2763B) collide onto the rear portion of my vehicle causing me to surge forward and hit vehicle C.


Note : Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

(We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Centre Personnel's Signature
Name
NRIC/Pass No

☐ Claim Own Policy ☐ Claim Third Party ☐ Reporting Only
☐ Claim OD/TP at other workshop ()

JWG INTERNATIONAL PTE. LTD.

Co. & GST Reg. No.: 201837488H

Blk 10, Ang Mo Kio Ind Park 2A,

#03-08 AMK AutoPoint,

Singapore 568047

H/P: 9069 7882 Fax: 6909 9592

E-Mail: jwg.claims@yahoo.com

DATE : 4/11/2019

VEHICLE NO : SMJ 9789 S
MODEL : MERCEDES E200
CHASSIS NO :

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BOOTLID /DD	1	\$ -	\$ -
2	REAR BOOTLID CENTER CHROME XSVL	1	\$ -	\$ -
3	REAR BOOTLID NUMBER PLATE LAMP XSVL	2	\$ -	\$ -
4	REAR BOOTLID EMBLEM E200 /NCL	1	\$ -	\$ -
5	REAR BOOTLID LOGO /NCL	1	\$ -	\$ -
6	REAR BOOTLID LOCK /BT	1	\$ -	\$ -
7	REAR BOOTLID CATCH XSVL	1	\$ -	\$ -
8	REAR BOOTLID HINGE XSVL	2	\$ -	\$ -
9	REAR BOOTLID HINGE GARNISH XSVL	2	\$ -	\$ -
10	REAR BOOTLID VACUUM LOCK COMPLETE ?	1	\$ -	\$ -
11	REAR BOOTLID INNER LOCK XSVL	1	\$ -	\$ -
12	REAR BOOTLID LOCK XSVL	1	\$ -	\$ -
13	REAR BOOTLID STOPPER XSVL	2	\$ -	\$ -
14	REAR BOOTLID SEAL XSVL	2	\$ -	\$ -
15	REAR BOOTLID OPERNER XSVL	1	\$ -	\$ -
16	REAR BOOTLID WEATHERSTRIP /DEF	1	\$ -	\$ -
17	REAR BOOTLID INNER TRIM ?	1	\$ -	\$ -
19	REAR BUMPER SIDE RETAINER ?	2	\$ -	\$ -
20	REAR BUMPER BRACKET ?	2	\$ -	\$ -
21	REAR BUMPER REFLECTOR ✓ LH / SVL RH XSVL	2	\$ -	\$ -
22	REAR BUMPER TOW COVER /DEF	1	\$ -	\$ -
23	REAR BUMPER REVERSE SENSOR /MIS	4	\$ -	\$ -
24	REAR BUMPER REVERSE SENSOR HOLDER /NCL	4	\$ -	\$ -
25	REVERSE SENSOR WIREHARNESS ?	1	\$ -	\$ -
26	REAR BUMPER CARRIER ?	1	\$ -	\$ -
27	REAR BUMPER SPONGE ?	1	\$ -	\$ -
28	REAR BUMPER REINFORCEMENT ?	1	\$ -	\$ -
29	REAR END PANEL ?	1	\$ -	\$ -

30	REAR END PANEL INNER SUPPORT ?	1	\$	-	\$	-
31	REAR END PANEL TOP GARNISH ?	1	\$	-	\$	-
32	REAR SPARE WHEEL PANEL ?	1	\$	-	\$	-
33	REAR SPARE WHEEL QUARTER PANEL LH ?	1	\$	-	\$	-
34	REAR SPARE WHEEL CONTAINER BOX ?	1	\$	-	\$	-
35	REAR SPARE WHEEL TOP BOARD ?	1	\$	-	\$	-
36	REAR SPARE WHEEL BOOTLID MOTOR ?	1	\$	-	\$	-
37	REAR BUMPER UNDERCOVER / LRU	1	\$	-	\$	-
38	REAR BUMPER SENSOR DETECTOR ?	1	\$	-	\$	-
39	REAR BUMPER SENSOR DETECTOR WIREHARN ?	1	\$	-	\$	-
40	REAR FENDER XSR Y LHR RH X SVL	2	\$	-	\$	-
41	REAR FENDER COWLING X SVL	2	\$	-	\$	-
42	REAR FENDER INNER TRIM X SVL	2	\$	-	\$	-
43	REAR FENDER AIR DUCT X SVL	2	\$	-	\$	-
44	WINDSCREEN COMPLETE WITH MOULDING XNN	1	\$	-	\$	-
45	TAILLAMP ?	2	\$	-	\$	-
46	TAILLAMP PANEL ?	2	\$	-	\$	-
47	TAILLAMP CLIPS ?	2	\$	-	\$	-
48	TAILLAMP GARNISH ?	2	\$	-	\$	-
49	BOOTLID INNER SIDE GARNISH ?	2	\$	-	\$	-
50	REAR EXHAUST PIPE COMPLETE ?	1	\$	-	\$	-
51	REAR EXHAUST PIPE GASKET ?	1	\$	-	\$	-
52	REAR EXHAUST PIPE HEAT SHEID ?	1	\$	-	\$	-
53	REAR EXHAUST PIPE MOUNTING ?	1	\$	-	\$	-
54	DRIVER HEADREST COMPLETE SET / NEL	1	\$	-	\$	-
55	PASSANGER HEADREST COMPLETE SET / NEL	1	\$	-	\$	-
56	DRIVER SEAT BELT / SAM	1	\$	-	\$	-
57	DRIEVR SEAT BELT BUCKET	1	\$	-	\$	-
58	PASSANGER SEAT BELT / SAM	1	\$	-	\$	-
59	PASSANGER SEAT BELT BUCKET	1	\$	-	\$	-
60	REAR SEAT BELT / RH	2	\$	-	\$	-
61	REAR SEAT BELT BUCKET	2	\$	-	\$	-
62	CENTER SEAT BELT X SVL	1	\$	-	\$	-
63	CENTER SEAT BELT BUCKET X SVL	1	\$	-	\$	-
64	SRS CONTROL MODULE / NEL	1	\$	-	\$	-
65	FRONT BONNET / DD	1	\$	-	\$	-
66	FRONT BONNET SEAL / NEL	1	\$	-	\$	-
67	FRONT BONNET LOGO / NEL	1	\$	-	\$	-
68	FRONT BONENT ISOLATOR ?	1	\$	-	\$	-
69	FRONT BONNET HINGE X SVL	2	\$	-	\$	-
70	FRONT BONNET LOCK ?	2	\$	-	\$	-

XR Δ
XR Δ

X Δ

X Δ

X Δ

X Δ

71	FRONT BONNET WEATHERSTRIP ?	1	\$ -	\$ -
72	FRONT BUMPER SIDE RETAINER ?	2	\$ -	\$ -
73	FRONT BUMPER BRACKET ?	2	\$ -	\$ -
74	FRONT BUMPER TOW COVER ?	1	\$ -	\$ -
75	FRONT GRILLE TRIM ?	1	\$ -	\$ -
76	FRONT GRILLE CENTER AIR GUIDE /BR	1	\$ -	\$ -
77	FRONT GRILLE SIDE AIR GUIDE ?	2	\$ -	\$ -
78	FRONT BUMPER NUMBER PLATE GARNISH /HIS	1	\$ -	\$ -
79	FRONT BUMPER AIR DUCT	1	\$ -	\$ -
80	FRONT BUMPER SPONGE ?	1	\$ -	\$ -
81	FRONT BUMPER SIDE SPONGE ?	2	\$ -	\$ -
82	FRONT BUMPER REINFORCEMENT ?	1	\$ -	\$ -
83	FRONT BUMPER CARRIER ?	1	\$ -	\$ -
84	FRONT BUMPER PARKING SENSOR /SVC	6	\$ -	\$ -
85	FRONT BUMPER PARKING SENSOR HOLDER /SVC	6	\$ -	\$ -
86	FRONT BUMPER PARKING SENSOR WIREHARN /SVC	1	\$ -	\$ -
87	FRONT SUPPORT PANEL ?	1	\$ -	\$ -
88	FRONT SUPPORT SIDE PANEL ?	2	\$ -	\$ -
89	TEMPERATURE SENSOR ?	1	\$ -	\$ -
90	HEADLAMP X SVC	2	\$ -	\$ -
91	HEADLAMP PANEL /SVC	2	\$ -	\$ -
92	HEADLAMP SIDE BRACKET /SVC	2	\$ -	\$ -
93	HEADLAMP PANEL LOWER SUPPORT /SVC	2	\$ -	\$ -
94	HEADLAMP SEAL /SVC	2	\$ -	\$ -
95	FRONT FENDER ?	2	\$ -	\$ -
96	FRONT FENDER COWLING ?	2	\$ -	\$ -
97	FRONT FENDER INNER TRIM ?	2	\$ -	\$ -
98	TURBO INTERCOOLER ?	1	\$ -	\$ -
99	TURBO INTERCOOLER SUPPORT ?	1	\$ -	\$ -
100	AUTO TRANSMISSION OIL COOLER ?	1	\$ -	\$ -
101	A/C CONDENSOR ?	1	\$ -	\$ -
102	A/C HIGH PRESSURE PIPE ?	1	\$ -	\$ -
103	A/C LOW PRESSURE PIPE ?	1	\$ -	\$ -
104	A/C DISCHARGE PIPE ?	1	\$ -	\$ -
105	RADIATOR ASSY ?	1	\$ -	\$ -
106	RADIATOR FAN MOTOR COMPLETE ?	1	\$ -	\$ -

XNFO

XNDL

TOTAL PRICE	\$ -
LESS 10%	\$ -
SUB TOTAL PRICE	\$ -

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE /DBE	1	\$ 180.00	\$ 180.00

30 2

3/NET

2	REAR NUMBER PLATE / NEL	1	\$ 180.00	\$ 180.00	XND Δ
3	FRONT BUMPER / CRK	1	\$ 3,800.00	\$ 3,800.00	
4	FRONT GRILLE COMPLETE / CRK	1	\$ 2,600.00	\$ 2,600.00	comp bumper Δ
5	FRONT GRILLE LOGO / MIS	1	\$ 450.00	\$ 450.00	
6	FRONT GRILLE BASE / MIS	1	\$ 1,000.00	\$ 1,000.00	
7	FRONT GRILLE EMBLEM / NEL	1	\$ 250.00	\$ 250.00	X Pt Δ
8	FRONT LOWER GRILLE COMPLETE ?	1	\$ 1,200.00	\$ 1,200.00	
9	FRONT LOWER GRILLE CARBON FIBRE MOULD	1	\$ 900.00	\$ 900.00	
10	FRONT BUMPER CARBON FIBRE LIPS / CRK	1	\$ 2,800.00	\$ 2,800.00	
11	CARBON FIBRE FOG LAMP PROTECTOR / CRK	2	\$ 800.00	\$ 1,600.00	
12	CARBON FIBRE FOG LAMP MOULDING - TOP / CRK	2	\$ 450.00	\$ 900.00	
13	CARBON FIBRE FOG LAMP MOULDING - BTM / CRK	2	\$ 450.00	\$ 900.00	
14	FOG LAMP COVER / CRK / LH X SVL	2	\$ 380.00	\$ 760.00	X Pt Δ
15	REAR BOOTLID LIPS / NEL	1	\$ 1,600.00	\$ 1,600.00	X SVL Δ
16	REAR BUMPER LOWER DIFFUSER - CARBON / CRK	1	\$ 2,800.00	\$ 2,800.00	
17	DIFFUSER LAMP / CRK	1	\$ 600.00	\$ 600.00	
18	REAR BUMPER / CRK	1	\$ 3,600.00	\$ 3,600.00	
19	REAR EXHAUST DIFFUSER ?	2	\$ 800.00	\$ 1,600.00	
20	BODY STICKER - COMPLETE / NEL	1	\$ 2,600.00	\$ 2,600.00	
21	REAR END PANEL SEALANT ?	1	\$ 100.00	\$ 100.00	
22	SPARE WHEEL PANEL SEALANT ?	1	\$ 100.00	\$ 100.00	
23	RADIATOR COOLANT ?	1	\$ 200.00	\$ 200.00	X Δ
24	SPARE WHEEL INSULATOR ?	1	\$ 400.00	\$ 400.00	
25	FRONT BUMPER CLIPS / NEL	1	\$ 100.00	\$ 100.00	
26	FRONT BONNET ISOLATOR CLIPS ?	1	\$ 100.00	\$ 100.00	
27	FRONT FENDER COWLING CLIPS ?	1	\$ 100.00	\$ 100.00	
28	REAR BUMPER CLIPS / NEL	1	\$ 100.00	\$ 100.00	
29	REAR FENDER COWLING CLIPS B X NN	1	\$ 100.00	\$ 100.00	
30	REAR FENDER INNER TRIM CLIPS X NN	1	\$ 100.00	\$ 100.00	
31	BOOTLID INNER TRIM CLIPS ?	1	\$ 100.00	\$ 100.00	
32	REAR END PANEL TOP GARNISH CLIPS ?	1	\$ 100.00	\$ 100.00	

TOTAL \$ 31,920.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS - FRONT	1,400 \$ 2,000.00	800 1,000 600 Δ
1	PANEL BEATING, REMOVAL AND REPLACING PARTS - REAR	\$ 2,800.00	800 1,000 800 Δ
2	TO SPRAY PAINT AFFECTED AREA - FRONT	\$ 1,800.00	1,400 1000 Δ

2	TO SPRAY PAINT AFFECTED AREA - REAR	\$ 2,600.00	1,000	800	5
3	TUFF COAT	\$ 250.00	150		
4	WIRING CHECK	\$ 180.00	100		30 Δ
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 600.00	X NN		
6	CONDUCT WATER LEAKAGE TEST	\$ 100.00	50		X Δ
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	40		
12	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD	\$ 200.00	?		60 Δ
13	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	\$ 250.00	?		X Δ
14	TO RNR UNDERCARRIAGE SYSTEM	\$ 350.00	?		X Δ
15	TO CHECK WHEEL ALIGNMENT	\$ 150.00	X NN		X Δ
16	TO RNR A/C CONDENSOR ASSY AND REFILL GAS	\$ 150.00	?		100 Δ
17	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	\$ 80.00	50		30 Δ
19	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	\$ 150.00	?		80 Δ
20	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	\$ 100.00	?		X Rpt. Δ
22	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 800.00	?		200 Δ

TOTAL \$ 12,640.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 31,920.00
TOTAL LABOUR COST : \$ 12,640.00
TOTAL REPAIR COST : \$ 44,560.00

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

KELVIN WO

NA 2 CLK
5/11/19 1700
- L/S
10 DAYS -
CHECK ITEMS PHOTO
AFTER REPAIR PHOTO.

[Signature]
6/11/19

JWG INTERNATIONAL PTE. LTD.

Co. & GST Reg. No.: 201837488H

Blk 10, Ang Mo Kio Ind Park 2A,

#03-08 AMK AutoPoint,

Singapore 568047

H/P: 9069 7882 Fax: 6909 9592

E-Mail: jwg.claims@yahoo.com

DATE : 4/11/2019

VEHICLE NO : SMJ 9789 S
MODEL : MERCEDES E200
CHASSIS NO :

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BOOTLID / DD	1	\$ -	\$ -
2	REAR BOOTLID CENTER CHROME XSVL	1	\$ -	\$ -
3	REAR BOOTLID NUMBER PLATE LAMP XSVL	2	\$ -	\$ -
4	REAR BOOTLID EMBLEM E200 / NEL	1	\$ -	\$ -
5	REAR BOOTLID LOGO / NEL	1	\$ -	\$ -
6	REAR BOOTLID LOCK / BT	1	\$ -	\$ -
7	REAR BOOTLID CATCH XSVL	1	\$ -	\$ -
8	REAR BOOTLID HINGE XSVL	2	\$ -	\$ -
9	REAR BOOTLID HINGE GARNISH XSVL	2	\$ -	\$ -
10	REAR BOOTLID VACUUM LOCK COMPLETE ?	1	\$ -	\$ -
11	REAR BOOTLID INNER LOCK XSVL	1	\$ -	\$ -
12	REAR BOOTLID LOCK XSVL	1	\$ -	\$ -
13	REAR BOOTLID STOPPER XSVL	2	\$ -	\$ -
14	REAR BOOTLID SEAL XSVL	2	\$ -	\$ -
15	REAR BOOTLID OPERNER XSVL	1	\$ -	\$ -
16	REAR BOOTLID WEATHERSTRIP / DEF	1	\$ -	\$ -
17	REAR BOOTLID INNER TRIM R XSVL	1	\$ -	\$ -
19	REAR BUMPER SIDE RETAINER R XSVL	2	\$ -	\$ -
20	REAR BUMPER BRACKET R XSVL	2	\$ -	\$ -
21	REAR BUMPER REFLECTOR ✓ LH / SVL RH XSVL	2	\$ -	\$ -
22	REAR BUMPER TOW COVER / DEF	1	\$ -	\$ -
23	REAR BUMPER REVERSE SENSOR / MJS	4	\$ -	\$ -
24	REAR BUMPER REVERSE SENSOR HOLDER / N8	4	\$ -	\$ -
25	REVERSE SENSOR WIREHARNES R / NEL	1	\$ -	\$ -
26	REAR BUMPER CARRIER R / DEF	1	\$ -	\$ -
27	REAR BUMPER SPONGE R XSVL	1	\$ -	\$ -
28	REAR BUMPER REINFORCEMENT R / BT	1	\$ -	\$ -
29	REAR END PANEL R XSVL / DEF	1	\$ -	\$ -

not working

	30	REAR END PANEL INNER SUPPORT	2 XSVL	1	\$	-	\$	-
	31	REAR END PANEL TOP GARNISH	2 / CR	1	\$	-	\$	-
XSVL	32	REAR SPARE WHEEL PANEL	2	1	\$	-	\$	-
XSVL	33	REAR SPARE WHEEL QUARTER PANEL LH	2	1	\$	-	\$	-
XSVL	34	REAR SPARE WHEEL CONTAINER BOX	2	1	\$	-	\$	-
XSVL	35	REAR SPARE WHEEL TOP BOARD	2	1	\$	-	\$	-
XNL	36	REAR SPARE WHEEL BOOTLID MOTOR	2	1	\$	-	\$	-
	37	REAR BUMPER UNDERCOVER	1 CRH	1	\$	-	\$	-
/ DEF	38	REAR BUMPER SENSOR DETECTOR	2	1	\$	-	\$	-
	39	REAR BUMPER SENSOR DETECTOR WIRE HARNESS	CONTROL M 2	1	\$	-	\$	-
	40	REAR FENDER	XSVL Y LH R 2 X SVL	2	\$	-	\$	-
	41	REAR FENDER COWLING	XSVL	2	\$	-	\$	-
	42	REAR FENDER INNER TRIM	XSVL	2	\$	-	\$	-
	43	REAR FENDER AIR DUCT	XSVL	2	\$	-	\$	-
	44	WINDSCREEN COMPLETE WITH MOULDING	XNN	1	\$	-	\$	-
	45	TAILLAMP	2 / CR	2	\$	-	\$	-
	46	TAILLAMP PANEL	2 XSVL	2	\$	-	\$	-
	47	TAILLAMP CLIPS	2 / NEL	2	\$	-	\$	-
	48	TAILLAMP GARNISH	2 XSVL	2	\$	-	\$	-
	49	BOOTLID INNER SIDE GARNISH	2 XSVL	2	\$	-	\$	-
	50	REAR EXHAUST PIPE COMPLETE	2 XSVL	1	\$	-	\$	-
	51	REAR EXHAUST PIPE GASKET	2 XSVL	1	\$	-	\$	-
	52	REAR EXHAUST PIPE HEAT SHEID	2 / DEF	1	\$	-	\$	-
	53	REAR EXHAUST PIPE MOUNTING	2 XSVL	1	\$	-	\$	-
	54	DRIVER HEADREST COMPLETE SET	/ NEL	1	\$	-	\$	-
	55	PASSANGER HEADREST COMPLETE SET	/ NEL	1	\$	-	\$	-
	56	DRIVER SEAT BELT	/ SAM	1	\$	-	\$	-
	57	DRIEVR SEAT BELT BUCKET	XSVL	1	\$	-	\$	-
	58	PASSANGER SEAT BELT	/ SAM	1	\$	-	\$	-
	59	PASSANGER SEAT BELT BUCKET	XSVL	1	\$	-	\$	-
	60	REAR SEAT BELT	/ RH	2	\$	-	\$	-
	61	REAR SEAT BELT BUCKET	XSVL	2	\$	-	\$	-
	62	CENTER SEAT BELT	X SVL	1	\$	-	\$	-
	63	CENTER SEAT BELT BUCKET	XSVL	1	\$	-	\$	-
	64	SRS CONTROL MODULE	/ NEL	1	\$	-	\$	-
	65	FRONT BONNET	/ DD	1	\$	-	\$	-
	66	FRONT BONNET SEAL	2 / NEL	1	\$	-	\$	-
	67	FRONT BONNET LOGO	/ NEL	1	\$	-	\$	-
	68	FRONT BONNET ISOLATOR	2 XSVL	1	\$	-	\$	-
	69	FRONT BONNET HINGE	2 XSVL	2	\$	-	\$	-
	70	FRONT BONNET LOCK	2 XSVL	2	\$	-	\$	-

71	FRONT BONNET WEATHERSTRIP	9 XSVL	1	\$ -	\$ -
72	FRONT BUMPER SIDE RETAINER	2 XSVL	2	\$ -	\$ -
73	FRONT BUMPER BRACKET	2 XSVL	2	\$ -	\$ -
74	FRONT BUMPER TOW COVER	1 DEF	1	\$ -	\$ -
75	FRONT GRILLE TRIM	1 DEF	1	\$ -	\$ -
76	FRONT GRILLE CENTER AIR GUIDE	1 BR	1	\$ -	\$ -
77	FRONT GRILLE SIDE AIR GUIDE	2 DEF	2	\$ -	\$ -
78	FRONT BUMPER NUMBER PLATE GARNISH	1 MS	1	\$ -	\$ -
79	FRONT BUMPER AIR DUCT	1 XSVL	1	\$ -	\$ -
80	FRONT BUMPER SPONGE	2 XSVL	1	\$ -	\$ -
81	FRONT BUMPER SIDE SPONGE	1 XSVL	2	\$ -	\$ -
82	FRONT BUMPER REINFORCEMENT	1 BT	1	\$ -	\$ -
83	FRONT BUMPER CARRIER	1 DEF	1	\$ -	\$ -
84	FRONT BUMPER PARKING SENSOR	6 XSVL	6	\$ -	\$ -
85	FRONT BUMPER PARKING SENSOR HOLDER	6 XSVL	6	\$ -	\$ -
86	FRONT BUMPER PARKING SENSOR WIREHARN	1 XSVL	1	\$ -	\$ -
87	FRONT SUPPORT PANEL	1 DEF	1	\$ -	\$ -
88	FRONT SUPPORT SIDE PANEL	2 XSVL	2	\$ -	\$ -
89	TEMPERATURE SENSOR	1 XSVL	1	\$ -	\$ -
90	HEADLAMP	2 CRK	2	\$ -	\$ -
91	HEADLAMP PANEL	2 XSVL	2	\$ -	\$ -
92	HEADLAMP SIDE BRACKET	2 XSVL	2	\$ -	\$ -
93	HEADLAMP PANEL LOWER SUPPORT	2 XSVL	2	\$ -	\$ -
94	HEADLAMP SEAL	2 XSVL	2	\$ -	\$ -
95	FRONT FENDER	2 RH BT LH XSVL	2	\$ -	\$ -
96	FRONT FENDER COWLING	2 XSVL	2	\$ -	\$ -
97	FRONT FENDER INNER TRIM	2 XSVL	2	\$ -	\$ -
98	TURBO INTERCOOLER	1 XSVL	1	\$ -	\$ -
99	TURBO INTERCOOLER SUPPORT	1 XSVL	1	\$ -	\$ -
100	AUTO TRANSMISSION OIL COOLER	1 DEF	1	\$ -	\$ -
101	A/C CONDENSOR	1 DEF	1	\$ -	\$ -
102	A/C HIGH PRESSURE PIPE	1 XSVL	1	\$ -	\$ -
103	A/C LOW PRESSURE PIPE	1 XSVL	1	\$ -	\$ -
104	A/C DISCHARGE PIPE	1 XSVL	1	\$ -	\$ -
105	RADIATOR ASSY	1 DEF	1	\$ -	\$ -
106	RADIATOR FAN MOTOR COMPLETE	1 CRK	1	\$ -	\$ -

TOTAL PRICE	\$ -
LESS 10%	\$ -
SUB TOTAL PRICE	\$ -

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE	1	\$ 180.00	\$ 180.00

3/NET

CRK

2	REAR NUMBER PLATE / NEL	1	\$ 180.00	\$ 180.00
3	FRONT BUMPER / CRK	1	\$ 3,800.00	\$ 3,800.00
4	FRONT GRILLE COMPLETE / CRK	1	\$ 2,600.00	\$ 2,600.00
5	FRONT GRILLE LOGO / MIS	1	\$ 450.00	\$ 450.00
6	FRONT GRILLE BASE / MJ	1	\$ 1,000.00	\$ 1,000.00
7	FRONT GRILLE EMBLEM / NEL	1	\$ 250.00	\$ 250.00
8	FRONT LOWER GRILLE COMPLETE ?	1	\$ 1,200.00	\$ 1,200.00
9	FRONT LOWER GRILLE CARBON FIBRE MOULD	1	\$ 900.00	\$ 900.00
10	FRONT BUMPER CARBON FIBRE LIPS / CRK	1	\$ 2,800.00	\$ 2,800.00
11	CARBON FIBRE FOG LAMP PROTECTOR / CRK	2	\$ 800.00	\$ 1,600.00
12	CARBON FIBRE FOG LAMP MOULDING - TOP / CRK	2	\$ 450.00	\$ 900.00
13	CARBON FIBRE FOG LAMP MOULDING - BTM / CRK	2	\$ 450.00	\$ 900.00
14	FOG LAMP COVER / CRK LH X SVL	2	\$ 380.00	\$ 760.00
15	REAR BOOTLID LIPS / NEL	1	\$ 1,600.00	\$ 1,600.00
16	REAR BUMPER LOWER DIFFUSER - CARBON / CRK	1	\$ 2,800.00	\$ 2,800.00
17	DIFFUSER LAMP / CRK	1	\$ 600.00	\$ 600.00
18	REAR BUMPER / CRK	1	\$ 3,600.00	\$ 3,600.00
19	REAR EXHAUST DIFFUSER ? / DEF	2	\$ 800.00	\$ 1,600.00
20	BODY STICKER - COMPLETE / NEL	1	\$ 2,600.00	\$ 2,600.00
21	REAR END PANEL SEALANT ? / NEL	1	\$ 100.00	\$ 100.00
22	SPARE WHEEL PANEL SEALANT ? X NN	1	\$ 100.00	\$ 100.00
23	RADIATOR COOLANT ? / NEL	1	\$ 200.00	\$ 200.00
24	SPARE WHEEL INSULATOR ? X SVL	1	\$ 400.00	\$ 400.00
25	FRONT BUMPER CLIPS / NEL	1	\$ 100.00	\$ 100.00
26	FRONT BONNET ISOLATOR CLIPS ? / NEL	1	\$ 100.00	\$ 100.00
27	FRONT FENDER COWLING CLIPS ? X NN	1	\$ 100.00	\$ 100.00
28	REAR BUMPER CLIPS / NEL	1	\$ 100.00	\$ 100.00
29	REAR FENDER COWLING CLIPS ? X NN	1	\$ 100.00	\$ 100.00
30	REAR FENDER INNER TRIM CLIPS X NN	1	\$ 100.00	\$ 100.00
31	BOOTLID INNER TRIM CLIPS ? / NEL	1	\$ 100.00	\$ 100.00
32	REAR END PANEL TOP GARNISH CLIPS ? / NEL	1	\$ 100.00	\$ 100.00

TOTAL \$ 31,920.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS - FRONT	4,400 \$ 2,000.00	8,000 1,000
1	PANEL BEATING, REMOVAL AND REPLACING PARTS - REAR	\$ 2,800.00	800 1,000
2	TO SPRAY PAINT AFFECTED AREA - FRONT	\$ 1,800.00	1,400

2	TO SPRAY PAINT AFFECTED AREA - REAR	\$ 2,800.00	1,000
3	TUFF COAT	\$ 250.00	150
4	WIRING CHECK	\$ 180.00	100
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 600.00	X NN
6	CONDUCT WATER LEAKAGE TEST	\$ 100.00	50
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	40
12	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD	\$ 200.00	2/50
13	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	\$ 250.00	2/50
14	TO RNR UNDERCARRIAGE SYSTEM	\$ 350.00	2 X NN
15	TO CHECK WHEEL ALIGNMENT	\$ 150.00	X NN
16	TO RNR A/C CONDENSOR ASSY AND REFILL GAS	\$ 150.00	2/100
17	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	\$ 80.00	50
19	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	\$ 150.00	2/100
20	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	\$ 100.00	2/40
22	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 800.00	2/1000

TOTAL \$ 12,640.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 31,920.00
TOTAL LABOUR COST : \$ 12,640.00
TOTAL REPAIR COST : \$ 44,560.00

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

KELVIN WO

NA 2 CLK
5/11/19 1700
- LK
10 DAYS -
CHECK ITEMS PHOTO

KELVIN WO
HP 9069 7882

JWG INTERNATIONAL PTE. LTD.

Co. & GST Reg. No.: 201837488H

Blk 10, Ang Mo Kio Ind Park 2A,

#03-08 AMK AutoPoint,

Singapore 568047

H/P: 9069 7882 Fax: 6909 9592

E-Mail: jwg.claims@yahoo.com

DATE : 4/11/2019

VEHICLE NO : SMJ 9789 S

MODEL : MERCEDES E200

CHASSIS NO :

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER SUPPORT BAR	1	\$ -	\$ -
2	FRONT BUMPER SUPPORT BAR BRACKET	1	\$ -	\$ -
3	REAR SENSOR DETECTOR CONTROL MODULE	2	\$ -	\$ -

TOTAL PRICE	\$ -
LESS 10%	\$ -
SUB TOTAL PRICE	\$ -

/ BT
/ DEF
/ not working

W.K. Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JWG INTERNATIONAL PTE. LTD.

Co. & GST Reg. No.: 201837488H

Blk 10, Ang Mo Kio Ind Park 2A,

#03-08 AMK AutoPoint,

Singapore 568047

H/P: 9069 7882 Fax: 6909 9592

E-Mail: jwg.claims@yahoo.com

DATE :

4/11/2019

VEHICLE NO : SMJ 9789 S

MODEL : MERCEDES E200

CHASSIS NO :

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BOOTLID / DD	1	\$ -	\$3145.00
2	REAR BOOTLID CENTER CHROME X SVL	1	\$ -	\$240.00
3	REAR BOOTLID NUMBER PLATE LAMP X SVL	2	\$ 49.50	\$99.00
4	REAR BOOTLID EMBLEM E200 / NPL	1	\$ -	\$157.50
5	REAR BOOTLID LOGO / NEL	1	\$ -	\$90.00
6	REAR BOOTLID LOCK / BT	1	\$ -	\$445.00
7	REAR BOOTLID CATCH X SVL	1	\$ -	\$795.00
8	REAR BOOTLID HINGE X SVL	2	\$ 457.50	\$915.00
9	REAR BOOTLID HINGE GARNISH X SVL	2	\$ 42.00	\$84.00
10	REAR BOOTLID VACUUM LOCK COMPLETE	1	\$ -	\$1688.70
11	REAR BOOTLID INNER LOCK X SVL	1	\$ -	\$562.00
12	REAR BOOTLID LOCK X SVL	1	\$ -	\$388.00
13	REAR BOOTLID STOPPER X SVL	2	\$ 48.00	\$96.00
14	REAR BOOTLID SEAL X SVL	2	\$ 585.00	\$1170.00
15	REAR BOOTLID OPERNER X SVL	1	\$ -	\$645.00
16	REAR BOOTLID WEATHERSTRIP / DEF	1	\$ -	\$540.00
17	REAR BOOTLID INNER TRIM R X SVL	1	\$ -	\$525.00
19	REAR BUMPER SIDE RETAINER R X SVL	2	\$ 142.50	\$285.00
20	REAR BUMPER BRACKET R X SVL	2	\$ 112.50	\$225.00
21	REAR BUMPER REFLECTOR ✓ LH / SVL RH X SVL	2	\$ 52.50	\$105.00
22	REAR BUMPER TOW COVER / DEF	1	\$ -	\$114.00
23	REAR BUMPER REVERSE SENSOR / MIS	24	\$ 42.50	\$1020.00
24	REAR BUMPER REVERSE SENSOR HOLDER / NPL	24	\$ 88.00	\$2112.00
25	REVERSE SENSOR WIREHARNESS R / NEL	1	\$ -	\$2480.00
26	REAR BUMPER CARRIER R / DEF	1	\$ -	\$139.50
27	REAR BUMPER SPONGE R X SVL	1	\$ -	\$550.00
28	REAR BUMPER REINFORCEMENT R / BT	1	\$ -	\$445.00
29	REAR END PANEL R X SVL / DEF	1	\$ -	\$2440.00

2,293 (2293/DD)

157.50 / NEL

90 / NEL

200 / BT

800 / not working

300 / DEF

\$52.50 / LH SCR

147 / DEF

500 / MIS

80 / NEL

1,000 / NEL

\$139.50 / DEF

465 / BT

1,300 / DEF

21,698.70 \$7524.50

not working

21/4 NGZ ✓

21/4 NGZ ✓

30	REAR END PANEL INNER SUPPORT	2 XSVL	1	\$ -	\$ 645.00 -
31	REAR END PANEL TOP GARNISH	2 / CRK	1	\$ -	\$ 144.00 -
32	REAR SPARE WHEEL PANEL	2	1	\$ -	\$ 292.50 -
33	REAR SPARE WHEEL QUARTER PANEL LH	2	1	\$ -	\$ 523.50 -
34	REAR SPARE WHEEL CONTAINER BOX	2	1	\$ -	\$ 1035.00 -
35	REAR SPARE WHEEL TOP BOARD	2	1	\$ -	\$ 840.00 -
36	REAR SPARE WHEEL BOOTLID MOTOR	2	1	\$ -	\$ 1430.00 -
37	REAR BUMPER UNDERCOVER	1 / CRK	1	\$ -	\$ 465.00 -
38	REAR BUMPER SENSOR DETECTOR	2	1	\$ -	\$ 195.00 -
39	REAR BUMPER SENSOR DETECTOR WIRE HARNESS	2	1	\$ -	\$ 210.00 -
40	REAR FENDER	2 XSVL	12	\$ 3825.00	\$ 7650.00 -
41	REAR FENDER COWLING	XSVL	2	\$ 342.00	\$ 684.00 -
42	REAR FENDER INNER TRIM	XSVL	2	\$ 322.50	\$ 645.00 -
43	REAR FENDER AIR DUCT	XSVL	2	\$ 45.00	\$ 90.00 -
44	WINDSCREEN COMPLETE WITH MOULDING	XSVL	1	\$ -	\$ 285.00 -
45	TAILLAMP	2 / CRK	2	\$ 1350.00	\$ 2700.00 -
46	TAILLAMP PANEL	2 XSVL	2	\$ 322.50	\$ 645.00 -
47	TAILLAMP CLIPS	2 / NEC	2	\$ 20.00	\$ 40.00 -
48	TAILLAMP GARNISH	2 XSVL	2	\$ 98.00	\$ 196.00 -
49	BOOTLID INNER SIDE GARNISH	2 XSVL	2	\$ 82.50	\$ 165.00 -
50	REAR EXHAUST PIPE COMPLETE	2 XSVL	1	\$ -	\$ 3225.00 -
51	REAR EXHAUST PIPE GASKET	2 XSVL	1	\$ -	\$ 39.00 -
52	REAR EXHAUST PIPE HEAT SHEILD	2 / DEF	1	\$ -	\$ 535.00 -
53	REAR EXHAUST PIPE MOUNTING	2 XSVL	1	\$ -	\$ 67.50 -
54	DRIVER HEADREST COMPLETE SET	1 / NEC	1	\$ -	\$ 885.00 -
55	PASSANGER HEADREST COMPLETE SET	1 / NEC	1	\$ -	\$ 885.00 -
56	DRIVER SEAT BELT	1 / JAM 750	1	\$ -	\$ 2505.00 -
57	DRIVER SEAT BELT BUCKET	XSVL	1	\$ -	\$ 240.00 -
58	PASSANGER SEAT BELT	1 / JAM 750	1	\$ -	\$ 2505.00 -
59	PASSANGER SEAT BELT BUCKET	XSVL	1	\$ -	\$ 240.00 -
60	REAR SEAT BELT	1 / JAM 650	12	\$ 2230.00	\$ 4460.00 -
61	REAR SEAT BELT BUCKET	XSVL	2	\$ 180.00	\$ 360.00 -
62	CENTER SEAT BELT	XSVL	1	\$ -	\$ 615.00 -
63	CENTER SEAT BELT BUCKET	XSVL	1	\$ -	\$ 180.00 -
64	SRS CONTROL MODULE	1 / NEC	1	\$ -	\$ 2650.00 -
65	FRONT BONNET	1 / DD	1	\$ -	\$ 3475.00 -
66	FRONT BONNET SEAL	2 / NEC	1	\$ -	\$ 122.00 -
67	FRONT BONNET LOGO	1 / NEC	1	\$ -	\$ 135.00 -
68	FRONT BONNET ISOLATOR	2 XSVL	1	\$ -	\$ 480.00 -
69	FRONT BONNET HINGE	2 XSVL	2	\$ 337.50	\$ 675.00 -
70	FRONT BONNET LOCK	2 XSVL	2	\$ 120.00	\$ 240.00 -

144 / CRK

465 / CRK

195 / DEF

XSVL
1700 / XR

1,600 / CRK

40 / NEC

300 / DEF

X(R)
X(R)
1,000 / JAM

1,000 / JAM

2,000 / JAM

800 / NEC

2,500 / DD

122 / NEC

135 / NEC

71	FRONT BONNET WEATHERSTRIP	1	\$ -	\$ 248.00 -
72	FRONT BUMPER SIDE RETAINER	2	\$ 112.50 -	\$ 225.00 -
73	FRONT BUMPER BRACKET	2	\$ 68.00 -	\$ 136.00 -
74	FRONT BUMPER TOW COVER	1	\$ -	\$ 112.50 -
75	FRONT GRILLE TRIM	1	\$ -	\$ 292.50 -
76	FRONT GRILLE CENTER AIR GUIDE	1	\$ -	\$ 440.00 -
77	FRONT GRILLE SIDE AIR GUIDE	2	\$ 289.00 -	\$ 578.00 -
78	FRONT BUMPER NUMBER PLATE GARNISH	1	\$ -	\$ 202.50 -
79	FRONT BUMPER AIR DUCT	1	\$ -	\$ 240.00 -
80	FRONT BUMPER SPONGE	1	\$ -	\$ 279.00 -
81	FRONT BUMPER SIDE SPONGE	2	\$ 233.00 -	\$ 466.00 -
82	FRONT BUMPER REINFORCEMENT	1	\$ -	\$ 967.50 -
83	FRONT BUMPER CARRIER	1	\$ -	\$ 187.50 -
84	FRONT BUMPER PARKING SENSOR	2	\$ 487.50 -	\$ 975.00 -
85	FRONT BUMPER PARKING SENSOR HOLDER	2	\$ 89.00 -	\$ 178.00 -
86	FRONT BUMPER PARKING SENSOR WIREHARN	1	\$ -	\$ 810.00 -
87	FRONT SUPPORT PANEL	1	\$ -	\$ 570.00 -
88	FRONT SUPPORT SIDE PANEL	2	\$ 285.00 -	\$ 570.00 -
89	TEMPERATURE SENSOR	1	\$ -	\$ 97.50 -
90	HEADLAMP	2	\$ 480.00 -	\$ 960.00 -
91	HEADLAMP PANEL	2	\$ 238.00 -	\$ 476.00 -
92	HEADLAMP SIDE BRACKET	2	\$ 303.00 -	\$ 606.00 -
93	HEADLAMP PANEL LOWER SUPPORT	2	\$ 218.00 -	\$ 436.00 -
94	HEADLAMP SEAL	2	\$ 150.00 -	\$ 300.00 -
95	FRONT FENDER	2	\$ 1725.00 -	\$ 3450.00 -
96	FRONT FENDER COWLING	2	\$ 345.00 -	\$ 690.00 -
97	FRONT FENDER INNER TRIM	2	\$ 337.50 -	\$ 675.00 -
98	TURBO INTERCOOLER	1	\$ -	\$ 3818.00 -
99	TURBO INTERCOOLER SUPPORT	1	\$ -	\$ 240.00 -
100	AUTO TRANSMISSION OIL COOLER	1	\$ -	\$ 975.00 -
101	A/C CONDENSOR	1	\$ -	\$ 2512.50 -
102	A/C HIGH PRESSURE PIPE	1	\$ -	\$ 210.00 -
103	A/C LOW PRESSURE PIPE	1	\$ -	\$ 225.00 -
104	A/C DISCHARGE PIPE	1	\$ -	\$ 480.00 -
105	RADIATOR ASSY	1	\$ 900 -	\$ 1175.50 -
106	RADIATOR FAN MOTOR COMPLETE	1	\$ -	\$ 945.00 -

112.50 / DEF
 292.50 / DEF
 440 - BR
 578 - DEF
 XNF Δ
 500 / BT
 187.50 / DEF
 500 / not working
 80 / nec
 900 / DEF
 4,000 / CRK
 1,000 / RH BT
 600 / DEF
 1,500 / DEF
 900 / DEF
 36,892 / DEF
 700 / CRK

TOTAL PRICE \$ -
 LESS 10% \$ -
 SUB TOTAL PRICE \$ 12,290.50

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE	1	\$ 180.00	\$ 180.00

30 Δ

3/12/21

CRK

2	REAR NUMBER PLATE	NEC X SVL	1	\$ 180.00	\$ 180.00	X SVL X Δ
3	FRONT BUMPER	/ CRK	1	\$ 3,800.00	\$ 3,800.00	2000 / CRK
4	FRONT GRILLE COMPLETE	/ CRK	1	\$ 2,600.00	\$ 2,600.00	Come together Δ
5	FRONT GRILLE LOGO	/ MIS	1	\$ 450.00	\$ 450.00	2,500
6	FRONT GRILLE BASE	/ MIS	1	\$ 1,000.00	\$ 1,000.00	
7	FRONT GRILLE EMBLEM	NEC X RPT	1	\$ 250.00	\$ 250.00	X RPT Δ
8	FRONT LOWER GRILLE COMPLETE	? X SVL	1	\$ 1,200.00	\$ 1,200.00	
9	FRONT LOWER GRILLE CARBON FIBRE MOULD		1	\$ 900.00	\$ 900.00	600 / CRK
10	FRONT BUMPER CARBON FIBRE LIPS	/ CRK	1	\$ 2,800.00	\$ 2,800.00	1000 / CRK
11	CARBON FIBRE FOG LAMP PROTECTOR	/ CRK	2	\$ 800.00	\$ 1,600.00	1000 / CRK
12	CARBON FIBRE FOG LAMP MOULDING - TOP	/ CRK	2	\$ 450.00	\$ 900.00	600 / CRK
13	CARBON FIBRE FOG LAMP MOULDING - BTM	/ CRK	2	\$ 450.00	\$ 900.00	600 / CRK
14	FOG LAMP COVER	Y LH - CRK X SVL LH X SVL	2	\$ 380.00	\$ 760.00	X RPT Δ
15	REAR BOOTLID LIPS	NEC X SVL	1	\$ 1,600.00	\$ 1,600.00	X SVL Δ
16	REAR BUMPER LOWER DIFFUSER - CARBON	/ CRK	1	\$ 2,800.00	\$ 2,800.00	1200 / CRK
17	DIFFUSER LAMP	/ CRK	1	\$ 600.00	\$ 600.00	600 / CRK
18	REAR BUMPER	/ CRK	1	\$ 3,600.00	\$ 3,600.00	2,000 / CRK
19	REAR EXHAUST DIFFUSER	2 / DEF	2	\$ 800.00	\$ 1,600.00	900 / DEF
20	BODY STICKER - COMPLETE	/ NEC	1	\$ 2,600.00	\$ 2,600.00	2,000 / NEC
21	REAR END PANEL SEALANT	2 / NEC	1	\$ 100.00	\$ 100.00	100 / NEC
22	SPARE WHEEL PANEL SEALANT	2 X NN	1	\$ 100.00	\$ 100.00	
23	RADIATOR COOLANT	2 / NEC X NN	1	\$ 200.00	\$ 200.00	X NN Δ
24	SPARE WHEEL INSULATOR	2 X SVL	1	\$ 400.00	\$ 400.00	
25	FRONT BUMPER CLIPS	/ NEC 50	1	\$ 100.00	\$ 100.00	100 / NEC
26	FRONT BONNET ISOLATOR CLIPS	2 / NEC 50	1	\$ 100.00	\$ 100.00	100 / NEC
27	FRONT FENDER COWLING CLIPS	2 X NN	1	\$ 100.00	\$ 100.00	
28	REAR BUMPER CLIPS	/ NEC 50	1	\$ 100.00	\$ 100.00	100 / NEC
29	REAR FENDER COWLING CLIPS	2 X NN	1	\$ 100.00	\$ 100.00	
30	REAR FENDER INNER TRIM CLIPS	X NN	1	\$ 100.00	\$ 100.00	
31	BOOTLID INNER TRIM CLIPS	2 / NEC 50	1	\$ 100.00	\$ 100.00	100 / NEC
32	REAR END PANEL TOP GARNISH CLIPS	2 / NEC	1	\$ 100.00	\$ 100.00	100 / NEC
50				TOTAL	\$ 31,920.00	16,600

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS - FRONT	\$ 2,400.00	2,400.00 (600)
1	PANEL BEATING, REMOVAL AND REPLACING PARTS - REAR	\$ 2,800.00	300.00 (800)
2	TO SPRAY PAINT AFFECTED AREA - FRONT	\$ 1,800.00	1,400.00 (1,000)

2	TO SPRAY PAINT AFFECTED AREA - REAR	\$ 2,000.00	1,000 800 Δ
3	TUFF COAT	\$ 250.00	150
4	WIRING CHECK	\$ 180.00	100 30 Δ
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 600.00	X NN
6	CONDUCT WATER LEAKAGE TEST	\$ 100.00	50 X NN Δ
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	40
12	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD	\$ 200.00	1/160 Δ
13	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	\$ 250.00	1/50 X NN Δ
14	TO RNR UNDERCARRIAGE SYSTEM	\$ 350.00	1/2 X NN Δ
15	TO CHECK WHEEL ALIGNMENT	\$ 150.00	X NN Δ
16	TO RNR A/C CONDENSOR ASSY AND REFILL GAS	\$ 150.00	1/100 Δ
17	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	\$ 80.00	30 Δ
19	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	\$ 150.00	1/100 80 Δ
20	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	\$ 100.00	1/40 X RLT
22	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 800.00	1/800 200 Δ

TOTAL

\$ 12,640.00

3,890

ESTIMATE REPORT

136, 251. 28

TOTAL PARTS COST : \$ 31,920.00
TOTAL LABOUR COST : \$ 12,640.00
TOTAL REPAIR COST : \$ 44,560.00

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

KELVIN WO

NA 2 CLK
5/11/19 1700
- LK
10 DAYS -
CITE

KELVIN WO
HP 9069 7882

JWG INTERNATIONAL PTE. LTD.

Co. & GST Reg. No.: 201837488H

Blk 10, Ang Mo Kio Ind Park 2A,

#03-08 AMK AutoPoint,

Singapore 568047

H/P: 9069 7882 Fax: 6909 9592

E-Mail: jwg.claims@yahoo.com

DATE : 4/11/2019

VEHICLE NO : SMJ 9789 S
MODEL : MERCEDES E200
CHASSIS NO :

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER SUPPORT BAR	1	\$ -	\$ 1480.70
2	FRONT BUMPER SUPPORT BAR BRACKET	1	\$ -	\$ 988.00
3	REAR SENSOR DETECTOR CONTROL MODULE	2	\$ 1475.00	\$ 2950.00

/ BT

/ DEF

/ not working

TOTAL PRICE \$ -
LESS 10% \$ -
SUB TOTAL PRICE \$ -

P \$ 61,686.40
Less 10% \$ 55,517.76

S/N \$ 30,740.00

L \$ 5,530.00

T \$ 91,787.76

LS \$ 73,430.20

≈ \$ 73,400.00

10 working days

PARTS : \$ 30,116.00

LESS 10% : \$ 27,104.40

S/NETT : \$ 16,600.00

LABOUR \$ 3,890.00

TOTAL \$ 47,594.40

LESS LIS 20% \$ 38,075.52

\$ 38,100.00 / 10 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PARTS	SN	LABOUR	
2293.00	30.00	600.00	27994.95
157.50	3000.00	800.00	16479
90.00	2500.00	1000.00	3890
200.00	600.00	800.00	48363.95
800.00	1000.00	150.00	20%
300.00	1000.00	30.00	38,691.16
52.50	600.00	40.00	
147.00	600.00	60.00	
500.00	1299.00	100.00	
1000.00	600.00	30.00	
139.50	2000.00	80.00	
80.00	900.00	200.00	
139.50	2000.00	3890.00	
465.00	100.00		
1300.00	50.00		
144.00	50.00		
465.00	50.00		
195.00	50.00		
1600.00	50.00		
40.00	16479.00		
300.00			
750.00			
750.00			
650.00			
800.00			
2500.00			
122.00			
135.00			
112.50			
292.50			
440.00			
578.00			
500.00			
187.50			
500.00			
80.00			
900.00			
4000.00			
1000.00			
600.00			
1500.00			
900.00			
700.00			
800.00			
400.00			
1500.00			
31105.50			
10%			
27994.95			

48,238.40

38,590.72

30,966

27,869.40

Veron Chen (LKKAUTO)

From: JWG CLAIMS <jwg.claims@yahoo.com>
Sent: Tuesday, 24 March 2020 2:11 PM
To: Naz (LKKAUTO)
Cc: SUR; Veron Chen (LKKAUTO)
Subject: RE: SMJ 9789S-DOA: 2/11/2019

Dear all,

Offer accepted .

Warmest Regard,

**JWG INTERNATIONAL
PTE. LTD.**

Co. & GST Reg. No.: 201837488H
Blk 10, Ang Mo Kio Ind Park 2A,
#03-08 AMK AutoPoint,
Singapore 568047

H/P: 9069 7882 | Fax: 6909 9592

E-Mail: jwg.claims@yahoo.com

From: Naz (LKKAUTO)
Sent: Tuesday, March 24, 2020 12:23 PM
To: JWG CLAIMS
Cc: SUR; Veron Chen (LKKAUTO)
Subject: Re: SMJ 9789S-DOA: 2/11/2019

Dear JWG Claims,

Apologies for the late reply. I have checked with senior surveyors Adrian and Marcus. Attached herewith is the amended marked estimate following our check on part prices. We will proceed to finalize if you are agreeable with the amended **Lump Sum COR of \$38,100.00 / 10 REPAIR DAYS;**

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: JWG CLAIMS <jwg.claims@yahoo.com>

Sent: Tuesday, 17 March 2020 5:04 PM

To: Naz (LKKAuto) <Naz@lkkauto.com>

Cc: SUR <sur@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: Re: SMJ 9789S-DOA: 2/11/2019

Dear all,

Any updates on COR \$42,000.00 as we are submitting the LOD to NTUC.

Thank you.

Warmest Regards,
JWG INTERNATIONAL PTE. LTD.

10, Ang Mo Kio Ind Park 2A
#03-08 AMK AutoPoint
Singapore 568047

TEL: 6909 8882 | FAX: 6909 9592

On Thursday, 27 February 2020, 11:32:34 am GMT+8, JWG CLAIMS <jwg.claims@yahoo.com> wrote:

Dear all,

As per Tele- conversation . Let's close the amount at \$42,000.00 /- 10 working days .

Warmest Regard,

JWG INTERNATIONAL
PTE. LTD.

Co. & GST Reg. No.: 201837488H

Blk 10, Ang Mo Kio Ind Park 2A,

#03-08 AMK AutoPoint,

Singapore 568047

H/P: 9069 7882 | Fax: 6909 9592

E-Mail: jwg.claims@yahoo.com

From: Naz (LKKAuto)

Sent: Thursday, February 27, 2020 11:15 AM

To: JWG CLAIMS

Cc: SUR; Veron Chen (LKKAuto)

Subject: Re: SMJ 9789S-DOA: 2/11/2019

Dear JWG Claims,

Apologies for the late reply. Attached herewith is the amended marked estimate following our check on part prices. We will proceed to finalize if you are agreeable with the amended **Lump Sum COR of \$38,500.00 / 10 REPAIR DAYS;**

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: JWG CLAIMS <jwg.claims@yahoo.com>
Sent: Monday, 10 February 2020 11:25 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Naz (LKKAuto) <Naz@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Re: SMJ 9789S-DOA: 2/11/2019

Dear All,

Please let us have the finalization amount as it has been more than a month.

Thank you.

Warmest Regards,
JWG INTERNATIONAL PTE. LTD.

10, Ang Mo Kio Ind Park 2A
#03-08 AMK AutoPoint
Singapore 568047

TEL: 6909 8882 | FAX: 6909 9592

On Friday, 10 January 2020, 10:30:08 am GMT+8, JWG CLAIMS <jwg.claims@yahoo.com> wrote:

Without Prejudice

Dear Sir/Madam,

Change of vehicle's number plate number invoice as attached.

Thanks and Best Regards,

JWG INTERNATIONAL PTE. LTD.
Co. & GST Reg. No.: 201837488H
Blk 10, Ang Mo Kio Ind Park 2A,
#03-08 AMK AutoPoint,
Singapore 568047
Phone: 6909 8882 | Fax: 6909 9592
E-Mail: jwg.claims@yahoo.com

From: [Veron Chen \(LKKAUTO\)](#)
Sent: Thursday, January 9, 2020 8:17 AM
To: [JWG CLAIMS](#); [Naz \(LKKAUTO\)](#)
Cc: [SUR](#)
Subject: RE: SMJ 9789S-DOA: 2/11/2019

Dear Sir,

NAZ is on leave, will follow up with him once he is back.

Refer to your after paint photos vehicle number is different.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: JWG CLAIMS <jwg.claims@yahoo.com>
Sent: Wednesday, 8 January 2020 7:26 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: RE: SMJ 9789S-DOA: 2/11/2019

Without Prejudice

Dear Sir/Madam,

Kindly update us on the status of the finalization as it has been awhile since we've sent the marked estimate and after paint.

Please confirm upon receiving this email.

Thanks and Best Regards,

JWG INTERNATIONAL PTE. LTD.
Co. & GST Reg. No.: 201837488H
Blk 10, Ang Mo Kio Ind Park 2A,
#03-08 AMK AutoPoint,
Singapore 568047

Phone: 6909 8882 | Fax: 6909 9592

E-Mail: jwg.claims@yahoo.com

From: JWG CLAIMS

Sent: Tuesday, December 17, 2019 1:03 PM

To: Veron Chen (LKKAUTO)

Subject: RE: SMJ 9789S-DOA: 2/11/2019

Without Prejudice

Dear Sir/Madam,

After paint as attached.

Thanks and Best Regards,

JWG INTERNATIONAL PTE. LTD.

Co. & GST Reg. No.: 201837488H

Blk 10, Ang Mo Kio Ind Park 2A,

#03-08 AMK AutoPoint,

Singapore 568047

Phone: 6909 8882 | Fax: 6909 9592

E-Mail: jwg.claims@yahoo.com

From: JWG CLAIMS

Sent: Monday, December 16, 2019 2:29 PM

To: Veron Chen (LKKAUTO)

Subject: RE: SMJ 9789S-DOA: 2/11/2019

Without Prejudice

Dear Sir/Madam,

As attached, kindly confirm the finalized amount of **S\$73,400.00/-** for stated vehicle with **10 working days**.

Thanks and Best Regards,

JWG INTERNATIONAL PTE. LTD.

Co. & GST Reg. No.: 201837488H

Blk 10, Ang Mo Kio Ind Park 2A,

#03-08 AMK AutoPoint,

Singapore 568047

Phone: 6909 8882 | Fax: 6909 9592

E-Mail: jwg.claims@yahoo.com

From: Veron Chen (LKKAUTO)

Sent: Thursday, December 5, 2019 9:30 AM

To: jwg.claims@yahoo.com

Subject: SMJ 9789S-DOA: 2/11/2019

Dear Sir,

WITHOUT PREJUDICE

Please forward estimate with parts prices as soon as possible.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)