

ASS. REC. BY:

REF: CS/CT2 19019592/R19f3d Special Instruction:

Surveyor: Rusu ASSIGNMENT (Office)From (Person): Iron Tan Hua Ping of CT2 Date/Time: 6.11.19 11.34.9.9

Estimated Cost: _____ Bill to: _____

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJT 7052H Insured: GBB 88342at Workshop m/s VSix AUTO Tel: 64552457of 26 Chia Ping RoadPolicy No: DMCVSN 19267719000 Claim No: SNM1911 205244002

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 5.11.2019
(Client's Record)CA / REV / REP. / REV 24 HRS mp H.O.D. Endorsement: _____Date/Time: 6.11.19 12.01p.m Person Contacted: Beng Seng Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJT 7052H - X
	GBB 88342 - CS/TP140 16304 / A2012 - R.01 - 25/00/2014
28/11/19 @ 3.07p	Room finalised US & 4600, 8 days. (led to 13145.76, 79%.)

written

INSPECTED BY: Rasul


138F
LOE NO: 2023/26P

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJJ 7052H
 at Workshop m/s VFX
 of 26, CHIA PINH RD
 Insured: CTI
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SJJ 7052H r/ Regn: 2008 / 26P
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: HONDA FIT c.c. 1339
 Colour: Red A/C: Insured / Std / NI / NA
 Sp. Reading: 457158 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 4E61081287
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / STD A/Rim or _____
 Tyre Size: F: 185/60 R15
 R: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: 23K
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 8 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. 5 mm Rear R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 05/11/19 D.O.I. 06/11/19
 Survey held at VFX
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Rasul</u>
	<u>Pls check parts prices</u>
	<u>RECEIVED 11 DEC 2019</u>
	<u>[Signature]</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report
 Date/Time, File Return to?
 Report Format: WEB-TP
 Temp. Sum. TP: 460

Days Of Repair: 8
 Resurvey No. of Trip: 1
 Survey Fee: 270
 Transportation: _____
 Add Fee: Site Insp (\$) Interview (\$) Tech. Invs (\$) Wheel end (\$)
 TOTAL: 270

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Nov 2019		06 Nov 2019 11:34 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:									
Main Claimant:	MOHAMMAD KHAIRUL BIN KAMSANI								
Vehicle Reg. No.:	SJJ7052H	Date of Loss:	05/11/2019 07:00 - :59						
Claim Type:	TP / SNM19D205244C02	Policy/Cover Note No.:	DMCVSN19267719000						
Vehicle Reg. No. (Insured):	GBB8834Z	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Vfix Auto Service Pte Ltd (HQ) 26 Chia Ping Road, 619977 Boon Lay - Tel: 64552957								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/11/2019]								
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
<input type="checkbox"/> ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: wskoh@vfixauto.com.sg
Sent: Wednesday, 6 November 2019 11:28 AM
To: 'Claims Dept of CTI'; 'Alfred Toh'; 'Chee So Chow'; 'assignments'; 'SUR'; 'Irene Tay'
Cc: ybsim@vfixauto.com.sg; kentsh@vfixauto.com.sg; jessicassy@vfixauto.com.sg; jeffbz@vfixauto.com.sg; alanclk@vfixauto.com.sg
Subject: RE: ACCIDENT INVOLVING SJJ7052H AND GBB8834Z ON 05 NOV 2019 - SNM19D205244C02/4(thp)
Attachments: estimate.pdf

Dear Alfred,

Good day.

As per requested, kindly refer the attached estimate for your kind perusal.



Thank You.

Remark: W.e.f 22nd April 2019, our office has been relocated to 26, Chia Ping Road, Singapore 619977. Please update your record with the following: Company contact number - 6455 2957 ; Company general email - contact@vfixauto.com.sg

Thanks & Regards,

Weng Sheng

Motor Claim Operation Admin

Vfix Auto Pte Ltd | Vfix Auto Service Pte Ltd | Vfix Leasing Pte Ltd

26 Chia Ping Road Singapore 619977

Contact: 6455 2957 | E: wskoh@vfixauto.com.sg

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Wednesday, 6 November 2019 10:35 AM
To: wskoh@vfixauto.com.sg; ybsim@vfixauto.com.sg; jessicassy@vfixauto.com.sg; jeffbz@vfixauto.com.sg; kentsh@vfixauto.com.sg; alanclk@vfixauto.com.sg; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Chee So Chow <sochow.chee@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>
Subject: RE: ACCIDENT INVOLVING SJJ7052H AND GBB8834Z ON 05 NOV 2019 - SNM19D205244C02/4(thp)

Without Prejudice

Your Ref: SJJ7052H

Our Ref: SNM19D205244C02/4(thp)

Dear Sirs

We refer to the above matter.

Please note that we shall be appointing M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

You may want to provide us your estimates for our consideration on Direct Settlement.

Aside to M/s LKK Auto Consultants Pte Ltd., please assist to arrange for the survey.

Aside to Irene, please assist to create the Merimen folder.

Best Regards

Alfred Toh
Senior Executive
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID : (65) 6389 6183
FAX: (65) 6224 7478

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: wskoh@vfixauto.com.sg [mailto:wskoh@vfixauto.com.sg]

Sent: Wednesday, 6 November, 2019 8:29 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>

Cc: Chee So Chow <sochow.chee@sg.cntaiping.com>; Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; ybsim@vfixauto.com.sg; jessicassy@vfixauto.com.sg; jeffbz@vfixauto.com.sg; kentsh@vfixauto.com.sg; alanclk@vfixauto.com.sg

Subject: RE: ACCIDENT INVOLVING SJJ7052H AND GBB8834Z ON 05 NOV 2019

Dear Alfred ,

Good day.

Kindly assist to arrange surveyor.

Thank You.

Remark: W.e.f 22nd April 2019, our office has been relocated to 26, Chia Ping Road, Singapore 619977. Please update your record with the following: Company contact number - 6455 2957 ; Company general email - contact@vfixauto.com.sg

Thanks & Regards,



Weng Sheng

Motor Claim Operation Admin

Vfix Auto Pte Ltd | Vfix Auto Service Pte Ltd | Vfix Leasing Pte Ltd

26 Chia Ping Road Singapore 619977

Contact: 6455 2957 | E: wskoh@vfixauto.com.sg

From: wskoh@vfixauto.com.sg <wskoh@vfixauto.com.sg>

Sent: Tuesday, 5 November 2019 1:07 PM

To: 'Claims Dept of CTI' <claimsdept@sg.cntaiping.com>

Cc: 'Alfred Toh' <alfred.toh@sg.cntaiping.com>; 'Chee So Chow' <sochow.chee@sg.cntaiping.com>; 'Elaine Cheong' <elaine.cheong@sg.cntaiping.com>; 'Chong Boon Sen' <boonsen.chong@sg.cntaiping.com>;

'ybsim@vfixauto.com.sg' <ybsim@vfixauto.com.sg>; 'jessicassy@vfixauto.com.sg' <jessicassy@vfixauto.com.sg>;
'jeffbz@vfixauto.com.sg' <jeffbz@vfixauto.com.sg>; 'kentsh@vfixauto.com.sg' <kentsh@vfixauto.com.sg>;
'alanclk@vfixauto.com.sg' <alanclk@vfixauto.com.sg>

Subject: ACCIDENT INVOLVING SJJ7052H AND GBB8834Z ON 05 NOV 2019

Dear China Taiping Team,

Please find attached copy for your arrangement.

Please take note vehicle have in our workshop.

Thank You.

Remark: W.e.f 22nd April 2019, our office has been relocated to 26, Chia Ping Road, Singapore 619977. Please update your record with the following: Company contact number - 6455 2957 ; Company general email - contact@vfixauto.com.sg

Thanks & Regards,



Weng Sheng

Motor Claim Operation Admin

Vfix Auto Pte Ltd | Vfix Auto Service Pte Ltd | Vfix Leasing Pte Ltd

26 Chia Ping Road Singapore 619977

Contact: 6455 2957 | E: wskoh@vfixauto.com.sg

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Shiau Chan (LKKAuto)

From: wskoh@vfixauto.com.sg
Sent: Thursday, 28 November 2019 3:07 PM
To: Rasul (LKKAuto); Shiau Chan (LKKAuto)
Cc: ybsim@vfixauto.com.sg; jeffbz@vfixauto.com.sg; jessicassy@vfixauto.com.sg; kentsh@vfixauto.com.sg; alanclk@vfixauto.com.sg
Subject: RE: ACCIDENT INVOLVING SJJ7052H & GBB8834Z ON 5/11/2019

Dear Rasul and Shiau Chan,

Good day.

As spoken, we accept your offer lump sump \$4600.00 (bef gst) and 8 days.

Advised by you, the original copies LOD we will post up to China Taiping.



Thank You.

Remark: W.e.f 22nd April 2019, our office has been relocated to 26, Chia Ping Road, Singapore 619977. Please update your record with the following: Company contact number - 6455 2957 ; Company general email - contact@vfixauto.com.sg

Thanks & Regards,

Weng Sheng

Motor Claim Operation Admin

Vfix Auto Pte Ltd | Vfix Auto Service Pte Ltd | Vfix Leasing Pte Ltd

26 Chia Ping Road Singapore 619977

Contact: 6455 2957 | E: wskoh@vfixauto.com.sg

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Thursday, 21 November 2019 12:26 PM
To: wskoh@vfixauto.com.sg
Cc: ybsim@vfixauto.com.sg; jeffbz@vfixauto.com.sg; jessicassy@vfixauto.com.sg; kentsh@vfixauto.com.sg; alanclk@vfixauto.com.sg
Subject: RE: ACCIDENT INVOLVING SJJ7052H & GBB8834Z ON 5/11/2019

Hi Weng Sheng,

Close at 4600.

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: wskoh@vfixauto.com.sg [mailto:wskoh@vfixauto.com.sg]

Sent: Monday, 18 November, 2019 4:35 PM

To: Rasul (LKKAuto)

Cc: ybsim@vfixauto.com.sg; jeffbz@vfixauto.com.sg; jessicassy@vfixauto.com.sg; kentsh@vfixauto.com.sg; alanclk@vfixauto.com.sg

Subject: RE: ACCIDENT INVOLVING SJJ7052H & GBB8834Z ON 5/11/2019

Dear Rasul,

We unable to accept your offer \$ 4,250.00 and we would like to counter offer to \$5,000.00.



Thank You.

Remark: W.e.f 22nd April 2019, our office has been relocated to 26, Chia Ping Road, Singapore 619977. Please update your record with the following: Company contact number - 6455 2957 ; Company general email - contact@vfixauto.com.sg

Thanks & Regards,

Weng Sheng

Motor Claim Operation Admin

Vfix Auto Pte Ltd | Vfix Auto Service Pte Ltd | Vfix Leasing Pte Ltd

26 Chia Ping Road Singapore 619977

Contact: 6455 2957 | E: wskoh@vfixauto.com.sg

From: Rasul (LKKAuto) <Rasul@lkkauto.com>

Sent: Monday, 18 November 2019 9:58 AM

To: wskoh@vfixauto.com.sg

Cc: ybsim@vfixauto.com.sg; jeffbz@vfixauto.com.sg; jessicassy@vfixauto.com.sg; kentsh@vfixauto.com.sg; alanclk@vfixauto.com.sg

Subject: RE: ACCIDENT INVOLVING SJJ7052H & GBB8834Z ON 5/11/2019

Hi Weng Sheng,

Refer to attachment

Part prices required to be checked and reduced

Finalise amount is \$ 4,250.00 / 8 days lump sum

Kindly confirm

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: wskoh@vfixauto.com.sg [mailto:wskoh@vfixauto.com.sg]

Sent: Friday, 15 November, 2019 4:09 PM

To: Rasul (LKKAuto)

Cc: ybsim@vfixauto.com.sg; jeffbz@vfixauto.com.sg; jessicassy@vfixauto.com.sg; kentsh@vfixauto.com.sg; alanclk@vfixauto.com.sg

Subject: ACCIDENT INVOLVING SJJ7052H & GBB8834Z ON 5/11/2019

Dear Rasul,

Good day.

As spoken, kindly refer the attached after paint photo & estimate to finalize COR.



Thank You.

Remark: W.e.f 22nd April 2019, our office has been relocated to 26, Chia Ping Road, Singapore 619977. Please update your record with the following: Company contact number - 6455 2957 ; Company general email - contact@vfixauto.com.sg

Thanks & Regards,

Weng Sheng

Motor Claim Operation Admin

Vfix Auto Pte Ltd | Vfix Auto Service Pte Ltd | Vfix Leasing Pte Ltd

26 Chia Ping Road Singapore 619977

Contact: 6455 2957 | E: wskoh@vfixauto.com.sg

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	138F
Vehicle Details	
Vehicle No.:	SJJ7052H
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Nov 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	L13A4090942
Chassis No.:	GE61081287
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$14,364.00
Original Registration Date:	23 Sep 2008
First Registration Date:	23 Sep 2008
Transfer Count:	2
Actual ARF Paid:	\$14,364.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	22 Sep 2023
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$16,170.00
COE Rebate Amount:	\$12,531.00
Total Rebate Amount:	\$12,531.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 07 Nov 2019

OK

23,000
12,531

10,469

9k



POLICY INFORMATION		Policy No. : VPA/P1899083
Source	: (01) 13950 META (PA/HOME X SELL 20110901)	
Insured	: MOHAMMAD KHAIRUL BIN KAMSANI	
Address	: BLK 703 WOODLANDS DRIVE 40 #07-74 SINGAPORE 730703	
Business/Profession	: TEACHER / TUTOR / LECTURER Carrying on or engaged in the business or profession last declared and no other for the purpose of this insurance.	
Period of Insurance	: From 23/09/2019 To 22/09/2020 (Both Dates Inclusive)	
Any subsequent period for which the Insured shall pay and the Company shall agree to accept a renewal premium.		
PREMIUM		
Premium After 40.00% NCD	: SGD 905.90	
Safe Driver Disc 10.00%	: SGD 90.59	
GST 7.00%	: SGD 57.07	
Annual Premium	: SGD 872.38	
Total Payable	: SGD 872.38	
RISK DETAILS THE MOTOR VEHICLE		
Type Of Cover	: Comprehensive	
Regn No.	: SJJ7052H	
Type Of Use	: Private Car	
Make/Model	: HONDA FIT 1.3G A	
Year of Manufacture	: 2008	Seating Capacity (excl. Driver) : 04
Body Type	: SALOON	Engine C.C. : 1339
Engine No.	: L13A4090942	
Chassis No.	: GE61081287	
Insured's Estimated Market Value	: Market Value At The Time Of Loss (including Accessories and Spare Parts)	
Limitations as to Use	: As specified in Certificate of Insurance	
Hire Purchase	: STANDARD CHARTERED BANK SINGAPORE LTD	
<u>Extra Coverage (Premium Breakdown)</u>	<u>Limits (SGD)</u>	<u>Premium (SGD)</u>
NCD Protector		
<u>Excess Applicable</u>		
Basic Own Damage Excess	: SGD 400.00	
<u>Named Drivers</u>		
1	MOHAMMAD KHAIRUL BIN KAMSANI	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



Vehicle A - SJJ7052H


Vehicle B - GBB 88342

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 5/11/2019 around 0730 hrs, Vehicle A from Upper Changi Rd E towards Bedok Road (near lamp posts) at lane 2 suddenly Vehicle B collided onto Vehicle A rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



ESTIMATE
 DATE :
 ACC DATE :
 REF NO :
 POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO :SJJ7052H HONDA FIT

DESCRIPTION	AMOUNT S\$
1 1 TAIL GATE <i>bt</i>	1,120.00 <i>808</i>
2 1 TAIL GATE WINDSCREEN MOULDING <i>na</i>	176.00 <i>144</i>
3 1 TAIL GATE WINDSCREEN INNER SEAL <i>na</i>	50.00
4 1 TAIL GATE WIPER MOTOR <i>X svc</i>	564.30 <i>X</i>
5 1 TAIL GATE OUTER GARNISH <i>ca</i>	272.00 <i>196</i>
6 2 TAIL GATE NUMBER PLATE LAMP <i>X svc</i>	45.00 90.00 <i>X</i>
7 1 TAIL GATE OUTER OPENER HANDLE <i>X svc</i>	57.30 <i>X</i>
8 1 TAIL GATE BADGE <i>na</i>	78.00 <i>56</i>
9 1 TAIL GATE EMBLEM (FIT) <i>na</i>	73.00 <i>45</i>
10 1 TAIL GATE INNER LOCK <i>bt</i>	321.30 <i>153</i>
11 1 TAIL GATE AUTO LOCK ACTUATOR <i>X svc</i>	120.00 <i>X</i>
12 1 TAIL GATE LOCK CATCH <i>X svc</i>	36.00 <i>X</i>
13 1 TAIL GATE WEATHERSTRIP <i>na</i>	196.40 <i>130</i>
14 2 TAIL GATE SIDE STOPPER <i>na</i>	20.00 <i>@</i> 40.00
15 1 TAIL GATE INNER TRIM <i>X svc</i>	521.40 <i>X</i>
16 2 TAIL GATE HINGE <i>X svc</i>	4111.90 62.00 124.00 <i>X</i>
17 2 TAIL GATE ABSORBE <i>X svc</i>	209 214.00 428.00 <i>X</i>
18 1 REAR BUMPER <i>de</i>	3289.52 845.60 <i>534</i>
19 2 REAR BUMPER SIDE RETAINER <i>na</i>	120.00 <i>@ 22.50</i> 240.00 <i>45</i>
20 10 REAR BUMPER CLIP <i>na</i>	5.00 50.00
21 1 REAR BUMPER TOWING COVER <i>svc</i>	62.50 <i>45</i>
22 2 REAR BUMPER DAMPER <i>X svc</i>	98.00 196.00 <i>X</i>
23 2 TAIL LAMP <i>ca</i>	395.40 <i>@ 38X</i> 790.80 <i>770</i>
24 6 TAIL LAMP CLIP <i>na</i>	5.00 30.00
25 2 TAIL LAMP PANEL <i>repair</i>	218.60 437.20 <i>XR</i>
26 1 END PANEL <i>bt</i>	854.60 <i>465</i>
27 1 END PANEL TOP TRIM <i>de</i>	215.90
28 1 SPARE TYRE PANEL <i>X svc</i>	1,180.60 <i>X</i>
29 1 SPARE TYRE PANEL TOP BOARD <i>X svc</i>	378.40 <i>X</i>
30 1 SPARE TYRE PANEL WHEEL NUT <i>X svc</i>	58.00 <i>X</i>
31 2 REAR CHASSIS FRAME MEMBER <i>X svc</i>	556.00 1,116.00 <i>X</i>
32 2 REAR FENDER <i>repair</i>	977.40 1,954.80 <i>XR</i>
33 2 REAR FENDER GLASS INNER SEAL <i>X na</i>	50.00 100.00 <i>X</i>
34 2 REAR FENDER INNER TRIM <i>de RH (LPC)</i>	677.30 <i>@ 341</i> 1,354.60 <i>341</i>
35 10 REAR FENDER INNER TRIM CLIP <i>X</i>	4.00 40.00 <i>X</i>
36 1 REAR FENDER INNER SHIELD LH <i>X svc</i>	96.00 192.00 <i>X</i>
37 10 REAR FENDER INNER SHIELD CLIP <i>X</i>	3.00 30.00 <i>X</i>

	\$	14,394.70
LESS 20%	\$	11,515.76

DESCRIPTIONS	UNIT PRICE	AMOUNT S\$
<u>SPECIAL NETT</u>		
1 <u>REVERSE CAMERA</u> X <i>gn</i>		\$ 550.00 X
1 <u>REVERSE SENSOR</u> <i>nw</i> /		\$ 200 400.00
1 <u>REAR WINDSCREEN SEALANT</u> <i>acc</i> /		\$ 40 90.00
1 <u>REAR FENDER GLASS SEALANT</u> X <i>nn</i>		\$ 120.00 X
1 <u>REAR NUMBER PLATE WITH COVER</u> 7 <i>scr</i> /		\$ 35 80.00
1 <u>BODAY PANEL JOINT SEALANT</u> 7 <i>nn</i> /		\$ 40 150.00
1 <u>REAR FLOOR INSULATOR PAD</u> X <i>nn</i>		\$ 180.00 X
		\$ 1,570.00

315 {

LABOUR & MISCELLANEOUS :

AMOUNT \$

		AMOUNT \$
1	To remove damaged body panel with all necessary components/attachments apply hot-works where necessary straighten front door pillar, repair/reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components / attachments	2,000.00 800
2	To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials	1000 1,800.00
3	To remove, refit rear windscreen	120 180.00
4	To remove, refit rear tail gate part	60 120.00
5	To remove, refit carpet and seat	60 350.00
6	To remove, refit reverse camera	60 150.00
7	To remove, refit reverse sensor	60 90.00
		\$ 4,660.00

2160

GRAND TOTAL : \$ 17,745.76

Vfix Auto Pte Ltd



[Handwritten signature]
11/11/19

[Handwritten signature]
Hp 90010068

8 days

L/S

06/11/19 @ 1550

Recovery after repair

3289.52

315.00

2160.00

5764.52

20%

4611.61

L/S - 4,600

8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "no win no fee" basis
- No illegal modifications allowed
- Supplementary items are subject to approval and is subject to final approval of insurance Company

Acknowledged by Repairer:
Signature:
Date:

Date of Accident : 5/11/2019 Accident Time: 0730 (24-HR-Format)

Accident Place : Upper Changi Rd E towards Bedok Rd

Vehicle No. (Car Plate No.) : SJJ 705H Make/Model: Honda Fit

Insurance Company : AXA Policy No: VPA/P1899083

Owner or Company Name /IC No. : MOHAMMAD KHAIRUL BIN KAMSANI

Owner or Company Contact No. : 8816 7035 Owner's Hp _____ Company Tel _____

DRIVER'S Name / IC No. : MOHAMMAD KHAIRUL BIN KAMSANI

DRIVER'S Date Of Birth : 31/10/1987 DRIVER'S License Pass Date 13/4/2012

Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: Owner

DRIVER'S Address : APT BLK 216 A COMPASSVALE DRIVE #04-544
SINGAPORE 541216

DRIVER'S Contact No./ Alt No. : 1) 8816 7035 2) _____

DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)

Email Address : khairul.kamsani@rocketmail.com

Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET

Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance

Number of Passengers (Including Driver): 1

Was there any video Captured by car camera: YES \ NO

Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose

Any Injury (If YES, Pls state): No injury

Other Party Driver's Particular (if any)

Vehicle No: <u>GBB 8834Z</u>	Vehicle No: _____
Vehicle Make/Model: <u>MITSUBISHI L200</u>	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

* NEW - Passenger's name & gender:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Nov 2019		06 Nov 2019 11:34 Edit Adj Rpt	S\$4,600.00 Edit Estimates	S\$4,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	MOHAMMAD KHAIRUL BIN KAMSANI								
Vehicle Reg. No.:	SJJ7052H	Date of Loss:	05/11/2019 07:00 - :59 [133 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D205244C02	Policy/Cover Note No.:	DMCVSN19267719000						
Vehicle Reg. No. (Insured):	GBB8834Z	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Vfix Auto Service Pte Ltd (HQ) 26 Chia Ping Road, 619977 Boon Lay - Tel: 64552957								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 15/11/2019]								
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/> View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJJ7052H (SNM19D205244C02)
[GBB8834Z]
TP
MOHAMMAD KHAIRUL BIN KAMSANI
Nov 5 2019 7:00AM
[-]
Vfix Auto Service Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	29/11/19 10:03	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>					
2	29/11/19 10:03	Chassis Number		Load JPG	<input checked="" type="checkbox"/>					
3	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
4	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
5	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
6	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
7	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
8	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
9	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
10	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
11	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
12	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
13	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
14	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
15	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
16	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
17	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
18	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
19	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
20	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
21	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
22	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
23	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
24	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
25	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
26	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
27	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
28	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
29	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
30	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
31	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
32	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
33	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
34	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
35	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
36	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
37	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
38	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
39	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
40	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
41	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
42	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					
43	29/11/19 10:03	General View		Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
45	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
46	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
47	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
48	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
49	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
50	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
51	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
52	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
53	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
54	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
55	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
56	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
57	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
58	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
59	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
60	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
61	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
62	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
63	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
64	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
65	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
66	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
67	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
68	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
69	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
70	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
71	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
72	29/11/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
73	29/11/19 10:03	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
74	29/11/19 10:03	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
75	29/11/19 10:03	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
76	29/11/19 10:03	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
77	29/11/19 10:03	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin: 5px 0;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19019592/R1QF3E2

Date: 13/12/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN19267719000
Claimant Vehicle No :	SJJ7052H	Insured Vehicle No :	GBB8834Z
Date of Loss:	05/11/2019	Nature of Claim:	TP
		Claim No:	SNM19D205244C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ7052H	Engine No:	L13A4090942
Make & Model:	HONDA FIT, 1.3 (A)	Chassis No:	GE61081287
Reg. Date:	23/09/2008 (Man. Year: 2008)	Odometer:	457158 km
Colour:	Red		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,085.76	3,604.52	9,481.24	72.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,660.00	2,160.00	2,500.00	53.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,745.76	5,764.52	11,981.24	67.52
Approved Total (Overridden) (S\$)		4,600.00		
	(S\$)	17,745.76	4,600.00	13,145.76
	+ GST 7.00/7.00% (S\$)	1,242.20	322.00	920.20
	Nett Amount (S\$)	18,987.96	4,922.00	14,065.96

INSPECTION

Date of Assignment:	06/11/2019		
Date Inspected:	06/11/2019	Inspected At:	Vfix Auto Service Pte Ltd (HQ) 26 Chia Ping Road Singapore 619977
Estimated Period of Repair:	8.0 days		

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2019)
Parts: 144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJJ7052H)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,120.00 FL	*808.00 FL
2	1		*TAIL GATE WINDSCREEN MOULDING	Necessary	176.00 FL	*144.00 FL
3	1		*TAIL GATE WINDSCREEN INNER SEAL	Necessary	50.00 FL	*50.00 FL
4	1		*TAIL GATE WIPER MOTOR	Serviceable	564.30 FL	*- FL
5	1		*TAIL GATE OUTER GARNISH	Cracked	272.00 FL	*190.00 FL
6	2		*TAIL GATE NUMBER PLATE LAMP	Serviceable	90.00 FL	*- FL
7	1		*TAIL GATE OUTER OPENER HANDLE	Serviceable	57.30 FL	*- FL
8	1		*TAIL GATE BADGE	Necessary	78.00 FL	*56.00 FL
9	1		*TAIL GATE EMBLEM (FIT)	Necessary	73.00 FL	*45.00 FL
10	1		*TAIL GATE INNER LOCK	Bent	321.30 FL	*153.00 FL
11	1		*TAIL GATE AUTO LOCK ACTUATOR	Serviceable	120.00 FL	*- FL
12	1		*TAIL GATE LOCK CATCH	Serviceable	36.00 FL	*- FL
13	1		*TAILGATE WEATHERSTRIP	Necessary	196.40 FL	*130.00 FL
14	2		*TAIL GATE SIDE STOPPER	Necessary	40.00 FL	*40.00 FL
15	1		*TAIL GATE INNER TRIM	Serviceable	521.40 FL	*- FL
16	2		*TAILGATE HINGE	Serviceable	124.00 FL	*- FL
17	2		*TAIL GATE ABSORBER	Serviceable	428.00 FL	*- FL
18	1		*REAR BUMPER	Deformed	845.60 FL	*534.00 FL
19	2		*REAR BUMPER SIDE RETAINER	Necessary	240.00 FL	*45.00 FL
20	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
21	1		*REAR BUMPER TOWING COVER	Scratched	62.50 FL	*45.00 FL
22	2		*REAR BUMPER DAMPER	Serviceable	196.00 FL	*- FL
23	2		*TAIL LAMP	Cracked	790.80 FL	*770.00 FL
24	6		*TAIL LAMP CLIP	Necessary	30.00 FL	*30.00 FL
25	2		*TAIL LAMP PANEL	Repair	437.20 FL	*- FL
26	1		*END PANEL	Bent	854.60 FL	*465.00 FL
27	1		*END PANEL TOP TRIM	Deformed	215.90 FL	*215.90 FL
28	1		*SPARE TYRE PANEL	Serviceable	1,180.60 FL	*- FL
29	1		*SPARE TYRE PANEL TOP BOARD	Serviceable	378.40 FL	*- FL
30	1		*SPARE TYRE PANEL WHEEL NUT	Serviceable	58.00 FL	*- FL
31	2		*REAR CHASSIS FRAME MEMBER	Serviceable	1,116.00 FL	*- FL
32	2		*REAR FENDER	Repair	1,954.80 FL	*- FL
33	2		*REAR FENDER GLASS INNER SEAL	Not Necessary	100.00 FL	*- FL
34	1		*REAR FENDER INNER TRIM	O/S Deformed	1,354.60 FL	*341.00 FL
35	10		*REAR FENDER INNER TRIM CLIP	Serviceable	40.00 FL	*- FL
36	1		*REAR FENDER INNER SHIELD LH	Serviceable	192.00 FL	*- FL
37	10		*REAR FENDER INNER SHIELD CLIP	Serviceable	30.00 FL	*- FL
38	1		*REVERSE CAMERA	Serviceable	550.00 FS	*- FS
39	1		*REVERSE SENSOR	Not Working	400.00 FS	*200.00 FS
40	1		*REAR WINDSCREEN SEALANT	Necessary	90.00 FS	*40.00 FS
41	1		*REAR FENDER GLASS SEALANT	Not Necessary	120.00 FS	*- FS
42	1		*REAR NUMBER PLATE WITH COVER	Scratched	80.00 FS	*35.00 FS
43	1		*BODY PANEL JOINT SEALANT	Necessary	150.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
44	1		*REAR FLOOR INSULATOR PAD	Not Necessary	180.00 FS	*- FS	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (\$\$)	15,964.70	4,426.90
					- List Item Discount on L Items 20.00/20.00% (\$\$)	2,878.94	822.38
					Total Parts (\$\$)	13,085.76	3,604.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE DAMAGED BODY PANEL WITH ALL NECESSARY COMPONENTS / ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY STRAIGHTEN FRONT DOOR PILLAR, REPAIR / RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS / ATTACHMENTS	New	2,000.00	800.00
2	TO SPRAY PAINT REPLACED / REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	1,800.00	1,000.00
3	TO REMOVE, REFIT REAR WINDSCREEN	New	150.00	120.00
4	TO REMOVE, REFIT REAR TAIL GATE PART	New	120.00	60.00
5	TO REMOVE, REFIT CARPET AND SEAT	New	350.00	60.00
6	TO REMOVE, REFIT REVERSE CAMERA	New	150.00	60.00
7	TO REMOVE, REFIT REVERSE SENSOR	New	90.00	60.00
Gross Labour Cost (\$\$)			4,660.00	2,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >