

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 18251

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1319/2019/NS
Date : 5-Nov-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Koh Eng Hwee (Xu Yonghui)
Address : 83 Compassvale Bow
#09-11
Singapore 544684
Telephone : HP +65 97465028
Type of Claim : Own Damage Claims
Policy No. : 1800121522
Vehicle No : **SME 7188 R**
Model Code : Audi A4 SEDAN 2.0 TFSI 8W
Model / Year : 11/10/2018
Engine No : CVK 067193
Chassis No : WAUZZZF45JA219394
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Nov-19
Place of Accident : Opposite Kopitiam Square Along 10 Sengakang Square

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SME 7188 R

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper, bonnet and both headlights. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00 1250	
3	✓ To respray front bumper and bonnet.	\$ 2,000.00 1100	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 5,472.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SME 7188 R**

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remarks
1	FRONT BUMPER <i>Rehnd</i>	\$ 1,999.00	✓
2	FRONT BUMPER FIXING PARTS <i>men</i>	\$ 258.00	+
3	FRONT BUMPER GRILLE - CENTRE <i>amld</i>	\$ 178.00	✓
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>men</i>	\$ 191.00	+
5	RADIATOR GRILLE <i>amld</i>	\$ 1,227.00	✓
6	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>men</i>	2 \$ 246.00	+
7	CAUTION SIGN STICKER <i>3 men</i>	NEC \$ 13.00	✓
8	AIRCON STICKER	NEC \$ 7.00	✓
9	FRONT BUMPER CARRIER <i>Best</i>	\$ 733.00	✓
10	FRONT BUMPER COVER ?	\$ 116.00	?
11	FRONT BUMPER FOAM FILLER PIECE <i>deformed</i>	\$ 113.00	✓
12	LOCK CARRIER BRACKET ?	\$ 125.00	?
13	FRONT BUMPER SUPPORT - LH / RH ?	2 \$ 52.00	?
14	HORN - LH HIGH TONE <i>2 men</i>	\$ 37.00	+
15	HORN - RH LOW TONE	\$ 262.00	+
16	SPRING SHACKLE - LH / RH <i>men</i>	2 \$ 52.00	+
17	FRONT PARKING AID SENSOR - INNER / OUTER <i>men</i>	2 \$ 462.00	+
18	FRONT PARKING AID SEAL RING <i>men</i>	4 \$ 12.00	+
19	BONNET <i>Dented</i>	\$ 2,554.00	✓
20	BONNET ATTACHMENT PARTS ?	\$ 111.00	?
SUB TOTAL SPARE PARTS		\$ 8,748.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SME 7188 R**

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remarks
21	BONNET LID HINGE - LH / RH <i>new</i>	2 \$	554.00 +
22	BONNET IMPACT PROTECTION - CENTRE <i>?</i>	\$	25.00 ✓
23	BONNET IMPACT PROTECTION - RH <i>new</i>	\$	25.00 ✓
24	BONNET IMPACT PROTECTION - LH	\$	25.00 ✓
25	BONNET GAS FILLED STRUT <i>new</i>	2 \$	217.00 +
26	BONNET STRIKER - LH / RH <i>?</i>	2 \$	92.00 ?
27	BONNET LID LOCK <i>?</i>	2 \$	391.00 ?
28	BONNET BOWDEN CABLE - CENTRE <i>?</i>	\$	53.00 ?
29	BONNET BOWDEN CABLE <i>?</i>	\$	53.00 ?
30	BONNET RELEASE LEVER <i>?</i>	\$	12.00 ?
31	LED HEADLIGHT - LH / RH <i>LH at, RH?</i>	2 \$	14,174.00 ?
32	LIFT CYLINDER - LH / RH <i>new</i>	2 \$	384.00 +
33	RADIATOR AIR GUIDE - LH / RH	2 \$	50.00 +
34	RADIATOR INNER DUCT - LH / RH <i>new</i>	2 \$	22.00 +
35	RADIATOR UPPER AIR GUIDE <i>?</i>	\$	15.00 ?
36	AIR INTAKE AIR DUCT <i>?</i>	\$	19.00 ?
37	AIR INTAKE AIR GUIDE <i>?</i>	\$	48.00 ?
38	AIR INTAKE AIR FILTER <i>new</i>	\$	339.00 +
39	AIR INTAKE AIR MASS METRE <i>new</i>	\$	533.00 +
40	AIR INTAKE HOSE <i>new</i>	\$	85.00 X
41	FRONT NO PLATE <i>Dented</i>	S/N \$	40.00 ✓
42	SUNDRIES <i>?</i>	\$	300.00 ?

TOTAL SPARE PARTS**: \$ 26,204.00****TOTAL LABOUR CHARGES****\$ 5,472.00****GRAND TOTAL****\$ 31,676.00**

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *06/11/19.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 05 days.*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant