

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 18134

## Telefax

|            |   |                    |
|------------|---|--------------------|
| Estimate   | : | Accident Repairs   |
| Workshop   | : | Ubi Road 1         |
| Contact No | : | 6366 2323          |
| Fax No     | : | 6841 1183          |
| Reference  | : | PA/OD/1316/2019/NS |
| Date       | : | 5-Nov-19           |

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept  
Tel: 6841 0055 - Fax: 6256 4315

|                   |   |                                                      |
|-------------------|---|------------------------------------------------------|
| Owner's Name      | : | Mr Lim Kay Yit                                       |
| Address           | : | Blk 1B Cantonment Road<br>#35-13<br>Singapore 085201 |
| Telephone         | : | (HP) +65 91788010                                    |
| Type of Claim     | : | Own Damage Claims                                    |
| Policy No.        | : | 2100174407-09                                        |
| Vehicle No        | : | <b>SJY 3113 M</b>                                    |
| Model Code        | : | Audi A4 SEDAN 2.0 TFSI QU 8K206                      |
| Model / Year      | : | 11/11/2009                                           |
| Engine No         | : | CDN 069823                                           |
| Chassis No        | : | WAUZZZ8K0aa055080                                    |
| Mileage           | : | -                                                    |
| Date In           | : | -                                                    |
| Estimated By      | : | Johnny Boo / Allan Wu                                |
| Accident Date     | : | 12-Oct-19                                            |
| Place of Accident | : | Whampoa Drive To Balestier                           |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. SJY 3113 M

| S/n                         | Nature of Jobs                                                                                                                                     | Estimated Charges           | Surveyor's Recommendations |
|-----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|----------------------------|
| 1                           | To remove , check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid. | S/N \$ 360.00 ✓             |                            |
| 2                           | To dismantle and renew front bumper, rhs front fender, and rhs headlight. Re-organise crash management components. Reinstall all parts removed.    | \$ <del>2,450.00</del> 1250 |                            |
| 3                           | To respray front bumper and rhs front fender.                                                                                                      | \$ <del>2,000.00</del> 1100 |                            |
| 4                           | To carry out diagnostic check.                                                                                                                     | S/N \$ 192.00 ✓             |                            |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                    | <b>: \$ 5,002.00</b>        |                            |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SJY 3113 M

| S/N | Parts Description                                                 | Damaged Parts & Prices |          |
|-----|-------------------------------------------------------------------|------------------------|----------|
|     |                                                                   | S/Nett                 | Remarks  |
| 1   | FRONT BUMPER <i>Rehman</i>                                        | \$ 2,470.00            | ✓ 1976   |
| 2   | FRONT BUMPER FIXING PARTS <i>new</i>                              | \$ 234.00              | +        |
| 3   | FRONT BUMPER SIDE REINFORCEMENT BEAM <i>new</i>                   | \$ 802.00              | +        |
| 4   | FRONT BUMPER SUPPORT - LH / RH <i>new</i>                         | 2 \$ 52.00             | +        |
| 5   | FRONT BUMPER GUIDE SECTION - RH <i>Not Nec.</i>                   | \$ 40.00               | ? X      |
| 6   | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>            | \$ 177.00              | +        |
| 7   | FRONT BUMPER PULL STRAP - LOWER <i>new</i>                        | \$ 47.00               | +        |
| 8   | FRONT BUMPER SPOILER - LOWER <i>new</i>                           | \$ 307.00              | +        |
| 9   | FRONT BUMPER FOAM FILLER PIECE <i>new</i>                         | \$ 113.00              | +        |
| 10  | FRONT BUMPER VENT GRILLE - RH <i>Missing</i>                      | \$ 123.00              | 98       |
| 11  | FRONT BUMPER VENT GRILLE COVER <i>Not Nec.</i>                    | \$ 89.00               | ? X      |
| 12  | RADIATOR GRILLE <i>new</i>                                        | \$ 645.00              | +        |
| 13  | RADIATOR GRILLE COVER <i>new</i>                                  | \$ 53.00               | +        |
| 14  | QUATTRO INSCRIPTION <i>new</i>                                    | \$ 87.00               | +        |
| 15  | FRONT FENDER - RH <i>Dented</i>                                   | \$ 904.00              | ✓ 722.80 |
| 16  | FRONT FENDER ATTACHMENT PARTS - FRONT <i>Not Nec</i>              | \$ 52.00               | ? X      |
| 17  | FRONT FENDER BRACKET - RH FRONT <i>Not Nec</i>                    | \$ 48.00               | +        |
| 18  | FRONT FENDER DEFORMATION ELEMENT BRACKET - RH REAR <i>Not Nec</i> | \$ 45.00               | +        |
| 19  | FRONT FENDER BRACE - RH LOWER <i>Not Nec</i>                      | \$ 107.00              | ? X      |
| 20  | FRONT WHEEL HOUSING LINER - RH <i>Not Nec.</i>                    | \$ 223.00              | ? X      |

SUB TOTAL SPARE PARTS

: \$ 6,618.00

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SJY 3113 M

| S/N | Parts Description                                   | Damaged Parts & Prices |           |
|-----|-----------------------------------------------------|------------------------|-----------|
|     |                                                     | S/Nett                 | Remarks   |
| 21  | WHEEL HOUSING LINER ATTACHMENT PARTS <i>2HP nec</i> | \$ 41.00               | ? X       |
| 22  | MAIN BEAM HEADLIGHT MOUNTING - RH <i>nec m</i>      | \$ 107.00              | +         |
| 23  | HEADLIGHT BRACKET - RH <i>nec m</i>                 | \$ 71.00               | +         |
| 24  | GAS DISCHARGE LAMP HEADLIGHT - RH <i>let</i>        | \$ 1,989.00            | ✓ 1591.20 |
| 25  | LIFT CYLINDER - RH <i>7HP nec</i>                   | \$ 192.00              | ? X       |
| 26  | HEADLIGHT HOSE <i>nec m</i>                         | 5 \$ 179.00            | +         |
| 27  | RADIATOR AIR GUIDE - RH <i>nec m</i>                | \$ 25.00               | +         |
| 28  | S-LINE INSCRIPTION <i>nec</i>                       | \$ 113.00              | ✓ 90      |
| 29  | CAUTION SIGN STICKER <i>nec m</i>                   | NEC \$ 13.00           | +         |
| 30  | AIRCON STICKER <i>nec m</i>                         | NEC \$ 18.00           | +         |
| 31  | FRONT NO PLATE <i>7HP m</i>                         | S/N \$ 40.00           | +         |
| 32  | SUNDRIES <i>7HP nec</i>                             | \$ 300.00              | ? X       |

TOTAL SPARE PARTS

TOTAL LABOUR CHARGES

GRAND TOTAL

|   |                     |
|---|---------------------|
| : | \$ 9,706.00         |
| : | \$ 5,002.00         |
| : | <u>\$ 14,708.00</u> |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name : Adrian King.  
Surveyed Date : 06/11/19.  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised, 04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Please Note

: This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel: 6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant