

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 06 Nov 2019

Preliminary Advice

Vehicle No	: SJY3113M	Accident Date	: 12/10/2019
Make	: AUDI A4	Policy No.	: 2100174407
Assignment Date	: 06/11/2019	Excess	: S\$0.00
Date of Inspection	: 06/11/2019	Est. Duration of Repair	: 4 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,708.00
Revised Amount	:S\$	8,501.00
Check Items (Estimated)	:S\$	1,092.00
Total	:S\$	9,593.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value before renewal	:S\$	23,000.00
Pre-Accident Value after renewal	:S\$	45,000.00
Paper value before renewal	:S\$	21,500.00
Paper value after renewal	:S\$	18,600.00
Salvage Value	:S\$	
Margin for Repair before renewal	:S\$	1,500.00
Margin for Repair after renewal	:S\$	26,400.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Margin for repair before renewal = \$ 1,500.00, Margin for repair after renewal = \$ 26,400.00