

MS167  
LKK



**ESTEEM  
PERFORMANCE**

**ESTEEM PERFORMANCE PTE LTD**

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

**Repair Estimates**

SLU 7679 T

**Parts** (a) Cost / List Price Items

Plus/Less 25%

Total of Cost / List

(b) Nett Price Items

Less

Total of Nett Item

(c) Special Nett Items

**Total Parts Cost**

**Labour**

**Total**

Finalised  
\$ 7246.75 14,517.18

\$ 1811.69 3,629.30

\$ 5435.06 10,887.89

\$ 610.00 1,565.00

\$ 6045.06 12,452.89

\$ 2502.00 3,502.00

\$ 8547.06 15,954.89

Not Authorized  
Permy B6paint

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 06 day(s)

(c) Resurvey : Required / ~~Not~~ Required

(d) Excess : \$

(e) Signature of surveyor

Kenneth

LKK

6/11/19 at 18:30

Lc

Date: 6/11/19



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts

Vehicle No. : **SLU 7679 T**  
Make & Model : **TOYOTA VOXY**  
Chassis No. : **ZWR800273876**

Submit By : **Carmen Lim**  
Year Manufacture : **2017**  
Engine No. :

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen <i>Shattered</i>	1	\$1,579.30		✓
2	Rear windscreen moulding <i>na</i>	1	\$70.20		X
3	Rear windscreen sealant <i>na</i>	1	\$50.00	S.N	For
4	Reverse sensor <i>na</i>	1	\$200.00	S.N	✓
5	Rear number plate <i>na</i>	1	\$45.00	S.N	X
6	Rear No.plate lamp LH	1	\$68.70		?
7	Rear No.plate lamp RH	1	\$69.70		?
8	Rear bumper <i>CM</i>	1	\$589.70		✓
9	Rear bumper clip <i>na</i>	10	\$40.00		✓
10	Rear bumper side retainer LH <i>na</i>	1	\$132.70		✓
11	Rear bumper side retainer RH <i>na</i>	1	\$132.70		✓
12	Rear bumper bracket LH	1	\$107.61		?
13	Rear bumper bracket RH	1	\$107.61		?
14	Rear bumper reflector LH <i>CM</i>	1	\$67.90		✓
15	Rear bumper reflector RH <i>na</i>	1	\$67.90		X
16	Rear bumper chrome plate <i>na</i>	1	\$350.00	S.N	✓
17	Rear bumper tow cover <i>na</i>	1	\$35.90		✓
18	Tail door <i>na</i>	1	\$1,795.80		✓
19	Tail door lock <i>na</i>	1	\$480.90		✓
20	Tail door emblem <i>na</i>	1	\$58.60		✓
21	Tail door chrome <i>CM</i>	1	\$598.79		✓
22	Tail door trim	1	\$645.70		?
23	Tail door inner trim LH	1	\$598.73		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829  
Company Reg No. 200005485N / GST No. 20-0005485-N

5/12/29  
5405N

# Spare Parts

Vehicle No. : **SLU 7679 T** Submit By : **Carmen Lim**  
 Make & Model : **TOYOTA VOXY** Year Manufacture : **2017**  
 Chassis No. : **ZWR800273876** Engine No. :

## Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail door trim clip <i>mm</i>	10	\$45.00		✓
25	Rear wiper blade	1	\$66.90		?
26	Tail end panel <i>Am</i>	1	\$958.30	(R)	✓
27	Tail end panel garnish	1	\$251.52		?
28	Tail end panel garnish clip	10	\$45.00		?
29	Boot weatherstrip	1	\$386.95		?
(30)	Tail lamp LH <i>cm</i>	1	\$894.73		✓
31	Tail lamp RH <i>sm</i>	1	\$894.73		(X)
32	Taillamp lower panel LH	1	\$198.44		?
33	Spare tyre well panel <i>R</i>	1	\$868.95		X
34	Spare tyre board	1	\$958.70		?
35	LHR Fender <i>R</i>	1	\$997.63		X
36	LHR fender protector upper	1	\$422.79		?
37	LHR Fender undershield <i>pm</i>	1	\$98.70		X
38	LHR Fender undershield clip <i>mm</i>	10	\$35.00		X
39	LHR Fender air duct	1	\$145.40		?
40	Private hirer sticker <i>nee</i>	1	\$20.00	S.N	✓
41	Rear camera	1	\$450.00	S.N	?
42	Rear recorder	1	\$450.00	S.N	?
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

173446  
 20511



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Labour

Vehicle No. : **SLU 7679 T** Submit By : **Carmen Lim**  
Make & Model : **TOYOTA VOXY** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER)	\$1,400.00	1000
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER)	\$1,200.00	1000
3	To check wiring	\$50.00	20
4	To remove & refit reverse sensor	\$120.00	50
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	100
6	To remove & refit rear windscreen.	\$120.00	✓
7	To tuff coat.	\$150.00	60
8	To transfer boot mechanism to new boot	\$120.00	60
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20
10	To arrange express service to do private hirer sticker	\$12.00	✓
11	Towing	\$60.00	✓

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Company Reg No. 200005485N / GST No. 20-0005485-N

2502