

INS. CASE OWNER:

CHAN KAM HING

CC 6 / AIG1901 9621, AIG 9

LKK:
IDAC

Surveyor:

Adrian

DOI:

ASSIGNMENT

6/11/19

Date / Time:

6/11/19

Registered in Merimen:

6/11/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SUB 52154

Claim No.:

2016424494

Name of Insured:

HITACHI CAPITAL ASIA PACIFIC Pte

Policy No.:

2016424494-03

Insured Tel No.:

HP:

Make / Model:

HYUNDAI

Excess Sec II :S\$

D.O.A.:

5/11/19

Place of Accident:

TPE TWS PUNTING

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

DEVKA PRASNO

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

Final ? Yes / No

SVH 86140



INSRS:

WSP:

Tel:

Liability:

RMKS:

WHT



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SVH 86140 / 14/11/19 / 14/11/19 / 14/11/19 / 14/11/19

STAGE DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI: 14/11/19-VIC

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

I.T.A / G.I.A:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

L6

S\$

4,500.00

(9 days)

Reduction:

63

%

Email

Call

FINAL SETTLEMENT

Date/Time:

16/12/20

Confirm with

enjoy

Email

Call

Final Liability:

%

100

(Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

(w/acc)

S\$

4,815.00

(OLD RATE-ENDDP TP)

Loss of Rental (LOR):

S\$

-

(days)

Loss of Use (LOU):

S\$

600.00 x 11 days

Loss of Income (LOI):

S\$

-

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

G.I.A./T.A Search

S\$

2.00

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$

5,474.00

Global Sum S\$:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

5,474.00

Name 1:

NEW HOCK TUCK MOTOR PTE LTD

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

-

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$310.00

COPY SENT
18/12/2020

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop no/s: _____

of: _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res: Yes or No

Lim Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SLH 8619D- Yr Regn 2006 Nov

Type: ☒ Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Toyota Yaris.

C/C

1497

Colour: _____

Red

A/C: Insured / Std / NI / NA

Sp. Reading: _____

120501

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

MR054HY9104020287

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orMod: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F:

195/55R15

R:

195/55R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken.

Front

Rear

R/Bal. _____

06

mm

R/Bal. _____

06

mm

L/Bal. _____

06

mm

L/Bal. _____

06

mm

D.O.A. _____

D.O.I. _____

06/11/19.

Survey held at _____

NHT.

Des. of Damages: Frt / ☒ Rep / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP A/G. COE Expiry: 28/11/21
	L1 @ \$ A,500.00
	(CR00: \$ 7,817.05 / 63%)
	MV: 4.5K 15.1K
	PV: 10.6K
	Nett. 3.9K 15K

Date/Time. File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time. File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

Site Insp \$

☐

Interview \$

☐

Tech. Insp \$

☐

Total \$

Survey Fee: _____

Transportation: _____

F + P: _____

F + P: _____

F + P: _____

F + P: _____

F + P: _____

Report Format: _____

Lump Sum / F + P: _____

672A



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

AIG

Ling Huey Mei Linda
Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

07/11/2019

T.P. AIG

Vic

Accident date: 05/11/2019

Estimated repair cost for vehicle no: SLH8619D TOYOTA YARIS 1.5 E A '06

CHASSIS: MR054HY9104020287

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid Repair		\$820.25
2	1	Rear Boot Lid Toyota Logo		\$29.75
3	1	Rear Boot Lid Yaris Logo		\$28.85
4	1	Rear Boot Lid E Logo		\$27.75
5	1	Rear Boot Lid Inner Lock		\$281.10
6	1	Rear Boot Lid Inner Trim Board		\$561.60
7	1	Rear Boot Lid Rubber		\$277.45
8	2	Rear Tail Lamp LH smashed	\$289.90	\$579.80
9	1	Rear Tail Lamp Panel Dented		\$160.10
10	1	Rear End Panel Distorted		\$781.45
11	1	Rear End Panel Top Garnish Deformed		\$174.45
12	1	Rear Spare Tyre Panel Repair		\$788.10
13	1	Rear Spare Tyre Panel Top Cover Deformed		\$289.10
14	1	Rear Fender Distorted		\$788.10
15	1	Rear Fender Inner Trim Board Deformed		\$588.10
16	1	Rear Fender Air Duct Cracked		\$58.10
17	1	Rear Bumper Distorted		\$374.10
18	1	Rear Bumper Spoiler Distorted		\$588.10
19	1	Rear Bumper Bracket Distorted		\$160.10
20	1	Rear Bumper Side Retainer New		\$132.20
21	1	Rear Bumper Reverse Sensor Damaged		\$350.00
22	1	Rear Number Plate New		\$50.00
23	1	Rear Number Plate Lamp New		\$123.50
24	1	Rear Tool Box Deformed		\$65.00

4099.60

Subtotal :- \$8,077.05

3074.70 S.N: 200

Labour charges

Remove & refit rear windscreen	\$120.00	*	
Gum	\$50.00	*	
Remove & refit rear cushion	\$100.00	60	
Remove & refit rear reverse sensor	\$150.00	50	
Remove & refit Rear Petrol Tank	\$100.00	hr	
Tuff kote	\$150.00	80	
To check wiring	\$100.00	30	
Panel beating	2500	\$2,000.00	1200
Spray painting		\$1,500.00	1000

Subtotal :- \$4,270.00

Total:- \$12,347.05

total: 5774.70
r/s: 4.5K (Nett Value)

59 days

4.5K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

» Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Singapore NRIC
Owner ID:	672A
Vehicle Details	
Vehicle No.:	SLH8619D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	06 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	YARIS E AUTO
Primary Colour:	Red
Manufacturing Year:	2006
Engine No.:	1NZX490874
Chassis No.:	MR054HY9104020287
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$14,933.00
Original Registration Date:	29 Nov 2006
First Registration Date:	29 Nov 2006
Transfer Count:	1
Actual ARF Paid:	\$15,429.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Nov 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,821.00
COE Rebate Amount:	\$10,643.00
Total Rebate Amount:	\$10,643.00
Remarks	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 06 Nov 2019

OK

Easily take studio-like photos

Meet the new Pixel 4. Everything you wish your phone could do. >

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[3 Ways of Selling](#)

Nissan Cabstar Diesel Lorry.

Please Contact Us For Details.
Direct Contact StarAd

StarAd

• Free VICOM evaluation
 • In-house grooming and 8 months maintenance
 • In-house workshop ensures quality service
 • Member of SITA and hire purchase association
 • 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category [Save Search](#) [Print](#)
 Sort by Date Posted 20 results/page

6 vehicles **Search** [Advanced Search](#) [Search](#) [View All](#)

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection



☐ **Toyota Yaris 1.5A E (COE till 10/2021)** \$13,888 \$7,000 /yr 31-Oct-2006 1,497 cc - Hatchback Available

Cheapest In Town, Full Loan, Bank And In House Loan Available, We Can Help To Convert To Z10 Usage If Needed. Genuine Selling Price. Trade In Available, Low Interest Rate From 3.18%. Call Now For More Enquires.

[Home](#)
[10/2021-2021](#)
[Toyota](#)
[2009 Toyota Yaris](#)
[2010 Toyota Yaris](#)
[Toyota Yaris](#)
[Toyota Yaris](#)
[Toyota Yaris](#)
[Toyota Yaris](#)
[Used Toyota](#)



☐ **Toyota Yaris 1.5A E (COE till 01/2024)** \$27,000 \$6,410 /yr 23-Jan-2009 1,497 cc 153,000 km Hatchback Available

S3N227X, Original Mileage, Brand New Pearl White Paint (Painted And Coating By Monster Shine), Black Interior Compared To Other Yaris(not Dirty). Just Serviced Engine Oil And ATF, Gaskets Changed, New Suspension, No Oil Leaks Or Squeaks, Clean Condition, Car T...

Carwhiz Selections Pte Ltd

[Home](#)
[01/2024-2019](#)
[Toyota](#)
[2009 Toyota Yaris](#)
[2009 Toyota Yaris](#)
[Toyota Yaris](#)
[Toyota Yaris](#)
[Toyota Yaris](#)
[Toyota Yaris](#)
[Used Toyota](#)



☐ **Toyota Yaris 1.5A E (New 5-yr COE)** \$27,800 \$5,550 /yr 05-Oct-2009 1,497 cc - Hatchback Available

Full Loan Available At \$700 Plus, We Can Help To Convert To Z10 Usage If Needed. In House Loan Or Bank Loan Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Buy With Confidence! Viewing And Test Drive Available Daily Including Wee...

88 Motor Trading

[Home](#)
[05-Oct-2009](#)
[Toyota](#)
[2009 Toyota Yaris](#)
[2009 Toyota Yaris](#)
[Toyota Yaris](#)
[Toyota Yaris](#)
[Toyota Yaris](#)
[Toyota Yaris](#)
[Used Toyota](#)



☐ **Toyota Yaris 1.5A E (New 5-yr COE)** \$31,800 \$6,350 /yr 25-Nov-2009 1,497 cc 115,000 km Hatchback Available

1 Year In House Warranty, Full/High Loan Available, Free 2 x Servicing, Warranty Not By 3rd Party Workshop, Price Stated Above Is Actual Selling Price. New Paintwork Done, Fully Refurbished, Guaranteed Accident Free, STA Or VICOM Evaluation Are Welcome. Purcha...

Carway

[Home](#)
[25-Nov-2009](#)
[Toyota](#)
[2009 Toyota Yaris](#)
[2009 Toyota Yaris](#)
[Toyota Yaris](#)
[Toyota Yaris](#)
[Toyota Yaris](#)
[Toyota Yaris](#)
[Used Toyota](#)



Door Visor

Toyota Yaris Door Visor for sale! Cheapest door visor in town! Best quality assured!

More info about this product



☐ **Toyota Yaris 1.5A E (New 5-yr COE)** \$28,800 \$5,750 /yr 04-Jan-2010 1,497 cc 108,320 km Hatchback Available

Superbly Well Maintained By Fussy Owner, GearBox And Engine Still In Excellent State. Warranty Provided, Flexible Loan Schemes And Trade In Are Welcome. Please Contact Our Friendly Sales Consultant For A Viewing Appointment Before It's Gone.

SmartCars Boutique Pte Ltd

[Home](#)
[04-Jan-2010](#)
[Toyota](#)
[2010 Toyota Yaris](#)
[2010 Toyota Yaris](#)
[Toyota Yaris](#)
[Toyota Yaris](#)
[Toyota Yaris](#)
[Toyota Yaris](#)
[Used Toyota](#)



☐ **Toyota Yaris 1.5A E (New 5-yr COE)** \$28,800 \$5,750 /yr 16-Mar-2010 1,497 cc 123,000 km Hatchback Available

We Are The COE Specialist, No Gimmicks, Honest Dealing Car In Superb Condition, Full Loan Available 100%. New Pearl White Paint, Black Interior Compared To Other Yaris (Not Dirty), Clean Condition, This Is A Fun Yet Economical Car For Daily Use. If You Like The Me...

SmartCars Boutique Pte Ltd

[Home](#)
[16-Mar-2010](#)
[Toyota](#)
[2010 Toyota Yaris](#)
[2010 Toyota Yaris](#)
[Toyota Yaris](#)
[Toyota Yaris](#)
[Toyota Yaris](#)
[Toyota Yaris](#)
[Used Toyota](#)

BOOK FLATBID REPORT

Compare

Print Received Message

This mail is associated with :

***SLH8619D (7016439479SG)**

[SLB5315G]

TP

LING HUEY MEI LINDA

Nov 5 2019 6:00PM

[HITACHI CAPITAL ASIA PACIFIC PTE LTD]

New Hock Teck Motor Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 18/02/2020 09:38 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5477.00) - SLH8619D - Claim Handler: Chan, Kian-Meng

Approved:5477.00.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Nov 2019 Edit Reg		06 Nov 2019 00:00 Edit Adj Rpt	\$4,500.00 Edit Estimates	\$4,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: HITACHI CAPITAL ASIA PACIFIC PTE LTD , Co. Reg. No.: 199400399N									
Main Claimant: LING HUEY MEI LINDA , ID: S7522672A									
Vehicle Reg. No.:	SLH8619D	Date of Loss:	05/11/2019 18:00 - :59 [155 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 7016439479SG	Policy/Cover Note No.:	2100464589 (Comprehensive) Coverage: 13/04/2019 - 12/04/2020						
Vehicle Reg. No. (Insured):	SLB5315G	Policy No. (Claimant):	DMPCSN3114451802						
		Excess:							
Repairer: New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Bld C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com									
Claimant's Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 15/11/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (18/02/2020): Alert - Adj Mandate Approved (\$5477.00) - SLH8619D - Claim Handler: Chan, Kian-... - AIG_SG (08/11/2019): Request to upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLH8619D (70164394795G)
[SLB5315G]

TP

LING HUEY MEI LINDA

Nov 5 2019 6:00PM

[HITACHI CAPITAL ASIA PACIFIC PTE LTD]
New Hock Teck Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Assessment Reports										1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	11/12/19 17:43	Adjuster Immediate Advice							Load HTM		
Photos/Images										3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	10/12/19 09:05	General View							Load JPG	☒	
2	10/12/19 09:05	General View							Load JPG	☒	
3	10/12/19 09:05	General View							Load JPG	☒	
4	10/12/19 09:05	General View							Load JPG	☒	
5	10/12/19 09:05	General View							Load JPG	☒	
6	10/12/19 09:05	General View							Load JPG	☒	
7	10/12/19 09:05	General View							Load JPG	☒	
8	10/12/19 09:05	General View							Load JPG	☒	
9	10/12/19 09:05	General View							Load JPG	☒	
10	10/12/19 09:05	General View							Load JPG	☒	
11	10/12/19 09:05	General View							Load JPG	☒	
12	10/12/19 09:05	General View							Load JPG	☒	
13	10/12/19 09:05	General View							Load JPG	☒	
14	10/12/19 09:05	General View							Load JPG	☒	
15	10/12/19 09:05	General View							Load JPG	☒	
16	10/12/19 09:05	General View							Load JPG	☒	
17	10/12/19 09:05	General View							Load JPG	☒	
18	10/12/19 09:05	General View							Load JPG	☒	
19	10/12/19 09:05	General View							Load JPG	☒	
20	10/12/19 09:05	General View							Load JPG	☒	
21	10/12/19 09:05	General View							Load JPG	☒	
22	10/12/19 09:05	General View							Load JPG	☒	
23	10/12/19 09:05	General View							Load JPG	☒	
24	10/12/19 09:05	General View							Load JPG	☒	
25	10/12/19 09:05	General View							Load JPG	☒	
26	10/12/19 09:05	General View							Load JPG	☒	
27	10/12/19 09:05	General View							Load JPG	☒	
28	10/12/19 09:05	Reinspection Photo							Load JPG	☒	
29	10/12/19 09:05	Reinspection Photo							Load JPG	☒	
30	10/12/19 09:05	Reinspection Photo							Load JPG	☒	
31	10/12/19 09:05	Reinspection Photo							Load JPG	☒	
32	10/12/19 09:05	Reinspection Photo							Load JPG	☒	
33	10/12/19 09:05	Reinspection Photo							Load JPG	☒	
34	10/12/19 09:05	Reinspection Photo							Load JPG	☒	
35	10/12/19 09:05	Reinspection Photo							Load JPG	☒	
36	10/12/19 09:05	Reinspection Photo							Load JPG	☒	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
38	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
39	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
40	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
41	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
42	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
43	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
44	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
45	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
46	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
47	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
48	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
49	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
50	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
51	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
52	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
53	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
54	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
55	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
56	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
57	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
58	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
59	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
60	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
61	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
62	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
63	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
64	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
65	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
66	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
67	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
68	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
69	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
70	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
71	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
72	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
73	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
74	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
75	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
76	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
77	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
78	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
79	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
80	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
81	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
82	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
83	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
84	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
85	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
86	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
87	10/12/19 09:05	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/11/19 17:17	TP GIA REPORT	 Load PDF	
2	14/11/19 09:11	LETTER TO OI	 Load PDF	
3	11/12/19 15:35	TP ESTIMATE - FINALIZED	 Load PDF	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
4	11/12/19 17:35	TP LOD		Load PDF
5	11/12/19 17:45	TP LTA REBATE		Load PDF
6	18/02/20 11:48	EMAIL FROM TP		Load PDF
7	19/02/20 09:36	WORKSHOP INVOICE		Load PDF
8	19/02/20 09:36	AUTHORISATION TO ACT FORM		Load PDF
9	19/02/20 09:36	Release Voucher		Load PDF
10	19/02/20 09:36	GIA SEARCH		Load PDF
11	19/02/20 09:36	LOD		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	08/11/19 08:30	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLB5315G (Insd veh)	Model:	TOYOTA YARIS 1.3 (A)
	SLH8619D (TP veh)		
Date of Accident:	05/11/2019		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	13,211.34
Final Repair Cost	:	\$	5,470.00
Loss of Use	:	\$	11.00 days at \$60.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	5,470.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability ____ 100 ____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: ____	
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	New Hock Teck Motor Pte Ltd	:	\$ 5,470.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

19 Feb
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19019621/AHS3Q2

Date: 19/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100464589
Claimant
Vehicle No : SLH8619D **Insured Vehicle No :** SLB5315G
Date of Loss: 05/11/2019 **Nature of Claim:** TP **Claim No:** 7016439479SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH8619D**
 Make & Model: TOYOTA YARIS, 1.3 (A) Engine No: 1NZX490874
 Reg. Date: 29/11/2006 (Man. Year: 2006) Chassis No: MR054HY9104020287
 Colour: Red Odometer: 120801 km
 Engine Capacity: 1497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,077.05	3,274.70	4,802.35	59.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,270.00	2,500.00	1,770.00	41.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,347.05	5,774.70	6,572.35	53.23
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	12,347.05	4,500.00	7,847.05	63.55
+ GST 7.00/7.00% (S\$)	864.29	315.00	549.29	63.55
Nett Amount (S\$)	13,211.34	4,815.00	8,396.34	63.55
+ Loss of Use (11.0 x S\$60.00/day) (S\$)		660.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,477.00		
Global Sum Settlement (S\$)		5,470.00		

INSPECTION

Date of Assignment: 06/11/2019
 Date Inspected: 06/11/2019 Inspected At: New Hock Teck Motor Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, Blk C #01-43
 Autobay@Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	820.25 F	*- FL
2	1		*REAR BOOT LID TOYOTA LOGO	Necessary	29.75 F	*29.75 FL
3	1		*REAR BOOT LID YARIS LOGO	Necessary	28.85 F	*28.85 FL
4	1		*REAR BOOT LID E LOGO	Necessary	27.75 F	*27.75 FL
5	1		*REAR BOOT LID INNER LOCK	Not Necessary	281.10 F	*- FL
6	1		*REAR BOOT LID INNER TRIME BOARD	Not Necessary	561.60 F	*- FL
7	1		*REAR BOOT LID RUBBER	Not Necessary	277.45 F	*- FL
8	1		*REAR TAIL LAMP	N/S Smashed	579.80 F	*289.90 FL
9	1		*REAR TAIL LAMP PANEL	Dented	160.10 F	*160.10 FL
10	1		*REAR END PANEL	Distorted	781.45 F	*595.00 FL
11	1		*REAR END PANEL TOP GARNISH	Deformed	174.45 F	*174.45 FL
12	1		*REAR SPARE TYRE PANEL	Repair	788.10 F	*- FL
13	1		*REAR SPARE TYRE PANEL TOP COVER	Deformed	289.10 F	*289.10 FL
14	1		*REAR FENDER	Distorted	788.10 F	*788.10 FL
15	1		*REAR FENDER INNER TRIM BOARD	Deformed	588.10 F	*339.00 FL
16	1		*REAR FENDER AIR DUCT	Cracked	58.10 F	*58.10 FL
17	1		*REAR BUMPER	Distorted	374.10 F	*374.10 FL
18	1		*REAR BUMPER SPOILER	Distorted	588.10 F	*588.10 FL
19	1		*REAR BUMPER BRACKET	Distorted	160.10 F	*160.10 FL
20	1		*REAR BUMPER SIDE RETAINER	Necessary	132.20 F	*132.20 FL
21	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
22	1		*REAR NUMBER PLATE	Not Necessary	50.00 F	*- FL
23	1		*REAR NUMBER PLATE LAMP	Not Necessary	123.50 F	*- FL
24	1		*REAR TOOL BOX	Deformed	65.00 F	*65.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,077.05	4,299.60
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,024.90
Total Parts (\$\$)	8,077.05	3,274.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIT REAR WINDSCREEN	New	120.00	0.00
2	GUM	New	50.00	0.00
3	REMOVE & REFIT REAR CUSHION	New	100.00	60.00
4	REMOVE & REFIT REAR REVERSE SENSOR	New	150.00	50.00
5	REMOVE & REFIT REAR PETROL TANK	New	100.00	80.00
6	TUFF KOTE	New	150.00	80.00
7	TO CHECK WIRING	New	100.00	30.00
8	PANEL BEATING	New	2,000.00	1,200.00
9	SPRAY PAINTING	New	1,500.00	1,000.00
Gross Labour Cost (S\$)			4,270.00	2,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >