



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

AIG

Ling Huey Mei Linda
Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

07/11/2019

TP AIG

Vic

Accident date: 05/11/2019

Estimated repair cost for vehicle no: SLH8619D TOYOTA YARIS 1.5 E A '06

CHASSIS: MR054HY9104020287

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Repair</i>		\$820.25 <i>+</i>
2	1	Rear Boot Lid Toyota Logo		\$29.75 <i>✓</i>
3	1	Rear Boot Lid Yaris Logo <i>new</i>		\$28.85 <i>✓</i>
4	1	Rear Boot Lid E Logo		\$27.75 <i>✓</i>
5	1	Rear Boot Lid Inner Lock		\$281.10 <i>+</i>
6	1	Rear Boot Lid Inner Trime Board <i>new</i>		\$561.60 <i>+</i>
7	1	Rear Boot Lid Rubber		\$277.45 <i>+</i>
8	2	Rear Tail Lamp <i>LH smashed</i>	\$289.90	\$579.80 <i>289.80</i>
9	1	Rear Tail Lamp Panel <i>Dented</i>		\$160.10 <i>✓</i>
10	1	Rear End Panel <i>Distorted</i>		\$781.45 <i>595</i>
11	1	Rear End Panel Top Garnish <i>Deformed</i>		\$174.45 <i>✓</i>
12	1	Rear Spare Tyre Panel <i>Repair</i>		\$788.10 <i>+</i>
13	1	Rear Spare Tyre Panel Top Cover <i>Deformed</i>		\$289.10 <i>✓</i>
14	1	Rear Fender <i>Distorted</i>		\$788.10 <i>✓</i>
15	1	Rear Fender Inner Trime Board <i>Deformed</i>		\$588.10 <i>338</i>
16	1	Rear Fender Air Duct <i>Crushed</i>		\$58.10 <i>✓</i>
17	1	Rear Bumper <i>Distorted</i>		\$374.10 <i>✓</i>
18	1	Rear Bumper Spoiler <i>Distorted</i>		\$588.10 <i>✓</i>
19	1	Rear Bumper Bracket <i>Distorted</i>		\$160.10 <i>✓</i>
20	1	Rear Bumper Side Retainer <i>new</i>		\$132.20 <i>✓</i>
21	1	Rear Bumper Reverse Sensor <i>Damaged</i>		\$350.00 <i>200/sn</i>
22	1	Rear Number Plate <i>new</i>		\$50.00 <i>+</i>
23	1	Rear Number Plate Lamp <i>new</i>		\$123.50 <i>+</i>
24	1	Rear Tool Box <i>Deformed</i>		\$65.00 <i>✓</i>

4099-60

Subtotal :- **\$8,077.05**

3074.70 S.N: 200

Labour charges

Remove & refit rear windscreen	\$120.00 *
Gum	\$50.00 *
Remove & refit rear cushion	\$100.00 60.
Remove & refit rear reverse sensor	\$150.00 50
Remove & refit Rear Petrol Tank	\$100.00 80
Tuff kote	\$150.00 80.
To check wiring	\$100.00 30.
Panel beating	2500 \$2,000.00 1200
Spray painting	\$1,500.00 1000

Subtotal :- \$4,270.00

Total:- \$12,347.05

total: 5774.70.
r/s: 4.5K (Nett Value)

09 days.

4.5K

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: