

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 95K**AAD1911-019***Not Authorised*
11 Pmg @ 3200L

Vehicle No.:

Chassis No.:

Vehicle Make:

05 NOV 2019

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 95K

VF1ABL15AUC282163

RENAULT

LATITUDE

2.11.19

AIG

14/8/2015

		PART		LIST	
1	1	BUMPER COVER REAR	\$	Bu 561.70	✓
2	1	BUMPER LOWER REAR	\$	Dalwa 411.90	✓
3	1	BUMPER BRACKET CTR REAR	\$	Sn 98.10	X
4	1	BUMPER BRACKET SIDE RH REAR	\$	Sn 82.10	X
5	1	BUMPER RETAINER RH REAR	\$	Sn 59.80	X
6	1	BUMPER REFLECTOR RH	\$	Sn 16.60	X
7	1	BUMPER BRACKET SIDE LH REAR	\$	Sn 80.80	X
8	1	BUMPER RETAINER LH REAR	\$	Sn 54.20	X
9	1	BUMPER REFLECTOR LH	\$	CM 16.60	✓
10	1	BUMPER BEAM REAR	\$	Bz 547.80	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	Bz 114.50	✓
12	1	BUMPER BEAM BRACKET RH REAR	\$	R 100.90	X
13	1	OUTER PANEL REAR (End Panel)	\$	Bz 745.80	✓
14	1	OUTER PANEL REAR (End Panel) TRIM	\$	Sn 404.56	X
15	1	TAILLAMP RH	\$	Sn 313.10	} X
16	1	TAILLAMP PANEL RH	\$	R 401.40	
17	1	TAILLAMP LH	\$	Sn 401.40	
18	1	TAILLAMP PANEL LH	\$	R 401.40	
19	1	BOOT REAR	\$	R 1,677.20	
20	1	BOOT FINISHER	\$	Sn 344.70	}
21	1	BOOT WHEATERSTRIP	\$	Sn 178.20	
22	1	BOOT REFLECTOR LAMP LH	\$	Sn 277.70	
23	1	BOOT REFLECTOR LAMP RH	\$	Sn 277.70	}
24	1	BOOT BADGE 'RENAULT'	\$	Sn 82.40	
25	1	BOOT BADGE	\$	Sn 95.80	
26	1	BOOT STRUT LH	\$	Sn 145.10	X

Trans-cab Auto Services Pte Ltd

AAD1911-019

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 95K

27	1	BOOT STRUT RH	\$	SL	145.10	}	X
28	1	BOOT HINGE LH	\$	N	254.20		
29	1	BOOT HINGE RH	\$	N	253.80		
30	2	BOOT RUBBER PLUG	\$	SL	139.90		
31	2	BOOT BUFFER	\$	SL	26.80		
32	1	BOOT LOCK LINKAGE	\$	SL	20.60		
33	1	BOOT LOCK LINKAGE HOLDER	\$	SL	99.50		
34	1	BOOT INNER TRIM BOARD	\$	SL	611.00		
35	1	BOOT SWITCH	\$	SL	113.00		
36	1	BOOT LOCK	\$	N	246.60		
37	1	BOOT LOCK CATCH	\$	N	41.70		
38	1	EXHAUST CAP REAR	\$	SL	125.40		
TOTAL			\$		9,969.06		
10%			\$		996.91		
			\$		8,972.15		

Special Nett

Special Net						
1	1SET	PARKING AID	\$	SL	700.00	X
2	1SET	REAR BUMPER CLIP	\$	N	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	N	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	N	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	N	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	N	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	N	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	N	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	N	66.00	—
10	1	BOOT STICKER "Trans-cab"	\$	N	30.00	—
11	1	BOOT STICKER "6555-3333"	\$	N	30.00	—
12	2	REAR WINDSCREEN SEALANT	\$	N	80.00	} X
13	1	WINDSCREEN MOULDING	\$	N	100.00	
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	N	100.00	
15	1	BOOT INNER TRIM CLIP	\$	N	45.00	
16	1SET	BOOT FINISHER CLIP	\$	N	24.20	
17	1	TAILLAMP CLIP LH	\$	N	5.00	}
18	1	TAILLAMP CLIP RH	\$	N	5.00	

Trans-cab Auto Services Pte Ltd**AAD1911-019**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 95K

19	1	Rear Bumper Protector	\$	<i>nn</i> 100.00	X
20	1	EXHAUST MOUNTING REAR	\$	<i>nn</i> 16.00	X

TOTAL	\$	1,482.20
--------------	-----------	-----------------

TOTAL PARTS	\$	10,454.35
--------------------	-----------	------------------

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	<i>601</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>301</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>6001</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>nn</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X

Trans-cab Auto Services Pte Ltd**AAD1911-019**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 95K

To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	~ 170.00 X
To repair and realign rear exhaust pipe.	\$	~ 170.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00 X
Putty and spray painting of the affected portion.	\$	6,000.00 6601
TOTAL	\$	14,510.00
Over All Total	\$	24,964.35

LUMP SUM (REPAIR DAY)**20 DAYS****4 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: