ALJANI MOTOR WORK PTE LTD

SEP AIRESTIMATE*

VEHI CLENO : SHA 8152S

MAKE : MODEL : HYUNDAI i40

DATE : 5.11.2019

TEL : 6542 5119

ODEL	: HYUNDAI i40		: 6542 5119	INPIA	
Qty	Parts Description/ Labour		: 6542 6039		
	Acar bumper Do to I	Туре	Unit Price	Amount	
	The state of the s			\$ 553.00	
	Rear Bumper Bracket N. I			\$ 22.00 L \$ 35.60 7	-
	Rear Fender With Housing (LH)			\$ 4,736.80	_
	Rear Fender Inner Lining (LH)			\$ 169.30 >	(
	Rear Windscreen Moulding w			\$ 28.30	_
	Rear Door (LH) Denty			\$ 2,201.10	
	Rear Door Gear/Regulator (LH)			\$ 242.80 >	4
	Rear Door Power Motor (LH) MH	PE 3		\$ 158.60	4
	Front Door (LH) Desth			\$ 2,256.40	_
	Front Door Gear / Regulator (LH) MA			\$ 250.60 ?	
	Front Door Power Motor, LH			\$ 172.70	۸ _
	Door Centre Pillar Outer (LH) Dardrel			\$ 2,527.80	
	Rocker Panel Outer Garnish (LH)			Life and the second	× ×
	Rear Tyre Rim (LH)			\$ 325.30 \$ 107.10 \$	2
	Rear Wheel Hup-Cap (LH) No.			1000	×
	Rear Wheelbearing ING & Hub			\$ 192.00	1
	Rear Trailing Arm (LH) NL			\$ 145.70	2
	Rear Assist (LH) HLI Rear Shock Absorber (LH) HLI			\$ 276.30	X
	Rear Shock Absorber Mounting (LH) Hu	1		S 81.30	X
	Rear Crossmember HA			S 1,021.50	X
	Stabilizer Bar HA	1		\$ 199.60	X
	Stabilizer Link	1		\$ 85.90	X
	Rear Upper Arm (LH) HH	1	17275.48	\$ 335.75	7.
	Rear Lower Arm (LH) Hall		12325.40	\$ 353.80	7
	Rear Knuckle Arm (LH)		9960.32	\$ 545.60	X
			1000		
	SUB TOTA	L		\$ 17,728.25	
	LESS 20°			\$ 3,545.65	1
	DISCOUNTED TOTA	L		\$ 14,182.60	
				\$ 50.00	Nett \
	Rear Bumper Rubber Mat He	1000		\$ 46.00	The same of the sa
	Rear Windscreen Sealant Nuc				Nett
	Rear Door Comfortdelgro & Apps Sticker (LH)	he		100	Nett
	Front Door Coloured Comfort Logo (LH) Ne		251.00		Nett
	Rear Tyre (LH) SV			210.00	
				\$ 467.0	0
				0 40110	