

Qty	Parts Description/ Labour	Type	Unit Price	SHA 8152S Amount
	Labour Charge			
	Panel Beating			\$ 1,800.00 800/-
	Spray Painting Charge			\$ 1,500.00 900/-
	Wiring Charge			\$ 100.00 30/-
	Tuff Kote			\$ 150.00 40/-
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass		2270.00	\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	Remove/Refix Fuel Tank			\$ 150.00 40/-
	Transfer of Door	\$	120.00	\$ 240.00 120/-
	Remove/Refix Undercarriage (RR)			\$ 200.00 40/-
	Rear Wheel Alignment			\$ 120.00 60/-
	Re-set Frt & Rear ABS System	\$	200.00	\$ 400.00 } 150/-
	Re-set Frt & Rear Power Window System	\$	200.00	\$ 400.00 }
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 }
				\$ 5,930.00
	TOTAL LABOUR			
	ESTIMATE TOTAL			\$ 20,579.60
	06/11/2019 @ 0945hrs		12381.32	
	N/A Actual		L/S 9900/-	
	2/Share 8 days.			
	ryou			
	LKK Auto			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: