

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

*Not within
Resurvey 134 part
3 days*

4, NOV 2019

China Taiping Insurance (S) PL
105 Cecil Street #18-00
The Octagon S 069534

Attn: Motor claim dept
Claiming against your insured vehicle no: YJ9044R
Accident involving vehicle no: SKT6269S/YJ9044R
DOA: 01/11/2019 AT Entrance Of Blk 22 Sin Ming Road

Sear officer incharge
Re: estimate cost of repair for vehicle no: SKT6269S
To supply—

Description	Qty	Amount
Rear door, Lh	1 <i>B1</i>	1,069.20 ✓
Rear door hinge @87.10	2 <i>R</i>	174.20 X
Rear door checker	1 <i>JL</i>	138.50 X
Parts		1,381.90
Parts less 25%		345.47
		1,036.43

To remove/transfer doorboard, power window mechanism, door glass
and all attachments to new door. 150.00 *601*

To repair/reshape damaged front door, straighten center pillar. 550.00 *2501*

Replace/align above parts into position. 750.00 *4001*

To spray paint -----

2,486.43

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: