



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2006671
INV Date 28/09/2020
Reference CC6/CTI19019666/Uea3q2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. YP 5234D
Insured Veh. YP 7680K
Claim No. SNM19D204775
Policy No. DMCVSN3067391900
Accident Date 07/10/2019
Inspection Date 05/11/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD	Ref : CC6/CTI19019666/Uea3q2
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909	Date : 28-09-2020
	Code : CTI



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh. YP 7680K	Veh. Inspected YP 5234D
Policy No. DMCVSN3067391900	Coverage (\$) 0.00
Claim No. SNM19D204775	Excess (\$) 0.00
Assign From	Assign Date 05/11/2019

2. Vehicle Particulars & Condition

Make & Model ISUZU FRR90 (A)	c.c 5193
Engine No. HIDDEN	Year of Reg. 2016
Chassis No. JALFRR907G7000199	Colour BLUE
Odometer 151827	Steering IN ORDER
Brakes IN ORDER	Modification NIL
General GOOD	

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/90 R17.5	BRIDGESTONE	6 mm
L/H Front Tyre	225/90 R17.5	BRIDGESTONE	6 mm
R/H Rear Tyre	225/90 R17.5 (D)	BRIDGESTONE	6/6 mm
L/H Rear Tyre	225/90 R17.5 (D)	BRIDGESTONE	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.	
----------------------------------------------------------------------------	--

5. General Information

Accident Date 07/10/2019	Inspection Date 05/11/2019
Survey held at LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	
----------------------------------------------------------------------------------------------------------------------------------------	--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 5234D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	REAR BACK DOOR @\$2890.00 (SN)	BADLY DENTED / CRACKED	5,780.00	4,000.00
2	SET REAR BACK DOOR HINGES @\$485.00 (SN)	O/S BENT	970.00	180.00
2	REAR BACK DOOR LOCK BAR BRACKET @\$275.00 (SN)	SERVICEABLE	550.00	-
2	REAR BACK DOOR LOCK BAR @\$895.00 (SN)	SERVICEABLE	1,790.00	-
2	REAR TAIL LAMP ASSY @\$285.10 (SN)	O/S CRACKED	570.20	150.00
2	REAR CARGO BOX REAR PILLARS @\$2580.00 (SN)	O/S CRACKED	5,160.00	800.00
1	REAR CARGO BOX LOWER WOODEN (SN)	CRACKED	850.00	850.00
2	REAR CHASSIS TOP WOODEN CROSS MEMBER @\$1800.00 (SN)	CRACKED	3,600.00	3,000.00
2	REAR CHASSIS TOP WOODEN "U" BRACKET @\$280.00 (SN)	BENT	560.00	160.00
1	REAR STEP WOODEN MEMBER (SN)	CRACKED	580.00	300.00
1	REAR SAFETY BAR BUMPER (SN) }	DISTORTED	1,850.00	1,000.00
2	REAR SAFETY BAR BUMPER BRACKETS @\$680.00 (SN) }		1,360.00	-
1	SET REAR CHASSIS TOP WOODEN "U" BRACKET NUTS (SN)	NOT NECESSARY	80.00	-
1	REAR "60KM/H" STICKER (SN)	NECESSARY	15.00	10.00
1	REAR LICENCE PLATE (SN)	BENT	38.00	14.00
1	REAR "CORPORATE" ADVERTISEMENT & ARTWORK (SN)	NECESSARY	600.00	150.00
			24,353.20	10,614.00
<u>LABOUR</u>				
TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.			80.00	20.00
TO LIFT-UP CARGO BOX FOR FACILATE REPLACING WOODEN CHASSIS. }			800.00	680.00
TO REPAIR CHASSIS MEMBER. }			600.00	-
LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS.			1,080.00	600.00
TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED.			880.00	600.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REPLACE AND TRANSFER BACK DOOR PANEL, FITTING AND MECHANISM.	NOT NECESSARY	280.00	-
			3,720.00	1,900.00
GRAND TOTAL			28,073.20	12,514.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,000.00

Report Ref No. CC6/CTI19019666/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YP 5234D

INSPECTION







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YP 5234D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

