



**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793 | Tel: 6741-1730 / 731. Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: YP5234D191007

**Estimate**

Customer

Name: China Taiping Insurance (Singapore) Pte Ltd

Date: 05-11-19

Address Motor Claims Department

Vehicle No: YP5234D

3 Anson Road #16-00

Model/Make: Isuzu

Springleaf Tower Singapore 079909

FRR90SUQA-C


Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Back Door 02 pcs (@ S\$2,890.00 SN) <i>600/one</i>	\$5,780.00	SN 4000 <i>S.N</i>
2	Back Door Hinges 02 set (@ S\$485.00 SN) <i>0/5 beat</i>	\$ 970.00	SN 126 180 <i>S.N</i>
3	Back Door Lock Bar Bracket 02 pcs (@ S\$275.00 SN) <i>see</i>	\$ 550.00	SN X
4	Back Door Lock Bar 02 pcs (@ S\$895.00 SN) <i>see</i>	\$ 1,790.00	SN X
5	Tail Lamp Assy 02 pcs (@ S\$285.10 SN) <i>0/scrn</i>	\$ 570.20	SN 126 150 <i>S.N</i>
6	Cargo Box Rear Pillars 02 pcs (@ S\$2,580.00 SN) <i>0/scrn</i>	\$ 5,160.00	SN 126 800 <i>S.N</i>
7	Cargo Box Lower Wooden <i>see</i>	\$ 850.00	SN ✓
8	Chassis Top Wooden Cross member 02 Pcs (@ S\$1800.00) <i>one</i>	\$3,600.00	SN 3000 <i>S.N</i>
9	Chassis Top Wooden "U" Bracket 02 pcs (@ S\$280.00 SN) <i>one</i>	\$ 560.00	SN 2pc 160 <i>S.N</i>
10	Step Wooden Member <i>one</i>	\$ 580.00	SN 300 <i>S.N</i>
11	Safety Bar Bumper <i>015</i>	\$ 1,850.00	SN 1000 <i>S.N</i>
12	Safety Bar Bumper Brackets 02 pcs (@ S\$680.00 SN) <i>comp</i>	\$ 1,360.00	SN ✓
13	Chassis Top Wooden "U" Bracket Nuts 01 set <i>12</i>	\$ 80.00	SN X
14	"60 KM/H" Sticker <i>see</i>	\$ 15.00	SN 105 <i>N</i>
15	Licence Plate <i>see</i>	\$ 38.00	SN 145 <i>N</i>
16	"Corporate" Advertisement & Artwork <i>see</i>	\$ 600.00	SN 150 <i>S.N</i>
	To check all wiring & electrical component for proper function	\$ 80.00	- 20
	To repair Chassis Member	\$ 600.00	680
	To lift-Up Cargo Box for facilitate replacing Wooden Chassis	\$ 800.00	600
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,080.00	600
	To putty & spray painting & including touch up paint on accident affected	\$ 880.00	600
	To remove, replace and transfer Back door panel, fitting and mechanism	\$ 280.00	12 X

Total Parts & Labour of estimate for damaged vehicle

\$ 28,073.20

*12514*

Total amount in Lump Sum Basis for repaired vehicle



SDLS:

M/s Liu's Brother Auto Engrg Wks

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Not Authorized*  
*date*  
*5/11/19*  
*2/s \$10,000*  
*12 day.*