

ASS. REC. BY:

REF: CS/FC1 19091688 | UV f3<sup>52</sup>

Special Instruction:

Surveyor: MARCUS

ASSIGNMENT (Office)

From (Person): Jason Teo chue kiat of FC1

Date/Time: 7.11.19 8.28a.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDB 1788X

Insured: SHA 3408m

at Workshop m/s Kah Motor

Tel: 967 8493

of 15 Ubi road 4

Policy No: \_\_\_\_\_

Claim No: D19067018m FCSH

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_  
(Client's Record)

D.O.A. 4.11.2019

CA / REV / REP. / REV 24 HRS

Map'

H.O.D. Endorsement:

Date/Time: 7.11.19 9.10a.m

Person Contacted: PO Soon

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SDB 1788X - X
	SHA 3408m - CS / ALG / 6006624 / H1Wb3A2 R.O.A. 10/04/2016
8/11/19	Email preli revised to FC1

AGS, REC. BY:

*MARCUS*

REF:

*Fel.*

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD  TP  WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SDB1788X*

at Workshop m/s *Koh Motor*

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *\$120k*

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

*PR* Seen: *2* Consistent? : Yes or No

Est. Repairs: *5* days Res.: Yes or No

Lum Sum: *13.1* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: *SDB1788X* Yr Regn: *6/18*

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *(A)*

Make: *Honda Odyssey* C.C. *2356*

Colour: *Purple* A/C:  Insured / Std / NI / NA

Sp. Reading: *0/5707* T/Radio:  Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: *JHMRC1880JC201529*

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or

Brake:  In order / Jammed / Leaked / Burnt or

Modi:  Nil  S/Rim / STD A/Rim or

Tyre Size: F: *215/55R17*

R: \_\_\_\_\_

BS:  EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front *7* mm Rear *7* mm

R/Bal. *7* mm R/Bal. *7* mm

L/Bal. *7* mm L/Bal. *7* mm

D.O.A. *4/11/19* D.O.I. *8/11/19*

Survey held at \_\_\_\_\_

Des. of Damages:  Frt /  Rear /  O/S /  N/S /  UIC /  Rooftop or

*Rear*

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*27A55090*

*30/1/19 \$5858.79 conf. with Posoon. (Recd 6525.65, 537)*

Date/Time, File Pass to?  : Prel. Report

: Final Report

Days Of Repair: *5*

Resurvey No. of Trip: *2*

Date/Time, File Return to?

*30/12 typist*

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Wash and (\$)

Survey Fee:	<i>200</i>
Transportation:	<i>50</i>
<i>S + PS</i> \$:	<i>50 + 50</i>
Photos:	<i>44</i>
Other:	
<b>Total:</b>	<b><i>394</i></b>

Report Format: *CWS*  
Kemp Price / B.J. #: *PP \$ 5858.79*

*2x15=30*  
*30+170=200*

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	05-11-2019	<b>Our Ref No.</b> D19007018MFSH
<b>Accident Date</b>	04-11-2019	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA3408M	<b>Third Party Vehicle.</b> SDB1788X
<b>Survey Location</b>	15 UBI ROAD 4	
<b>Contact Person.</b>	YOU PO SOON	
<b>Contact No.</b>	96786493/ 96786493	<b>Fax No.</b> 0
<b>Survey Type</b>	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

## THIRD PARTY SURVEY REQUEST

<b>Cc : Workshop</b>	KAH MOTOR CO SDN BHD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	JASON TEA CHEE KIAT	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Friday, 8 November 2019 4:48 PM  
**To:** 'CWS Motor Claims'; SUR  
**Cc:** 'Jason Tea'  
**Subject:** RE: SURVEY ASSESSMENT - D19007018MFSH/1-SDB 1788X  
**Attachments:** SDB 1788X PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SDB 1788X  
Date of survey: 8/11/2019  
Number of days (estimated) : 5 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto) <admin-d@lkkauto.com>  
**Sent:** Thursday, 7 November 2019 9:12 AM  
**To:** 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>  
**Cc:** 'Jason Tea' <JasonTea@msfirstcapital.com.sg>  
**Subject:** RE: SURVEY ASSESSMENT - D19007018MFSH/1

RE-SEND.

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

**Summer Lee** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Summer Lee (LKK Auto) <admin-d@lkkauto.com>  
**Sent:** Thursday, 7 November, 2019 9:12 AM  
**To:** 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>; 'sur@lkkauto.com' <sur@lkkauto.com>  
**Cc:** 'Jason Tea' <JasonTea@msfirstcapital.com.sg>  
**Subject:** RE: SURVEY ASSESSMENT - D19007018MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

**Summer Lee** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>

**Sent:** Thursday, 7 November, 2019 8:28 AM

**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)

**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Jason Tea <[JasonTea@msfirstcapital.com.sg](mailto:JasonTea@msfirstcapital.com.sg)>

**Subject:** PRI: SURVEY ASSESSMENT - D19007018MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19007018MFSH

Our ref: CS/FCI19019688/Uvf3

DATE: 8/11/2019

The Motor Claims Department  
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

**INITIAL INSPECTION REPORT OF VEHICLE NO SDB 1788X**


We thank for your instruction on 7/11/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 8/11/2019 at the premises of M/s KAH MOTOR CO SDN BHD

Workshop Estimate Amount	: S\$12,383.24	_____
Revised Estimate Amount	: S\$5,492.52	_____
"Check" Items Amount	: S\$687.94	_____
Market Value	: S\$	_____
LTA Reimbursement Value	: S\$	_____
Nett Value	: S\$	_____

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA  
Licensed Appraiser

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/11/2019 14:24
Date Of Accident	04/11/2019 23:15
Exact Location Of Accident	JUNCTION OF YIO CHU KANG RD AND HOUGANG AVE 9
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDB1788X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KAREN WANG SIEW KHIM
NRIC No	S1716262D
Email Address	KARENWANG@ASAIKI.NET
Mobile Phone No	(LOCAL) +65-98461788
Alternative Phone No	OTHERS-90881788

### Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY-2.4 (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10843964
Cover Note Number	

### Driver

Name of Driver	YAP KEE SIANG , BENJAMIN
NRIC No	S9226309F
Date Of Birth	24/07/1992
Occupation	INDOOR
Date Of Driving Pass	21/07/2012
Driving Experience	7 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83602442
Fax Number	
Contact Number	
EMail Address	BENYAP@ASAIKI.NET

Address	10 BEGONIA CRESCENT SINGAPORE
Postcode	809979
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TAN MIN YI GENDER: : FEMALE

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

REFER TO ATTACHED STATEMENT - THIRD PARTY DIRECT SETTLEMENT

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA3408M
Vehicle Make/Model/Colour	HYUNDAI / BLUE
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	ABDUL WAHID BIN ABU BAKAR
NRIC/Passport Number	S1389919C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Vehicle Number: SDB 1988X

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
  - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
  - (e) the information so collected under (d) above may be shared / disclosed:
    - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
    - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time: 5/11/19


  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 05/11/2019  
10:30AM

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

Sketch Plan Pg. 2

Vehicle Number: SD81788X

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle came to a stop at the junction of Yio Chu Kang Road and Hougang Ave 9 while traveling on YCK road. A few seconds later, SMA3408M rear-ended my vehicle that was not moving. We then came out of vehicles to exchange details.

My  
 - Vehicle came to a stop due to red light at junction.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time: 5/11/19

  
 X Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 05/11/2019  
10.30 AM

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
 Owner ID: 262D

### Vehicle Details

Vehicle No.: SDB1788X  
 Vehicle to be Exported: No  
 Intended Deregistration Date: 08 Nov 2019  
 Vehicle Make: HONDA  
 Vehicle Model: ODYSSEY 2.4 EX-S CVT  
 Primary Colour: Purple  
 Manufacturing Year: 2018  
 Engine No.: K24W72400549  
 Chassis No.: JHMRC1880JC201529  
 Maximum Power Output: 129.0 kW (172 bhp)  
 Open Market Value: \$27,448.00  
 Original Registration Date: 08 Jun 2018  
 First Registration Date: 08 Jun 2018  
 Transfer Count: 0  
 Actual ARF Paid: \$30,428.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
 PARF Eligibility Expiry Date: 07 Jun 2028  
 PARF Rebate Amount: \$22,821.00

### Intended COE Rebate Details

COE Expiry Date: 07 Jun 2028  
 COE Category: B - Car above 1600cc or 97kW (130bhp)  
 COE Period(Years): 10  
 QP Paid: \$37,605.00  
 COE Rebate Amount: \$32,269.00  
**Total Rebate Amount: \$55,090.00**

The information contained herein is correct as at 08 Nov 2019

OK

# Google Home Mini

Buy Google Home Mini for hands-free control of your smart home. Shop

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

2017 Ford Mondeo.



Beautiful Luxury A Executive Sedan With Top Notch Technology And Comfort. Direct Owner StarAd

**Lake View Credit Pte Ltd**

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are fair

Post an Ad Advertiser Login Ways of Selling

Browse by Category

Sort by Date Posted

Advanced Search

Honda Odyssey

3 vehicles

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Honda	Odyssey	Any	Any	2018	Any	Any	Any
	<b>Honda Odyssey 2.4A EXV-S Sunroof</b>	<b>\$126,300</b>	<b>\$12,480 /yr</b>	<b>16-Jul-2018</b>	<b>2,356 cc</b>	<b>27,000 km</b>	<b>MPV</b>
Kah Motors Unit. 5 Years Warranty. The Stylish Ride With Comfort. Save A Lot From Buying Brand New. 90% Loan Of The Car Price Available With Interest Rates From 2.28% Available. Trade In Welcome. Call Now To Book An Appointment To View This Beauty. Viewin... Posted: 06-Nov-2019 Tags: 2018 Honda Odyssey, 2018 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda							
	<b>Honda Odyssey 2.4A EX-S</b>	<b>\$123,000</b>	<b>\$12,150 /yr</b>	<b>03-Sep-2018</b>	<b>2,356 cc</b>	<b>11,700 km</b>	<b>MPV</b>
1 Owner, Super Low Original Mileage, Accident Free, Kah Motor Unit, 2 More Years Complimentary Service Package, Regular Serviced Kah Motor, Last Serviced May 2019, 3+2 Yrs Warranty Till 2023, Dunlop Tyre, Comes With 3-Digit Car Plate Number, Excellent Condition, Bra... 360 VR Cars Posted: 26-Oct-2019 Tags: 2018 Honda Odyssey, 2018 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda							
	<b>Honda Odyssey 2.4A EXV-S Sunroof</b>	<b>\$123,800</b>	<b>\$12,750 /yr</b>	<b>02-Apr-2018</b>	<b>2,356 cc</b>	<b>26,450 km</b>	<b>MPV</b>
Kah Motors Unit. 5 Years Warranty. Female Owner. Trade In Welcome. High Loan Available. Consignment Unit. Call Now For A Viewing Appt. Prem Roy Motoring Posted: 17-Oct-2019 Tags: 2018 Honda Odyssey, 2018 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda							

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
------	-------	-------	--------------	----------	---------	---------	----------

For old advertisements, view Expired ads



# QUOTATION

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer** : MS FIRST CAPITAL INSURANCE LIMITED  
 36 ROBINSON ROAD  
 #16-01 CITY HOUSE  
 SINGAPORE 068877

**Registration No** : SDB1788X

**Chassis No** : JHMRC1880JC201529

**Model** : ODYSSEY 2.4 EX-S 18YM (EURO 6)

**Owner's Name** : KAREN WANG SIEW KHIM

**Ins Policy No.** :

**Date of Accident** : 4/11/2019

**Document No.** : SQT19004827 **Page** 1

**Date** : 5. Nov 2019

**Customer No.** : WZF002

**Svc Advisor** : YOU PO SOON

**Engine No** : K24W72400549

**Date | Time** : 5. Nov 2019 2:44:09 PM

**Surveyor Name** :

**Survey Date** :

**Authorisation Date** :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: KAREN WANG OWNER INSURER: AVIVA LTD ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED TP VEH: SHA3408M						
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	18.00 ✓	25	27.00 ✓	1.89	28.89
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	16.90 ✓	25	12.67 ✓	0.89	13.56
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.90 ✓	25	12.67 ✓	0.89	13.56
73221-SR4-000	SPACERRR.W/SHIELD	4	3.90 ✓	25	11.70 ✓	0.82	12.52
73225-TM8-000	RUBBER AWINDSHIELD DAM	1	3.70 ✓	25	2.77 ✓	0.19	2.96
73226-SZW-000	DAMPERSTD 5X5	2	8.50 ✓	25	12.75 ✓	0.89	13.64
76711-T6A-003	CAPPIVOT	1	4.80 ✓	25	3.60 ✓	0.25	3.85
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00 ✓		60.00 ✓	4.20	64.20
68100-T6A-Q10ZZ	TAILGATE COMP	1	1070.80 ✓	25	803.10 ✓	56.22	859.32
75701-T6A-000	EMBLEMH	1	26.30 ✓	25	19.72 ✓	1.38	21.10
75722-T6A-901	EMBLEM,RR.	1	31.00 ✓	25	23.25 ✓	1.63	24.88
74440-T6A-003	WEATHERSTRIPTAILGATE	1	117.40 X	25	88.05 X	6.16	94.21
74800-TF0-J02	LOCKTAILGATE	1	185.40 X	25	139.05 X	9.73	148.78
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN	1	175.50 X	25	131.62 X	9.21	140.83
04715-T6A-900ZZ	FACERR.BUMPER	1	568.30 ✓	25	426.22 ✓	29.84	456.06
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	19.10 X	25	14.32 X	1.00	15.32
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	19.10 X	25	14.32 X	1.00	15.32
91505-TM8-003	CLIP,BUMPER	7	2.30 ✓	25	12.07 ✓	0.84	12.91
33555-SLJ-013	REFLECTOR ASSYL.RR.	1	45.40 X	25	34.05 X	2.38	36.43

Printed on 5/11/2019 3:01:36 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



# QUOTATION

**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

<b>Customer</b>	: MS FIRST CAPITAL INSURANCE LIMITED 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877	<b>Document No.</b>	: SQT19004827	<b>Page</b>	2
<b>Registration No</b>	: SDB1788X	<b>Date</b>	: 5. Nov 2019	<b>Customer No.</b>	: WZF002
<b>Chassis No</b>	: JHMRC1880JC201529	<b>Svc Advisor</b>	: YOU PO SOON	<b>Engine No</b>	: K24W72400549
<b>Model</b>	: ODYSSEY 2.4 EX-S 18YM (EURO 6)	<b>Date   Time</b>	: 5. Nov 2019 2:44:09 PM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: KAREN WANG SIEW KHIM	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 4/11/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
33505-SLJ-013	REFLECTOR ASSYR.RR.	17	45.40	25	34.05	2.38	36.43
84640-T6A-003ZA	LINING ASSYRR.PANEL	17	103.60	25	77.70	5.44	83.14
34150-T6A-003	LIGHT ASSYR.LID	17	386.20	25	289.65	20.28	309.93
34155-T6A-003	LIGHT ASSYL.LID	17	386.20	25	289.65	20.28	309.93
33500-T6A-003	TAILLIGHT ASSYR.	17	838.10	25	628.57	44.00	672.57
33550-T6A-003	TAILLIGHT ASSYL.	17	838.10	25	628.57	44.00	672.57
74940-TR0-003	BUZZER ASSYSMART	CM	61.70	25	45.07	3.15	48.22
38387-SLE-003	ANTENNA ASSY.L.RR.	17	60.60	25	45.45	3.18	48.63
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
66100-T6A-Q00ZZ	PANEL COMP.REAR	R	460.80	25	345.60	24.19	369.79
<b>Sum Item</b>					<b>4553.24</b>	<b>318.71</b>	<b>4,871.95</b>
BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	100.00		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	17	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	17	80.00		80.00	5.60	85.60
BP00R	APPLY BODY UNDERSIDE COATING (N)	17	250.00		250.00	17.50	267.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4PCS-(N)	1	150.00	130	150.00	10.50	160.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00		300.00	21.00	321.00
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	350.00	320	350.00	24.50	374.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	350.00	320	350.00	24.50	374.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	350.00	180	350.00	24.50	374.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	450.00		450.00	31.50	481.50
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN	1	2400.00	1120	2400.00	168.00	2568.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2900.00	1125	2900.00	203.00	3103.00
<b>Sum Labor</b>					<b>7830.00</b>	<b>548.10</b>	<b>8,378.10</b>

Printed on 5/11/2019 3:01:36 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



# QUOTATION

**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Service and Body Repair  
Tel: +65 6841 3838 Website: www.honda.com.sg  
For 24-hours Roadside Assistance, Call 98203838

<b>Customer</b>	: MS FIRST CAPITAL INSURANCE LIMITED 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877	<b>Document No.</b>	: SQT19004827	<b>Page</b>	3
<b>Registration No</b>	: SDB1788X	<b>Date</b>	: 5. Nov 2019	<b>Customer No.</b>	: WZF002
<b>Chassis No</b>	: JHMRC1880JC201529	<b>Svc Advisor</b>	: YOU PO SOON	<b>Engine No</b>	: K24W72400549
<b>Model</b>	: ODYSSEY 2.4 EX-S 18YM (EURO 6)	<b>Date   Time</b>	: 5. Nov 2019 2:44:09 PM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: KAREN WANG SIEW KHIM	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 4/11/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Includ GST
Survey By	<u>Marcus Hk</u>						
Date & Time	<u>8/11/19 @ 9.30am.</u>						
Excess							
Status	<u>Not Approved</u>						
Signature	<u>To be ph. before repair.</u> <u>Sdy.</u>						
<b>Total Amount</b>					12,383.24	866.81	13,250.05
<b>Total (Inclusive of GST)</b>							<b>13,250.05</b>
							12,384.44*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No ill. communication(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Printed on 5/11/2019 3:01:36 PM  
This is a computer generated invoice. No signature is required.  
Part prices are subjected to change without notice.  
The above estimated cost of repair do not include any unforeseen damages.  
GST Amount is calculated from individual line(s).  
An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.  
However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**HONDA**26/11/2019  
Attn: Marcus**SERVICE PRE-INVOICE****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380GCustomer: CU0052150 / MS FIRST CAPITAL  
Chassis No: JHMRC1880JC201529  
License No: SDB1788X  
Mileage: 15873  
Engine No: K24W72400549Document No: SVO19073628  
Printed By: PSYOU  
Order Date: 14. November 2019  
Order Time: 10:24:41 AM  
Service Advisor: YOU PO SOON

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 73778 ) OWNER: KAREN WANG OWNER INSURER: AVIVA LTD ACC DATE: 04/11/2019 SURVEYED BY: MARCUS CHUA DATE: 8/11/2019 REF NO: D19007018MFSH TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED TP VEH: SHA3408M						
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	18.00	25	27.00	1.89	28.89
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	16.90	25	12.67	0.89	13.56
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.90	25	12.67	0.89	13.56
73221-SR4-000	SPACERRR.W/SHIELD	4	3.90	25	11.70	0.82	12.52
73225-TM8-000	RUBBER A WINDSHIELD DAM	1	3.70	25	2.77	0.19	2.96
73226-SZW-000	DAMPERSTD 5X5	2	8.50	25	12.75	0.89	13.64
76711-T6A-003	CAPPIVOT	1	4.80	25	3.60	0.25	3.85
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-T6A-Q10ZZ	TAILGATE COMP	1	1,070.80	25	803.10	56.22	859.32
75701-T6A-000	EMBLEMH	1	26.30	25	19.72	1.38	21.10
75722-T6A-901	EMBLEM,RR.	1	31.00	25	23.25	1.63	24.88
04715-T6A-900ZZ	FACERR.BUMPER	1	568.30	25	426.22	29.84	456.06
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
74940-TR0-003	BUZZER ASSYSMART	1	61.70	25	46.27	3.24	49.51
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
	<b>SUM PARTS:</b>				<b>1,793.79</b>	<b>125.57</b>	<b>1,919.36</b>
BOSUN	0760 SUNDRIES	1	20.00		20.00	1.40	21.40
BML02I	0760 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	100.00		100.00	7.00	107.00
BA02R	1864 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00		130.00	9.10	139.10
BG02D	1864 REMOVE & INSTALL RR. WINDSCREEN. (N)	1	300.00		300.00	21.00	321.00
BC012R	0760 RESET VEHICLE SMART ENTRY SYSTEM	1	320.00		320.00	22.40	342.40
BC011R	0760 REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	320.00		320.00	22.40	342.40
BMI03D	1864 REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	180.00		180.00	12.60	192.60
BKTG02R	1864 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	450.00		450.00	31.50	481.50



# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022  
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

<b>Customer:</b>	CU0052150 / MS FIRST CAPITAL	<b>Document No:</b>	SVO19073628
<b>Chassis No:</b>	JHMRC1880JC201529	<b>Printed By:</b>	PSYOU
<b>License No:</b>	SDB1788X	<b>Order Date:</b>	14. November 2019
<b>Mileage:</b>	15873	<b>Order Time:</b>	10:24:41 AM
<b>Engine No:</b>	K24W72400549	<b>Service Advisor:</b>	YOU PO SOON

<b>BKRP02M</b>	1864 CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN FLOOR PANEL INCLUDING FITTINGS ON ATTACHMENT ITEM	1	1,120.00	1,120.00	78.40	1,198.40	
<b>BP06R</b>	1865 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	1,125.00	1,125.00	78.75	1,203.75	
				<b>SUM LABOUR:</b>	<b>4,065.00</b>	<b>284.55</b>	<b>4,349.55</b>
				<b>TOTAL SGD</b>	<b>5,858.79</b>	<b>410.12</b>	<b>6,268.91</b>
<b>Total Payable (SGD)</b>						<b>6,268.91</b>	

GST Amount is calculated from individual line(s)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19019688/Uvf3s2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 09-01-2020	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 3408M	Veh. Inspected	SDB 1788X
Policy No.		Coverage (\$)	0.00
Claim No.	D19007018MFSH	Excess (\$)	0.00
Assign From	JASON TEA CHEE KIAT	Assign Date	07/11/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA ODYSSEY (A)	c.c	2356
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JHMRC1880JC201529	Colour	PURPLE
Odometer	015707	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	DUNLOP	7 mm
L/H Front Tyre	215/55 R17	DUNLOP	7 mm
R/H Rear Tyre	215/55 R17	DUNLOP	7 mm
L/H Rear Tyre	215/55 R17	DUNLOP	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/11/2019	Inspection Date	08/11/2019
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDB 1788X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
2	MOLDINGRR.WINDSHIELD SIDE (SN)	NECESSARY	27.00	27.00
1	MOLDINGR.RR.WINDSHIELD CORNER (SN)	NECESSARY	12.67	12.67
1	MOLDINGL.RR.WINDSHIELD CORNER (SN)	NECESSARY	12.67	12.67
4	SPACERRR.W/SHIELD (SN)	NECESSARY	11.70	11.70
1	RUBBER AWINDSHIELD DAM (SN)	NECESSARY	2.77	2.77
2	DAMPERSTD 5X5 (SN)	NECESSARY	12.75	12.75
1	CAPPIVOT (SN)	NECESSARY	3.60	3.60
1	WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	TAILGATE COMP (SN)	DENTED	803.10	803.10
1	EMBLEMH (SN)	NECESSARY	19.72	19.72
1	EMBLEM,RR. (SN)	NECESSARY	23.25	23.25
1	WEATHERSTRIP TAILGATE (SN)	NOT NECESSARY	88.05	-
1	LOCK TAILGATE (SN)	SERVICEABLE	139.05	-
1	MOLDING ASSYRR.LICENSE GARN (SN)	NOT NECESSARY	131.62	-
1	FACERR.BUMPER (SN)	DENTED / DEFORMED	426.22	426.22
1	SPACERR.RR.BUMPER SIDE (SN)	NOT NECESSARY	14.32	-
1	SPACERL.RR.BUMPER SIDE (SN)	NOT NECESSARY	14.32	-
7	CLIP, BUMPER (SN)	NECESSARY	12.07	12.07
1	REFLECTOR ASSYL.RR. (SN)	NOT NECESSARY	34.05	-
1	REFLECTOR ASSYR.RR. (SN)	NOT NECESSARY	34.05	-
1	LINING ASSYRR.PANEL (SN)	NOT NECESSARY	77.70	-
1	LIGHT ASSYR.LID (SN)	NOT NECESSARY	289.65	-
1	LIGHT ASSYL.LID (SN)	NOT NECESSARY	289.65	-
1	TAILLIGHT ASSYR. (SN)	NOT NECESSARY	628.57	-
1	TAILLIGHT ASSYL. (SN)	NOT NECESSARY	628.57	-
1	BUZZER ASSYSMART (SN)	CRACKED	46.27	46.27
1	ANTENNA ASSY,L.RR. (SN)	NOT NECESSARY	45.45	-
4	ACT RR.SENSOR (SN)	SHORTED	320.00	320.00
1	PANEL COMP, REAR (SN)	TO REPAIR SEE LABOUR	345.60	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			4,604.44	1,813.79
	<b>LABOUR</b>			
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		100.00	100.00
	BODY UNDERSIDE COATING.	NOT NECESSARY	100.00	-
	BODY JOINT SEALANT.	NOT NECESSARY	80.00	-
	APPLY BODY UNDERSIDE COATING.	NOT NECESSARY	250.00	-
	REMOVE & RENEW REVERSE SENSORS.		150.00	130.00
	REMOVE & INSTALL RR. WINDSCREEN.		300.00	300.00
	RESET VEHICLE SMART ENTRY SYSTEM.		350.00	320.00
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA.		350.00	320.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		350.00	180.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &.		450.00	450.00
	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN. INCLUSIVE OF THE REPAIR OF PANEL COMP, REAR.		2,400.00	1,120.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		2,900.00	1,125.00
			7,780.00	4,045.00
	<b>GRAND TOTAL</b>		<b>12,384.44</b>	<b>5,858.79</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>5,858.79</b>

Report Ref No. CS/FCI19019688/Uvf3s2

**CHUA KANG SENG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.