

ASS. REC. BY:

REF: CS/INC 19019706 / Av f3

Special Instruction:

SURVJOY = Adrian

ASSIGNMENT (Office)

From (Person): HA 21149 Buty Ibrahim

of INC

Date/Time: 7.11.19 10.08.19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMH 8938x

Insured:

SLR 4461P

at Workshop m/s Dynamic Autoware

Tel:

98564815

of 8 Kaki Buti Ave 4 #08-09

Policy No:

Claim No:

M7/1070738-002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

5.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

m/s

H.O.D. Endorsement:

Date/Time: 7.11.19 10.37.19

Person Contacted:

m/s

Vehicle IN

OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

SMH 8938x - x

25/11/19

Adrian confirmed LS \$ 6300 (Red 11397.20, 6410)

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SMH8938X - Yr Regn: 2019 Feb.

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel C.C. 1496

Colour: Bronze A/C: Insured / Std / NI / NA

Sp. Reading: 26154 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: Ru11313744

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 12/11/19

Survey held at Dynamic 3.39pm

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP INC.

RECEIVED 28 NOV 2019

MV:

PV:

Nett:

Date/Time, File Pass 1/7

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return In/7

26/11 typist

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee

Transportation

3 + PS

Stamps

Office

250

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Insp (\$

☐ Final Insp (\$

Report Format: TP

Lump Sum / MP/10 6300k

## **Nivitha (LKK Auto)**

---

**From:** Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>  
**Sent:** Thursday, 7 November 2019 11:28 AM  
**To:** Admin-D (LKKAuto); assignments; SUR  
**Cc:** Hazalysa Binte Ibrahim  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 07/11/2019

Dear LKK,

Re-send with details.

Thank you.

Warmest Regards

**Hazalysa Bte Ibrahim**  
Admin Assistant  
Motor Department  
[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
**Find out more at [income.com.sg/careers](http://income.com.sg/careers)**

**in** with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

**From:** Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]  
**Sent:** Thursday, 7 November 2019 10:56 AM  
**To:** Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>  
**Cc:** Thio Tse Kiat <tsekiat.thio@income.com.sg>  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 07/11/2019

Dear Hazalysa,

Noted with thanks.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Hazalya Binte Ibrahim [mailto:[hazalya.ibrahim@income.com.sg](mailto:hazalya.ibrahim@income.com.sg)]  
**Sent:** Thursday, 7 November 2019 10:54 AM  
**To:** Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** Thio Tse Kiat <[tsekiat.thio@income.com.sg](mailto:tsekiat.thio@income.com.sg)>; Hazalya Binte Ibrahim <[hazalya.ibrahim@income.com.sg](mailto:hazalya.ibrahim@income.com.sg)>  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 07/11/2019

Dear LKK,

Please cancel the survey.

Thank you.

|   |                |          |                    |                                                                |                 |             |  |  |  |  |  |
|---|----------------|----------|--------------------|----------------------------------------------------------------|-----------------|-------------|--|--|--|--|--|
| 5 | MT/1069323-001 | GBB8385C | RYDER AUTO PTE LTD | 2 KAKI BUKIT AVE 2 #02-19 AUTOHUB @ KAKI BUKIT SINGAPOR 417921 | june / 67418277 | 10-00-12-00 |  |  |  |  |  |
|---|----------------|----------|--------------------|----------------------------------------------------------------|-----------------|-------------|--|--|--|--|--|

Warmest Regards

**Hazalya Bte Ibrahim**  
Admin Assistant  
Motor Department  
[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
**Find out more at [income.com.sg/careers](http://income.com.sg/careers)**

**in** with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

**From:** Admin-D (LKKAuto) [<mailto:admin-d@lkkauto.com>]  
**Sent:** Thursday, 7 November 2019 10:33 AM  
**To:** Hazalya Binte Ibrahim <[hazalya.ibrahim@income.com.sg](mailto:hazalya.ibrahim@income.com.sg)>; [assignments@lkkauto.com](mailto:assignments@lkkauto.com); SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** Thio Tse Kiat <[tsekiat.thio@income.com.sg](mailto:tsekiat.thio@income.com.sg)>  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 07/11/2019

Dear Sir/Madam,

Thank you for your assignment.

SDB2382B,SMM5544S car not in the workshop,repairer will arrange.

Best Regards,

**Summer Lee** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Hazalya Binte Ibrahim <[hazalya.ibrahim@income.com.sg](mailto:hazalya.ibrahim@income.com.sg)>  
**Sent:** Thursday, 7 November, 2019 10:08 AM  
**To:** Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>; [assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** Thio Tse Kiat <[tsekiat.thio@income.com.sg](mailto:tsekiat.thio@income.com.sg)>; Hazalya Binte Ibrahim <[hazalya.ibrahim@income.com.sg](mailto:hazalya.ibrahim@income.com.sg)>  
**Subject:** TP CASES FARMED OUT TO LKK ON 07/11/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng instruction :-

| SN | OIC             | Claim No.      | Vehicle  | WorkShop Name                       | WorkShop Address                                                  | WorkShop Contact              | Survey Time | OI VEH    | DOA      | Additional Remarks |
|----|-----------------|----------------|----------|-------------------------------------|-------------------------------------------------------------------|-------------------------------|-------------|-----------|----------|--------------------|
| 1  | Jeff Lin        | MT/1069832-002 | SMG282L  | ADVANCE AUTO GARAGE                 | 23 KAKI BUKIT AVE 4 #04-01 AAS KAKI BUKIT CENTRE SINGAPORE 415933 | Xavier Lim / 9007 9247        |             | 5AMH6759C | 04/11/19 |                    |
| 2  | Azhari          | MT/1070238-002 | SMH8938X | DYNAMIC AUTOWORK PTE LTD            | 8 KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT                 | Michelle / 9856 4815          |             | 5LR4461P  | 05/11/19 |                    |
| 3  | Charlotte Chew  | MT/1070066-002 | SLZ9192R | MG SOLUTION PTE LTD                 | 23 KAKI BUKIT AVENUE 4 #02-03B (SOUTH WING)                       | Ms Hong / 6243 1373           |             | 5MD5781X  | 05/11/19 |                    |
| 4  | Quek Swee Keng  | MT/1070309-001 | SHC6019Y | PREMIER AUTOMOTIVE SERVICES PTE LTD | 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443                  | MR CHUA / 65446689            |             | FBP5293E  | 05/11/19 |                    |
| 5  |                 | MT/1069323-001 | GBB8385G | RYDER-AUTO PTE LTD                  | 2 KAKI BUKIT AVE 2 #02-19 AUTOHUB @ KAKI BUKIT SINGAPORE 417921   | John / 67418277               | 10-00-12-00 | -         |          | CANCEL THE SURVEY  |
| 6  | Muhammad Airwan | MT/1062113-003 | JTM5751  | STAXX PTE LTD                       | 1 KAKI BUKIT ROAD 1 #02-09 ENTERPRISE ONE SINGAPORE 415934        | Chong / 6741 1480 / 9839 1819 |             | YN7028C   | 11/09/19 |                    |
| 7  | David Phua      | MT/1070247-001 | SKK6749X | CHEW MOTOR PTE LTD                  | 1 KAKI BUKIT AVENUE 6 #01-11/41 AUTOBAY @ KAKI BUKIT              | Sukyl Chong / 6747 9241       |             | 5LN6600M  | 05/11/19 |                    |

|    |                |                |          |                     |                                                                       |                          |             |          |          |  |
|----|----------------|----------------|----------|---------------------|-----------------------------------------------------------------------|--------------------------|-------------|----------|----------|--|
| 8  | Charlotte Chew | MT/1069303-002 | YN1408G  | CHIN MENG MOTORS    | 1 KAKI BUKIT AVENUE 6 #01-40/63 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 | QUEK KIM SENG / 67474810 | 10:00-12:00 | GV3920B  | 29/10/19 |  |
| 9  | Azhari         | MT/1068654-002 | SD82382B | SME MOTOR PTE. LTD. | 1 KAKI BUKIT AVENUE 6 #02-15 AUTOBAY @ KAKI BUKIT SINGAPORE 417883    | Jacob Ang / 6747 6106    | 10:00-12:00 | SMG3816C | 24/10/19 |  |
| 10 | Fiona Shen     | MT/1069889-002 | SMM5544S | SME MOTOR PTE. LTD. | 1 KAKI BUKIT AVENUE 6 #02-15 AUTOBAY @ KAKI BUKIT SINGAPORE 417883    | Jacob Ang / 6747 6106    | 10:00-12:00 | SLT7636F | 01/11/19 |  |

**Please contact workshops.**

**Please revert to officer-in-charge after survey.**

**Thank you.**

**Warmest Regards**

**Hazalya Bte Ibrahim**  
Admin Assistant  
Motor Department  
**T +65 6430 7902**  
[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
**Find out more at [Income.com.sg/careers](http://Income.com.sg/careers)**

**in** with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

---

#### Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

---

#### Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

---

#### Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                         |
|----------------------------|-----------------------------------------|
| Date Of Report             | 06/11/2019 15:03                        |
| Date Of Accident           | 05/11/2019 16:00                        |
| Exact Location Of Accident | CROSS JUNCTION OF SIMS WAY / GEYLANG RD |
| Country/State of Loss      | SINGAPORE                               |

### DETAILS OF OWN VEHICLE

|                             |                           |
|-----------------------------|---------------------------|
| Vehicle Registration Number | SMH8938X                  |
| <b>Insured/Policyholder</b> |                           |
| Name Of Registered Owner    | MOHAMED SOFIAN BIN NORDIN |
| NRIC No                     | S8323154H                 |
| Email Address               | SOFIANBOY@HOTMAIL.COM     |
| Mobile Phone No             | (LOCAL) +65-96459011      |
| Alternative Phone No        | OTHERS-96459011           |

### Vehicle Particulars

|                                                                              |                |
|------------------------------------------------------------------------------|----------------|
| Manufacturer                                                                 | HONDA          |
| Model                                                                        | VEZEL 1.5X CVT |
| Exact Purpose for which vehicle was being used at time of accident           |                |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO             |
| If No, Please state action to be taken                                       | THIRD PARTY    |
| Vehicle Category                                                             | PRIVATE CAR    |

### Insurance Company

|                           |                           |
|---------------------------|---------------------------|
| Name of Insurance Company | LIBERTY INSURANCE PTE LTD |
| Type Of Coverage          | COMPREHENSIVE             |
| Fleet Policy              | NO                        |
| Policy Number             | SD19V02278/VPE/R00        |
| Cover Note Number         |                           |

### Driver

|                      |                           |
|----------------------|---------------------------|
| Name of Driver       | NUR HAMIZAH BINTI NOORDIN |
| NRIC No              | S9007876C                 |
| Date Of Birth        | 05/03/1990                |
| Occupation           | INDOOR                    |
| Date Of Driving Pass | 22/10/2008                |
| Driving Experience   | 11 YEARS AND 0 MONTHS     |
| Gender               | FEMALE                    |
| Mobile Number        | (LOCAL) +65-92316374      |
| Fax Number           |                           |
| Contact Number       |                           |
| E-Mail Address       | NOEMAIL                   |

|                                                     |                               |
|-----------------------------------------------------|-------------------------------|
| Address                                             | BLK 310C PUNGGOL WALK #02-594 |
| Postcode                                            | 823310                        |
| Was driver an employee of the Insured's Company     | NO                            |
| If No, Relationship of the Driver with the Insured  | SPOUSE                        |
| Vehicle Registration Number of Driver's Own Vehicle | -                             |
|                                                     | -                             |
|                                                     | -                             |
| Insurance Company of Driver's Own Vehicle           | -                             |
|                                                     | -                             |
|                                                     | -                             |

#### General Information of the Accident

|                    |                          |
|--------------------|--------------------------|
| Type Of Accident   | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR                    |
| Road Surface       | DRY                      |

#### Other Information

|                                                                                             |     |
|---------------------------------------------------------------------------------------------|-----|
| Was any foreign vehicle involved in this accident?                                          | NO  |
| Number of vehicles (including own vehicle) involved in the accident                         | 2   |
| Was any body injured in the Accident?                                                       | NO  |
| Was any injured conveyed to hospital by ambulance?                                          | NO  |
| Was any other material or property damaged?                                                 | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (Including Driver)                                                     | 1   |

#### Details of Police Action

|                                           |    |
|-------------------------------------------|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

REFER ATTACHED;

#### Attachment(s)

|                                               |     |
|-----------------------------------------------|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                                     |                                       |
|-------------------------------------|---------------------------------------|
| Vehicle Registration Number         | SLR4461P                              |
| Vehicle Make/Model/Colour           | HONDA / JAZZ 1.3 CVT ABS D/AIRBAG 2WD |
| Details Of Properties               |                                       |
| Vehicle Category                    | PRIVATE CAR                           |
| Name of Driver                      |                                       |
| NRIC/Passport Number                |                                       |
| Contact Number                      |                                       |
| Address                             |                                       |
| Postcode                            |                                       |
| Insurance Company Name              |                                       |
| Nature Of Damage                    |                                       |
| No. Of Passenger (Including Driver) |                                       |

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4  
Singapore 415933  
Name: \_\_\_\_\_  
Tel: 67416697 Fax: 67492305  
Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)

# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attach

## DECLARATION

We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

IDAC KAKI BUKIT (VAC)  
23 Kaki Bukit Ave 4  
Singapore 415935  
Tel: 67416697 Fax: 67492305  
Email: yockb@singnet.com.sg

### Accident Sketch Plan

On 05.11.19 at about 16:00 hours at Cross Junction of Sims Way and Geylang Road. I was turning right with the lane 3 from Sims Way towards Geylang Road (Kallang Road) and the traffic light was green in my favour.

Suddenly I heard a loud bang and felt an impact. When I alighted I realised vehicle (B) had collided onto right hand side portion of my vehicle (A).

Vehicle (A): SMH 8938X

Vehicle (B): SLR 4461P



A small handwritten mark or signature, possibly a stylized 'P' or 'R', located below the vehicle information.

# Dynamic Autowork Pte.Ltd.

( ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 12.11.19

TO : NTUC MOTOR CLAIMS DEPTS  
VEHICLE NO : SMH8938X  
MODEL : HONDA VEZEL *Veron*  
DATE OF ACCIDENT : 05.11.19  
TIME OF ACCIDENT : 16:00HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

| S/N | DESCRIPTION                                              | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|----------------------------------------------------------|-----|-----------------|------------------|
| 1   | FRONT DOOR RH <i>Dented</i>                              | 1   | \$ 950.00       | \$ 950.00        |
| 2   | FRONT DOOR OUTER MOULDING RH <i>new</i>                  | 1   | \$ 87.00        | \$ 87.00         |
| 3   | FRONT DOOR HINGE RH <i>new</i>                           | 2   | \$ 55.00        | \$ 110.00        |
| 4   | FRONT DOOR WEATHER STRIP RH <i>cut</i>                   | 1   | \$ 127.00       | \$ 127.00        |
| 5   | FRONT DOOR GLASS CHANNEL RH <i>new</i>                   | 1   | \$ 106.00       | \$ 106.00        |
| 6   | FRONT DOOR INNER LOCK RH <i>Damaged</i>                  | 1   | \$ 262.00       | \$ 262.00        |
| 7   | FRONT DOOR LOCK CATCH RH <i>new</i>                      | 1   | \$ 27.00        | \$ 27.00         |
| 8   | FRONT DOOR INNER TRIM BOARD RH <i>Cracked</i>            | 1   | \$ 650.00       | \$ 650.00        |
| 9   | FRONT DOOR REGULATOR RH <i>new</i>                       | 1   | \$ 215.00       | \$ 215.00        |
| 10  | FRONT DOOR POWER WINDOW MOTOR RH <i>new</i>              | 1   | \$ 400.00       | \$ 400.00        |
| 11  | FRONT DOOR FRAME WEATHER STRIP RH <i>new</i>             | 1   | \$ 135.00       | \$ 135.00        |
| 12  | FRONT DOOR BLACK STICKER RH <i>New</i>                   | 1   | \$ 95.00        | \$ 95.00         |
| 13  | SIDE SKIRT RH <i>cut</i>                                 | 1   | \$ 650.00       | \$ 650.00        |
| 14  | CENTER PILLAR ( OUTER) RH <i>Dented</i>                  | 1   | \$ 975.00       | \$ 975.00        |
| 15  | REAR DOOR RH <i>Dented</i>                               | 1   | \$ 1,135.00     | \$ 1,135.00      |
| 16  | REAR DOOR SPEAKER RH <i>new</i>                          | 1   | \$ 190.00       | \$ 190.00        |
| 17  | REAR DOOR CHECKER RH <i>new</i>                          | 1   | \$ 125.00       | \$ 125.00        |
| 18  | REAR DOOR HINGE RH <i>Lower Bent</i>                     | 2   | \$ 55.00        | \$ 110.00        |
| 19  | REAR DOOR INNER LOCK RH <i>new</i>                       | 1   | \$ 285.00       | \$ 285.00        |
| 20  | REAR DOOR LOCK CATCHER RH <i>new</i>                     | 1   | \$ 25.00        | \$ 25.00         |
| 21  | REAR DOOR INNER TRIM RH <i>Cracked</i>                   | 1   | \$ 725.00       | \$ 725.00        |
| 22  | REAR DOOR WEATHER STRIP RH <i>cut</i>                    | 1   | \$ 145.00       | \$ 145.00        |
| 23  | REAR DOOR POWER WINDOW MOTOR C/W REGULATOR RH <i>new</i> | 1   | \$ 490.00       | \$ 490.00        |
| 24  | REAR DOOR FRONT RUBBER LH <i>new</i>                     | 1   | \$ 210.00       | \$ 210.00        |
| 25  | REAR DOOR OUTER STRIP RH <i>new</i>                      | 1   | \$ 110.00       | \$ 110.00        |
| 26  | REAR DOOR STICKER (BLACK) RH <i>New</i>                  | 1   | \$ 105.00       | \$ 105.00        |

TO : NTUC MOTOR CLAIMS DEPTS  
 VEHICLE NO : SMH8938X  
 MODEL : HONDA VEZEL  
 DATE OF ACCIDENT : 05.11.19  
 TIME OF ACCIDENT : 16:00HRS

|    |                                            |   |             |             |         |
|----|--------------------------------------------|---|-------------|-------------|---------|
| 27 | REAR DOOR FRAME WEATHER STRIP RH <i>NY</i> | 1 | \$ 170.00   | \$ 170.00   | +       |
| 28 | REAR FENDER ARCED GARNISH RH <i>lt</i>     | 1 | \$ 165.00   | \$ 165.00   | ✓       |
| 29 | REAR WHEEL RIM RH <i>lt</i>                | 1 | \$ 1,450.00 | \$ 1,450.00 | 560(SN) |
| 30 | REAR ABS SENSOR <i>2</i>                   | 1 | \$ 430.00   | \$ 430.00   | +       |
| 31 | REAR AXLE <i>NE</i>                        | 1 | \$ 1,670.00 | \$ 1,670.00 | +       |
| 32 | REAR SHOCK ABSORBER RH <i>NE</i>           | 1 | \$ 395.00   | \$ 395.00   | +       |
| 33 | REAR WHEEL HUP WITH BEARING RH             | 1 | \$ 435.00   | \$ 435.00   | +       |

6529  
 5223.20  
 S.N. 500

TOTAL PRICE \$ 13,159.00  
 LESS 20% \$ 2,631.80  
 SUB TOTAL PRICE \$ 10,527.20

#### SPECIAL NETT ITEMS

| S/N | DESCRIPTION                                        | QTY | UNIT S/NETT | TOTAL S/NETT         |
|-----|----------------------------------------------------|-----|-------------|----------------------|
| 1   | SIDE SKIRT CLIP RH <i>Neu</i>                      | 1   | \$ 80.00    | \$ <del>80.00</del>  |
| 2   | FRONT DOOR TRIM BOARD CLIP (SET) <i>Neu</i>        | 1   | \$ 80.00    | \$ <del>80.00</del>  |
| 3   | CENTER PILLAR ( OUTER) RH SEALANT <i>Neu</i>       | 1   | \$ 150.00   | \$ <del>150.00</del> |
| 4   | CENTER PILLAR INNER TRIM CLIP (SET) <i>Neu</i>     | 1   | \$ 50.00    | \$ 50.00             |
| 5   | REAR FENDER COWLING CLIP RH (SET) <i>Neu</i>       | 1   | \$ 80.00    | \$ 80.00             |
| 6   | REAR FENDER ARCED GARNISH CLIP RH (SET) <i>Neu</i> | 1   | \$ 50.00    | \$ <del>50.00</del>  |
| 7   | REAR DOOR INNER TRIM CLIP LH (SET) <i>Neu</i>      | 1   | \$ 80.00    | \$ <del>80.00</del>  |
| 8   | REAR WHEEL TYRE RH <i>2pc Neu</i>                  | 1   | \$ 450.00   | \$ 450.00            |
| 9   | BRAKE OIL                                          | 1   | \$ 50.00    | \$ 50.00             |

170

TOTAL \$ 1,070.00

#### CLAIM DETAILS: LABOUR AND SPRAY PAINTING

| S/N | JOB DESCRIPTION                                                           | PRICE       | ADJUSTED COST |
|-----|---------------------------------------------------------------------------|-------------|---------------|
| 1   | PANEL BEATING, REMOVING AND REPLACING PARTS                               | \$ 1,800.00 | 800           |
| 2   | SPRAY PAINTING TO AFFECTED AREA                                           | \$ 1,800.00 | 800           |
| 3   | TUFF COAT                                                                 | \$ 250.00   | 60            |
| 4   | WIRING CHECK                                                              | \$ 120.00   | 30            |
| 5   | REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR | \$ 350.00   | 100           |
| 6   | REMOVE & REFIX AUDIO SPEAKER                                              | \$ 120.00   | X             |
| 7   | TRANSFER FRONT DOOR MECHANISM                                             | \$ 80.00    | 40            |

TO : NTUC MOTOR CLAIMS DEPTS  
 VEHICLE NO : SMH8938X  
 MODEL : HONDA VEZEL  
 DATE OF ACCIDENT : 05.11.19  
 TIME OF ACCIDENT : 16:00HRS

|    |                                                                                                |           |    |
|----|------------------------------------------------------------------------------------------------|-----------|----|
| 8  | REMOVE & REINSTALL FRONT WINDOW GLASS                                                          | \$ 60.00  | 40 |
| 9  | CONDUCT WATER LEAKAGE TEST                                                                     | \$ 80.00  | x  |
| 10 | FOUR WHEEL ALIGNMENT                                                                           | \$ 120.00 | 80 |
| 11 | TRANSFER REAR DOOR MECHANISM                                                                   | \$ 80.00  | 40 |
| 12 | REMOVE & REINSTALL REAR WINDOW GLASS                                                           | \$ 60.00  | 40 |
| 13 | REMOVE AND REFIX REAR UNDERCARRIAGE                                                            | \$ 650.00 | x  |
| 14 | RESET ABS LIGHT                                                                                | \$ 350.00 | x  |
| 15 | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC. | \$ 180.00 | x  |

**TOTAL \$ 6,100.00**

2030

TOTAL PARTS COST : \$ 11,597.20  
 TOTAL LABOUR COST : \$ 6,100.00  
 TOTAL REPAIR COST : \$ 17,697.20

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.  
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

**ABBY**

SERVICE ADVISOR  
 ABBY  
 HP : 9856 4815

Adrian Ling, total: 7923.20  
 h/s 12/11/19. h/s 6.3K  
 06 Days.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19019706/Avf3n2

73 BRAS BASAH ROAD

Date: 26-11-2019

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN: AZHARI

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                        |                |            |
|--------------|------------------------|----------------|------------|
| Insured Veh. | SLR 4461P              | Veh. Inspected | SMH 8938X  |
| Policy No.   |                        | Coverage (\$)  | 0.00       |
| Claim No.    | MT/1070238-002         | Excess (\$)    | 0.00       |
| Assign From  | HAZALYSA BINTI IBRAHIM | Assign Date    | 07/11/2019 |

#### 2. Vehicle Particulars & Condition

|              |             |              |            |
|--------------|-------------|--------------|------------|
| Make & Model | HONDA VEZEL | c.c          | 1496       |
| Engine No.   | HIDDEN      | Year of Reg. | 2019       |
| Chassis No.  | RU11313744  | Colour       | BRONZE     |
| Odometer     | 26154 KM    | Steering     | IN ORDER   |
| Brakes       | IN ORDER    | Modification | SPORTS RIM |
| General      | GOOD        |              |            |

#### 3. Conditions of Tyres

|                | Size       | Make   | Balance |
|----------------|------------|--------|---------|
| R/H Front Tyre | 215/60 R16 | DUNLOP | 6 mm    |
| L/H Front Tyre | 215/60 R16 | DUNLOP | 6 mm    |
| R/H Rear Tyre  | 215/60 R16 | DUNLOP | 6 mm    |
| L/H Rear Tyre  | 215/60 R16 | DUNLOP | 6 mm    |

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  
DAMAGES SEE DETAILS.

#### 5. General Information

|                |                                                                                                |                     |                         |
|----------------|------------------------------------------------------------------------------------------------|---------------------|-------------------------|
| Accident Date  | 05/11/2019                                                                                     | Inspect Date / Time | 12/11/2019 ( 03:39 PM ) |
| Survey held at | DYNAMIC AUTOWORK PTE LTD<br>8 KAKI BUKIT AVE 4<br>#08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875 |                     |                         |

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 8938X

| Qty | Description of Parts                          | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------------------------|---------------|---------------------------|-------------------|
|     | <b>REPLACEMENT OF PARTS</b>                   |               |                           |                   |
| 1   | FRONT DOOR RH                                 | DENTED        | 950.00                    | 950.00            |
| 1   | FRONT DOOR OUTER MOULDING RH                  | NOT NECESSARY | 87.00                     | -                 |
| 2   | FRONT DOOR HINGE RH @\$55.00                  | NOT NECESSARY | 110.00                    | -                 |
| 1   | FRONT DOOR WEATHER STRIP RH                   | CUT           | 127.00                    | 127.00            |
| 1   | FRONT DOOR GLASS CHANNEL RH                   | NOT NECESSARY | 106.00                    | -                 |
| 1   | FRONT DOOR INNER LOCK RH                      | DAMAGED       | 262.00                    | 262.00            |
| 1   | FRONT DOOR LOCK CATCH RH                      | NOT NECESSARY | 27.00                     | -                 |
| 1   | FRONT DOOR INNER TRIM BOARD RH                | CRACKED       | 650.00                    | 650.00            |
| 1   | FRONT DOOR REGULATOR RH                       | NOT NECESSARY | 215.00                    | -                 |
| 1   | FRONT DOOR POWER WINDOW MOTOR RH              | NOT NECESSARY | 400.00                    | -                 |
| 1   | FRONT DOOR FRAME WEATHER STRIP RH             | NOT NECESSARY | 135.00                    | -                 |
| 1   | FRONT DOOR BLACK STICKER RH                   | NECESSARY     | 95.00                     | 95.00             |
| 1   | SIDE SKIRT RH                                 | CUT           | 650.00                    | 650.00            |
| 1   | CENTER PILLAR (OUTER) RH                      | DENTED        | 975.00                    | 975.00            |
| 1   | REAR DOOR RH                                  | DENTED        | 1,135.00                  | 1,135.00          |
| 1   | REAR DOOR SPEAKER RH                          | NOT NECESSARY | 190.00                    | -                 |
| 1   | REAR DOOR CHECKER RH                          | NOT NECESSARY | 125.00                    | -                 |
| 2   | REAR DOOR HINGE RH @\$55.00                   | LOWER BENT    | 110.00                    | 55.00             |
| 1   | REAR DOOR INNER LOCK RH                       | NOT NECESSARY | 285.00                    | -                 |
| 1   | REAR DOOR LOCK CATCHER RH                     | NOT NECESSARY | 25.00                     | -                 |
| 1   | REAR DOOR INNER TRIM RH                       | CRACKED       | 725.00                    | 725.00            |
| 1   | REAR DOOR WEATHER STRIP RH                    | CUT           | 145.00                    | 145.00            |
| 1   | REAR DOOR POWER WINDOW MOTOR C/W REGULATOR RH | DAMAGED       | 490.00                    | 490.00            |
| 1   | REAR DOOR FRONT RUBBER LH                     | NOT NECESSARY | 210.00                    | -                 |
| 1   | REAR DOOR OUTER STRIP RH                      | NOT NECESSARY | 110.00                    | -                 |
| 1   | REAR DOOR STICKER (BLACK) RH                  | NECESSARY     | 105.00                    | 105.00            |
| 1   | REAR DOOR FRAME WEATHER STRIP RH              | NOT NECESSARY | 170.00                    | -                 |
| 1   | REAR FENDER ARCED GARNISH RH                  | CUT           | 165.00                    | 165.00            |
| 1   | REAR ABS SENSOR                               | NOT NECESSARY | 430.00                    | -                 |
| 1   | REAR AXLE                                     | NOT NECESSARY | 1,670.00                  | -                 |
| 1   | REAR SHOCK ABSORBER RH                        | NOT NECESSARY | 395.00                    | -                 |
| 1   | REAR WHEEL HUP WITH BEARING RH                | NOT NECESSARY | 435.00                    | -                 |

Report Ref No. CS/INC19019706/Avf3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                                                       | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|----------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|     | LESS 20% DISCOUNT                                                          |               | -2,341.80                 | -1,305.80         |
|     |                                                                            |               | 9,367.20                  | 5,223.20          |
| 1   | REAR WHEEL RIM RH (SN)                                                     | CUT           | 1,450.00                  | 500.00            |
|     | LESS 20% DISCOUNT                                                          |               | -290.00                   | -                 |
|     |                                                                            |               | 1,160.00                  | 500.00            |
|     | <b><u>SPECIAL NETT ITEMS</u></b>                                           |               |                           |                   |
| 1   | SIDE SKIRT CLIP RH (SN)                                                    | NECESSARY     | 80.00                     | 30.00             |
| 1   | SET FRONT DOOR TRIM BOARD CLIP (SN)                                        | NECESSARY     | 80.00                     | 30.00             |
| 1   | CENTER PILLAR (OUTER) RH SEALANT (SN)                                      | NECESSARY     | 150.00                    | 60.00             |
| 1   | SET CENTER PILLAR INNER TRIM CLIP (SN)                                     | NOT NECESSARY | 50.00                     | -                 |
| 1   | SET REAR FENDER COWLING CLIP RH (SN)                                       | NOT NECESSARY | 80.00                     | -                 |
| 1   | SET REAR FENDER ARCED GARNISH CLIP RH (SN)                                 | NECESSARY     | 50.00                     | 20.00             |
| 1   | SET REAR DOOR INNER TRIM CLIP LH (SN)                                      | NECESSARY     | 80.00                     | 30.00             |
| 1   | REAR WHEEL TYRE RH (SN)                                                    | NOT NECESSARY | 450.00                    | -                 |
| 1   | BRAKE OIL (SN)                                                             | NOT NECESSARY | 50.00                     | -                 |
|     |                                                                            |               | 1,070.00                  | 170.00            |
|     | <b><u>LABOUR</u></b>                                                       |               |                           |                   |
|     | PANEL BEATING, REMOVING AND REPLACING PARTS.                               |               | 1,800.00                  | 800.00            |
|     | SPRAY PAINTING TO AFFECTED AREA.                                           |               | 1,800.00                  | 800.00            |
|     | TUFF COAT.                                                                 |               | 250.00                    | 60.00             |
|     | WIRING CHECK.                                                              |               | 120.00                    | 30.00             |
|     | REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR. |               | 350.00                    | 100.00            |
|     | REMOVE & REFIX AUDIO SPEAKER.                                              | NOT NECESSARY | 120.00                    | -                 |
|     | TRANSFER FRONT DOOR MECHANISM.                                             |               | 80.00                     | 40.00             |
|     | REMOVE & REINSTALL FRONT WINDOW GLASS.                                     |               | 60.00                     | 40.00             |
|     | CONDUCT WATER LEAKAGE TEST.                                                | NOT NECESSARY | 80.00                     | -                 |
|     | FOUR WHEEL ALIGNMENT.                                                      |               | 120.00                    | 80.00             |
|     | TRANSFER REAR DOOR MECHANISM.                                              |               | 80.00                     | 40.00             |
|     | REMOVE & REINSTALL REAR WINDOW GLASS.                                      |               | 60.00                     | 40.00             |
|     | REMOVE AND REFIX REAR UNDERCARRIAGE.                                       | NOT NECESSARY | 650.00                    | -                 |
|     | RESET ABS LIGHT.                                                           | NOT NECESSARY | 350.00                    | -                 |

Report Ref No. CS/INC19019706/Avf3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty                                                                              | Description of Parts                                                                          | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|                                                                                  | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC. | NOT NECESSARY | 180.00                    | -                 |
|                                                                                  |                                                                                               |               | 6,100.00                  | 2,030.00          |
| GRAND TOTAL                                                                      |                                                                                               |               | 17,697.20                 | 7,923.20          |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED) |                                                                                               |               |                           | 6,300.00          |

Report Ref No. CS/INC19019706/Avf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.