

ASS. REC. BY:

REF: CS/INC 19019707/A9f3 n2

Special Instruction:

SUPERVISOR: Adnan

ASSIGNMENT (Office)From (Person): HAZALYCA BINTI INBRAHIM of INC Date/Time: 7.11.19 10:00A.M

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLZ 9192R Insured: SMD 5781Xat Workshop m/s MG Solution Tel: 62431373of 23 Kaki Bukit Ave 4 #02-03BPolicy No: _____ Claim No: MT/107066-002

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A 5.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 7.11.19 10:40am Person Contacted: MS Hong H.O.D. Endorsement: _____Vehicle IN/OUT

Date/Time	Action/Instruction (☒) Estimate
	<u>SLZ 9192R - RA/ AIG 17/01/2001/13</u> <u>RCR 05/11/2019</u>
	<u>US \$7400, 10 days (Red \$14430.16, 66%)</u>

ASS. REC. BY:

REF: INC

ASSIGNMENT

From: Date: 7.11.2019

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLZ 9192R

at Workshop m/s MG Solution

at 23 Bakri Bukit Ave 4 # 02-03B

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLZ9192R Yr Regn: 2018 / May

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 2 C.C. 1496

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 25169 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MM6DL2SAAJW380481

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: 185/60R15

BS ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 07/11/19

Survey held at MG Solution 1.36

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP INC.

RECEIVED 30 JAN 2020

Date/Time, File Pass to?

1) 30/1/2020

Date/Time, File Return to?

3

Pop. Form:

Lump Sum / Fee:

☐ Preli. Report☐ Final Report

Days Of Repair: 10

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation

S + RS \$

Petrol

Other

TOTAL

250

Noted with thanks.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hazalya Binte Ibrahim [mailto:hazalya.ibrahim@income.com.sg]
Sent: Thursday, 7 November 2019 10:54 AM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 07/11/2019

Dear LKK,

Please cancel the survey.

Thank you.

5	MT/1069323-001	G888385C	RYDER AUTO PTE LTD	2 KAKI BUKIT AVE 2 #02-19 AUTOHUB @ KAKI BUKIT SINGAPOR 417921	june / 67418277	10:00-12:00					
---	----------------	----------	--------------------	--	-----------------	-------------	--	--	--	--	--

Warmest Regards

Nivitha (LKK Auto)

From: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>
Sent: Thursday, 7 November 2019 11:28 AM
To: Admin-D (LKKAuto); assignments; SUR
Cc: Hazalya Binte Ibrahim
Subject: RE: TP CASES FARMED OUT TO LKK ON 07/11/2019

Dear LKK,

Re-send with details.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 7 November 2019 10:56 AM
To: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 07/11/2019

Dear Hazalya,

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
www.income.com.sg



in with
you

At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Admin-D (LKKAuto) [<mailto:admin-d@lkkauto.com>]
Sent: Thursday, 7 November 2019 10:33 AM
To: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 07/11/2019

Dear Sir/Madam,

Thank you for your assignment.

SDB2382B, SMM5544S car not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>
Sent: Thursday, 7 November, 2019 10:08 AM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>
Subject: TP CASES FARMED OUT TO LKK ON 07/11/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Jeff Lin	MT/1069832-002	SMG282L	ADVANCE AUTO GARAGE	23 KAKI BUKIT AVE 4 #04-01 AAS KAKI BUKIT CENTRE SINGAPORE 415933	Xavier Lim / 9007 9247		SMN6759C	04/11/19	
2	Azhari	MT/1070238-002	SMH8938X	DYNAMIC AUTOWORK PTE LTD	8 KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT	Michelle / 9856 4815		SLR4461P	05/11/19	
3	Charlotte Chew	MT/1070066-002	SL29192R	MG SOLUTION PTE LTD	23 KAKI BUKIT AVENUE 4 #02-03B (SOUTH WING)	Ms Hong / 6243 1373		SMO5781X	05/11/19	
4	Quek Swee Keng	MT/1070309-001	SHC6019V	PREMIER AUTOMOTIVE SERVICES PTE LTD	23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443	MR CHUA / 65446689		FBP5293E	05/11/19	
5		MT/1069323-001	GBR8385E	RYDER AUTO PTE LTD	2 KAKI BUKIT AVE 2 #02-19-AUTOHUB @ KAKI BUKIT SINGAPOR 412921	June / 67418277	10-00-12-00	-		CANCEL THE SURVEY
6	Muhammad Airwan	MT/1062113-003	JTM5751	STAXX PTE LTD	1 KAKI BUKIT ROAD 1 #02-09 ENTERPRISE ONE SINGAPORE 415934	Chong / 6741 1480 / 9839 1819		YN7098C	11/09/19	
7	David Phua	MT/1070247-001	SKK6749X	CHEW MOTOR PTE LTD	1 KAKI BUKIT AVENUE 6 #01-11/41 AUTOBAY @ KAKI BUKIT	Sukyl Chong / 6747 9241		SLN6600M	05/11/19	

8	Charlotte Chew	MT/1069303-002	YN14D8G	CHIN MENG MOTORS	1 KAKI BUKIT AVENUE 6 #01-40/63 AUTOBAY @ KAKI BUKIT SINGAPORE 417883	QUEK KIM SENG / 67474810	10:00-12:00	GV3920B	29/10/19	
9	Azhari	MT/1068654-002	SDB2382B	SME MOTOR PTE. LTD.	1 KAKI BUKIT AVENUE 6 #02-15 AUTOBAY @ KAKI BUKIT SINGAPORE 417883	Jacob Ang / 6747 6106	10:00-12:00	SMA3816C	24/10/19	
10	Fiona Shen	MT/1069889-002	SMN55445	SME MOTOR PTE. LTD.	1 KAKI BUKIT AVENUE 6 #02-15 AUTOBAY @ KAKI BUKIT SINGAPORE 417883	Jacob Ang / 6747 6106	10:00-12:00	SLT2636E	01/11/19	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
T +65 6430 7902
www.income.com.sg

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/11/2019 12:44
Date Of Accident	05/11/2019 07:30
Exact Location Of Accident	YISHUN AVE 1 TWDS YISHUN AVE 2 B4 YISHUN AVE 8
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ9192R
Insured/Policyholder	
Name Of Registered Owner	TAN PUEY PUEY
NRIC No	S7271621C
Email Address	WYNNEFERTAN@YAHOO.COM
Mobile Phone No	(LOCAL) +65-96676872
Alternative Phone No	OTHERS-96676872

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA 2
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800068944
Cover Note Number	

Driver

Name of Driver	TAN PUEY PUEY
NRIC No	S7271621C
Date Of Birth	28/08/1972
Occupation	OUTDOOR
Date Of Driving Pass	08/09/2012
Driving Experience	7 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-96676872
Fax Number	
Contact Number	OTHERS-96676872
Email Address	WYNNEFERTAN@YAHOO.COM

Address	BLK 226A SUMANG LANE #13-214
Postcode	821226
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMD5781X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJQ9753T
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Individual Statement

SKETCH PLAN



DETAILED CIRCUMSTANCES OF THE INCIDENT

On 05/11/2019 at about 0730 hrs at along Yishun Ave 1 towards Yishun Ave 2 before Yishun Ave B. I was travelling on the extreme Right lane and when my front vehicle slow down a stop hence I follow suit and came to a complete stop. Suddenly I felt a great impact from the Rear and the impact forced my Vehicle (A) forward to hit onto the Rear Portion of Vehicle (C). When I alighted, I realised that it was Vehicle (B) who hit onto my Rear Portion of my Vehicle (A) causing damages to my Vehicle. It was a chain collision of total 3 vehicles involved.

(A) SLZ 9192 R
(B) SMD 5781 X
(C) SJQ 9753 T

Note: Please note that your insurer may have 14 days time frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check your policy for more information.

DECLARATION

We declare that the information provided is true and correct.

[Signature]
Driver's Signature

Date: 05/11/2019

Witness's Signature

[Signature]
Driver's Signature
Witness's Signature
Date: 05/11/2019

[Signature]
Victim's Signature
Date: 05/11/2019

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: NTUC INCOME	DATE	: 06/11/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLZ9192R		
MODEL	: MAZDA 2	Xima Chen.	
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 5-Nov-19
		TIME	: 07:30HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Del'd</i>	1	\$ 866.90	\$ 866.90 ✓
2	FRONT BUMPER RETAINER <i>new</i>	2	\$ 55.00	\$ 110.00 ✓
3	CENTER GRILLE <i>canb'd</i>	1	\$ 422.30	\$ 422.30 ✓
4	CENTER GRILLE LOGO <i>new</i>	1	\$ 55.00	\$ 55.00 ✓
5	CENTER GRILLE CHROME <i>new</i>	2	\$ 168.50	\$ 337.00 ✓
6	HEADLAMP (LED) <i>new</i>	2	\$ 2,393.60	\$ 4,787.20 ✓
7	BOOTLID <i>Del'd</i>	1	\$ 1,050.80	\$ 1,050.80 ✓
8	BOOTLID LOGO <i>2</i>	1	\$ 60.00	\$ 60.00 ✓
9	BOOTLID EMBLEM 'MAZDA' <i>new</i>	1	\$ 55.00	\$ 55.00 ✓
10	BOOTLID EMBLEM '2'	1	\$ 42.00	\$ 42.00 ✓
11	BOOTLID EMBLEM 'SKYACTIV'	1	\$ 70.50	\$ 70.50 ✓
12	BOOTLID TOP LOCK <i>Del'd</i>	1	\$ 286.70	\$ 286.70 ✓
13	BOOTLID ALTERNATIVE <i>new</i>	1	\$ 155.20	\$ 155.20 ✓
14	BOOTLID DAMPER <i>new</i>	2	\$ 90.80	\$ 181.60 ✓
15	BOOTLID WEATHERSTRIP <i>bt</i>	1	\$ 190.00	\$ 190.00 ✓
16	REAR BUMPER <i>Distab'd</i>	1	\$ 920.50	\$ 920.50 ✓
17	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 42.50	\$ 85.00 ✓
18	REAR BUMPER REFLRCTOR LH <i>at</i>	2	\$ 98.30	\$ 196.60 ✓
19	REAR BUMPER HOOD <i>canb'd</i>	1	\$ 80.00	\$ 80.00 ✓
20	REAR BUMPER HOLDER <i>Del'd</i>	2	\$ 95.70	\$ 191.40 ✓
21	TAILLAMP <i>canb'd</i>	2	\$ 650.50	\$ 1,301.00 ✓

9830

29.

150

22	TAILLAMP INNER PANEL <i>Regis</i>	2	\$ 320.00	\$ 640.00	+
23	REAR FENDER <i>Regis</i>	2	\$ 955.80	\$ 1,911.60	+
24	REAR FENDER INNER TRIM <i>new LH could</i>	2	\$ 420.00	\$ 840.00	+
25	REAR END PANEL <i>Dented</i>	1	\$ 450.00	\$ 450.00	-
26	REAR END PANEL SIDE <i>Regis</i>	2	\$ 211.50	\$ 423.00	+
27	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 180.00	\$ 180.00	✓
28	REAR END PANEL TOP BRACKET <i>Dented</i>	1	\$ 80.00	\$ 80.00	45
29	REAR TOOLS SIDE TRAY <i>could</i>	2	\$ 180.00	\$ 360.00	✓
30	REAR TOOLS TOP TRAY <i>could</i>	1	\$ 250.00	\$ 250.00	✓
31	REAR FLOOR PANEL <i>Regis</i>	1	\$ 955.60	\$ 955.60	+
32	REAR FLOOR PANEL TOP BOARD <i>Dented</i>	1	\$ 355.00	\$ 355.00	✓
33	REAR EXHAUST PIPE <i>?</i>	1	\$ 1,080.50	\$ 1,080.50	+
34	REAR EXHAUST MOUNTING <i>not in</i>	2	\$ 37.40	\$ 74.80	+
35	REAR EXHAUST INSULATOR	1	\$ 190.00	\$ 190.00	+

7753

620240

TOTAL PRICE \$ 19,235.20

LESS 20% \$ 3,847.04

SUB TOTAL PRICE \$ 15,388.16

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>not in</i>	1	\$ 50.00	\$ 50.00	+
2	FRONT BUMPER CLIPS (SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
3	FRONT BUMPER CENTER GRILLE CLIP (SET) <i>new</i>	1	\$ 20.00	\$ 20.00	+
4	HEADLAMP CLIPS (SET) <i>not in</i>	1	\$ 20.00	\$ 20.00	+
5	REAR NUMBER PLATE <i>not in</i>	1	\$ 50.00	\$ 50.00	+
6	REAR BUMPER CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
7	TAIL LAMP CLIP <i>new</i>	1	\$ 20.00	\$ 20.00	-
8	REAR FENDER INNER TRIM CLIPS(SET) <i>not in</i>	1	\$ 22.00	\$ 22.00	+
9	REAR END PANEL TOP GARNISH CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	10
10	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 120.00	\$ 120.00	60
11	REAR FLOOR PANEL INSULATION SEAL <i>not in</i>	1	\$ 150.00	\$ 150.00	+
12	REVERSE SENSOR <i>changed</i>	1	\$ 220.00	\$ 220.00	200

330

TOTAL \$ 732.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING & REPLACING PARTS	\$ 1,000.00	<i>200</i>	
2	SPRAY PAINTING TO AFFECTED AREAS	\$ 1,000.00	<i>200</i>	
3	TUFF COAT	\$ 150.00	<i>X</i>	

4	WIRING, BULB CHECKING	\$ 150.00	X	
---	-----------------------	-----------	---	--

TOTAL \$ 2,300.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$2,400.00	1000	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 2,000.00	1000	
3	TUFF COAT	\$ 250.00	60	
4	WIRING CHECK	\$ 150.00	30	
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 150.00	60	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50	
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 150.00	50	
8	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓	
9	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	X	
10	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 150.00	X	
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X	

TOTAL \$5,710.00 2730

ESTIMATE REPORT

TOTAL PARTS COST : \$ 16,120.16

TOTAL LABOUR COST : \$ 5,710.00

TOTAL REPAIR COST : \$ 21,830.16

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

PART BY PART / LUMP SUM :

NO OF DAYS

FAX :

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj

L/s 07/11/18.

10 Days -

total: 9262.40

L/s - 7.41K.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19019707/Aqf3n2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 30-01-2020



ATTN: CHARLOTTE CHEW

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMD 5781X	Veh. Inspected	SLZ 9192R
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1070066-002	Excess (\$)	0.00
Assign From	HAZALYSA BTE IBRAHIM	Assign Date	07/11/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 2	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MM6DL2SAAJW380481	Colour	WHITE
Odometer	25169 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	DUNLOP	6 mm
L/H Front Tyre	185/60 R15	DUNLOP	6 mm
R/H Rear Tyre	185/60 R15	DUNLOP	6 mm
L/H Rear Tyre	185/60 R15	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	05/11/2019	Inspect Date / Time	07/11/2019 (01:36 PM)
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 9192R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	866.90	866.90
2	FRONT BUMPER RETAINER @\$55.00	NECESSARY	110.00	110.00
1	CENTER GRILLE	CRACKED	422.30	422.30
1	CENTER GRILLE LOGO	NECESSARY	55.00	55.00
2	CENTER GRILLE CHROME @\$168.50	NOT NECESSARY	337.00	-
2	HEADLAMP (LED) @\$2393.60	NOT NECESSARY	4,787.20	-
1	BOOTLID	DENTED	1,050.80	1,050.80
1	BOOTLID LOGO	NECESSARY	60.00	60.00
1	BOOTLID EMBLEM "MAZDA"	NECESSARY	55.00	55.00
1	BOOTLID EMBLEM "2"	NECESSARY	42.00	42.00
1	BOOTLID EMBLEM "SKYACTIV"	NECESSARY	70.50	70.50
1	BOOTLID TOP LOCK	DAMAGED	286.70	286.70
1	BOOTLID ALTERNATIVE	NOT NECESSARY	155.20	-
2	BOOTLID DAMPER @\$90.80	NOT NECESSARY	181.60	-
1	BOOTLID WEATHERSTRIP	CUT	190.00	190.00
1	REAR BUMPER	DISTORTED	920.50	920.50
2	REAR BUMPER SIDE RETAINER @\$42.50	NECESSARY	85.00	85.00
2	REAR BUMPER REFLECTOR @\$98.30	N/S CUT	196.60	98.30
1	REAR BUMPER HOOD	CRACKED	80.00	29.00
2	REAR BUMPER HOLDER @\$95.70	DAMAGED	191.40	150.00
2	TAILLAMP @\$650.50	CRACKED	1,301.00	1,301.00
2	TAILLAMP INNER PANEL @\$320.00	TO REPAIR SEE LABOUR	640.00	-
2	REAR FENDER @\$955.80	TO REPAIR SEE LABOUR	1,911.60	-
2	REAR FENDER INNER TRIM @\$420.00	N/S CRACKED	840.00	320.00
1	REAR END PANEL	DENTED	450.00	450.00
2	REAR END PANEL SIDE @\$211.50	TO REPAIR SEE LABOUR	423.00	-
1	REAR END PANEL TOP GARNISH	DEFORMED	180.00	180.00
1	REAR END PANEL TOP BRACKET	DEFORMED	80.00	45.00
2	REAR TOOLS SIDE TRAY @\$180.00	CRACKED	360.00	360.00

Report Ref No. CS/INC19019707/Aqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TOOLS TOP TRAY	CRACKED	250.00	250.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	955.60	-
1	REAR FLOOR PANEL TOP BOARD	DEFORMED	355.00	355.00
1	REAR EXHAUST PIPE	NOT NECESSARY	1,080.50	-
2	REAR EXHAUST MOUNTING @\$37.40	NOT NECESSARY	74.80	-
1	REAR EXHAUST INSULATOR	NOT NECESSARY	190.00	-
	LESS 20% DISCOUNT		-3,847.04	-1,550.60
			15,388.16	6,202.40
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
1	SET FRONT BUMPER CENTER GRILLE CLIP (SN)	NOT NECESSARY	20.00	-
1	SET HEADLAMP CLIPS (SN)	NOT NECESSARY	20.00	-
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	20.00	20.00
1	TAIL LAMP CLIP (SN)	NECESSARY	20.00	20.00
1	SET REAR FENDER INNER TRIM CLIPS (SN)	NOT NECESSARY	22.00	-
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	20.00	10.00
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	120.00	60.00
1	REAR FLOOR PANEL INSULATION SEAL (SN)	NOT NECESSARY	150.00	-
1	REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
			732.00	330.00
	LABOUR			
	PANEL BEATING & REPLACING PARTS.		1,000.00	200.00
	SPRAY PAINTING TO AFFECTED AREAS.		1,000.00	200.00
	TUFF COAT.	NOT NECESSARY	150.00	-
	WIRING BULB.	NOT NECESSARY	150.00	-
	PANEL BEATING,REMOVING AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAILLAMP INNER PANEL,REAR FENDER,REAR END PANEL SIDE AND REAR FLOOR PANEL.		2,400.00	1,000.00
	SPRAY PAINTING TO AFFECTED AREAS.		2,000.00	1,000.00
	TUFF COAT.		250.00	60.00

Report Ref No. CS/INC19019707/Aqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING CHECK.		150.00	30.00
	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR.		150.00	60.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	50.00
	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING.		150.00	50.00
	TRANSFER TAILGATE MECHANISM.		80.00	80.00
	REMOVE AND REFIX TAILGATE WINDSCREEN.	NOT NECESSARY	120.00	-
	REMOVE AND REFIX REAR EXHAUST PIPE.	NOT NECESSARY	150.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			8,010.00	2,730.00
GRAND TOTAL			24,130.16	9,262.40

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			7,400.00
--	--	--	----------

Report Ref No. CS/INC19019707/Aqf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.