

27/03/2007

ASS. REC. BY:

Surveyor

GA

REF: CS / INC 19019709 / GLF3⁵²

Special Instruction:

ASSIGNMENT (Office)

Date/Time: 7.11.19 10.00am

From (Person): Hazalya Bakti Ibrahim of

INC

Bill to:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

No Inspect Vehicle No: JTM 5751

Insured:

YN 7098C

Tel:

67411480 / 98341819

at Workshop n/s STAXX DIE LTD

of 1. kaki Bukit Rond 1#02-09

Policy No:

Claim No: M7 / 1012113-003

Sum Insured:

Excess:

D.O.A. 11.9.2019

Make of Veh:
(Client's Record)

my

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time: 7.11.19 11.00am

Person Contacted:

Chong

Vehicle IN / OUT

Date/Time Action/Instruction (✓) Estimate

JTM 5751 - X

ASS. REC. BY:

6ul.

REF: INC

ASSIGNMENT

From:

Date: 7.11.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: JTM 5751

at Workshop m/s STAXX PTE LTD

of 1 kaki Bukit Road 1 #02-09

Insured:

Policy No. chong - 98391819

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$2000 RM 9000

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

JTM5751

Yr Regn:

2019 Jul

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha 135LC

c.c

134

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

04081

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

PMYUG0810K0/22322

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

70/90-17

R:

80/90-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

See Rubber

Front

Rear

R/Bal.

5 mm

R/Bal.

5 mm

L/Bal.

5 mm

L/Bal.

5 mm

D.O.A.

D.O.I.

07-11-19

Survey held at

w/s

4pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

and

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

07/11 Estimate Give later

20/2 Finalized \$2557.4 with chong. (Red. 438.60/14%)

RECEIVED 24 FEB 2020

20/2/2020

Date/Time, File Pass to?

☐

: Preli. Report

1) 24/2 Typist

☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

Pop. Form

Emp. Sing. /

TP 2557.40

Nivitha (LKK Auto)

From: Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>
Sent: Thursday, 7 November 2019 11:28 AM
To: Admin-D (LKKAuto); assignments; SUR
Cc: Hazalysa Binte Ibrahim
Subject: RE: TP CASES FARMED OUT TO LKK ON 07/11/2019

Dear LKK,

Re-send with details.

Thank you.

Warmest Regards

Hazalysa Bte Ibrahim
Admin Assistant
Motor Department
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 7 November 2019 10:56 AM
To: Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 07/11/2019

Dear Hazalysa,

Noted with thanks.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hazalysa Binte Ibrahim [mailto:hazalysa.ibrahim@income.com.sg]

Sent: Thursday, 7 November 2019 10:54 AM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>

Subject: RE: TP CASES FARMED OUT TO LKK ON 07/11/2019

Dear LKK,

Please cancel the survey.

Thank you.

5	MT/1069323-001	GB88385C	RYDER AUTO PTE LTD	2 KAKI BUKIT AVE 2 #02-19 AUTOHUB @ KAKI BUKIT SINGAPOR 417921	june / 67418277	10:00-12:00					
---	----------------	----------	--------------------	--	-----------------	-------------	--	--	--	--	--

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
www.income.com.sg



in with
you

At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Admin-D (LKKAuto) [<mailto:admin-d@lkkauto.com>]
Sent: Thursday, 7 November 2019 10:33 AM
To: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>; **assignments** <assignments@lkkauto.com>; **SUR** <sur@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 07/11/2019

Dear Sir/Madam,

Thank you for your assignment.

SDB2382B, SMM5544S car not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>
Sent: Thursday, 7 November, 2019 10:08 AM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; **assignments** <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>
Subject: TP CASES FARMED OUT TO LKK ON 07/11/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Jeff Lin	MT/1069832-002	SMG282L	ADVANCE AUTO GARAGE	23 KAKI BUKIT AVE 4 #04-01 AAS KAKI BUKIT CENTRE SINGAPORE 415933	Xavier Lim / 9007 9247		SMN6759C	04/11/19	
2	Azhari	MT/1070238-002	SMH8938X	DYNAMIC AUTOWORK PTE LTD	8 KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT	Michelle / 9856 4815		SLR4461P	05/11/19	
3	Charlotte Chew	MT/1070066-002	SLZ9192R	MG SOLUTION PTE LTD	23 KAKI BUKIT AVENUE 4 #02-03B (SOUTH WING)	Ms Hong / 6243 1373		SMD5781X	05/11/19	
4	Quek Swee Keng	MT/1070309-001	SHC6019Y	PREMIER AUTOMOTIVE SERVICES PTE LTD	23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443	MR CHUA / 65446689		FBP5293E	05/11/19	
5		MT/1069323-001	GBB8385C	RYDER AUTO PTE LTD	2 KAKI BUKIT AVE 2 #02-19 AUTOHUB @ KAKI BUKIT SINGAPORE 417921	June / 67418277	10:00-12:00			CANCEL THE SURVEY
6	Muhammad Airwan	MT/1062113-003	JTM5751	STAXX PTE LTD	1 KAKI BUKIT ROAD 1 #02-09 ENTERPRISE ONE SINGAPORE 415934	Chong / 6741 1480 / 9839 1819		YN7098C	11/09/19	
7	David Phua	MT/1070247-001	SKK6749X	CHEW MOTOR PTE LTD	1 KAKI BUKIT AVENUE 6 #01-11/41 AUTOBAY @ KAKI BUKIT	Sukyl Chong / 6747 9241		SLN6600M	05/11/19	

8	Charlotte Chew	MT/1069303-002	YN1408G	CHIN MENG MOTORS	1 KAKI BUKIT AVENUE 6 #01-40/63 AUTOBAY @ KAKI BUKIT SINGAPORE 417883	QUEK KIM SENG / 67474810	10:00-12:00	GV3920B	29/10/19	
9	Azhari	MT/1068654-002	SDB2382B	SME MOTOR PTE. LTD.	1 KAKI BUKIT AVENUE 6 #02-15 AUTOBAY @ KAKI BUKIT SINGAPORE 417883	Jacob Ang / 6747 6106	10:00-12:00	SMG3816C	24/10/19	
10	Fiona Shen	MT/1069889-002	SMM5544S	SME MOTOR PTE. LTD.	1 KAKI BUKIT AVENUE 6 #02-15 AUTOBAY @ KAKI BUKIT SINGAPORE 417883	Jacob Ang / 6747 6106	10:00-12:00	SLT2636E	01/11/19	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
T +65 6430 7902
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



CONFIRMATION	D02168-10000842
E-C/Note No	06 JUL 2019 05:33:04pm
Issue Date & Time	From 08 JUL 2019 To 07 JUL 2020
Period of Cover	JTM5751
Vehicle Registration No.	YAMAHA 135 LC
Make of Vehicle	G3G5E-122352
Engine No.	134.00 CC
Capacity	Classis No.
Insured Name	Year of Make
Address	RAMASANDERAN A/L CHELLADURY
NRIC/Business Reg No.	NO 55 JALAN KEMULIAAN 39 TAMAN UNIVERSITI, 81300, SKUDAI, JOHOR DARUL TAKZIM
Type of Cover	620705-01-5569
Use of Vehicle	V-CO MOTOR COMPREHENSIVE
HP Owner	MOTORCYCLE - Z-RIDER
Sum Insured (RM)	SOON LEE MOTOR AND ENTERPRISE
Transaction Type	9 000.00
All Claims Excess	New
Voluntary Excess	RM 100.00
	0.00

Voluntary Excess		0.00			
Sum Insured	(RM)	9,000.00	Premium	(RM)	246.96
All Rider (Y/N)		Y	All Rider Amt	(RM)	123.48
NCD %		0.000000 %	NCD Amt	(RM)	0.00
			Basic Net	(RM)	370.44
Tuition Load %		0 %	Tuition Load Amt	(RM)	0.00
			Extra Coverage	(RM)	0.00
SST		6.00 %	SST	(RM)	22.23
			Stamp Duty	(RM)	10.00
			Cycle PAC	(RM)	13.78
Act Premium	(RM)	62.91	Payable Premium	(RM)	416.45

Extra Benefits	Extra Sumin (RM)	Extra Premium (RM)
ALL RIDERS	0.00	0.00
Cycle PAC including premium for extra coverage wherever applicable. GST and stamp DUTY	5,500.00	13.75

Naked Diver
ALL RIDERS



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

NFTBBGMS

No. Pendaftaran	JTM5751
No. ID	620705015569
Nama Pemunya Berdaftar	RAMASANDERAN A/L CHELLADURY
Alamat	NO 55 JALAN KEMULIAAN 39 TAMAN UNIVERSITI 81300 SKUDAI JOHOR
No. Chasis/No. Enjin	PMYUG0810K0122322 / 0305E-122352
Buatan/Nama Model	YAMAHA / 135LC
Keupayaan Enjin	134
Bahan Bakar	PETROL
Status Asas	PEMASANGAN TEMPATAN
Kelas Kegunaan	MOTOSIKAL
Jenis Badan/Tahun Dibuat	MOTOSIKAL / 2019
Tarikh Pendaftaran	08/07/2019
B. D. M/B U. K/BTW	-
Syarat Pendaftaran 1	-
Syarat Pendaftaran 2	-
Syarat Pendaftaran 3	-

LESEN KENDERAAN MOTOR
MOTOSIKAL No. Sijil AS 001539
07 JUL 2020
JTM5751

003145 06072019 JTM5751 RM42.00
0801041 KUALA KUMPANG 07/07/2020 134 SP AA 2201000
SILM49
MRE1 D00185 19000442
MRE2 VEL8291



**SINGAPORE
POLICE FORCE**



T/20190930/2153

2 of 3

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

Report No. T/20190930/2153

CONTINUATION OF REPORT

Rider			
Name	RAMASANDERAN CHELLADURY	ID No.	F1062778T
Related Vehicle	JTM5751 (Motorcycle)	Contact No.	0149254082
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	11/09/2019	Date Discharge	19/09/2019
No. of Days granted Medical Leave	24	Degree of Injury	Serious

Brief Details.

On 11/09/2019 at about 1228hrs, I was riding my motorcycle bearing registration of JTM5751 along Tuas Basin Link to work.

On the same day at about 1230hrs, along Tuas Basin Link, there is a lorry with unknown registration plate travelling at the opposite direction of the road. Suddenly, the lorry turned towards me wanting to enter the company on my left. As the lorry was too close to me and there is no signals by the lorry, it hit my motorcycle from the right and I was thrown out from my motorcycle for about 02 meters. At that moment, I am very dizzy and uncomfortable, so I not sure what is happening exactly. I only can roughly remembered the ambulance and Police came and the police retrieved my work permit from my wallet. After that, I was being sent to National University Hospital. I was discharged on the 19/09/2019. The doctor gave me medication leave until 04/10/2019.

I also want to inform that no government property was damaged. My boss number is 83664563.

I have already lodged a Traffic Accident report vide T/20190919/2103. However, my motorcycle registration number was wrong. I am lodging this report as I need a new report with my correct motorcycle registration number for insurance claim purposes.



**SINGAPORE
POLICE FORCE**



T/20190930/2153

1 of 3

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

Report No T/20190930/2153

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/09/2019 16:15	File Report No.: T/20190919/2103	Station Diary No: 425
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: RAMASANDERAN CHELLADURY			Address:	
ID Type / ID No.: FIN NO / F1062778T			Contact No.: Home/Office:	Mobile: 0149254082
Nationality: MALAYSIAN			Email:	
Sex: Male	Age: 57	Date of Birth: 05/07/1962	Type of Informant: Rider	
Race: Indian			Language:	Institution / School Name
Occupation: Private security officer			Driving Licence Information: Class:	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 11/09/2019 12:30	Type of Location Straight Road
Location: TUAS BASIN LINK				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JTM5751	Motorcycle				Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL		



**SINGAPORE
POLICE FORCE**



T/20190930/2153

3 of 3

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

Report No. T/20190930/2153

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /
Sgt 2 WU JIALEI

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /
SI THABAGESH JEYATHESH
Contact No.: 65476232

Signature Of Informant:

Date/Time:

30/09/2019 16:15

Classification Of Case:

Authentication Stamp

NP165

Search for manufacturers, brand or products



POST FREE AD

Yamaha 135 LC

D/P: Rm700

4 thn Rm235 ±

Cash : RM 7,250

(otr)



135LC



Klang

RM 6,762

NEGOTIABLE PRICE

CONTACT SELLER

Brand

Yamaha

Model

135LC

Type

Motorcycle

Year

2019

Color

Other

Engine

135 Cc

Gearbox

Manual

Engine Type

Petrol

Warranty

2 Year/50

STAXX PTE LTD

1 Kakit Bukit Road 1
#02-09 Enterprise One
Singapore 415934
Email: sales@staxx.com.sg
Tel: 6741 1480

Quotation

Number:	10
Date:	12/11/2019
Ref. #:	
Terms:	
Salesperson	
Page:	1 / 3

Client

NTUC INCOME INSURANCE CO-OPERATIVE LIMIT
75 BRAS BASAH ROAD,
INCOME CENTRE

SINGAPORE

Delivery

CLAIM FOR JTM5751

Part Number	Item Details	Qty	Amount \$	Disc. %	Total \$
55DF000005P00M	LC135 BODYSET KIT	1	180.00	0.00%	180.00
55DFG000005PG	LC135 GRAPHIC SET	1	58.00	0.00%	58.00
5YPE24610000	LC135 RADIATOR ASSY	1	80.00	0.00%	80.00
5YPE2405001	LC135 FAN, ELECTRIC	1	58.00	0.00%	58.00
55DE47181000	LC135N PROTECTOR MUFFLER	1	28.00	0.00%	28.00
55DE47991000	LC135 CAP, MUFFLER SILVER	1	18.00	0.00%	18.00
55DF21100000	LC135N/55D5 REAR ARM, MT, BK	1	90.00	0.00%	90.00
4ULF21230000	SRL BUST 1, ARM RR 5B9	2	8.00	0.00%	16.00
1S8F21510000	LC135 SEAL GUARD	1	5.00	0.00%	5.00
50CF21410000	LC135/50C ARM SHAFT	1	8.00	0.00%	8.00
55CF34610000	LC135N BRACKET, HANDLE	1	18.00	0.00%	18.00
55CF331A1000	LC135/10 STAY	1	12.00	0.00%	12.00
55DF31001000	LC135 FRONT FORK COMP	1	180.00	0.00%	180.00
1S8F51680033	LC135 CAST WHEEL FR (BLACK)	1	90.00	0.00%	90.00
1S8F3168000XSET	LC135 CAST WHEEL - FS388	1	190.00	0.00%	190.00
90450101292	LC135 SPACER FR WHEEL	1	5.00	0.00%	5.00
93306300X8	6300Z/2AS BEARING(NTN)	2	35.00	0.00%	70.00
3AYF51810100	LC135 AXLE, FR WHEEL(3NA)	1	8.00	0.00%	8.00
5NTF5190RE	LC135N SPEEDO GEAR, 28D	1	20.00	0.00%	20.00
31DF582U0000	LC135 DISC PLATE FR	1	38.00	0.00%	38.00
55SF53810000	LC135N/55D AXLE WHEEL REAR	1	12.00	0.00%	12.00

Paid by:

23

Amount \$: 1,184.00

Price quoted subject to change without prior notice.

Subtotal \$: 1,184.00

STAXX PTE LTD

1 Kakit Bukit Road 1
#02-09 Enterprise One
Singapore 415934
Email: sales@staxx.com.sg
Tel: 6741 1480

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Quotation

Number: 10
Date: 11/12/2019
Ref. #:
Terms:
Salesperson
Page: 1 / 2

NTUC INCOME INSURANCE CO-OPERATIVE LIMIT
75 BRAS BASAH ROAD,
INCOME CENTRE

SINGAPORE

CLAIM FOR JTM5751

PMYUG0810K0122322

Part Number	Item Details	Qty	Amount \$	Disc %	Total \$
55DF000035P00M	LC135 BODYSET KIT / CNA	1	180.00	0.00%	180.00
55DFG00005PG	LC135 GRAPHIC SET / BT	1	58.00	0.00%	58.00
5YPE24610000	LC135 RADIATOR ASSY / BT	1	80.00	0.00%	80.00
5YPE2405001	LC135 FAN, ELECTRIC / CNA	1	58.00	0.00%	58.00
55DE47181000	LC135N PROTECTOR MUFFLER / Lt.	1	28.00	0.00%	28.00
55DE47991000	LC135 CAP, MUFFLER SILVER / Lt.	1	18.00	0.00%	18.00
55DF21100000	LC135N/55D5 REAR ARM, MT. BK / BT	1	90.00	0.00%	90.00
4ULF21230000	SRL BUST 1, ARM RR 5B9 / BT	2	8.00	0.00%	16.00
1S8F21510000	LC135 SEAL GUARD / CNA	1	5.00	0.00%	5.00
50CF21410000	LC135/50C ARM SHAFT / BT	1	8.00	0.00%	8.00
55CF34610000	LC135N BRACKET, HANDLE / BT	1	18.00	0.00%	18.00
55CF331A1000	LC135/10 STAY / BT	1	12.00	0.00%	12.00
55DF31001000	LC135 FRONT FORK COMP / CNA	1	180.00	0.00%	180.00
1S8F51680033	LC135 CAST WHEEL FR (BLACK) / CNA	1	90.00	0.00%	90.00
1S8F3169000XSET	LC135 CAST WHEEL - FS388 / CNA	1	190.00	0.00%	190.00
90450101292	LC135 SPACER FR WHEEL / CNA	1	5.00	0.00%	5.00
93306300X5	6300Z/2AS BEARING(NTN) / CNA	2	35.00	0.00%	70.00
3AYF51810100	LC135 AXLE, FR WHEEL(3NA) / CNA	1	8.00	0.00%	8.00
5NTF5190RE	LC135N SPEEDO GEAR, 28D / BT	1	20.00	0.00%	20.00
31DF582U0000	LC135 DISC PLATE FR / BT	1	38.00	0.00%	38.00
55SF53810000	LC135N/55D AXLE WHEEL REAR / BT	1	12.00	0.00%	12.00
Paid by:		23	Amount \$:		1,184.00
Price quoted subject to change without prior notice.					
Subtotal \$:					1,184.00

STAXX PTE LTD

1 Kakit Bukit Road 1
#02-09 Enterprise One
Singapore 415934
Email: sales@staxx.com.sg
Tel: 6741 1480

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Quotation

Number: 10
Date: 11/12/2019
Ref.#:
Terms:
Salesperson
Page: 2 / 2

Client

NTUC INCOME INSURANCE CO-OPERATIVE LIMIT
75 BRAS BASAH ROAD,
INCOME CENTRE

SINGAPORE

Delivery

CLAIM FOR JTM5751

Handwritten signature

Part Number	Item Details	Qty	Amount \$	Disc %	Total \$
55DF62100000	LC135 HANDLE BAR / BT	1	22.00	0.00%	22.00
55CH35590100	LC135N COVER METER / CRA	1	8.00	0.00%	8.00
2WBF6280/90	Y15 BACK MIRROR LH & RH / Cut	1	18.00	0.00%	18.00
55SF72310000	LC135N BRAKE ROD /	1	8.00	0.00%	8.00
1S8F74110000	LC135 FOOTREST 1 / Cut	1	28.00	0.00%	28.00
5LLF74130000	LC135 COVER, FOOTREST /	2	5.00	0.00%	10.00
55DF33910000	LC135 HORN PANEL / R / Cut	1	12.00	0.00%	12.00
5VWF313B0000	LC135 EMBLEM /	1	5.00	0.00%	5.00
55CF835J0000	LC135N BODY, FRONT LOWER 1 / Cut	1	10.00	0.00%	10.00
55CF835K0000	LC135N BODY, FRONT UNDER 2 /	1	10.00	0.00%	10.00
55DH33102000	LC135N/2016 SIGNAL FR/LH, 55D5 / CRA	1	38.00	0.00%	38.00
55DH33202000	LC135N/2016 FR SIGNAL RH 5D5 / 9CR	1	38.00	0.00%	38.00
55DH35102000	LC135N SPEEDOMETER ASSY(55D5) / CRA	1	90.00	0.00%	90.00
55DH431000	LC135 NEW/55D5 HEADLAMP / Dis.	1	58.00	0.00%	58.00
LABOUR	LABOUR	1	800.00	0.00%	800.00
1068					
10% : 967.2					
1367.2					
20% : 1100					
Paid by:		39	Amount \$:		2,339.00
Price quoted subject to change without prior notice.					
Subtotal \$:					2,339.00

5 Days.

P/p ~~Insurance~~ Repair

After repair photos.

Gua Qiang - 82880282

(LKK) 7/11/19.

1539 + 195

3175.60

10% : 1385.1

1734

+ 10% : 1907.4

650

2557.4

STAXX PTE LTD

1 Kakit Bukit Road 1
#02-09 Enterprise One
Singapore 415934
Email: sales@staxx.com.sg
Tel: 6741 1480

Quotation

Number:	10
Date:	12/11/2019
Ref. #:	
Terms:	
Salesperson	
Page:	2 / 3

Client

NTUC INCOME INSURANCE CO-OPERATIVE LIMIT
75 BRAS BASAH ROAD,
INCOME CENTRE

SINGAPORE

Delivery

CLAIM FOR JTM5751

Part Number	Item Details	Qty	Amount \$	Disc. %	Total \$
55DF62100000	LC135 HANDLE BAR	1	22.00	0.00%	22.00
55CH35590100	LC135N COVER METER	1	8.00	0.00%	8.00
2WBF6280/90	Y15 BACK MIRROR LH & RH	1	18.00	0.00%	18.00
55SF72310000	LC135N BRAKE ROD	1	8.00	0.00%	8.00
1S8F74110000	LC135 FOOTREST 1	1	28.00	0.00%	28.00
5LLF74130000	LC135 COVER, FOOTREST	2	5.00	0.00%	10.00
55DF33910000	LC135 HORN PANEL	1	12.00	0.00%	12.00
5VWF313B0000	LC135 EMBLEM	1	5.00	0.00%	5.00
55CF835J0000	LC135N BODY, FRONT LOWER 1	1	10.00	0.00%	10.00
55CF835K0000	LC135N BODY, FRONT UNDER 2	1	10.00	0.00%	10.00
55DH33102000	LC135N/2016 SIGNAL FR/LH, 55D5	1	38.00	0.00%	38.00
55DH33202000	LC135N/2016 FR SIGNAL RH 5D5	1	38.00	0.00%	38.00
55DH35102000	LC135N SPEEDOMETER ASSY(55D5)	1	90.00	0.00%	90.00
55DH431000	LC135 NEW/55D5 HEADLAMP	1	58.00	0.00%	58.00
LABOUR	LABOUR	1	800.00	0.00%	800.00
1S8F614500P0	COVER, HANDLEBAR UP	1	38.00	0.00%	38.00
OTHER	FRAME ALIGNMENT	1	400.00	0.00%	400.00
BKP-LC135	BASKET PLASTIC	1	28.00	0.00%	28.00
55DF83810000	WINDSCREEN	1	18.00	0.00%	18.00
1S7H3973RE	HANDLE SWITCH LH, 28D	1	38.00	0.00%	38.00
55CF836K00	PANEL, INNER 1	1	24.00	0.00%	24.00

Paid by:

45

Amount \$: 2,885.00

Price quoted subject to change without prior notice.

Subtotal \$: 2,885.00

2996

STAXX PTE LTD

1 Kakit Bukit Road 1
#02-09 Enterprise One
Singapore 415934
Email: sales@staxx.com.sg
Tel: 6741 1480

Quotation

Number:	10
Date:	12/11/2019
Ref. #:	
Terms:	
Salesperson	
Page:	3 / 3

Client

NTUC INCOME INSURANCE CO-OPERATIVE LIMIT
75 BRAS BASAH ROAD,
INCOME CENTRE

SINGAPORE

Delivery

CLAIM FOR JTM5751

Part Number	Item Details	Qty	Amount \$	Disc. %	Total \$
55CF836K00	PANEL, INNER 1 X repeat	1	24.00	0.00%	24.00 X
55CH355900P6	COVER, METER (DOM7) / Cut	1	12.00	0.00%	12.00 /
1S8F614500P0	COVER, HANDLEBAR UP X NN	1	38.00	0.00%	38.00 X
5YPH35500000	CABLE, SPEEDOMETER / BR	1	18.00	0.00%	18.00 /
5YPF62570000	CLIP / MC	1	4.00	0.00%	4.00 /
5TPH33710000	YAMAHA HORN / mis	1	15.00	0.00%	15.00 /
					195

Paid by:

51

Amount \$: 2,996.00

Price quoted subject to change without prior notice.

Subtotal \$: 2,996.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19019709/Gtf3s2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 25-02-2020



ATTN: MUHAMMAD AIRWAN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 7098C	Veh. Inspected	JTM 5751
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1062113-003	Excess (\$)	0.00
Assign From	HAZALYSA BTE IBRAHIM	Assign Date	07/11/2019

2. Vehicle Particulars & Condition

Make & Model	YAMAHA 135LC	c.c	134
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	PMYUG0810K0122322	Colour	BLUE
Odometer	04081 KM	Steering	JAMMED
Brakes	JAMMED	Modification	NIL
General	POOR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	70/90-17	VEERUBBER	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90-17	VEERUBBER	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	11/09/2019	Inspect Date / Time	07/11/2019 (04:00 PM)
Survey held at	STAXX PTE LTD - 1 KAKI BUKIT RD 1 #02-09		
Repairer	-		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JTM 5751

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	LC135 BODYSET KIT (WCP)	CRACKED	180.00	180.00
1	SET LC135 GRAPHIC (WCP)	NECESSARY	58.00	58.00
1	LC135 RADIATOR ASSY (WCP)	BENT	80.00	80.00
1	LC135 FAN.ELECTRIC (WCP)	CRACKED	58.00	58.00
1	LC135N PROTECTOR MUFFLER (WCP)	CUT	28.00	28.00
1	LC135 CAP, MUFFLER SILVER (WCP)	CUT	18.00	18.00
1	LC135N/55D5 REAR ARM, MT. BK (WCP)	BENT	90.00	90.00
2	SRL BUST 1, ARM RR 5B9 @ \$8.00 (WCP)	NECESSARY	16.00	16.00
1	LC135 SEAL GUARD (WCP)	NECESSARY	5.00	5.00
1	LC135/50C ARM SHAFT (WCP)	BENT	8.00	8.00
1	LC135N BRACKET, HANDLE (WCP)	BENT	18.00	18.00
1	LC135/10 STAY (WCP)	BENT	12.00	12.00
1	LC135 FRONT FORK COMP (WCP)	BENT	180.00	180.00
1	LC135 CAST WHEEL FR (BLACK) (WCP)	CUT	90.00	90.00
1	LC135 CAST WHEEL - FS388 (WCP)	CUT	190.00	190.00
1	LC135 SPACER FR WHEEL (WCP)	NECESSARY	5.00	5.00
2	6300Z/2AS BEARING (NTN) @ \$35.00 (WCP)	NECESSARY	70.00	70.00
1	LC135 AXLE, FR WHEEL (3NA) (WCP)	NECESSARY	8.00	8.00
1	LC135 SPEEDO GEAR, 28D (WCP)	BENT	20.00	20.00
1	LC135 DISC PLATE FR (WCP)	BENT	38.00	38.00
1	LC135/55D AXLE WHEEL REAR (WCP)	BENT	12.00	12.00
1	LC135 HANDLE BAR (WCP)	BENT	22.00	22.00
1	LC135N COVER METER (WCP)	CRACKED	8.00	8.00
1	Y15 BACK MIRROR LH & RH (WCP)	CUT	18.00	18.00
1	LC135N BRAKE ROD (WCP)	CUT	8.00	8.00
1	LC135 FOOTREST 1 (WCP)	CUT	28.00	28.00
2	LC135 COVER, FOOTREST @ \$5.00 (WCP)	CUT	10.00	10.00
1	LC135 HORN PANEL (WCP)	CUT	12.00	12.00
1	LC135 EMBLEM (WCP)	NECESSARY	5.00	5.00
1	LC135N BODY, FRONT LOWER 1 (WCP)	CUT	10.00	10.00
1	LC135N BODY, FRONT UNDER 2 (WCP)	CUT	10.00	10.00

Report Ref No. CS/INC19019709/Gtf3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LC135N/2016 SIGNAL FR/LH, 55D5 (WCP)	CRACKED	38.00	38.00
1	LC135N/2016 FR SIGNAL RH 5D5 (WCP)	SCRATCHED	38.00	38.00
1	LC135N SPEEDOMETER ASSY (55D5) (WCP)	CRACKED	90.00	90.00
1	LC135 NEW/55D5 HEADLAMP (WCP)	DISTORTED	58.00	58.00
1	COVER, HANDLEBAR UP (WCP) (ADDITIONAL)	CUT	38.00	38.00
1	BASKET PLASTIC (WCP) (ADDITIONAL)	BENT	28.00	28.00
1	WINDSCREEN (WCP) (ADDITIONAL)	CUT	18.00	18.00
1	HANDLE SWITCH LH, 28D (WCP) (ADDITIONAL)	DAMAGED	38.00	38.00
1	PANEL, INNER 1 (WCP) (ADDITIONAL)	CRACKED	24.00	24.00
1	PANEL, INNER 1 (WCP) (ADDITIONAL)	REPEATED	24.00	-
1	COVER, METER (WCP) (DOM7) (ADDITIONAL)	CUT	12.00	12.00
1	COVER, HANDLEBAR UP (WCP) (ADDITIONAL)	NOT NECESSARY	38.00	-
1	CABLE, SPEEDOMETER (WCP) (ADDITIONAL)	BROKEN	18.00	18.00
1	CLIP (WCP) (ADDITIONAL)	NECESSARY	4.00	4.00
1	YAMAHA HORN (WCP) (ADDITIONAL)	MISSING	15.00	15.00
	COST PLUS 10%		179.60	173.40
			1,975.60	1,907.40
	LABOUR			
	LABOUR.		800.00	400.00
	FRAME ALIGNMENT. (ADDITIONAL)		400.00	250.00
			1,200.00	650.00
	GRAND TOTAL		3,175.60	2,557.40
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			2,557.40

Report Ref No. CS/INC19019709/Gtf3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.