

振明摩托 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

ESTIMATE

Our Ref: EST386/19/CIS

Your Ref: To be advised

6-Nov-19

NTUC Income Insurance Co-operative Ltd

75 Bras Basah Road

Singapore 189557

Veron

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimate cost of repair to Isuzu NHR85 no: YN1408G

Date of accident: 29-10-19

Parts supply:

2 pcs Taillamps @\$252.00

2 pcs Taillamp brackets @\$186.00

LH cmlcd

LH Bent

438

372.30

504.00 252
372.00 186

876.00

Less 15%:

(131.40)

S/Nett Items

2 pcs Taillamp wiremesh @\$100.00 (S/Nett) RH Bent

1 set Rear reverse sensor (S/Nett) Dmgd

1 pc Rear reverse sensor holder base New

2 pcs Stoppers @\$60.00 (S/Nett) RH cut

1 pc Rear no. plate (S/Nett) New

1 pc Rear no. plate bracket (S/Nett) New

1 pc Rear bumper (S/Nett) Bent

2 pcs Rear bumper brackets @\$150.00 (S/Nett) Bent

1 pc Rear centre step bracket (S/Nett) Bent

1 pc Rear lock bar (S/Nett) New

1 pc Rear lock bar bracket (S/Nett) New

1 pc Rear end panel (S/Nett) Repair

1 pc Rear compartment door R/h (S/Nett) Bent

1 pc Rear compartment door sticker - Certis CISCO (S/Nett) New

1 pc Rear compartment door sticker - ANTI-HIJACK (S/Nett) New

1 pc Rear compartment door sticker - AUXILIARY POLICE (S/Nett) New

1 pc Rear R/h compartment door sticker - 60km/h (S/Nett) New

1 pc Rear R/h compartment door emblem - Tyron (S/Nett) New

200.00 100

350.00 300

200.00 +

120.00 40

35.00 +

120.00 +

350.00 ✓

300.00 ✓

80.00 60

280.00 +

60.00 +

380.00 +

650.00 ✓

100.00 ✓

100.00 ✓

100.00 ✓

10.00 ✓

60.00 +

4,239.60

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the parts as mentioned above etc.

To respray affected part.

To apply underseal.

To remove & refit rear reverse sensor

To remove & refit of wirings.

1220

800.00 600

800.00 500

60.00 40

60.00 30

30.00 ✓

S\$

5,989.60

Adrian Lij
H/S 07/11/19.

05 Days

total: 3702.30

L/S: 2950