



ESTIMATE TO REPAIR

VEHICLE NO. : SMQ 7788 X
 MAKE : TOYOTA
 MODEL : NOAH HYBIRD 1.8X CVT
 YEAR : 2019
 CHASSIS NO : ZWR800404194

SURVEYOR NAME : Kenneth LKK
 DATE OF SURVEY : 13.11.2019
 TIME OF SURVEY : 10-30 am

DATE : 5-Nov-19
 DATE OF ACCIDENT : 2-Nov-19
 THIRD PARTY REF : XE 2430 T / EQ INSURANCE

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	front bumper				\$1,587.60
1 set	front bumper clip				\$55.04
1 pc	front grille complete				\$2,604.00
1 pc	o/s headlamp				\$3,400.80
					\$7,647.44
	Less 25%				\$1,911.86
					\$5,735.58
1 pc	front number plate	S.Nett		cm	\$40.00
	To putty and spray paint.				\$500.00
	Labour charges.				\$400.00
TG-ML/-	Total				\$6,675.58
<i>Not Authorized Resurvey By painting 2 days</i> LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____					

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd