

ESTIMATE TO REPAIR

VEHICLE NO. : SMQ 7788 X MAKE : TOYOTA

MODEL : NOAH HYBIRD 1.8X CVT

YEAR : 2019

CHASSIS NO : ZWR800404194

SURVEYOR NAME 2019 DATE OF SURVEY TIME OF SURVEY

DATE : 5-Nov-19 **DATE OF ACCIDENT: 2-Nov-19**

THIRD PARTY REF : XE 2430 T / EQ INSURANCE

No.	Parts Description/ Labour	Туре	Unit Price	Nett Item Amt	Amount
1 pc 1 set 1 pc 1 pc	front bumper front bumper clip front grille complete o/s headlamp		cut	R svc \$3,001.75	\$3,400.80 \$7,647.44
1 pc	front number plate	S.Nett			\$1,911.86 \$5,735.58 cm \$40.00
	To putty and spray paint.				\$500.00 \$400.00
	Labour charges.				
TG-ML/-	Total				\$6,675.58
	Resony B	B Grain,			
			To res To dis Parts Third; No ille	uto Consultants he pairer of the follow urvey before/after spray blay damaged part(s) du prices are subject to con arty survey is on a "Witt gal modification(s) is allowed to final approval from ect to final approval from	ng: painting ting resurvey irmation out Prejudice" basis wed
			Acknowle Signature Date:	edged by Repairer :	

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg

Website: www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd