

ASS. REC. BY:

REF: 09/CTI/19019738/Ktd302 Special Instruction:Surveyor: KennethASSIGNMENT (Office)From (Person): Tung Hock Lye of CTI Date/Time: 6/11/2019 6:17pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: WC 7631U Insured: WC 6440Kat Workshop m/s AE Auto Tel: 9382 5367of 160 Sin Ming Drive #06-01Policy No: DMLVSN1A00000361900 Claim No: SNM19D205252

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 5/11/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 9:50am 7/11/19 Person Contacted: Ryan Vehicle IN / OUT

Date/Time	Action/Instruction
	<u>Johnnie ✓</u>
	<u>WC 7631U - X</u>
	<u>WC 6440K - X</u>
	<u>lump sum \$19,500 - (Red: 16083.44, 45%)</u>

REF: CTI

ASS. REQ. BY:

Kenneth

ASSIGNMENT

From: _____ Date: 7/11/2019

Veh No: WC 76314 Yr Regn: 06/14

Estimated Cost: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or Concrete Mixer
Make: Iruu CYH52S C.C. 15681

To Inspect Vehicle No: WC 76314

Colour Multi Colour A/C: Insured / Std / NI / NA

at Workshop m/s AE Auto
of 160 Sin Ming Drive # 06-01

Sp. Reading 219173 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No. _____

C/No: JALCYH52SE7000010

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: _____

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: Fransway 295/80R22-5

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

R: Golden Crown
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI
TOYO / YOKO or Hito

Bal. or Market Value: _____

Front

IDAC Accident Rpt: _____ Consistent?: Yes or No

R/Bal. 6 mm

GIA / PR Seen: _____ Consistent?: Yes or No

L/Bal. 6 mm

Est. Repairs: 07 days Res.: Yes or No

D.O.A. 5/11/19

Lum Sum: 20 % 3 Val.: Yes or No

Survey held at

CA / REV / REP. / 24 HRS ^{up}

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

O/S Br

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	EM NOT ready, no key.

Date/Time, File Pass to? : Prel. Report

Days Of Repair: 7

1) 5/12 Typist : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to? _____

Add Fee: : Site Insp (\$)

Survey Fee:	<u>220</u>
Transportation:	
S + FS ST	
Photos:	
Other:	
TOTAL	<u>220</u>

Report Format: TP

: Interview (\$)

Lum 0 / L.B.I. 19,500/-

: Tech. Insp (\$)

: Weekend (\$)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/11/2019 11:29
Date Of Accident	05/11/2019 19:15
Exact Location Of Accident	MARINA GROVE - (CONCRETE PLANT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	WC7631U
Insured/Policyholder	
Name Of Registered Owner	V.S BUILDERS AND ENGINEERING PTE. LTD.
Co Reg No	201204048N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91410372
Vehicle Particulars	
Manufacturer	ISUZU
Model	CYH52S-15.7 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5095698575-01
Cover Note Number	
Driver	
Name of Driver	CHINNASAMY POOMINATHAN
Passport No/FIN	G8114070M
Date Of Birth	14/06/1982
Occupation	OUTDOOR
Date Of Driving Pass	06/02/2018
Driving Experience	1 YEAR AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91410372
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	14A CUFF ROAD
Postcode	209725
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - EMPLOYEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WC6440K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repeal policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: **06 NOV 2019**
NRIC/FIN No.:

SKETCH PLAN



My vehicle stationary, In Wash bay, I was standing at the back of my vehicle waiting. (WC 76314)

Vehicle WC 6440K on my right hit onto my vehicle.

at the time of accident no one in vehicle WC 76314 was Injurd.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: 06 NOV 2019
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 048N

Vehicle Details

Vehicle No.: WC7631U
Vehicle to be Exported: Yes
Intended Deregistration Date: 06 Nov 2019
Vehicle Make: ISUZU
Vehicle Model: CYH52S
Primary Colour: Blue
Manufacturing Year: 2013
Engine No.: 6WG1420128
Chassis No.: JALCYH52SE7000010
Maximum Power Output: -
Open Market Value: \$121,678.00
Original Registration Date: 17 Jun 2014
First Registration Date: 17 Jun 2014
Transfer Count: 0
Actual ARF Paid: \$6,084.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 16 Jun 2024
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
QP Paid: \$40,889.00
COE Rebate Amount: \$18,854.00
Total Rebate Amount: \$18,854.00

The information contained herein is correct as at 06 Nov 2019

OK

MT

Not Worked
U/Lamp @ 19500
Running After Paint

AE AUTO PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-01
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

today

Date : 06/11/2019

QUOTATION -THIRD PARTY CLAIM

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Attn: Motor Claim Department . Officer In Charge

Claim : Third Party Claim
Veh. No : WC 7631 U
Model : ISUZU CHY52S
Insured Ins: NTUC INCOME

Accident on : 05/11/2019

QTY	PARTICULARS	AMOUNT	SURVEYOR
	Your Insurer Vehicle No : WC 6440 K		
1	FRONT RH DOOR <i>Ry</i>	\$ 3,800.00	✓
1	FRONT RH DOOR PILLAR <i>Ry</i>	\$ 1,850.00	✓
1	FRONT RH DOOR PILLAR RUBBER <i>In Car</i>	\$ 280.00	50% X
1	FRONT RH DOOR WEATHERSTRIP <i>Car</i>	\$ 385.60	50% In 198.80
1	FRONT RH DOOR SIDE MOULDING <i>D11</i>	\$ 280.00	✓
1	FRONT RH DOOR TOP OUTER GARNISH <i>D11</i>	\$ 680.00	✓
	FRONT RH DOOR LOWER GARNISH INNER <i>Ry</i>	\$ 588.45	✓
1	FRONT RH DOOR LOWER OUTER GARNISH <i>R11</i>	\$ 1,211.00	✓
1	FRONT RH DOOR LAMP <i>R2</i>	\$ 298.50	✓
1	FRONT RH SIDE MIRROR <i>R2</i>	\$ 780.00	✓
1	FRONT RH SIDE MIRROR STAND	\$ <i>R2</i> 1,685.00	✓
1	FRONT RH SIDE MIRROR STAND LOWER COVER	\$ <i>In</i> 220.00	X
1	FRONT W/SCREEN RUBBER ASSY	\$ <i>Car</i> 980.00	50% In 490.00
1	FRONT RH W/SCREEN <i>In</i>	\$ 3,200.00	X
1	FRONT RH W/SCREEN SIDE PILLAR <i>Ry</i>	\$ 1,650.00	✓
1	FRONT RH CORNER PANEL <i>Ry</i>	\$ 1,128.00	✓
1	FRONT RH DOOR REAR DOOR PILLAR	REPAIR	
1	FRONT RH DUST COVER	\$ <i>In</i> 380.00	X
1	FRONT BUMPER <i>Ry</i>	\$ 3,285.60	✓
1	FRONT BUMPER BRACKET RH	\$ <i>Ry</i> 480.00	✓
1	FRONT BUMPER RH LOWER BRACKET	\$ <i>Ry</i> 280.00	
1	FRONT BUMPER RH LOWER PANEL <i>R11</i>	\$ 480.50	X
1	FRONT BUMPER TOP SIDE PAD RH	\$ <i>M11</i> 228.00	✓
1	FRONT BUMPER TOP CENTER GARNISH	\$ <i>Ry</i> 588.00	✓
1	FRONT RH DOOR LOWER GARNISH	\$ <i>In</i> 680.00	X
1	FRONT RH LAMP SOCKET WIRING ASSY	\$ <i>R</i> 850.90	X
1	HEADLAMP RH <i>B20</i>	\$ 980.65	✓
1	HEADLAMP HOLDER BRACKET RH <i>M11</i>	\$ 825.00	✓
1	HEADLAMP LOWER BRACKET RH <i>M11</i>	\$ 280.00	✓
1	HEADLAMP OUTER RIM RH <i>M11</i>	\$ 652.40	✓
1	FRONT SIGNAL LAMP RH <i>B20</i>	\$ 840.00	✓
1	FRONT BUMPER LAMP RH <i>CMF</i>	\$ 415.00	✓
1	FRONT RH STEP HOUSING TOP <i>Ry</i>	\$ 1,220.00	✓
1	FRONT RH STEP PANEL TOP	\$ <i>Ry</i> 850.00	✓
1	FRONT RH STEP PANEL TOP LAMP	\$ <i>CMF</i> 280.00	✓
1	FRONT RH STEP PANEL CENTER RUBBER STRIP <i>T1</i>	\$ 280.00	✓
1	FRONT RH STEP PANEL LOWER <i>Ry</i>	\$ 850.00	✓
1	FRONT STEP PANEL SUPPORT RH <i>Ry</i>	\$ 1,128.50	✓
2	FRONT STEP PANEL SUPPORT BRACKET RH <i>R11</i>	\$ 380.00	✓
	TOTAL :	\$ 35,251.10	

108

AE AUTO PTE LTD
 160, Sin Ming Drive
 Sin Ming Auto City #06-01
 Singapore 575722
 Tel: 64535654, 64591630
 Fax: 64591698

		LESS 15%	\$ 29,963.44	
	S/NETT :			
4 T	FRONT W/SCREEN SEALANT	<i>na</i>	\$ 320.00	X
1	1054 DOOR NUMBER	<i>na</i>	\$ 200.00	<i>301n</i>
	TOTAL S/NETT :		\$ 520.00	
	TOTAL PARTS :		\$ 30,483.44	
	Balance b/f		\$ 30,483.44	
	LABOUR CHARGES			
	Labour charges to do cutting, welding , align, adjust, repair replace on damage affected area		\$ 2,000.00	<i>1200l</i>
	To replace front w/screen		\$ 500.00	<i>150l</i>
	To transfer front RH door parts to another door		\$ 200.00	<i>80l</i>
	To do wiring , checkjng replace tear wire, forcus headlamp, replace all damage wire socket assy		\$ 300.00	<i>100l</i>
	To do anti rust		\$ 200.00	<i>90l</i>
	To do sealant, seal gap, waterproofing on cutting welding affected area		\$ 400.00	<i>30l</i>
	To do spray painting on affected area		\$ 1,500.00	<i>1000l</i>
	LABOUR CHARGES		\$ 5,100.00	
	Grand Total Parts & Labour :		\$ 35,583.44	

37345 99

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Nivitha (LKK Auto)

From: Tang Hock Lye <hocklye.tang@sg.cntaiping.com>
Sent: Wednesday, 6 November 2019 6:17 PM
To: assignments@lkkauto.com
Subject: FW: OUR REF: SNM19D205252-WC6440K-CML- PRE REPAIR SURVEY FOR WC 7631U; New Assignment

Importance: High

Dear LKK

We refer to above matter.

Please assist to arrange for PRS survey of TP vehicle WC 7631U.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Autoexcel Engineering <aeexcel@singnet.com.sg>
Sent: Wednesday, November 6, 2019 5:04 PM
To: Tang Hock Lye <hocklye.tang@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Jeffrey Tay <Jeffrey.Tay@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D205252-WC6440K-CML- PRE REPAIR SURVEY FOR WC 7631U
Importance: High

Dear Sir,

We wish to appoint HENRY NG.

Thank you

Best Regards
Ryan Soh

From: Tang Hock Lye <hocklye.tang@sg.cntaiping.com>
Sent: Wednesday, November 6, 2019 5:00 PM
To: aeexcel@singnet.com.sg
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Jeffrey Tay <Jeffrey.Tay@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D205252-WC6440K-CML- PRE REPAIR SURVEY FOR WC 7631U

WITHOUT PREJUDICE

Hi Ryan

We refer to your email of 06.11.19.

We would like to conduct pre-repair survey of the vehicle at the appointed workshop.

We propose the following list of surveyors to be nominated as the Single Joint Expert to conduct survey of the claimant's vehicle:-

1. ADRIAN LING	6. KENNETH KONG
2. Kelvin Ang	7. SIMON HO
3. SEE CHEW SENG	8. CHUA WEIJIE
4. MOHD FADHILAH BIN OSMAN	9. MARCUS CHUA
5. XING QUO QIANG	10. HENRY NG

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

As per the NIMA Protocol, the survey by our appointed surveyor would include survey of your vehicle pre-repair, after it is dismantled, and post repairs. Hence, you need to provide us / our surveyors with the list of items that were damaged and required to be replaced or repaired to facilitate an effective survey.

As stated above, please inform us and our surveyor after the claimant's vehicle had been repaired so that our surveyor can carry out post repair inspection before the vehicle is returned to your client. Please co-ordinate with our surveyor immediately after the repair is completed.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Wednesday, November 6, 2019 4:33 PM

To: Tang Hock Lye <hocklye.tang@sg.cntaiping.com>; Jeffrey Tay <Jeffrey.Tay@sg.cntaiping.com>; aeexcel@singnet.com.sg

Subject: OUR REF: SNM19D205252-WC6440K-CML- PRE REPAIR SURVEY FOR WC 7631U

Importance: High

Dear Ben,

Please conduct PRS WC7631U.

Note : officer in charge – Ben Tang 63896175.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Autoexcel Engineering [<mailto:aeexcel@singnet.com.sg>]

Sent: Wednesday, 6 November, 2019 1:30 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: PRE REPAIR SURVEY FOR WC 7631U

Importance: High

Dear Officer,

Please help us arrange for pre repair survey.

Our vehicle – WC 7631U

Accident date – 05/11/2019

Your insure – WC 6440K

Location – AE AUTO PTE LTD

160 SIN MING DRIVE # 06-01

SIN MING AUTOCITY (S) 575722

Please also let us have the list of surveyor to appoint.

Thank you

Regards
Ryan Soh
93825367

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 048N

Vehicle Details

Vehicle No.: WC7631U
Vehicle to be Exported: Yes
Intended Deregistration Date: 06 Nov 2019
Vehicle Make: ISUZU
Vehicle Model: CYH52S
Primary Colour: Blue
Manufacturing Year: 2013
Engine No.: 6WG1420128
Chassis No.: JALCYH52SE7000010
Maximum Power Output: -
Open Market Value: \$121,678.00
Original Registration Date: 17 Jun 2014
First Registration Date: 17 Jun 2014
Transfer Count: 0
Actual ARF Paid: \$6,084.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 16 Jun 2024
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
QP Paid: \$40,889.00
COE Rebate Amount: \$18,854.00
Total Rebate Amount: \$18,854.00

The information contained herein is correct as at 06 Nov 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Dec 2019		11 Dec 2019 15:58 Edit Adj Rpt	S\$19,500.00 Edit Estimates	S\$19,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	-, Co. Reg. No.: -		
Main Claimant:	V.S BUILDERS AND ENGINEERING PTE. LTD., Co. Reg. No.: 201204048N		
Vehicle Reg. No.:	WC7631U	Date of Loss:	05/11/2019 19:00 - :59 [64 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D205252C02	Policy/Cover Note No.:	DMCVSNA00000361900
Vehicle Reg. No. (Insured):	WC6440K	Policy No. (Claimant):	5095698575-01
		Excess:	S\$0.00
Repairer:	Ae Auto Pte Ltd (HQ) 160 Sin Ming Drive,#06-01, Sin Ming AutoCity, 575722 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 20/12/2019]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

*WC7631U (SNM19D205252C02)
 [WC6440K]
 TP
V.S BUILDERS AND ENGINEERING PTE. LTD.
 Nov 5 2019 7:00PM
 [-]
 Ae Auto Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View View in Browser	
Assessment Reports						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)		Thumbnail	Print		
1	06/11/19 11:39	Accident Statement		 Load HTM	<input type="checkbox"/>		
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)		Thumbnail	Print		
1	06/11/19 11:38	Accident Photo <small>[Linked Accident Report Documents]</small>		 Load JPG	<input checked="" type="checkbox"/>		
2	06/11/19 11:38	Accident Photo <small>[Linked Accident Report Documents]</small>		 Load JPG	<input checked="" type="checkbox"/>		
3	06/11/19 11:38	Accident Photo <small>[Linked Accident Report Documents]</small>		 Load JPG	<input checked="" type="checkbox"/>		
4	06/11/19 11:38	Accident Photo <small>[Linked Accident Report Documents]</small>		 Load JPG	<input checked="" type="checkbox"/>		
5	06/11/19 11:38	Accident Photo <small>[Linked Accident Report Documents]</small>		 Load JPG	<input checked="" type="checkbox"/>		
6	06/11/19 11:38	Accident Photo <small>[Linked Accident Report Documents]</small>		 Load JPG	<input checked="" type="checkbox"/>		
7	06/11/19 11:38	Accident Photo <small>[Linked Accident Report Documents]</small>		 Load JPG	<input checked="" type="checkbox"/>		
8	06/11/19 11:38	Accident Photo <small>[Linked Accident Report Documents]</small>		 Load JPG	<input checked="" type="checkbox"/>		
9	06/11/19 11:38	Accident Photo <small>[Linked Accident Report Documents]</small>		 Load JPG	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
2	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
3	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
4	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
5	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
6	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
7	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
8	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
9	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
10	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
11	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
12	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
13	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
14	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
15	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
16	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
17	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
18	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
19	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
20	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
21	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
22	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
23	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
24	11/12/19 16:04	General View		 Load JPG	<input checked="" type="checkbox"/>		
25	11/12/19 16:04	General View		Load JPG	<input checked="" type="checkbox"/>		
26	11/12/19 16:04	General View		Load JPG	<input checked="" type="checkbox"/>		
27	11/12/19 16:04	General View		Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
28	11/12/19 16:04	General View	Load JPG	<input checked="" type="checkbox"/>
29	11/12/19 16:04	General View	Load JPG	<input checked="" type="checkbox"/>
30	11/12/19 16:04	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)	Thumbnail	Print
1	06/11/19 11:38	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	06/11/19 11:38	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)	Thumbnail	Print
1	06/11/19 11:39	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)	Thumbnail	Print
1	06/11/19 11:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	06/11/19 11:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	06/11/19 11:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	06/11/19 11:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	06/11/19 11:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	06/11/19 11:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	06/11/19 11:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	06/11/19 11:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	06/11/19 11:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)	Thumbnail	Print
1	06/11/19 11:38	Sketch Plan	Load TIF	
2	06/11/19 11:38	Sketch Plan #2	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19019738/KTD3E2

Date: 17/12/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00000361900
Claimant Vehicle No :	WC7631U	Insured Vehicle No :	WC6440K
Date of Loss:	05/11/2019	Nature of Claim:	TP
		Claim No:	SNM19D205252C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	WC7631U	Engine No:	6WG1420128
Make & Model:	ISUZU CYH52S, 15.7 D (M)	Chassis No:	JALCYH52SE7000010
Reg. Date:	17/06/2014 (Man. Year: 2013)	Odometer:	219173 km
Colour:	Multi-colour		
Engine Capacity:	15681 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5 (D)	Rear Tyre Size:	295/80 R22.5 (D/D)
Front Left Side:	FRONWAY 6/6 mm	Rear Left Side:	Golden Crown 8/8/6/6 mm
Front Right Side:	FRONWAY 6/6 mm	Rear Right Side:	Golden Crown 8/8/6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,245.99	25,727.49	6,518.50	20.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	2,650.00	2,450.00	48.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,345.99	28,377.49	8,968.50	24.01
Approved Total (Overridden) (S\$)		19,500.00		
Nett Amount (S\$)	37,345.99	19,500.00	17,845.99	47.79

INSPECTION

Date of Assignment:	11/12/2019	
Date Inspected:	07/11/2019 Inspected At:	Ae Auto Pte Ltd (HQ) 160 Sin Ming Drive,#06-01, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	7.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 17 Dec 2019)	
Parts:	N/A	ISUZU CYH52S 15.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for WC7631U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT RH DOOR	Bent	3,800.00 FL	*3,800.00 FL
2	1	*FRONT RH DOOR PILLAR	Bent	1,850.00 FL	*1,850.00 FL
3	1	*FRONT RH DOOR PILLAR RUBBER	Serviceable	280.00 FL	*- FL
4	1	*FRONT RH DOOR WEATHERSTRIP (\$385.60)(50%)	Cut	347.04 FS	*192.80 FS
5	1	*FRONT RH DOOR SIDE MOULDING	Distorted	280.00 FL	*280.00 FL
6	1	*FRONT RH DOOR TOP OUTER GARNISH	Distorted	680.00 FL	*680.00 FL
7	1	*FRONT RH DOOR LOWER GARNISH INNER	Bent	588.45 FL	*588.45 FL
8	1	*FRONT RH DOOR LOWER OUTER GARNISH	Missing	1,211.00 FL	*1,211.00 FL
9	1	*FRONT RH DOOR LAMP	Broken	298.50 FL	*298.50 FL
10	1	*FRONT RH SIDE MIRROR	Dented	780.00 FL	*780.00 FL
11	1	*FRONT RH SIDE MIRROR STAND	Bent	1,685.00 FL	*1,685.00 FL
12	1	*FRONT RH SIDE MIRROR STAND LOWER COVER	Serviceable	220.00 FL	*- FL
13	1	*FRONT W/SCREEN RUBBER ASSY (\$980.00)(50%)	Cut	882.00 FS	*490.00 FS
14	1	*FRONT RH W/SCREEN	Serviceable	3,200.00 FL	*- FL
15	1	*FRONT RH W/SCREEN SIDE PILLAR	Bent	1,650.00 FL	*1,650.00 FL
16	1	*FRONT RH CORNER PANEL	Bent	1,128.00 FL	*1,128.00 FL
17	1	*FRONT RH DOOR REAR DOOR PILLAR (NPA)	Repair	0.00 FL	*- FL
18	1	*FRONT RH DUST COVER	Serviceable	380.00 FL	*- FL
19	1	*FRONT BUMPER	Bent	3,285.60 FL	*3,285.60 FL
20	1	*FRONT BUMPER BRACKET RH	Bent	480.00 FL	*480.00 FL
21	1	*FRONT BUMPER RH LOWER BRACKET	Bent	280.00 FL	*280.00 FL
22	1	*FRONT BUMPER RH LOWER PANEL	No such part	480.50 FL	*- FL
23	1	*FRONT BUMPER TOP SIDE PAD RH	Missing	228.00 FL	*228.00 FL
24	1	*FRONT BUMPER TOP CENTER GARNISH	Bent	588.00 FL	*588.00 FL
25	1	*FRONT RH DOOR LOWER GARNISH	Serviceable	680.00 FL	*- FL
26	1	*FRONT RH LAMP SOCKET WIRING ASSY	Repair	850.90 FL	*- FL
27	1	*HEADLAMP RH	Broken	980.65 FL	*980.65 FL
28	1	*HEADLAMP HOLDER BRACKET RH	Missing	825.00 FL	*825.00 FL
29	1	*HEADLAMP LOWER BRACKET RH	Missing	280.00 FL	*280.00 FL
30	1	*HEADLAMP OUTER RIM RH	Missing	652.40 FL	*652.40 FL
31	1	*FRONT SIGNAL LAMP RH	Broken	840.00 FL	*840.00 FL
32	1	*FRONT BUMPER LAMP RH	Cracked	415.00 FL	*415.00 FL
33	1	*FRONT RH STEP HOUSING TOP	Bent	1,220.00 FL	*1,220.00 FL
34	1	*FRONT RH STEP PANEL TOP	Bent	850.00 FL	*850.00 FL
35	1	*FRONT RH STEP PANEL TOP LAMP	Cracked	280.00 FL	*280.00 FL
36	1	*FRONT RH STEP PANEL CENTER RUBBER STRIP	Torn	280.00 FL	*280.00 FL
37	1	*FRONT RH STEP PANEL LOWER	Bent	850.00 FL	*850.00 FL
38	1	*FRONT STEP PANEL SUPPORT RH	Bent	1,128.50 FL	*1,128.50 FL
39	2	*FRONT STEP PANEL SUPPORT BRACKET RH	Distorted	380.00 FL	*380.00 FL
40	4	*T FRONT W/SCREEN SEALANT	Not Necessary	320.00 FS	*- FS
41	1	*1054 DOOR NUMBER	Necessary	200.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 35,634.54 28,506.90

- List Item Discount on L Items 10.00/10.00% (\$\$) 3,388.55 2,779.41

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (S\$)	32,245.99	25,727.49

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO DO CUTTING, WELDING, ALIGN, ADJUST, REPAIR REPLACE ON DAMAGE AFFECTED AREA	New	2,000.00	1,200.00
2	TO REPLACE FRONT W/SCREEN	New	500.00	150.00
3	TO TRANSFER FRONT RH DOOR PARTS TO ANOTHER DOOR	New	200.00	80.00
4	TO DO WIRING, CHECKING REPLACE TEAR WIRE, FORCUS HEADLAMP, REPLACE ALL DAMAGE WIRE SOCKET ASSY	New	300.00	100.00
5	TO DO ANTI RUST	New	200.00	90.00
6	TO DO SEALANT, SEAL GAP, WATERPROOFING ON CUTTING WELDING AFFECTED AREA	New	400.00	30.00
7	TO DO SPRAY PAINTING ON AFFECTED AREA	New	1,500.00	1,000.00
Gross Labour Cost (S\$)			5,100.00	2,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >