



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

ESTIMATE

NO : QUOT201911-000013(00)

DATE : 06/11/2019

POLICY NO : 999995580

VEH REG NO : GBH5171R

MAKE/MODEL : MERCEDES BENZ VITO 114
CDI PANEL VAN LONG AT ABS
5DR

CHASSIS NO : WDF44760323334100

ENGINE NO : 65195034196832

REG. DATE : 2017

YOUR REF NO :

CLAIM TYPE : THIRD PARTY

TP INS. CO. : LONPAC INSURANCE BHD

ACCIDENT DATE : 01/11/2019

TP VEH REG NO : YN9515C

Not Notarise
Recovery After Party
4 days

Estimate Repair Cost to Vehicle No : GBH5171R

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Taillamp assy - RH	1	733.00 <i>CM</i>	733.00 ✓
2 Taillamp lower garnish - RH	1	140.00 <i>CM</i>	140.00 ✓
3 Rear bumper	1 <i>Red/Gn</i>	1,240.00	1,240.00 ✓
4 Rear bumper clips	15	9.00 <i>ma</i>	135.00 ✓
			2,248.00
		Less 10%	224.80
			2,023.20
SPECIAL NET			
5 Rear bumper sensor (set)	1	380.00 <i>Per</i>	380.00 X
			380.00
LABOUR			
6 To remove and refix rear bumper sensor	1	100.00	100.00 <i>500</i>
7 To check and rectify wiring system	1	80.00	80.00 <i>200</i>
8 To panel beat and straighten RH rear fender, RH taillamp panel, RH rear chassis frame including replacement of parts and align where necessary, to refit and adjust the same	1	800.00	800.00 <i>500</i>
9 To putty and spray same on affected areas	1	800.00	800.00 <i>400</i>
10 To supply and paste logos/letterings on RH rear fender	1 <i>(Bill)</i>	680.00	680.00 ?
			2,460.00
		TOTAL	S\$ 4,863.20
		ADD GST @ 7%	340.42
		GRAND TOTAL	S\$ 5,203.62

SINGAPORE DOLLAR FIVE THOUSAND TWO HUNDRED THREE AND CENTS SIXTY-TWO ONLY

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE