

AERO GARAGE PTE LTD

Blk 160, Sin Ming Drive, #08-07 Sin Ming AutoCity, Singapore 575722
Tel : 6266 9511 Fax : 6266 9512

Vehicle No : SMM8162R
Vehicle Model : Toyota Voxy

Estimate Repair Cost

No.	Qty	Parts List Items
1	1	Rear bumper 770.40
2	2	Rear bumper retainers
3	2	Rear bumper brackets
4	2	Rear bumper reflectors
5	2	Rear bumper tow cover
6	1 set	Rear bumper clips
7	1	Rear tailgate
8	1	Rear tailgate centre logo
9	1	Rear tailgate outer chrome handle
10	1	Rear tailgate lock 561.25
11	2	Rear tailgate hinges
12	2	Rear tailgate dampers
13	2	Rear tailgate weatherstrip
14	1	Rear tailgate number plate lamp
15	1	Rear tailgate inner top garnish
16	2	Rear tailgate inner side garnishes
17	1	Rear tailgate inner trim board
18	2	Tail lamps
19	2	Rear fender inner side trims @ 681.10
20	1	Rear end panel 781.10
21	1	Rear end panel top garnish 235
22	1	Rear spare tyre compartment
23	1	Rear spare tyre top board 540
24	1	Rear exhaust silencer
25	1	Rear exhaust silencer mounting

Not Authorised
L1 Smg @ 8350/h
Running After Pain
11 days

Bro \$	891.60	✓
Dit \$	95.60	✓
\$ R	98.90	✓
\$ M	92.90	✓
\$ M	48.90	✓
\$ M	40.00	✓
R \$	1,561.90	✓
R	68.90	✓
Warp \$	769.50	✓
R1/1m	771.80	✓
\$ R	129.60	X
\$ R	419.50	X
Od/1m	471.60	✓
\$ R	98.70	X
\$ R	652.90	X
\$ M	783.60	✓
Bur \$	619.60	✓
\$ R	1,973.80	X
Bur \$	1,979.80	✓
\$ R	918.00	✓
Dit Ind.	352.90	✓
\$ R	1,211.90	✓
\$ CM	938.00	✓
\$ R	711.60	X
\$ R	89.60	X
Total	\$ 15,791.10	

256

Parts Special Nett Items

26	1	Rear number plate
27	1 set	Reverse sensor
28	1	Reverse camera

Mit \$	60.00	455A
\$ T	300.00	✓
\$ R	250.00	X
\$	610.00	

Total Parts

\$ 16,401.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour

Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	\$ 2,800.00	1200/-
To putty and respray painting on affected areas.	\$ 1,800.00	1000/-
To remove, replace rear tailgate fittings to facilitate repair.	\$ 350.00	60/-
To remove, replace rear windscreen glass.	\$ 200.00	120/-
To remove, replace reverse camera.	\$ 200.00	60/-
To remove, replace reverse sensor.	\$ 150.00	60/-
To remove, replace rear exhaust silencer.	na \$ 250.00	x
To check wiring and lightings.	\$ 80.00	20/-

Total Labour	\$ 5,830.00
--------------	-------------

Total Parts and Labour	\$ 22,231.10
------------------------	--------------