

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : ECICS LIMITED
 10 EUNOS ROAD 8
 #09-04A SINGAPORE POST CENTRE
 SINGAPORE 408600

TEL: 63374779 **FAX:** 63389267
ATTN: Motor Claim Department \ ECICS

Estimate No: EST1505439
Date: 11 Dec 2019
Policy No: GA027739
Veh Reg No: SDS839A
Make/Model: TOYOTA VELLFIRE
 2.4Z GOLDEN EYES II
 2WD

Your Ref No: TP 1119-5741
Claim Type: Third Party
Accident Date: 03-11-2019
TP Veh Reg No: SLR 3612 C

Chassis No: ANH208346738
Engine No: 2AZG444066
Reg. Date: 27-03-2015

Estimate Repair Cost to Vehicle No : SDS839A


Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair				
Spare Parts				
1 RETAINER FRONT FENDER LINER	5.00	1 PCS	5.00	5.00
			5.00	
	Add 10%		0.50	5.50

SUPP 5.50
 PARTS 2502.50
 SN 95.00
 LAB. 2200.00

 4803.00

Total	S\$ 5.50
GST Amount	S\$ 0.39
Total Amount payable	S\$ 5.89

For Progressive Car Care Pte Ltd



 AUTHORISED SIGNATURE

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : ECICS LIMITED

10 EUNOS ROAD 8

#09-04A SINGAPORE POST CENTRE

SINGAPORE 408600

TEL: 63374779

FAX: 63389267

ATTN: Motor Claim Department \ ECICS

Estimate No: EST1505439

Date: 06-Nov-2019

Policy No: GA027739

Veh Reg No: SDS839A

Make/Model: TOYOTA VELLFIRE
 2.4Z GOLDEN EYES II
 2WD

Chassis No: ANH208346738

Engine No: 2AZG444066

Reg. Date: 27/03/2015

Your Ref No: TP 1119-5741

Claim Type: Third Party

Accident Date: 03/11/2019

TP Veh Reg No: SLR 3612 C

Estimate Repair Cost to Vehicle No : SDS839A

Description	U/Price	Quantity	Cost	Amount
			SS	SS
Special Net				
1 FRONT PARKING CAMERA <i>Re m</i>	350.00	1 PCS	350.00	
2 FRONT NUMBER PLATE WITH CASING <i>Best</i>	35.00	1 PC	35.00	
3 SPONGE TAPE <i>3 m</i>	20.00	1 PCS	20.00	
4 SEALANT	20.00	2 PC	40.00	
				445.00
Spare Parts				
5 REAR BOOT <i>Dishd</i>	700.00	1 PCS	700.00	
6 REAR BOOT REFLECTOR - LH <i>Re m</i>	170.00	1 PC	170.00	
7 REAR BOOT REFLECTOR - RH <i>Re m</i>	170.00	1 PCS	170.00	
8 REAR BOOT TOP LOCK <i>3 m</i>	170.00	1 PC	170.00	
9 REAR BOOT BOTTOM LOCK	28.00	1 PC	28.00	
10 REAR BOOT RUBBER <i>re m cut</i>	140.00	1 PC	140.00	140
11 REAR BOOT VELLFIRE WORDING	45.00	1 PCS	45.00	
12 REAR BOOT GOLDEN EYES II WORDING <i>3 m</i>	45.00	1 PC	45.00	45
13 REAR BOOT OUTER LOWER CHROME <i>Re m</i>	680.00	1 PCS	680.00	
14 REAR BOOT KEYLESS SENSOR <i>Re m</i>	100.00	1 PCS	100.00	
15 REAR BUMPER <i>Dishd</i>	350.00	1 PC	350.00	
16 REAR BUMPER CLIPS <i>Re</i>	1.50	10 PC	15.00	25
17 REAR BUMPER SIDE HOLDER - LH <i>3 m</i>	40.00	1 PCS	40.00	
18 REAR BUMPER SIDE HOLDER - RH <i>3 m</i>	40.00	1 PCS	40.00	
19 REAR BUMPER END PANEL BRACKET - RH <i>Re m</i>	70.00	1 PCS	70.00	
20 REAR BUMPER END PANEL BRACKET - LH <i>Re m</i>	70.00	1 PCS	70.00	
21 REAR BUMPER SENSOR <i>Re m</i>	160.00	4 PC	640.00	
22 REAR BUMPER SENSOR COVER - OUTER <i>2 m Re m</i>	15.00	1 PC	15.00	
23 REAR BUMPER SENSOR WIRE <i>Re m</i>	200.00	1 PCS	200.00	
24 REAR BUMPER REFLECTORS - LH <i>3 m</i>	28.00	1 PC	28.00	
25 REAR BUMPER REFLECTORS - RH <i>3 m</i>	28.00	1 PC	28.00	
26 REAR BUMPER TOW COVER - LH <i>3 m</i>	35.00	1 PC	35.00	
27 REAR BUMPER TOW COVER - RH <i>3 m</i>	35.00	1 PC	35.00	
28 REAR PANEL - INNER/OUTER <i>Dented</i>	360.00	1 PCS	360.00	320
29 REAR PANEL TOP GARNISH <i>Re m</i>	110.00	1 PCS	110.00	
30 TAILLAMP ASSY - RH <i>Re m</i>	210.00	1 PCS	210.00	
31 TAILLAMP LOWER GARNISH - RH <i>Dishd</i>	50.00	1 PCS	50.00	
32 FRONT BUMPER <i>Dishd</i>	300.00	1 PC	300.00	

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : ECICS LIMITED
 10 EUNOS ROAD 8
 #09-04A SINGAPORE POST CENTRE
 SINGAPORE 408600

Estimate No: EST1505439

Date: 06-Nov-2019

TEL: 63374779 FAX: 63389267

Policy No: GA027739

ATTN: Motor Claim Department \ ECICS

Veh Reg No: SDS839A

Make/Model: TOYOTA VELLFIRE
 2.4Z GOLDEN EYES II
 2WD

Your Ref No: TP 1119-5741

Chassis No: ANH208346738

Claim Type: Third Party

Engine No: 2AZG444066

Accident Date: 03/11/2019

Reg. Date: 27/03/2015

TP Veh Reg No: SLR 3612 C

Estimate Repair Cost to Vehicle No : SDS839A

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
33 FRONT BUMPER CLIPS <i>Mer</i>	1.50	10 PC	15.00	✓ ✓
34 FRONT BUMPER SIDE HOLDER - LH <i>for</i>	40.00	1 PC	40.00	
35 FRONT BUMPER SIDE HOLDER - RH	40.00	1 PC	40.00	
36 FRONT BUMPER CENTRE LOWER GRILLE <i>Deled</i>	85.00	1 PCS	85.00	✓ ✓
37 FRONT BUMPER PARKING SENSOR <i>Mer</i>	190.24	1 PCS	190.24	
38 FRONT BUMPER REINFORCEMENT <i>Mer</i>	180.00	1 PC	180.00	
39 FRONT BUMPER FOAM <i>Mer</i>	50.00	1 PC	50.00	
			5,444.24	<i>2775</i>
	Add 10%		544.42	5,988.66
<i>retainer frt fender liner 1 X \$5.00 = \$5 ✓</i>				<i>2502.50</i>
Labour				
40 TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, REMOVE, REPLACE FRONT BUMPER, REAR BUMPER AND REMOVE, REPLACE ACCIDENT PARTS	1,200.00	1 JOB	1,200.00	<i>1000 ✓</i>
41 TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,400.00	1 JOB	1,400.00	<i>800 ✓</i>
42 TO CHECK WIRING	50.00	1 JOB	50.00	<i>30 ✓</i>
43 TO REMOVE, REFIT REAR GARNISH	150.00	1 JOB	150.00	<i>60 ✓</i>
44 TO TUFF-KOTE	120.00	1 JOB	120.00	<i>60 ✓</i>
45 TO TRANSFER REAR BUMPER SENSOR	100.00	1 JOB	100.00	<i>50 ✓</i>
46 TO TRANSFER FRONT BUMPER SENSOR	100.00	1 JOB	100.00	<i>50 ✓</i>
47 TO RESET CHECK LIGHT	60.00	1 JOB	60.00	<i>30 ✓</i>
48 TO REMOVE, REFIT REAR BOOT GLASS	150.00	1 JOB	150.00	<i>120 ✓</i>
49 TO REMOVE, REPAIR REAR EXHAUST PIPE	120.00	1 JOB	120.00	<i>+</i>
			3,450.00	<i>2200</i>