

12/20/00

INS. REC. BY:

REP:

es/ICS19019758/Av d36

Special Instruction:

Surveyor: Audra

Mormen

ASSIGNMENT (Office)

Froth (Person): Elizabeth Chew of ICS

ICS

Date/Time: 7/11/19 @ 11:20am

Estimated Cost: \_\_\_\_\_

Bill to: \_\_\_\_\_

OD / REP / FWS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: \_\_\_\_\_

SDS 839 A

Insured: \_\_\_\_\_

SLR 3612C

at Workshop n/s \_\_\_\_\_

Progressive Car

Tel: \_\_\_\_\_

67415336

of \_\_\_\_\_

Blk 3022A ubi Road 1 #01-45/46

Policy No: \_\_\_\_\_

Claim No: \_\_\_\_\_

DMPC 19002804

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_

(Client's Record)

D.O.A. \_\_\_\_\_

3/11/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: \_\_\_\_\_

11:50am @ 7/11/19

Person Contacted: \_\_\_\_\_

pei wen / Ray

Vehicle IN / OUT

Date/Time	Action/Instruction
	<u>Estimate</u> ✓
<u>4/2/2020</u>	<u>Final fig \$4616 confirmed by email (Ref 573.16, 537) CNO LS)</u>

REF: ICS

## ASSIGNMENT

From: \_\_\_\_\_ Date: 8/11/19

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SDS839A

at Workshop with progressive Car

of B1K3022A Ubi Road 1# 01-45/46

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: 11:30am (waiting)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS <sup>1up</sup>

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SDS839A. Yr Regn: 2015, March.

Type: ~~M.CAR~~ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Pajero Vellfire cc 2362

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 119348. T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: ANH208346738.

Gen. Cond: ~~Good~~ Fair / Poor / Burnt

Steering: ~~In order~~ / Jammed / Leaked / Burnt or

Brake: ~~In order~~ / Jammed / Leaked / Burnt or

Modi: Nil (~~S/Rim~~) / STD A/Rim or

Tyre Size: F: 235/50R18-  
R: 235/50R18-

BS / ~~DUN~~ EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 06 mm R/Bal. 06 mm


L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 08/11/19

Survey held at Progressive (Ubi)

Des. of Damages: Frt / ~~Rear~~ / O/S / N/S / U/C / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TPECICS
	RECEIVED 05 FEB 2020
	
	11/2/2020

Date/Time, File Pass to?  : Prel. Report)  : Final Report

Date/Time, File Return to?

3 sp - typist

Report Format: menmen

Lump Sum / (P. 1) 4616 / =

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee:  : Site Insp (\$) \_\_\_\_\_ : Interview (\$) \_\_\_\_\_ : Tech. Insp (\$) \_\_\_\_\_ : Wheel and (\$) \_\_\_\_\_

Survey Fee: 200

Transportation: \_\_\_\_\_

S + PS: 0

Phone: \_\_\_\_\_

Other: 11

TOTAL: 261

## View Sent Message

This mail is associated with :

**\*SDS839A**  
**[SLR3612C]**  
TP

Nov 3 2019 12:00AM

Progressive Car Care Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 08/11/2019 15:51 PM.  
**To** elizabeth\_chew@ecics.com.sg  
**Subject** TP SURVEY SDS 839A

Dear Elizabeth,

Please be informed that we have inspected the vehicle SDS 839A on 8/11/2019.

We are pending estimate from repairer.

Best Regards,  
Veron Chen

### DOCUMENTS SUMMARY

There are no documents.

## Nivitha (LKK Auto)

---

**From:** ECICS Claims <claims@ecics.com.sg>  
**Sent:** Thursday, 7 November 2019 11:20 AM  
**To:** Admin-D (LKKAuto); SUR; assignments  
**Subject:** FW: Arrange for survey - Acc on 03.11.2019 invlg SDS 839 A & SLR 3612 C ECICS REF: DMPC1900280H  
**Attachments:** SDS839A.PDF; SLR3612C.PDF; SME6700T.PDF

Dear LKK,

Please refer to the below email and conduct PRI.

We attached our insured and third party GIA reports for your attention.

Best regards

**Elizabeth Chew**

AVP | Claims



DID (65) 6303 0182

Tel (65) 6337 4779

Email [elizabeth\\_chew@ecics.com.sg](mailto:elizabeth_chew@ecics.com.sg) Web [www.ecics.com.sg](http://www.ecics.com.sg)

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

---

**From:** Lily [mailto:bhlim@procarcare.com.sg] **On Behalf Of** Claims

**Sent:** Thursday, 7 November 2019 9:57 AM

**To:** ECICS Claims

**Cc:** Wendy; Claims

**Subject:** RE: Arrange for survey - Acc on 03.11.2019 invlg SDS 839 A & SLR 3612 C ECICS REF: DMPC1900280H

Hi

Please arrange LKK

Thank you

Regards,

**Lily LIM**

Claims Advisory

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

T: +65 6741 5336 | F: +65 6741 7208

E: [claims@procarcare.com.sg](mailto:claims@procarcare.com.sg)

W: [www.procarcare.com.sg](http://www.procarcare.com.sg)



**IMPORTANT NOTICE:** The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof.

---

**From:** ECICS Claims [mailto:claims@ecics.com.sg]

**Sent:** Thursday, 7 November, 2019 9:41 AM

**To:** Lily

**Subject:** FW: Arrange for survey - Acc on 03.11.2019 invlg SDS 839 A & SLR 3612 C ECICS REF: DMPC1900280H

WITHOUT PREJUDICE

Dear Lily,

We refer to your email below.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. Ajax Inspection Services Pte Ltd
2. Appraisals Associates Pte Ltd
3. Infiniti Appraisal Services
4. LKK Auto Consultants

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Best regards

**Elizabeth Chew**

AVP | Claims



DID (65) 6303 0182

Tel (65) 6337 4779

Email [elizabeth\\_chew@ecics.com.sg](mailto:elizabeth_chew@ecics.com.sg) Web [www.ecics.com.sg](http://www.ecics.com.sg)

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

---

**From:** Lily [mailto:bhlim@procarcare.com.sg] **On Behalf Of** Claims

**Sent:** Wednesday, 6 November 2019 4:42 PM

**To:** ECICS Claims

**Cc:** Claims

**Subject:** Arrange for survey - Acc on 03.11.2019 invlg SDS 839 A & SLR 3612 C

Dear Sirs

Please refer to attached and arrange for survey  
VEHICLE IS NOT IN WORKSHOP

Regards,

**Lily LIM**

Claims Advisory

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

T: +65 6741 5336 | F: +65 6741 7208

E: [claims@procarcare.com.sg](mailto:claims@procarcare.com.sg)

W: [www.procarcare.com.sg](http://www.procarcare.com.sg)



**IMPORTANT NOTICE:** The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof.

---

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

---

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	04/11/2019 14:57
Date Of Accident	03/11/2019 10:30
Exact Location Of Accident	AIRPORT ROAD TOWARDS MAC[HERSON
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDS839A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HO YEW SIONG
NRIC No	S1664773Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96390926
Alternative Phone No	OTHERS-96390926

### Vehicle Particulars

Manufacturer	TOYOTA
Model	VELLFIRE-2.4 V (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA027739
Cover Note Number	

### Driver

Name of Driver	HO YEW SIONG
NRIC No	S1664773Z
Date Of Birth	01/05/1964
Occupation	INDOOR
Date Of Driving Pass	24/01/1984
Driving Experience	35 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96390926
Fax Number	
Contact Number	OTHERS-96390926
EMail Address	NOEMAIL

Address 8 BEDOK RESERVOIR VIEW #15-23  
 Postcode 479235  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident CHAIN COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 3  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 4  
 Passenger 1 NAME: : Z,T HO  
 GENDER: : MALE  
 Passenger 2 NAME: : LIONG WAI HAN  
 GENDER: : FEMALE  
 Passenger 3 NAME: : ZORA HO  
 GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes,Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes,against whom?

#### Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORD BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLR3612C  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver TAN BENG HWEE  
 NRIC/Passport Number S7104806C  
 Contact Number 93375393

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number

SME6700T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

CHAN HEE TECK

NRIC/Passport Number

Contact Number

97672129

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716  
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg  
 GST:201006949C RCB NO:201006949C

M/S : ECICS LIMITED  
 10 EUNOS ROAD 8  
 #09-04A SINGAPORE POST CENTRE  
 SINGAPORE 408600  
 TEL: 63374779 FAX: 63389267  
 ATTN: Motor Claim Department \ ECICS

Estimate No: EST1505439  
 Date: 06 Nov 2019  
 Policy No: GA027739  
 Veh Reg No: SDS839A  
 Make/Model: TOYOTA VELLFIRE  
 2.4Z GOLDEN EYES II  
 2WD  
 Chassis No: ANH208346738  
 Engine No: 2AZG444066  
 Reg. Date: 27/03/2015

Your Ref No: TP 1119-5741  
 Claim Type: Third Party  
 Accident Date: 03/11/2019  
 TP Veh Reg No: SLR 3612 C

## Estimate Repair Cost to Vehicle No : SDS839A

Description	U/Price	Quantity	Cost	Amount
			SS	SS
<b>Special Net</b>				
1 FRONT PARKING CAMERA <i>Repl</i>	350.00	1 PCS	350.00	<del>350.00</del>
2 FRONT NUMBER PLATE WITH CASING <i>Best</i>	35.00	1 PC	35.00	<del>35.00</del>
3 SPONGE TAPE <i>3/4</i>	20.00	1 PCS	20.00	<del>20.00</del>
4 SEALANT	20.00	2 PC	40.00	<del>40.00</del>
				445.00
<b>Spare Parts</b>				
5 REAR BOOT <i>Dish</i>	700.00	1 PCS	700.00	<del>700.00</del>
6 REAR BOOT REFLECTOR - LH <i>Repl</i>	170.00	1 PC	170.00	<del>170.00</del>
7 REAR BOOT REFLECTOR - RH <i>Repl</i>	170.00	1 PCS	170.00	<del>170.00</del>
8 REAR BOOT TOP LOCK <i>3/4</i>	170.00	1 PC	170.00	<del>170.00</del>
9 REAR BOOT BOTTOM LOCK	28.00	1 PC	28.00	<del>28.00</del>
✓ 10 REAR BOOT RUBBER <i>not on car</i>	140.00	1 PC	140.00	<del>140.00</del>
11 REAR BOOT VELLFIRE WORDING	45.00	1 PCS	45.00	<del>45.00</del>
12 REAR BOOT GOLDEN EYES II WORDING <i>3/4</i>	45.00	1 PC	45.00	<del>45.00</del>
13 REAR BOOT OUTER LOWER CHROME <i>Repl</i>	680.00	1 PCS	680.00	<del>680.00</del>
14 REAR BOOT KEYLESS SENSOR <i>Repl</i>	100.00	1 PCS	100.00	<del>100.00</del>
15 REAR BUMPER <i>Dish</i>	350.00	1 PC	350.00	<del>350.00</del>
16 REAR BUMPER CLIPS <i>Re</i>	1.50	10 PC	15.00	<del>15.00</del>
17 REAR BUMPER SIDE HOLDER - LH <i>3/4</i>	40.00	1 PCS	40.00	<del>40.00</del>
18 REAR BUMPER SIDE HOLDER - RH <i>3/4</i>	40.00	1 PCS	40.00	<del>40.00</del>
19 REAR BUMPER END PANEL BRACKET - RH <i>Repl</i>	70.00	1 PCS	70.00	<del>70.00</del>
20 REAR BUMPER END PANEL BRACKET - LH <i>Repl</i>	70.00	1 PCS	70.00	<del>70.00</del>
21 REAR BUMPER SENSOR <i>Repl</i>	160.00	4 PC	640.00	<del>640.00</del>
22 REAR BUMPER SENSOR COVER - OUTER <i>Repl</i>	15.00	1 PC	15.00	<del>15.00</del>
23 REAR BUMPER SENSOR WIRE <i>new</i>	200.00	1 PCS	200.00	<del>200.00</del>
24 REAR BUMPER REFLECTORS - LH <i>3/4</i>	28.00	1 PC	28.00	<del>28.00</del>
25 REAR BUMPER REFLECTORS - RH <i>3/4</i>	28.00	1 PC	28.00	<del>28.00</del>
26 REAR BUMPER TOW COVER - LH <i>3/4</i>	35.00	1 PC	35.00	<del>35.00</del>
27 REAR BUMPER TOW COVER - RH <i>3/4</i>	35.00	1 PC	35.00	<del>35.00</del>
28 REAR PANEL - INNER/OUTER <i>Dented</i>	360.00	1 PCS	360.00	<del>360.00</del>
29 REAR PANEL TOP GARNISH <i>Repl</i>	110.00	1 PCS	110.00	<del>110.00</del>
30 TAILLAMP ASSY - RH <i>Repl</i>	210.00	1 PCS	210.00	<del>210.00</del>
31 TAILLAMP LOWER GARNISH - RH <i>Repl</i>	50.00	1 PCS	50.00	<del>50.00</del>
32 FRONT BUMPER <i>Dish</i>	300.00	1 PC	300.00	<del>300.00</del>

# Progressive Car Care Pte Ltd

Bik 3022A Ubi Road I #01-45/46 Singapore 408716  
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg  
 GST:201006949C RCB NO:201006949C

M/S : ECICS LIMITED  
 10 EUNOS ROAD 8  
 #09-04A SINGAPORE POST CENTRE  
 SINGAPORE 408600

TEL: 63374779 FAX: 63389267  
 ATTN: Motor Claim Department \ ECICS

Estimate No: EST1505439

Date: 06 Nov 2019

Policy No: GA027739

Veh Reg No: SDS839A

Make/Model: TOYOTA VELLFIRE  
 2.4Z GOLDEN EYES II  
 2WD

Your Ref No: TP 1119-5741

Claim Type: Third Party

Accident Date: 03/11/2019

TP Veh Reg No: SLR 3612 C

Chassis No: ANH208346738

Engine No: 2AZG444066

Reg. Date: 27/03/2015

## Estimate Repair Cost to Vehicle No : SDS839A

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
33 FRONT BUMPER CLIPS <i>new</i>	1.50	10 PC	15.00 ✓	
34 FRONT BUMPER SIDE HOLDER - LH <i>part</i>	40.00	1 PC	40.00 ✗	
35 FRONT BUMPER SIDE HOLDER - RH <i>part</i>	40.00	1 PC	40.00 ✗	
36 FRONT BUMPER CENTRE LOWER GRILLE <i>Del</i>	85.00	1 PCS	85.00 ✓	
37 FRONT BUMPER PARKING SENSOR <i>new</i>	190.24	1 PCS	190.24 ✗	
38 FRONT BUMPER REINFORCEMENT <i>del new</i>	180.00	1 PC	180.00 ✗	
39 FRONT BUMPER FOAM <i>del new</i>	50.00	1 PC	50.00 ✗	
			5,444.24	
	Add 10%		544.42	5,988.66
<b>Labour</b>				
40 TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, REMOVE, REPLACE FRONT BUMPER, REAR BUMPER AND REMOVE, REPLACE ACCIDENT PARTS	1,200.00	1 JOB	<del>1,200.00</del> 1000	
41 TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,400.00	1 JOB	<del>1,400.00</del> 800	
42 TO CHECK WIRING	50.00	1 JOB	<del>50.00</del> 30	
43 TO REMOVE, REFIT REAR GARNISH	150.00	1 JOB	<del>150.00</del> 60	
44 TO TUFF-KOTE	120.00	1 JOB	<del>120.00</del> 60	
45 TO TRANSFER REAR BUMPER SENSOR	100.00	1 JOB	<del>100.00</del> 50	
46 TO TRANSFER FRONT BUMPER SENSOR	100.00	1 JOB	<del>100.00</del> 50	
47 TO RESET CHECK LIGHT	60.00	1 JOB	<del>60.00</del> 30	
48 TO REMOVE, REFIT REAR BOOT GLASS	150.00	1 JOB	<del>150.00</del> 120	
49 TO REMOVE, REPAIR REAR EXHAUST PIPE	120.00	1 JOB	<del>120.00</del> ✗	
				3,450.00

# Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716  
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg  
 GST:201006949C RCB NO:201006949C

M/S : ECICS LIMITED  
 10 EUNOS ROAD 8  
 #09-04A SINGAPORE POST CENTRE  
 SINGAPORE 408600  
 TEL: 63374779 FAX: 63389267  
 ATTN: Motor Claim Department \ ECICS

Estimate No: EST1505439  
 Date: 06-Nov-2019  
 Policy No: GA027739  
 Veh Reg No: SDS839A  
 Make/Model: TOYOTA VELLFIRE  
 2.4Z GOLDEN EYES II  
 2WD

Your Ref No: TP 1119-5741  
 Claim Type: Third Party  
 Accident Date: 03/11/2019  
 TP Veh Reg No: SLR 3612 C

Chassis No: ANH208346738  
 Engine No: 2AZG444066  
 Reg. Date: 27/03/2015

## Estimate Repair Cost to Vehicle No : SDS839A

Description	U/Price	Quantity	Cost	Amount
			SS	SS
<b>Special Net</b>				
1 FRONT PARKING CAMERA <i>the m</i>	350.00	1 PCS	<del>350.00</del>	
2 FRONT NUMBER PLATE WITH CASING <i>Best</i>	35.00	1 PC	35.00	
3 SPONGE TAPE <i>the m</i>	20.00	1 PCS	20.00	
4 SEALANT	20.00	2 PC	40.00	
				445.00
<b>Spare Parts</b>				
5 REAR BOOT <i>Distal</i>	700.00	1 PCS	700.00	
6 REAR BOOT REFLECTOR - LH <i>the m</i>	170.00	1 PC	170.00	
7 REAR BOOT REFLECTOR - RH <i>the m</i>	170.00	1 PCS	<del>170.00</del>	
8 REAR BOOT TOP LOCK <i>the m</i>	170.00	1 PC	<del>170.00</del>	
9 REAR BOOT BOTTOM LOCK <i>the m</i>	28.00	1 PC	<del>28.00</del>	
10 REAR BOOT RUBBER <i>not cut</i>	140.00	1 PC	<del>140.00</del>	140
11 REAR BOOT VELLFIRE WORDING	45.00	1 PCS	45.00	
12 REAR BOOT GOLDEN EYES II WORDING <i>the m</i>	45.00	1 PC	<del>45.00</del>	45
13 REAR BOOT OUTER LOWER CHROME <i>the m</i>	680.00	1 PCS	<del>680.00</del>	
14 REAR BOOT KEYLESS SENSOR <i>the m</i>	100.00	1 PCS	<del>100.00</del>	
15 REAR BUMPER <i>the m</i>	350.00	1 PC	350.00	
16 REAR BUMPER CLIPS <i>the m</i>	1.50	10 PC	15.00	25
17 REAR BUMPER SIDE HOLDER - LH <i>the m</i>	40.00	1 PCS	40.00	
18 REAR BUMPER SIDE HOLDER - RH <i>the m</i>	40.00	1 PCS	40.00	
19 REAR BUMPER END PANEL BRACKET - RH <i>the m</i>	70.00	1 PCS	<del>70.00</del>	
20 REAR BUMPER END PANEL BRACKET - LH <i>the m</i>	70.00	1 PCS	<del>70.00</del>	
21 REAR BUMPER SENSOR <i>the m</i>	160.00	4 PC	<del>640.00</del>	
22 REAR BUMPER SENSOR COVER - OUTER <i>the m</i>	15.00	1 PC	<del>15.00</del>	
23 REAR BUMPER SENSOR WIRE <i>the m</i>	200.00	1 PCS	<del>200.00</del>	
24 REAR BUMPER REFLECTORS - LH <i>the m</i>	28.00	1 PC	<del>28.00</del>	
25 REAR BUMPER REFLECTORS - RH <i>the m</i>	28.00	1 PC	<del>28.00</del>	
26 REAR BUMPER TOW COVER - LH <i>the m</i>	35.00	1 PC	<del>35.00</del>	
27 REAR BUMPER TOW COVER - RH <i>the m</i>	35.00	1 PC	<del>35.00</del>	
28 REAR PANEL - INNER/OUTER <i>Distal</i>	360.00	1 PCS	<del>360.00</del>	320
29 REAR PANEL TOP GARNISH <i>the m</i>	110.00	1 PCS	<del>110.00</del>	
30 TAILLAMP ASSY - RH <i>the m</i>	210.00	1 PCS	<del>210.00</del>	
31 TAILLAMP LOWER GARNISH - RH <i>the m</i>	50.00	1 PCS	<del>50.00</del>	
32 FRONT BUMPER <i>the m</i>	300.00	1 PC	300.00	

# Progressive Car Care Pte Ltd

Blk 3022A Ubi Road | #01-45/46 Singapore 408716  
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg  
 GST:201006949C RCB NO:201006949C

M/S : ECICS LIMITED

10 EUNOS ROAD 8

#09-04A SINGAPORE POST CENTRE

SINGAPORE 408600

TEL: 63374779

FAX: 63389267

ATTN: Motor Claim Department \ ECICS

Estimate No: EST1505439

Date: 06-Nov-2019

Policy No: GA027739

Veh Reg No: SDS839A

Make/Model: TOYOTA VELLFIRE  
 2.4Z GOLDEN EYES II  
 2WD

Your Ref No: TP 1119-5741

Claim Type: Third Party

Accident Date: 03/11/2019

TP Veh Reg No: SLR 3612 C

Chassis No: ANH208346738

Engine No: 2AZG444066

Reg. Date: 27/03/2015

## Estimate Repair Cost to Vehicle No : SDS839A

Description	U/Price	Quantity	Cost	Amount
			SS	SS
33 FRONT BUMPER CLIPS <i>Neu</i>	1.50	10 PC	15.00 ✓	
34 FRONT BUMPER SIDE HOLDER - LH <i>Part</i>	40.00	1 PC	<del>40.00</del> ✓	
35 FRONT BUMPER SIDE HOLDER - RH	40.00	1 PC	<del>40.00</del> ✓	
36 FRONT BUMPER CENTRE LOWER GRILLE <i>Del</i>	85.00	1 PCS	85.00 ✓	
37 FRONT BUMPER PARKING SENSOR <i>Neu</i>	190.24	1 PCS	<del>190.24</del> ✓	
38 FRONT BUMPER REINFORCEMENT <i>2nd Neu</i>	180.00	1 PC	<del>180.00</del> ✓	
39 FRONT BUMPER FOAM <i>3rd Neu</i>	50.00	1 PC	<del>50.00</del> ✓	
			5,444.24 <i>27%</i>	
	Add 10%		544.42	5,988.66
<i>rebuil frt fender liner 1 x \$5.00 = \$5 ✓</i>				<i>2502.50</i>
<b>Labour <i>Neu</i></b>				
40 TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, REMOVE, REPLACE FRONT BUMPER, REAR BUMPER AND REMOVE, REPLACE ACCIDENT PARTS	1,200.00	1 JOB	<del>1,200.00</del> <i>1000</i> ✓	
41 TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,400.00	1 JOB	<del>1,400.00</del> <i>800</i> ✓	
42 TO CHECK WIRING	50.00	1 JOB	<del>50.00</del> <i>30</i> ✓	
43 TO REMOVE, REFIT REAR GARNISH	150.00	1 JOB	<del>150.00</del> <i>60</i> ✓	
44 TO TUFF-KOTE	120.00	1 JOB	<del>120.00</del> <i>60</i> ✓	
45 TO TRANSFER REAR BUMPER SENSOR	100.00	1 JOB	<del>100.00</del> <i>50</i> ✓	
46 TO TRANSFER FRONT BUMPER SENSOR	100.00	1 JOB	<del>100.00</del> <i>50</i> ✓	
47 TO RESET CHECK LIGHT	60.00	1 JOB	<del>60.00</del> <i>30</i> ✓	
48 TO REMOVE, REFIT REAR BOOT GLASS	150.00	1 JOB	<del>150.00</del> <i>120</i> ✓	
49 TO REMOVE, REPAIR REAR EXHAUST PIPE	120.00	1 JOB	<del>120.00</del> <i>x</i>	

3,450.00

*2200*

# Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716  
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg  
GST:201006949C RCB NO:201006949C

M/S : ECICS LIMITED  
10 EUNOS ROAD 8  
#09-04A SINGAPORE POST CENTRE

SINGAPORE 408600  
TEL: 63374779 FAX: 63389267  
ATTN: Motor Claim Department \ ECICS

Estimate No: EST1505439

Date: 06 Nov 2019

Policy No: GA027739

Veh Reg No: SDS839A

Make/Model: TOYOTA VELLFIRE  
2.4Z GOLDEN EYES II  
2WD

Chassis No: ANH208346738

Engine No: 2AZG444066

Reg. Date: 27/03/2015

Your Ref No: TP 1119-5741

Claim Type: Third Party

Accident Date: 03/11/2019


TP Veh Reg No: SLR 3612 C

## Estimate Repair Cost to Vehicle No : SDS839A

9889.16	Total	S\$ 9,883.66
	Add GST @ 7%	691.86
	Total Amount payable	S\$ 10,575.52

TOTAL: SINGAPORE DOLLAR TEN THOUSAND FIVE HUNDRED SEVENTY FIVE AND CENTS FIFTY TWO ONLY

For Progressive Car Care Pte Ltd



4900.16

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Adrian King  
P/P 08/11/19

~~06~~ Days?

06 Days.

# Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716  
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg  
 GST:201006949C RCB NO:201006949C

**M/S :** ECICS LIMITED  
 10 EUNOS ROAD 8  
 #09-04A SINGAPORE POST CENTRE  
 SINGAPORE 408600  
**TEL:** 63374779                      **FAX:** 63389267  
**ATTN:** Motor Claim Department \ ECICS

**Estimate No:** EST1505439  
**Date:** 11 Dec 2019  
**Policy No:** GA027739  
**Veh Reg No:** SDS839A  
**Make/Model:** TOYOTA VELLFIRE  
 2.4Z GOLDEN EYES II  
 2WD  
**Chassis No:** ANH208346738  
**Engine No:** 2AZG444066  
**Reg. Date:** 27-03-2015

**Your Ref No:** TP 1119-5741  
**Claim Type:** Third Party  
**Accident Date:** 03-11-2019  
**TP Veh Reg No:** SLR 3612 C


### Estimate Repair Cost to Vehicle No : SDS839A

Description	U/Price	Quantity	Cost	Amount	
				<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair					
<b>Spare Parts</b>					
1 RETAINER FRONT FENDER LINER <i>new</i>	5.00	1 PCS	5.00	5.00 ✓	
	Add 10%		0.50	5.50	

Total	S\$ 5.50
GST Amount	S\$ 0.39
<b>Total Amount payable</b>	<b>S\$ 5.89</b>

<i>SUPP</i>	<i>5.50</i>
<i>PARTS</i>	<i>2502.50</i>
<i>SN</i>	<i>95.00</i>
<i>LAB.</i>	<i>2200.00</i>
	<hr/> <i>4803.00</i>

For Progressive Car Care Pte Ltd

  
 \_\_\_\_\_  
 AUTHORISED SIGNATURE




日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3016 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:  
60 JALAN LAM HUAT #B1-05/06 GARROS CENTRE  
SINGAPORE 737869 TEL: 63625225 FAX: 63626977

Email: jaeauto@pacific.net.sg  
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Wiper blades: NWB (Nippon Wiper blade), Siliiper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD

Block 3022A #01-45/46  
UBI ROAD 1  
BUITON 92712711  
SINGAPORE 408716  
TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY  
ALIN WENDY

TAX INVOICE : AR201911-04294  
DATE : 08/11/2019  
CUSTOMER ID : PRO005  
VEH REG. NO. : SDS839A  
TERMS : 30 days  
PO NO.  
PAGE NO. : Page 1 of 1  
CURR. : SGD

SO STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
T67005-58140 VEIL-ANH20	RR BOOT	UI SUPPLIER	1	700.00	700.00 ✓
T67005-58181 ANH20-2012	RR BOOT REFLECTOR RH	UI L2-C16	1	700.00	700.00 ✓
T52161-16010 ROC ALL MODEL	BUMPER CLIP	UI L2-T9	10	1.50	15.00 ✓
T67005-58100 ZIG VEIL-GGH20	FRONT BUMPER T.WR GRILLE	UI L2-B16-C	1	85.00	85.00 ✓

SUB-TOTAL : 970.00  
ADD GST@7.00% : 67.90

R.&O.E. TOTAL AMOUNT SGD : 1,037.90

[F] 08/11/2019 3:51:24PM

[E] 08/11/2019 3:41:02PM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on Over Due Account

Goods Received in Good Order

JAE Auto Pte Ltd  
Sales Executive: LOON



This is computer generated document.  
No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司  
**JAE AUTO PTE LTD**

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
 TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:  
 48A SUNGAI KADUT AVE SINGAPORE 729672  
 TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg  
 GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),  
 Forch (Made in Germany)  
 Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD  
 BLOCK 3022A #01-45/46  
 UBI ROAD 1  
 BU10N 92712711  
 SINGAPORE 408716  
 TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY  
 ATTN : WENDY

TP 5741

TAX INVOICE : AR201911-09779  
 DATE : 20/11/2019  
 CUSTOMER ID : PRO005  
 VEH REG. NO. : SDS839A  
 TERMS : 30 days  
 PO NO. :  
 PAGE NO. : Page 1 of 1  
 CURR. : SGD

SO STOCK ID	DESCRIPTION	Stk no	QTY	U/PRICE	AMOUNT
167881-58020	RR BOOT RUBBER	CC12-O-03B2	1	140.00	140.00 ✓
VELL-ANH20					
190975-02066	BONNET HMBLKM	CC12-O-3B10	1	45.00	45.00 ✓
KDH222					

SUB-TOTAL : 185.00  
 A/D (1ST 7.00 % 12.95

E. & O E TOTAL AMOUNT SGD : 197.95

[P] 20/11/2019 10:36:23

[E] 20/11/2019 10:31:32AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDues Account(s).

JAE Auto Pte. Ltd.

Sales Executive: LOON



This is computer generated document.  
 No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE  
SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Wiper blade: NWB (Nippon Wiper blade), Silpar (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD  
BLOCK 3022A #01-145/146  
UBI ROAD 1  
SINGAPORE 408716  
TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY  
ATTN: WENDY

TAX INVOICE : AR201911-09780  
DATE : 20/11/2019  
CUSTOMER ID : PRO005  
VEH REG. NO. : SDS839A  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 1 of 1  
CURR. : SGD

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
T75441-58040 VELL-ANF20	RR BOOT "VELLFIRE" RMBLEM	UJ L2-ZZ-10	1	45.00	45.00

SUB-TOTAL : 45.00  
ADD GST 7.00 % 3.15  
E. & O.E TOTAL AMOUNT SGD: 48.15

[P] 20/11/2019 10:34:54AM  
Goods Sold are not refundable for Cash.  
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 20/11/2019 10:32:19AM

JAE Auto Pte. Ltd.  
Sales Executive: LOON



This is computer generated document.  
No signature is required!

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450816 (Account)

WAREHOUSE:  
#60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE  
SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 189307741M

WIPERBLADE BLANK  
Dept Direct: 6417 8701 / 6743 9033



Wiper blade: NWD (Nippon Wiper blade), Silpiper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD  
BLOCK 3022A #01-45/46  
UBI ROAD 1  
BUTION 92712711  
SINGAPORE 408716  
TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY  
ATTN: WENDY

TAX INVOICE : AR201911-04328  
DATE : 08/11/2019  
CUSTOMER ID : PRO005  
VEH REG NO : SDS839A  
TERMS : 30 days  
PO NO :  
PAGE NO : Page 1 of 1  
CURR : SGD

STOCK ID	DESCRIPTION	Stk Loc	QTY	U PRICE	AMOUNT
152159-58925	RR BUMPER	LI1	1	350.00	350.00 ✓
VEH PLANE 20	SUPPLIER				

SUB-TOTAL : 350.00  
ADD GST 7.00% : 24.50  
TOTAL AMOUNT SGD : 374.50

[P] 08/11/2019 4:09:56PM

[E] 08/11/2019 4:09:22PM

Goods Sold are not refundable for Cash.  
Interest Rate of 1.5% per month will be imposed on OverDue Account(s)

Goods Received in Good Order

JAE Auto Pte Ltd  
Sales Executive: LOON  
\*AR-201911-04328\*



This is computer generated document.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:  
48A SUNGAI KADUT AVE SINGAPORE 729672  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg  
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS  
Dept Direct: 6417 8191 / 8743 8838



Wiper blade: NWB (Nippon Wiper blade), Silliper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD  
BLOCK 3022A #01-45/46  
UBI ROAD 1  
BUTION 92712711  
SINGAPORE 408716  
TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY  
ATTN : WENDY

TP 574

TAX INVOICE : AR201911-04295  
DATE : 08/11/2019  
CUSTOMER ID : PRO005  
VEH REG. NO. : SDS839A  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 1 of 1  
CURR. : SGD

SQ	STOCKID	DISCRIPTION	Stk No	QTY	U/PRICE	AMOUNT
✓	T52155-58030 VEIL-ANH20	RR BUMPER S/RETAINER RH	CG C12-O-05B2	1	40.00	40.00 ✓
✓	T52156-58020 VELL-ANH20	RR BUMPER S/RETAINER LH	CG CC12-H-01A5	1	40.00	40.00 ✓
✓	T52161-16010 ROC ALL MODEL	BUMPER CLIP	CG C14-A1-6B1	10	1.50	15.00 ✓

SUB-TOTAL : 95.00  
ADD GST 7.00 % 6.65

E & OE TOTAL AMOUNT SGD : 101.65

[P] 08/11/2019 15:47:55

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[S] 08/11/2019 3:41:06PM

JAE Auto Pte. Ltd.

Sales Executive: LOON

This is computer generated document.  
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:  
48A SUNGEI KADUT AVE SINGAPORE 729672  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg  
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WIDEVUE CLASS  
Dept Direct 8417 9791 / 8148 0029



Wiper blade: NWB (Nippon Wiper blade), Sliper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD  
BLOCK 3022A #01-45/46  
UBI ROAD 1  
BUTTION 92712711  
SINGAPORE 408716  
TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY  
ATTN : WENDY

TP 5741

TAX INVOICE : AR201911-08551  
DATE : 18/11/2019  
CUSTOMER ID : PRO005  
VEH REG. NO. : SDS839A  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 1 of 1  
CURR. : SGD

STOCK ID	DESCRIPTION	Stk	QTY	U/PRICE	AMOUNT
T58307-58038 VELL-ATH20	HND PANEL	13-J1-5A	1	320.00	320.00

SUB-TOTAL : 320.00  
ADDD GST 7.00 % 22.40

E. & D.E TOTAL AMOUNT SGD : 342.40

[P] 18/11/2019 12:43:40  
Goods Sold are not refundable for Cash.  
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 18/11/2019 12:39:21PM

JAE Auto Pte. Ltd.  
Sales Executive: HAO



This is computer generated document.  
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:  
48A SUNGEI KADUT AVE SINGAPORE 729572  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg  
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS  
Dept Direct: 6417 9781 / 6745 0821

Jurango by

Letter

JAM



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD  
BLOCK 3022A #01-45/46  
UBI ROAD 1  
BUTTON 92712711  
SINGAPORE 408716  
TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY  
ATTN : WENDY

TP 5741

TAX INVOICE : AR201911-04305  
DATE : 08/11/2019  
CUSTOMER ID : PRO005  
VEH REG. NO. : SDS839A  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 1 of 1  
CURR. : SGD

STOCK ID	DESCRIPTION	UNIT	QTY	U/PRICE	AMOUNT
T52119-58935 ✓ VELL-GGH20	FRT BUMPER 12" Z/G	SG AA4-8	1	300.00	300.00

SUB-TOTAL : 300.00  
ADD GST 7.00 % 21.00

E & OE TOTAL AMOUNT SGD : 321.00

[P] 08/11/2019 15:54:54

[B] 08/11/2019 3:49:51PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.  
Sales Executive: LOON



This is computer generated document.  
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67458833 FAX: 67454442, 67450618 (Account)

WAREHOUSE:  
80 JALAN LAM HUAT #B1-05/06 GARROS CENTRE  
SINGAPORE 737869 TEL: 63625226 FAX: 63625977

Email: jaeauto@paciflc.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Wiper blade: NWB (Nippon Wiper blade), Gilper ( Made in Korea ),  
Forch ( Made in Germany )  
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD  
BLOCK 3022A #01-45/46  
UBI ROAD 1  
BUENON 92/127/11  
SINGAPORE 408716  
TEL: 67415336 FAX: 67417208 EIEY / 68444802 WENDY  
ATTN: WENDY

(P. 574)

TAX INVOICE : AR201911-09579  
DATE : 19/11/2019  
CUSTOMER ID : PRO005  
VEH REG. NO. : SDS839A  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 1 of 1  
CURR. : SGD

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T53879-28030	RETAINER,FRONT FENDER LINER	UI	1	5.00	5.00
ACRSO		SUPPLIER			

SUB-TOTAL : 5.00  
ADD GST 7.00 % 0.35  
TOTAL AMOUNT SGD : 5.35

[F] 19/11/2019 4:31:11PM  
\*Goods Sold are not refundable for Cash.  
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 19/11/2019 4:30:39PM

JAE Auto Pte. Ltd.  
Sales Executive : LOON



This is computer generated document.  
No signature is required.

Goods Received in Good Order

Signature / Stamp / Date

ORIGINAL



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 301B UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:


60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE  
SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0110201-3 CO. REG. NO.: 100307741M



Arrange By \_\_\_\_\_ Driver \_\_\_\_\_



Wiper blade: NWB (Nippon Wiper blade), Silliper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

AGGRESSIVE AUTOMOTIVE PTE LTD (DO)  
CK 3021A #01-43 UBI RD 1

TP 5741

8716  
: 67415336, 67417208 LILY FAX : 68444802 W  
EN.: WENDY 82585595

TAX INVOICE : AR201911-09208  
DATE : 19/11/2019  
CUSTOMER ID : PRO005DO  
VEH REG. NO. : SDS839A  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 1 of 1  
CURR. : SS

STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
T75819-33010 ACV31	RR BOOT GARISH CLIP	U1 L2-M47-C	4	2.50	10.00 ✓

SUB-TOTAL : 10.00  
ADD GST 7.00 % .70

E. & O.R TOTAL AMOUNT S\$: 10.70

19/11/2019 11:43:21

[E] 19/11/2019 11:33:06AM

Goods Sold are not refundable for Cash.  
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Executive: HAO

This is computer generated document.  
Signature is required.



Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Tuesday, 4 February 2020 5:41 PM  
**To:** Ray; SUR  
**Subject:** RE: SDS839A - TO FINALIZE

Dear Ray,

Noted with thanks.

**Kindly send Final invoice and all supporting documents directly to ECICS INSURANCE**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ray <ray@procarcare.com.sg>  
**Sent:** Tuesday, 4 February 2020 9:59 AM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Subject:** RE: SDS839A - TO FINALIZE

Hi Veron,

Amount confirm, thank you.

Regards,

**Ray Lin**

Damage Assessment

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

T: +65 6741 5336 | F: +65 6741 7208

E: [claims@procarcare.com.sg](mailto:claims@procarcare.com.sg)

W: [www.procarcare.com.sg](http://www.procarcare.com.sg)



**IMPORTANT NOTICE:** The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof.

**From:** Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]  
**Sent:** Monday, February 03, 2020 4:18 PM  
**To:** Ray; Wendy; SUR  
**Cc:** Wayne; Pelwen; Chermaine  
**Subject:** RE: SDS839A - TO FINALIZE

Dear Ray,

WITHOUT PREJUDICE

As spoken with Ms Wendy this afternoon, Rear boot reflector-LH cancel.

Finalize amount \$4616 before GST @ 6 working days.

Please check and confirm.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :[sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Ray <[ray@procarcare.com.sg](mailto:ray@procarcare.com.sg)>  
**Sent:** Tuesday, 14 January 2020 9:43 AM  
**To:** Wendy <[wendy@procarcare.com.sg](mailto:wendy@procarcare.com.sg)>  
**Cc:** Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>  
**Subject:** FW: SDS839A - TO FINALIZE

Hi Wendy,

Refer to email as below, please assist to send photo to Veron, thank you.

Regards,

**Ray Lin**

Damage Assessment

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

T: +65 6741 5336 | F: +65 6741 7208

E: [claims@procarcare.com.sg](mailto:claims@procarcare.com.sg)

W: [www.procarcare.com.sg](http://www.procarcare.com.sg)



**IMPORTANT NOTICE:** The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof.

**From:** Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]  
**Sent:** Tuesday, January 14, 2020 9:09 AM  
**To:** Ray  
**Subject:** FW: SDS839A - TO FINALIZE

Dear Ray,

Please provides photo for rear boot reflector-LH

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :[sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Ray <[ray@procarcare.com.sg](mailto:ray@procarcare.com.sg)>  
**Sent:** Monday, 13 January 2020 11:40 AM  
**To:** Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>  
**Cc:** Adrian Ling (LKKAuto) <[adrianling@lkkauto.com](mailto:adrianling@lkkauto.com)>  
**Subject:** FW: SDS839A - TO FINALIZE

Hi Veron,

Please see attached

Regards,

**Ray Lin**

Damage Assessment

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

T: +65 6741 5336 | F: +65 6741 7208

E: [claims@procarcare.com.sg](mailto:claims@procarcare.com.sg)

W: [www.procarcare.com.sg](http://www.procarcare.com.sg)



**IMPORTANT NOTICE:** The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof.

**From:** Ray  
**Sent:** Friday, December 20, 2019 3:19 PM  
**To:** Adrian Ling (LKKAuto)  
**Cc:** Wayne; Peiwen; Chermaine  
**Subject:** SDS839A - TO FINALIZE

Hi Adrian,

\* Please refer to finalize  
Total amount is \$4803.00

Regards,

**Ray Lin**

Damage Assessment

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

T: +65 6741 5336 | F: +65 6741 7208

E: [claims@procarcare.com.sg](mailto:claims@procarcare.com.sg)

W: [www.procarcare.com.sg](http://www.procarcare.com.sg)



**IMPORTANT NOTICE:** The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof.

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Midnight Accident

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Feb 2020 12:20 <a href="#">Edit Reg</a>		07 Nov 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$4,616.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,616.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>0</b> , Co. Reg. No.: 0, Email: email@email.com									
Main Claimant: <b>HO YEW SIONG</b> , ID: S16647732									
Vehicle Reg. No.: <b>SDS839A</b>		Date of Loss: 03/11/2019 00:00 - :59 [55 Months and 7 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP</b>		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): <b>SLR3612C</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Progressive Car Care Pte Ltd (HQ)</b> Blk 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336									
Handling Insurer: <b>ECICS Limited (HQ)</b> - Tel: 63374779 /6303 0178									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... [Final Rpt due 18/11/2019]									
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a> <a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

**\*SDS839A**  
**[SLR3612C]**  
**TP**  
**HO YEW SIONG**  
**Nov 3 2019 12:00AM**  
**[0]**  
**Progressive Car Care Pte Ltd**

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			View <input type="button" value="View in Browser"/>
<b>Photos/Images</b>			3 per page <input type="button" value=""/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="button" value="Print"/>
1	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
2	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
3	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
4	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
5	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
6	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
7	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
8	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
9	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
10	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
11	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
12	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
13	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
14	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
15	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
16	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
17	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
18	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
19	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
20	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
21	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
22	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
23	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
24	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
25	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
26	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
27	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
28	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
29	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
30	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
31	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
32	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
33	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
34	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
35	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
36	04/02/20 17:43	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
37	04/02/20 17:46	Reinspection Photo	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	04/02/20 17:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	04/02/20 17:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	04/02/20 17:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	04/02/20 17:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	04/02/20 17:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	04/02/20 17:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	04/02/20 17:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	04/02/20 17:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	04/02/20 17:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	04/02/20 17:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	04/02/20 17:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	04/02/20 17:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	04/02/20 17:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	04/02/20 17:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	04/02/20 17:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	04/02/20 17:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	04/02/20 17:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	04/02/20 17:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	04/02/20 17:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/02/20 14:06	Supplementary	 Load PDF	
2	05/02/20 14:06	Parts Invoice	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/ICS19019758/AVD3E2  
**Date:** 05/02/2020

#### REFERENCE

Handling Insurer: ECICS Limited	Policy No:		
<b>Claimant Vehicle No :</b> SDS839A	<b>Insured Vehicle No :</b>	SLR3612C	
Date of Loss: 03/11/2019	Nature of Claim:	TP	Claim No: N/A

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SDS839A</b>		
Make & Model:	HONDA CR-V, 1.5 (A)	Engine No:	2AZG444066
Reg. Date:	27/03/2015 (Man. Year: 2014)	Chassis No:	ANH208346738
Colour:	White	Odometer:	119348 km
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,450.16	2,416.00	4,034.16	62.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,450.00	2,200.00	1,250.00	36.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,900.16</b>	<b>4,616.00</b>	<b>5,284.16</b>	<b>53.37</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>693.01</b>	<b>323.12</b>	<b>369.89</b>	<b>53.37</b>
<b>Nett Amount (S\$)</b>	<b>10,593.17</b>	<b>4,939.12</b>	<b>5,654.05</b>	<b>53.37</b>

#### INSPECTION

Date of Assignment:	07/11/2019		
Date Inspected:	08/11/2019	Inspected At:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	6.0 days		

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b>	(Last Synchronised: 05 Feb 2020)
<b>Parts:</b>	N/A HONDA CR-V 1.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's (Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SDS839A)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PARKING CAMERA	Not Necessary	350.00 FS	*- FS
2	1		*FRONT NUMBER PLATE WITH CASING	Bent	35.00 FS	*35.00 FS
3	1		*SPONGE TAPE	Necessary	20.00 FS	*20.00 FS
4	2		*SEALANT	Necessary	40.00 FS	*40.00 FS
5	1		*REAR BOOT	Distorted	700.00 F	*700.00 F
6	1		*REAR BOOT REFLECTOR - LH	Not Necessary	170.00 F	*- F
7	1		*REAR BOOT REFLECTOR - RH	Not Necessary	170.00 F	*- F
8	1		*REAR BOOT TOP LOCK	Not Necessary	170.00 F	*- F
9	1		*REAR BOOT BOTTOM LOCK	Not Necessary	28.00 F	*- F
10	1		*REAR BOOT RUBBER	Cut	140.00 F	*140.00 F
11	1		*REAR BOOT VELLFIRE WORDING	Necessary	45.00 F	*45.00 F
12	1		*REAR BOOT OUTER LOWER CHROME	Not Necessary	680.00 F	*- F
13	1		*REAR BOOT KEYLESS SENSOR	Not Necessary	100.00 F	*- F
14	1		*REAR BUMPER	Deformed	350.00 F	*350.00 F
15	10		*REAR BUMPER CLIPS	Necessary	25.00 F	*25.00 F
16	1		*REAR BUMPER SIDE HOLDER - LH	Necessary	40.00 F	*40.00 F
17	1		*REAR BUMPER SIDE HOLDER - RH	Necessary	40.00 F	*40.00 F
18	1		*REAR BUMPER END PANEL BRACKET - RH	Not Necessary	70.00 F	*- F
19	1		*REAR BUMPER END PANEL BRACKET - LH	Not Necessary	70.00 F	*- F
20	4		*REAR BUMPER SENSOR	Not Necessary	640.00 F	*- F
21	1		*REAR BUMPER SENSOR COVER - OUTER	Not Necessary	15.00 F	*- F
22	1		*REAR BUMPER SENSOR WIRE	Not Necessary	200.00 F	*- F
23	1		*REAR BUMPER REFLECTORS - LH	Not Necessary	28.00 F	*- F
24	1		*REAR BUMPER REFLECTORS - RH	Not Necessary	28.00 F	*- F
25	1		*REAR BUMPER TOW COVER - LH	Not Necessary	35.00 F	*- F
26	1		*REAR BUMPER TOW COVER - RH	Not Necessary	35.00 F	*- F
27	1		*REAR PANEL - INNER / OUTER	Dented	360.00 F	*320.00 F
28	1		*REAR PANEL TOP GARNISH	Not Necessary	110.00 F	*- F
29	1		*TAILLAMP ASSY - RH	Not Necessary	210.00 F	*- F
30	1		*TAILLAMP LOWER GARNISH - RH	Not Necessary	50.00 F	*- F
31	1		*FRONT BUMPER	Deformed	300.00 F	*300.00 F
32	10		*FRONT BUMPER CLIPS	Necessary	15.00 F	*15.00 F
33	1		*FRONT BUMPER SIDE HOLDER - LH	Not Necessary	40.00 F	*- F
34	1		*FRONT BUMPER SIDE HOLDER - RH	Not Necessary	40.00 F	*- F
35	1		*FRONT BUMPER CENTRE LOWER GRILLE	Deformed	85.00 F	*85.00 F
36	1		*FRONT BUMPER PARKING SENSOR	Not Necessary	190.24 F	*- F
37	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	180.00 F	*- F
38	1		*FRONT BUMPER FOAM	Not Necessary	50.00 F	*- F
39	1		*RETAINER FRONT FENDER LINER	Necessary	5.00 F	*5.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
40	1		*REAR BOOT GOLDEN EYES II WORDING	Necessary	45.00 F	*45.00 F	
					<b>Sub Total (\$\$)</b>	<b>5,904.24</b>	<b>2,205.00</b>
					<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	<b>545.92</b>	<b>211.00</b>
					<b>Total Parts (\$\$)</b>	<b>6,450.16</b>	<b>2,416.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, REMOVE / REPLACE FRONT BUMPER, REAR BUMPER AND REMOVE, REPLACE ACCIDENT PARTS	New	1,200.00	1,000.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,400.00	800.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE, REFIT REAR GARNISH	New	150.00	60.00
5	TO TUFF-KOTE	New	120.00	60.00
6	TO TRANSFER REAR BUMPER SENSOR	New	100.00	50.00
7	TO TRANSFER FRONT BUMPER SENSOR	New	100.00	50.00
8	TO RESET CHECK LIGHT	New	60.00	30.00
9	TO REMOVE, REFIT REAR BOOT GLASS	New	150.00	120.00
10	TO REMOVE, REPAIR REAR EXHAUST PIPE	New	120.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,450.00</b>	<b>2,200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >