



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 08.11.2019

China Taiping Insurance (S) Pte Ltd
2 Anson Road #16-00
Springleaf Tower
Singapore 079909

Attn: Motor Claims Dept

RE: ESTIMATE REPAIR COST TO SHD2649A TOYOTA CAMRY HYBRID 2.5G CVT (2019

To Supply

1) 1pc	rear bumper cover / <i>DD</i>	\$	1,273.50
2) 1pc	rear bumper lower cover / <i>CNT</i>	\$	366.58
3) 1pc	rear bumper reinforcement / <i>DD</i>	\$	202.84
4) 1pc	rear bumper center pad <i>X</i>	\$	1,539.00
5) 1pc	rear boot lid / <i>DD</i>	\$	1,130.69
6) 1pc	rear boot lid weatherstrip / <i>TN</i>	\$	174.83
7) 1pc	rear boot lid right cover <i>X</i>	\$	42.10
8) 1pc	rear boot lid left cover <i>X</i>	\$	42.10
9) 1pc	rear boot lid cushion 64459-33030 <i>X</i>	\$	20.70
10) 1pc	rear boot lid lock / <i>BT</i>	\$	365.78
11) 1pc	rear boot lid stricker <i>X</i>	\$	41.70
12) 1pc	rear boot lid "Toyota" emblem / <i>MC</i>	\$	68.00
13) 1pc	rear boot lid "Hybrid Synergy" emblem / <i>MC</i>	\$	55.00
14) 1pc	right rear tail lamp cover / <i>CNT</i>	\$	33.27
15) 1pc	left rear tail lamp cover / <i>CNT</i>	\$	33.27
16) 1pc	rear end panel / <i>DD</i>	\$	542.37
17) 1pc	rear end panel garnish 58387-33140-C0 / <i>CR4</i>	\$	280.22
18) 1pc	luggage compartment door stricker cover 64749-33030-C0 / <i>CR4</i>	\$	25.70
19) 1pc	rear floor pan <i>X R</i>	\$	949.43
20) 1pc	spare wheel cover 64770-33140-C1 / <i>CR4 (Top M)</i>	\$	467.51
21) 1pc	spare wheel cover tray 64779-33260 / <i>CR4</i>	\$	457.40
22) 1pc	inner boot lid trim pad 64727-33060 <i>X</i>	\$	184.40
23) 1pc	left rear under side cover 76974-33020-C0 <i>?</i>	\$	220.70
24) 1pc	rear under cover 76971-33020 <i>?</i>	\$	295.00
25) 1pc	right rear under side cover 76973-33020-C0 <i>?</i>	\$	220.70

Steve CLKK) *(wrt Net) 7/11/19, 5.09pm*
8322 8813
5 day
Steve chng 1kkamb.com
P/P
RJ AL SM

26) 1pc	exhaust tail pipe baffle / CHT	\$	199.80
27) 1pc	electrical key antenna X	\$	145.70

Sub total parts	\$	9,378.29
Less: 25% discount	\$	(2,344.57)
	\$	7,033.72

To Supply S.Nett parts

1) 1set	reverse sensor / SL	\$ 200	300.00
2) 1set	floor pan sealant / M	\$ 30	120.00
3) 1set	rear bumper clip / MC	\$	30.00
4) 1pc	rear no plate / BR	\$	38.00
5) 1pc	"Prime Taxi" sticker / MC	\$	55.00
6) 1pc	"Prime Limousine" sticker / MC	\$	35.00

Sub total S.Nett Parts	\$	578.00
------------------------	----	--------

L/charges

1) Towing charges (use king-trolley) / (bill)	\$	100.00
2) To tuff kote	\$ 40	80.00
3) To remove & replace reverse sensor & electrical key antenna, check wiring	\$ 3050	150.00
4) To transfer rear boot lid trim board & mechanism parts	\$ 50	60.00
5) To remove rear bumper, rear boot lid, cut / welding end panel, floor pan & replace the above parts. Adjust & align rear bumper & rear boot lid	\$ 900	1,000.00
6) To putty, respray painting rear bumper, rear boot lid inlet & outer, end panel, floor panel. To polish	\$ 800	1,000.00

Sub total L/charges	\$	2,390.00
Estimated total	\$	10,001.72

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: