

ASS. REC. BY:

REF: es/ICS19019773/Kt03n2 Special Instruction:Singer: KennethASSIGNMENT (Office)From (Person): Elizabeth Chew of ICS Date/Time: 7/11/19 @ 4:10pm

Estimated Cost: _____ Bill to: _____

OD FD / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLW 4170C Insured: SLT 4013Sat Workshop m/s: St H Motor Tel: 6453 4730of 160 Sin Ming Drive # 07-02Policy No: _____ Claim No: DMPC19002844

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 21/11/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 4:37pm @ 7/11/19 Person Contacted: Cynthia Vehicle IN OUT

Date/Time	Action/Instruction
	<u>SLW 4170C-X</u>
	<u>SLT 4013S-X</u>
<u>22/11</u>	<u>61 Pm @ 535d email & confirmed</u> <u>(Red: 3108.90; 36%)</u>

ASS. FILE BY

REF: JCS

ASSIGNMENT

From

Date

8/11/19

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLW 4170C

at Workshop m/s

S & H Motor

of

160 Sin Ming Drive # 07-02

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

After 1pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res:

Yes or No

Lum Sum:

1-B, %

3 Val:

Yes or No

CA / REV / REP. / 24 HRS (up)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLW 4170C (Reg):

02 18

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Opel Insignia Turbo D 1518

Colour:

M. L. Blue

A/C: Insured / Std / NI / NA

Sp Reading:

4747

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

W0V8M8EPXJ1069131

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

245/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

1 Hankook

Front

R/Bal.

7 mm

Rear

R/Bal.

7 mm

L/Bal.

7 mm

L/Bal.

7 mm

D.O.A.

2/11/19

D.O.I.

8/11/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rn body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 20 NOV 2019

Date/Time, File Pass to?



Prel. Report



Final Report

Dell Typist

Date/Time, File Pass to?

31

Days Of Repair: 5

Resurvey No. of Trip: -

Add Fee:



Site Insp \$



Interview \$



Tech. Insp \$



Misc. exp \$

Survey Fee:

Transportation:

250

S - RS - 34

11

Taxes:

Other:

TOTAL

261

Report Form#:

TP

Emp: 511 / 12345

5350

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: suri@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 26 Nov 2019

Preliminary Advice

Insured Vehicle No	: SLJ4013S	Accident Date	: 02/11/2019
TP Vehicle No	: SLW4170C	Assignment Date	: 07/11/2019
Make	: HONDA CIVIC	Est. Duration of Repair	: 5.00
Date of Inspection	: 08/11/2019		
Inspection At	: S&H MOTOR PTE LTD (HQ) BLK 11#01-83 SIN MING ROAD, SIN MING INDUSTRIAL ESTATE SINGAPORE 575655		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages N/S front body portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,458.90
Revised Amount	:S\$	6,722.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,722.20
Lump Sum Repair	:S\$	5,350.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : survey on wp

Nivitha (LKK Auto)

From: Elizabeth Chew Ming Lai (ECICS, Claims) <Elizabeth_Chew@ecics.com.sg>
Sent: Thursday, 7 November 2019 4:10 PM
To: Enquiry
Cc: Admin-D (LKKAuto); SUR; assignments
Subject: RE: Accident involving our vehicle no : SLW4170C claiming TP vehicle no : SLJ4013S D.O.A. 02/11/2019 ECICS REF: DMPC1900281H
Attachments: VID-20191102-WA0008.mp4

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Ms Wong,

We refer to the above matter.

Without prejudice to any other related claims we agree to have a direct settlement with your company on behalf of our insured, subject to our surveyor's recommendation on costs of repair and number of days for LOU/LOR. As for quantum on the LOU/LOR we follow the NIMA Protocol Benchmark.

Kindly forward us all the supporting document to enable us to consider your client's claim.

Aside to LKK, please refer to the below email and conduct PRI.

We shall forward the documents to you shortly.

Best regards

Elizabeth Chew

AVP | Claims



DID (65) 6303 0182

Tel (65) 6337 4779

Email elizabeth_chew@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunus Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Enquiry [mailto:enquiry@sh-motor.com]
Sent: Thursday, 7 November 2019 10:44 AM
To: Elizabeth Chew Ming Lai (ECICS, Claims)
Subject: Accident involving our vehicle no : SLW4170C claiming TP vehicle no : SLJ4013S D.O.A. 02/11/2019

Dear Elizabeth,

As per requested, pls see attached video footage for your perusal.

Thanks & Best Regards,

Ms Wong
S&H MOTOR PTE LTD

160 Sin Ming Drive #07-02
Sin Ming AutoCity
Singapore 575722
Tel: 6453 4730 Fax: 6457 1931

From: Wong [mailto:wong@sh-motor.com]
Sent: Wednesday, 6 November 2019 10:06 AM
To: 'elizabeth_chew@ecics.com.sg'
Subject: Accident involving our vehicle no : SLW4170C claiming TP vehicle no : SLJ4013S D.O.A. 02/11/2019

Dear Elizabeth,

Kindly check whether did your Insured make any report and what is the status of liability?

Thanks & Best Regards,

Ms Wong
S&H MOTOR PTE LTD
160 Sin Ming Drive #07-02
Sin Ming AutoCity
Singapore 575722
Tel: 6453 4730 Fax: 6457 1931

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	507F
Vehicle Details	
Vehicle No.:	SLW4170C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Nov 2019
Vehicle Make:	OPEL
Vehicle Model:	INSIGNIA GRANDSPORT B16DTH
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	A2172858GKCX0404
Chassis No.:	W0VZM6EFXJ1069131
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$26,980.00
Original Registration Date:	09 Feb 2018
First Registration Date:	09 Feb 2018
Transfer Count:	1
Actual ARF Paid:	\$29,772.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Feb 2028
PARF Rebate Amount:	\$22,329.00
Intended COE Rebate Details	
COE Expiry Date:	08 Feb 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$44,000.00
COE Rebate Amount:	\$34,128.00
Total Rebate Amount:	\$56,457.00

The information contained herein is correct as at 04 Nov 2019

OK

TEO TAT YONG
BLK 130A #19-510
LORONG 1 TOA PAYOH
SINGAPORE 311130

File No :
Date : 07-November-2019

Estimated cost of repair for vehicle no: **SLW4170C OPEL**
Accident involving vehicle no: **SLW4170C & SLJ4013S on 02-November-2019**

Description	Quantity	List Price
Lh front fender	1	\$ <i>As</i> 895.00 ✓
LH front fender signal lamp	1	\$ <i>Sur</i> 175.00 ✓
LH front fender wheel cowling	1	\$ <i>Or</i> 185.00 ✓
LH front fender wheel cowling clips	1	\$ <i>As</i> 35.00 ✓
Front bumper	1	\$ <i>As</i> 1,795.00 ✓
LH bumper retainer	1	\$ <i>Or</i> 180.00 ✓
LH head lamp	1	\$ <i>Sur</i> 1,250.00 ✓
LH front bumper parking sensor	1	\$ <i>As</i> 380.00 X
LH alloy wheel (to-check)	1	\$ <i>As</i> 850.00 ✓
LH wheel bearing (to-check)	1	\$ <i>As</i> 890.00 ✓
LH knuckle arm (to-check)	1	\$ <i>Sur</i> 800.00 X
LH front bumper bottom rubber	1	\$ <i>As</i> 198.00 X
Wheel cowling and garnish clips @ set	1	\$ <i>As</i> 33.00 ✓
Front LH door front rubber (to-check)	1	\$ <i>Sur</i> 285.00 X
		\$ 7,951.00
	Less 10%	\$ 795.10
		\$ 7,155.90
Labour to panel beating LH front door and respray damaged areas.	1	\$ 350.00 ✓
To spray painting front bumper, LH front fender and bonnet, and accident damaged areas.	1	\$ 650.00 <i>bon</i>
To check and reset front wheel and steering alignment.	1	\$ 65.00 ✓
Labour to check LH front suspension, to remove, install and repair front knuckle, front wheel bearing.	1	\$ 220.00 <i>3d</i>
To remove and reinstall LH front tyre.	1	\$ 18.00 ✓
		\$ 8,458.90

T/Party: ECICS LIMITED

Not Authorize
Penalty B4 point
5 days
11 Nov @ 5350h

LKK Auto Consultants hence notify the Repairer of the following:

- To survey (estimate) spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Work(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature
Date

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS19019773/KTD3N2

Date: 28/11/2019

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SLW4170C	Insured Vehicle No :	SLJ4013S
Date of Loss:	02/11/2019	Nature of Claim:	TP
		Claim No:	DMPC1900281H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW4170C		
Make & Model:	OPEL INSIGNIA GRANDSPORT B16DTH, 1.6 Turbo (A)	Engine No:	A2172858GKCX0404
Reg. Date:	09/02/2018 (Man. Year: 2017)	Chassis No:	W0VZM6EFXJ1069131
Colour:	Metallic Light Blue	Odometer:	47471 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45R18	Rear Tyre Size:	245/45R18
Front Left Side:	Hankook 7 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 7 mm	Rear Right Side:	Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,155.90	5,659.20	1,496.70	20.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,303.00	1,063.00	240.00	18.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,458.90	6,722.20	1,736.70	20.53
Approved Total (Overridden) (\$\$)		5,350.00		
(\$\$)	8,458.90	5,350.00	3,108.90	36.75
+ GST 7.00/7.00% (\$\$)	592.12	374.50	217.62	36.75
Nett Amount (\$\$)	9,051.02	5,724.50	3,326.52	36.75

INSPECTION

Date of Assignment:	07/11/2019		
Date Inspected:	08/11/2019	Inspected At:	S & H MOTOR PTE LTD 160 SIN MING DRIVE #07-02 SIN MING AUTOCITY SINGAPORE 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Nov 2019)
Parts:	143	OPEL INSIGNIA GRANDSPORT B16DTH 1.6 Turbo (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW4170C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH FRONT FENDER	Bent	895.00 FL	*895.00 FL
2	1		*LH FRONT FENDER SIGNAL LAMP	Scratched	175.00 FL	*175.00 FL
3	1		*LH FRONT FENDER WHEEL COWLING	Distorted	185.00 FL	*185.00 FL
4	1		*LH FRONT FENDER WHEEL COWLING CLIPS	Necessary	35.00 FL	*35.00 FL
5	1		*FRONT BUMPER	Buckled	1,795.00 FL	*1,795.00 FL
6	1		*LH BUMPER RETAINER	Distorted	180.00 FL	*180.00 FL
7	1		*LH HEAD LAMP	Cut	1,250.00 FL	*1,250.00 FL
8	1		*LH FRONT BUMPER PARKING SENSOR	Serviceable	380.00 FL	*- FL
9	1		*LH ALLOY WHEEL	Dented	850.00 FL	*850.00 FL
10	1		*LH WHEEL BEARING	Bent/Jammed	890.00 FL	*890.00 FL
11	1		*LH KNUCKLE ARM	Serviceable	800.00 FL	*- FL
12	1		*LH FRONT BUMPER BOTTOM RUBBER	Serviceable	198.00 FL	*- FL
13	1		*SET WHEEL COWLING AND GARNISH CLIPS	Necessary	33.00 FL	*33.00 FL
14	1		*FRONT LH DOOR FRONT RUBBER	Serviceable	285.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	7,951.00	6,288.00
- List Item Discount on L Items 10.00/10.00% (S\$)	795.10	628.80
Total Parts (S\$)	7,155.90	5,659.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO PANEL BEATING LH FRONT DOOR AND RESPRAY DAMAGED AREAS	New	350.00	350.00
2	TO SPRAY PAINTING FRONT BUMPER,LH FRONT FENDER AND BONNET,AND ACCIDENT DAMAGED AREAS	New	650.00	600.00
3	TO CHECK AND RESET FRONT WHEEL AND STEERING ALIGNMENT	New	65.00	65.00
4	LABOUR TO CHECK LH FRONT SUSPENSION,TO REMOVE,INSTALL AND REPAIR FRONT KNUCKLE,FRONT WHEEL BEARING	New	220.00	30.00
5	TO REMOVE AND INSTALL LH FRONT TYRE	New	18.00	18.00
Gross Labour Cost (S\$)			1,303.00	1,063.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >