

Case Details

Case Reference Number : TAX/11/19/2011
Type of Repair : Accident Repair
Vehicle Registration Number : SHD6074G

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-9192-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
Accident Date and Time : 05/11/2019 01:05 AM
Vehicle Age(In Months) : 49

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation					Repair/ Replace	Surveyor Approval				Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace		
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	1	542.55	Replace	✓	DD
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	1	38.92	Replace	✓	MC
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	0	0	Not Give	X	MM
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	0	0	Not Give	X	MM
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	0	0	Not Give	X	MM
One Time Key In	Main			QUARTER GLASS FRT/LH	1	234.90	234.90	25.00	176.18	0	0	Not Give	X	MM
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	0	0	Not Give	X	MM
One Time Key In	Main			DOOR FRT/LH	1	894.40	894.40	25.00	670.80	1	670.80	Replace	✓	DD
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	1	60.00	Replace	✓	MC
One Time Key In	Main			HINGE UPPER LHF, DOOR	1	80.50	80.50	25.00	60.38	0	0	Not Give	X	MM

Total Spare Part Cost 4,080.06

Surveyor Total 1,312.27

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 3,264.05

Final Sur Total 1,049.82

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			HINGE LOWER LHF, DOOR	1	90.10	90.10	25.00	67.57	Replace	0	0	Not Give	X NM
One Time Key In	Main			MIRROR ASSY, LH	1	1,224.90	1,224.90	25.00	918.68	Replace	0	0	Not Give	X NM
One Time Key In	Main			COVER, OUTER MIRROR, LH	1	107.40	107.40	25.00	80.55	Replace	0	0	Not Give	X NM
One Time Key In	Main			MIRROR LAMP LH	1	65.30	65.30	10.00	58.77	Replace	0	0	Not Give	X NM
Total Spare Part Cost									4,080.06	Surveyor Total				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)				
										20				
Final Spare Part Cost									3,264.05	Final Sur Total				
										1,312.27				
										1,049.82				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH PORTION	676.00	400	
Total:			676.00	400.00	

Spray Cost Detail


S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
2	Main	TO RESPRAY FRONT DOOR LH	378.00	200	
3	Main	TO RESPRAY VIEW MIRROR	180.00	0	
4	Main	TO RESPRAY RIM	180.00	0	
Total:			1,116.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	NK
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	NK
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
Total:			1,094.88	329.88	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
4	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
5	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0	
6	Main	TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	120.00	0	
7	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	269.88	269.88	OK
8	Main	TO REPLACE SUNDRY PARTS	100.00	20	OK
9	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,094.88	329.88	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare,Part Detail	3,264.05	1,049.82
Total Labour Cost	676.00	400.00
Total Spray Painting	1,116.00	400.00
Other	1,094.88	329.88
Overall Total	6,150.93	2,179.70
Lump Sum Repair Option		☒
Lump Sum Total	6,150.00	2,200.00
Surveyor Approved Amount		2,200.00
No of Repair Days*	5	3
Remarks		L/S repair, take after spray
Surveyor Name		STEVE CHEN
Signature		
Survey Date	06/11/2019	

Save Clear

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: