

Date: 06/11/2019

To: AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way #07-16
Singapore 079120

Estimate Cost Of Repair For Toyota Estima Hybrid 2.4X A (SFJ9688H)

To supply the following parts:

		Amount
1	Rear Bumper Assy X R	\$ 2,560.56 X
2	Rear Bumper Retainer / BR	\$ 86.50 ✓
3	Rear Bumper clip 12pcs @2.60 X SVC	\$ 31.20 X 86.56
Sub Total		\$ 2,678.26
Less 10%		\$ 267.83
Total on Parts		<u>\$ 2,410.43</u> 77.85

Labour Charges:

1	Being remove and replace new Bumper	\$ 400.00 250
2	Being plastic primer coat on the bumper and painting on replacing and repair parts	\$ 800.00 500

Repair day - 2 days

Total on Labour \$ 1,200.00

Total Repair Cost \$ 3,610.43

Prepare By



Pang Tian Hook

$$\begin{array}{r}
 P = 77.85 \\
 L = 750 \\
 \hline
 827.85
 \end{array}$$

PIP
\$827.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: