

ASS. REC. BY:

REF: CS/CT1 19019835/K9f3ST

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Alfred Toh

of

CT2

Date/Time: 8.11.19 14.18 p.m.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SML 3282R

Insured:

at Workshop m/s

Lai Hual

Tel:

64539110

of 160 Sen Ming Drx #04-01

Policy No: DMPGA 304191900

Claim No:

SNM190 25293

Sum Insured:

Excess:

#0

Make of Veh:

D.O.A.

6.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time:

8.11.19 2.42 p.m.

Person Contacted:

Jenny

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SML 3282R - x

08/11/19 @ 4.28pm revert to Alfred Toh via messenger.

11/11/19 @ 10:16am inform by Boon Sen authorise repair

11/11/19 @ 11:25am inform Jenny authorise repair excess #0

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Nov 2019 Sendback Est	08 Nov 2019 11:16 S\$4,523.28	08 Nov 2019 14:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	TEO CHIN CHAI (ZHANG JINCAI), ID: S8133107C, Tel: +6590686133, Email: kelvinteocc@gmail.com								
Vehicle Reg. No.:	SML3282R	Date of Loss:	06/11/2019 11:00 - :59 [101 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D205293-SML3282R-CBS	Policy/Cover Note No.:	DMPCSN3041191900 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Alfred Toh - 6389 6183]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/11/2019]								
Driver/Custodian:	TEO CHIN CHAI (ZHANG JINCAI) (38 / Male), NRIC: S8133107C, Tel: +6590686133 Email: kelvinteocc@gmail.com								
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
View All Compose Case Mail									
ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

SML3282R (SNM19D205293-SML3282R-CBS)

OD

Nov 6 2019 11:00AM

[TEO CHIN CHAI (ZHANG JINCAI)]

Lai Huat (Meng Kee) Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 11/11/2019 10:16 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4523.28) - SML3282R - Claim Handler: Alfred Toh

Approved:4523.28.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Alfred Toh

Date: 08 Nov 2019

Preliminary Advice

Vehicle No	: SML3282R	Accident Date	: 06/11/2019
Make	: BMW 523I	Policy No.	: DMPCSN3041191900
Assignment Date	: 08/11/2019	Excess	: S\$0.00
Date of Inspection	: 08/11/2019	Est. Duration of Repair	: 4.00
Inspection At	: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #04-01, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,523.28
Revised Amount	:S\$	3,558.28
Check Items (Estimated)	:S\$	965.00
Total	:S\$	4,523.28

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	48,000.00
COE / PARF Rebate	:S\$	35,940.00
Salvage Value	:S\$	
Margin for Repair	:S\$	12,060.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/11/2019 11:50
Date Of Accident	06/11/2019 11:25
Exact Location Of Accident	OPEN SPACE CAPARK BLK 22 ST GEORGE'S RD LOT 127
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SML3282R
Insured/Policyholder	
Name Of Registered Owner	TEO CHIN CHAI (ZHANG JINCAI)
NRIC No	S8133107C
Email Address	KELVINTEOCC@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90686133
Alternative Phone No	OTHERS-90686133

Vehicle Particulars

Manufacturer	BMW
Model	523I A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3041191900
Cover Note Number	

Driver

Name of Driver	TEO CHIN CHAI (ZHANG JINCAI)
NRIC No	S8133107C
Date Of Birth	21/10/1981
Occupation	OUTDOOR
Date Of Driving Pass	07/01/2003
Driving Experience	16 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90686133
Fax Number	
Contact Number	OTHERS-90686133
Email Address	KELVINTEOCC@GMAIL.COM



Nature Of Damage

No. Of Passenger (Including Driver)



**SINGAPORE
POLICE FORCE**



T/20191106/2104

2 of 3

Police Station Of Origin:
Kolam Ayer NPP
72 Geylang Bahru #01-3038 SINGAPORE
330072
Tel No: 1800-2969999

Report No: T/20191106/2104

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TEO CHIN CHAI	ID No.	S8133107C
Related Vehicle	SML3282R (Car)	Contact No.	90686133
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 06/11/2019 at around 1000hrs, I drove my vehicle bearing licence plate no. SML3282R as I went to send my daughter to school. I then parked my vehicle at Blk 22 Saint Geroge's Road OSCP, Lot No. 127. I then went home. At around 1133hrs, my wife was walking towards my vehicle and saw that there were Police at my vehicle. As such, she gave me a call. There was a vehicle bearing licence plate no. SJT7332Y that collided onto the front right side of my vehicle. My vehicle suffered a slightly dislodged front bumper, broken right head light and dents in the bumper. The driver that collided into my vehicle had already left the scene. His car was still at scene.

As such, I am lodging this report as instructed by the Traffic Police. That is all.

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No.

IMPOS10041121950

Engine No: 10151692051205AF
Chassis No: WAKRF20300054094

1. Index Mark and Registration
Number of Vehicle

2HTJ0825

2. Name of Policy Holder

MR. PEO SENG CHAN (CHANG JINCAI)

3. Effective date of the Commencement of Insurance for
the purposes of the Regulations, Ordinance or Enactment

02 JUNE 2019
11:11 2019
02 JUNE 2020

NAMED DRIVERS EX SECT. 1.....\$51,000.00
IN ADDITION TO NAMED DRIVERS EX:
EX SECT. 1 - AGE < 25.....\$99,000.00
EX SECT. 1 - AGE > 26.....\$5500.00
AGE AS AT DATE OF ACCIDENT
EX ON WINDSCREEN.....\$9100.00

5. Persons or Classes of Persons entitled to drive *

(A) THE POLICYHOLDER.

(B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS PERMISSION.

PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR
REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A
COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATION IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.

6. Limitations as to use: *

USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS.
THE POLICY DOES NOT COVER USE FOR HIRE OR REWARD TUITION DRIVING TEST RACING PACE-MAKING, RELIABILITY
TEST, SPEED-TESTING, THE CARRIAGE OF GOODS OTHER THAN SAMPLES IN CONNECTION WITH ANY TRADE OR BUSINESS
OR USE FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.

EXCESS WHICHEVER IS APPLICABLE FOR LOSSES OCCURRING OUTSIDE SINGAPORE (CONSTRUCTIVE TOTAL LOSS / THEFT)
WILL BE DOUBLED.

ONE TIME WAIVER OF EXCESS FOR THE FIRST \$51,000 WILL APPLY TO THE INSURED AND NAMED DRIVERS IN THE EVENT
OF OWN DAMAGE CLAIM AT OUR AUTHORISED WORKSHOPS FOR EACH POLICY YEAR.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles
(Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia). Please see reverse
For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Countersigned By:

Authorised Officer

Authorised Signatory

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	107C
Vehicle Details	
Vehicle No.:	SML3282R
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Nov 2019
Vehicle Make:	B.M.W.
Vehicle Model:	523I A
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	10407692N52B25AF
Chassis No.:	WBAFP32030C864394
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$49,384.00
Original Registration Date:	03 Jun 2011
First Registration Date:	03 Jun 2011
Transfer Count:	1
Actual ARF Paid:	\$49,384.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Jun 2021
PARF Rebate Amount:	\$27,161.00
Intended COE Rebate Details	
COE Expiry Date:	02 Jun 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$56,490.00
COE Rebate Amount:	\$8,779.00
Total Rebate Amount:	\$35,940.00

The information contained herein is correct as at 08 Nov 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 107C

Vehicle Details

Vehicle No.: SML3282R

Vehicle to be Exported: Yes

Intended Deregistration Date: 07 Nov 2019

Vehicle Make: B.M.W.

Vehicle Model: 523I A

Primary Colour: Black

Manufacturing Year: 2011

Engine No.: 10407692N52B25AF

Chassis No.: WBAFP32030C864394

Maximum Power Output: 150.0 kW (201 bhp)

Open Market Value: \$49,384.00

Original Registration Date: 03 Jun 2011

First Registration Date: 03 Jun 2011

Transfer Count: 1

Actual ARF Paid: \$49,384.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 02 Jun 2021

PARF Rebate Amount: \$27,161.00

Intended COE Rebate Details

COE Expiry Date: 02 Jun 2021

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$56,490.00

COE Rebate Amount: \$8,794.00

Total Rebate Amount: \$35,955.00

The information contained herein is correct as at 07 Nov 2019

OK

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: DMPCSN3041191900
 Repairer Reference: 71020
 Date calculated: 08/11/2019 11:04 AM

Full Report
 Registration: SML 3282R
 Printed: 08/11/2019 11:04 AM

Summary Information

Claim		Work Provider:	China Taiping Insurance
Location:	Singapore (SG)		(Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	DMPCSN3041191900	Date of Incident:	06/11/19
Estimated Repair Time:		Fire Car Start:	
Actual Repair Days:		Fire Car End:	

Vehicle Details

Vehicle:			
Manufacturer:	BMW		
Model:	5 SERIES F10		
Sub Model:	523 i		
Model Sheet Number:	01 42 01		
Registration:	SML 3282R		
VIN number:	WBAFP32030C864394		
Odometer:	111510		
Model Specs			
FROM 01/2011	AIR CON AUTO 2-ZONES	02 VOLUME	DIP REAR VIEW MIRROR
HI-FI SPEAKER SYSTEM	XENON HEADLAMPS	INTER LIGHT AMBIENCE	DAKOTA LEATHER TRIM
ELEC/SEAT ADJ MEMORY	DIP REAR VIEW MIRROR	FRT/RR PARK DIST CON	2.5 LTR 150KW
SPORT S-WHEEL LEATH	8-GEAR AUTOMATIC	TYRES 225/55 YR 17	WHEELS 8J X 17 ALLOY
NOBLE WOOD FINELINE	ELECTRIC SUNROOF	TWO COAT METALLIC	TYRE W/FLAT RUNNING

Handwritten notes:
 F10 523i Not Authorized Repairer
 4 days
 Ref: 62564315

Labour

Code	Description	Time Base 12 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	ADD/TIME FOR MAIN WORK		2.0	7.00
51 64 532	RENEW R/FRONT PANEL SUPPORT (FRT BUMPER SUPPORT REMOVED) INCLUDES: HEADLAMP AIR GUIDE RADIATOR AND IMPACT ELEMENT REMOVE AND REFIT		15.0	52.50
51 11 656	R + R FRONT BUMPER		9.0	31.50
51 11 551	R + R FRONT UPPER BUMPER CARRIER		4.0	14.00
51 11 592	REMOVE/REFIT FRONT BUMPER BAR TRIM (WITH FRONT BUMPER BAR REMOVED)		6.0	21.00
66 20 610	ADD/WORK PARK DISTANCE CONTROL		4.0	14.00
63 10 514	ALIGN FRONT FOG LAMPS		2.0	7.00
63 12 524	RENEW R/HEADLAMP (REMOVED)		4.0	14.00
0742	R/F WING REPAIR		10.0	35.00

Audatex System Using Manufacturer Times

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To declare damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1 of 3 PRINT DATE 08/11/2019

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	4,70	56.0	196.00
Total of Labour			196.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD
	FRONT BUMPER NEW PART PAINT K1R	15.0	
	R/WASHER NOZZLE TRIM NEW PART PAINT K1R	3.0	
	BONNET REPAIR PAINTING <50%	30.0	
	R/F WING REPAIR PAINTING <50%	12.0	

Paint Material Per Part

Code	Description	Price SGD
		77.74
0283	FRONT BUMPER NEW PART PAINT K1R	0.49
0634	R/WASHER NOZZLE TRIM NEW PART PAINT K1R	65.57
0471	BONNET REPAIR PAINTING <50%	15.18
0742	R/F WING REPAIR PAINTING <50%	

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor		60.0	
Time Paint	2.10	21.0	88.20
Preparation Main Work Metal	0.50	5.0	21.00
Preparation Comp. Work Plastic	3.60	36.0	361.20
Total	10 WU/h	8.60	103.2
Total	12 WU/h	8.60	361.20

Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	78.23
Repair Painting	80.75
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	186.08

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2018-09-10/12	Price SGD
0283	FRONT BUMPER COVER	51 11 7 285 961		By	910.00 ✓
0306	R/AIR INTAKE TRIM	51 11 7 231 860			45.00 ?
0336	FRT UPP BUMPER SUPP	SEE GUIDE NO. 0333			440.00 ?
0340	FRT UPP IMPACT DAMP	51 11 7 200 707		By	40.00 ✓
0348	R/OUT U-SONIC SENDER	66 20 9 270 495		By	190.00 ✓
0562	RIGHT HEADLAMP ASSY	63 11 7 343 914		CN	1,520.00 ✓
0634	R/WASHER NOZZLE TRIM	51 11 7 246 870			35.00 ?
0638	R/F FOG LAMP	63 17 7 216 886		By Br	155.00 ✓
1188	R/F PANEL SUPPORT	51 64 7 200 794			120.00 ?

Code	Description	Part Number	Supplier	Price SGD
1000	R/HEADLAMP NOZZLE	RENEW		145.00 ?
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			3,600.00
u: Used parts	Fixed Sundry Parts Price			100.00 7
	Total			3,700.00

Extras Code	Description	Price SGD
1001	CHK/ERASE FAULT CODE SN	80.00* 7
	Total Extras	80.00

Final Calculation

	SGD	SGD
Parts		
Fixed Sundry Parts Price	3,600.00	
Total Parts	100.00	3,700.00
Labour Time Base 12 WU/h		
Total 56.0 WU X 42.00 SGD/h	196.00	196.00
Total of Labour		80.00
Total Of Extras		
Paint Work Time Base 10 WU/h		
Labour Cost 86.0 WU X 42.00 SGD/h	361.20	
Material Cost	186.08	547.28
Total Paint Including Material		
Repair Cost Excludes GST		4,523.28
GST (+7.0%)		316.63
Repair Cost Included GST		4,839.91

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: DMPCSN3041191900
 Repairer Reference: 71020
 Date calculated: 08/11/2019 11:04 AM

Full Report
 Registration: SML 3282R
 Printed: 08/11/2019 11:04 AM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	DMPCSN3041191900	Date of Incident:	06/11/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	BMW		
Model:	5 SERIES F10		
Sub Model:	523 I		
Model Sheet Number:	01 42 01		
Registration:	SML 3282R		
VIN number:	WBAFP32030C864394		
Odometer:	111510		
Model Specs			
FROM 01/2011	AIR CON AUTO 2-ZONES	O2 VOLUME	DIP REAR VIEW MIRROR
HI-FI SPEAKER SYSTEM	XENON HEADLAMPS	INTER LIGHT AMBIENCE	DAKOTA LEATHER TRIM
ELEC/SEAT ADJ MEMORY	DIP REAR VIEW MIRROR	FRT/RR PARK DIST CON	2.5 LTR 150KW
SPORT S-WHEEL LEATH	8-GEAR AUTOMATIC	TYRES 225/55 YR 17	WHEELS 8J X 17 ALLOY
NOBLE WOOD FINELINE	ELECTRIC SUNROOF	TWO COAT METALLIC	TYRE W/FLAT RUNNING

Handwritten notes:
 Fm d/s
 Not Authorized
 Repair B4 paint
 4 days
 Fax: 62564315

Labour

Code	Description	Time Base 12 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	ADD/TIME FOR MAIN WORK		2.0	7.00
51 64 532	RENEW R/FRONT PANEL SUPPORT (FRT BUMPER SUPPORT REMOVED) INCLUDES: HEADLAMP, AIR GUIDE RADIATOR AND IMPACT ELEMENT REMOVE AND REFIT		15.0	52.50
51 11 656	R + R FRONT BUMPER		9.0	31.50
51 11 551	R + R FRONT UPPER BUMPER CARRIER		4.0	14.00
51 11 592	REMOVE/REFIT FRONT BUMPER BAR TRIM (WITH FRONT BUMPER BAR REMOVED)		6.0	21.00
66 20 610	ADD/WORK PARK DISTANCE CONTROL		4.0	14.00
63 10 514	ALIGN FRONT FOG LAMPS		2.0	7.00
63 12 524	RENEW R/HEADLAMP (REMOVED)		4.0	14.00
0742	R/F WING REPAIR		10.0*	35.00 ✓

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	4.70	56.0	196.00
Total of Labour			196.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	FRONT BUMPER NEW PART PAINT K1R	15.0
	R/WASHER NOZZLE TRIM NEW PART PAINT K1R	3.0
	BONNET REPAIR PAINTING <50%	30.0
	R/F WING REPAIR PAINTING <50%	12.0

Paint Material Per Part

Code	Description	Price SGD
0283	FRONT BUMPER NEW PART PAINT K1R	77.74
0634	R/WASHER NOZZLE TRIM NEW PART PAINT K1R	0.49
0471	BONNET REPAIR PAINTING <50%	65.57
0742	R/F WING REPAIR PAINTING <50%	15.18

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			60.0	
Preparation Main Work Metal		2.10	21.0	88.20
Preparation Comp. Work Plastic		0.50	5.0	21.00
Total	10 WU/h	8.60	86.0	361.20
Total	12 WU/h	8.60	103.2	361.20

Material Cost - Paint

New Part Painting - Plastic K1R	Price SGD
Repair Painting	78.23
Material-constant Metal	80.75
Material-constant Plastic	18.10
Total	9.00
	186.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Spare Parts

Code	Description	Part Number	Supplier	prices as at	2018-09-10/12	Price SGD
0283	FRONT BUMPER COVER	51 11 7 285 961		728	Rt	910.00 ✓
0306	R/AIR INTAKE TRIM	51 11 7 231 860			nd	45.00 ✓
0336	FRT UPP BUMPER SUPP	SEE GUIDE NO. 0333		352	Rt	440.00 ✓
0340	FRT UPP IMPACT DAMP	51 11 7 200 707			nd	40.00 ✓
0348	R/OUT U-SONIC SENDER	66 20 9 270 495		152	nd	190.00 ✓
0562	RIGHT HEADLAMP ASSY	63 11 7 343 914		1216	CM	1,520.00 ✓
0634	R/WASHER NOZZLE TRIM	51 11 7 246 870		42	nd Sm	35.00 ✓
0638	R/F FOG LAMP	63 17 7 216 886			nd Bro	155.00 ✓
1188	R/F PANEL SUPPORT	51 64 7 200 794			n	120.00 ✓

Code	Description	Part Number	Supplier	Price SGD
1000	R/HEADLAMP NOZZLE	RENEW		145.00 X
f: OEM Parts				0.00
n: Non-OEM Parts				3,600.00
u: Used parts				100.00
	Savings			
	Subtotal			
	Fixed Sundry Parts Price			
	Total			3,700.00

Extras

Code	Description	Price SGD
1001	CHK/ERASE FAULT CODE SN	80.00*
	Total Extras	80.00

Final Calculation

	SGD	SGD
Parts	3,600.00	
Fixed Sundry Parts Price	100.00	
Total Parts		3,700.00
Labour Time Base 12 WU/h		
Total 56.0 WU X 42.00 SGD/h	196.00 /68	
Total of Labour		196.00
Total Of Extras		80.00
Paint Work Time Base 10 WU/h		
Labour Cost 86.0 WU X 42.00 SGD/h	361.20	
Material Cost	186.08	
Total Paint Including Material		547.28
Repair Cost Excludes GST		4,523.28
GST (+7.0%)		316.63
Repair Cost Included GST		4,839.91

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

4839.28

來發(明記)摩多有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	71020
Policy No:	DMPCSN3041191900	Date of Loss:	06/11/2019
Vehicle Reg. No.:	SML3282R	Driveable?	
Driver Age/Info:	38 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TEO CHIN CHAI (ZHANG JINCAI)	Contact No:	+6590686133
Driver:	TEO CHIN CHAI (ZHANG JINCAI)		
Make/Model:	BMW 523I, 2.5 (A)	Vehicle Reg. Date:	03/06/2011
Vehicle Colour:	BLACK	Chassis No:	WBAFP32030C864394
Engine No:	10407692N52B25AF		
Odometer:	111510 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN AND POLICE REPORT: T/20191106/2104.		
Present Location:	LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	3,600.00
Miscellaneous Items	180.00
Labour	196.00
Paintwork Labour	547.28
Towing	0.00
Gross Total (\$\$)	4,523.28
+ GST 7.00% (\$\$)	316.63
Nett Amount (\$\$)	4,839.91

This claim is handled by: JENNY LIM LAI FOONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Nov 2019)

Parts: 143 BMW 523I 2.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SML3282R/08/11/2019 11:16

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*SPARE PARTS	0.00	0.00	*3,600.00 F
Total Parts (S\$)						3,600.00

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SML3282R/08/11/2019 11:16. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 CHK/ERASE FAULT CODE
2 1 SUNDRY PARTS

80.00 /

100.00 /

Sub Total (S\$)

180.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1 TOTAL PAINT INCLUDING MATERIAL

New

547.28 /

Labour Items

2 TOTAL OF LABOUR

New

168

196.00

Gross Labour Cost (S\$)

743.28

Lai Huat (Meng Kee) Motor Pte Ltd/SML3282R/08/11/2019 11:16. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference: DMPCSN3041191900
Repairer Reference: 71020
Date calculated: 11/12/2019 3:21 PM

Full Report
Registration: SML 3282R
Printed: 11/12/2019 3:21 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	DMPCSN3041191900	Date of Incident:	06/11/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	BMW		
Model:	5 SERIES F10		
Sub Model:	523 I		
Model Sheet Number:	01 42 01		
Registration:	SML 3282R		
VIN number:	WBAFP32030C864394		
Odometer:	111510		
Model Specs			
FROM 01/2011	AIR CON AUTO 2-ZONES	O2 VOLUME	DIP REAR VIEW MIRROR
HI-FI SPEAKER SYSTEM	XENON HEADLAMPS	INTER LIGHT AMBIENCE	DAKOTA LEATHER TRIM
ELEC/SEAT ADJ MEMORY	DIP REAR VIEW MIRROR	FRT/RR PARK DIST CON	2.5 LTR 150KW
SPORT S-WHEEL LEATH	8-GEAR AUTOMATIC	TYRES 225/55 YR 17	WHEELS 8J X 17 ALLOY
NOBLE WOOD FINELINE	ELECTRIC SUNROOF	TWO COAT METALLIC	TYRE W/FLAT RUNNING

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

		Time Base 12 WU/h	Price = 42.00 SGD/h	
Code	Description		WU	Price SGD
NO NUMBER	ADD/TIME FOR MAIN WORK		2.0	7.00
51 11 656	R + R FRONT BUMPER		9.0	31.50
51 11 551	R + R FRONT UPPER BUMPER CARRIER		4.0	14.00
51 11 592	REMOVE/REFIT FRONT BUMPER BAR TRIM (WITH FRONT BUMPER BAR REMOVED)		6.0	21.00
66 20 610	ADD/WORK PARK DISTANCE CONTROL		4.0	14.00
63 10 514	ALIGN FRONT FOG LAMPS		2.0	7.00
63 12 522)	R + R RIGHT HEADLAMP		5.0	17.50
63 12 524	RENEW R/HEADLAMP (REMOVED)		4.0	14.00
61 67 623	R + R R/HEADLAMP WASHER NOZZLE		2.0	7.00
0742	R/F WING REPAIR		10.0*	35.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		4.00	48.0	168.00
Total of Labour				168.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	FRONT BUMPER NEW PART PAINT K1R		15.0	
	R/WASHER NOZZLE TRIM NEW PART PAINT K1R		3.0	
	BONNET REPAIR PAINTING <50%		30.0	
	R/F WING REPAIR PAINTING <50%		12.0	

Paint Material Per Part

Code	Description	Price SGD
		77.74
0283	FRONT BUMPER NEW PART PAINT K1R	0.49
0634	R/WASHER NOZZLE TRIM NEW PART PAINT K1R	65.57
0471	BONNET REPAIR PAINTING <50%	15.18
0742	R/F WING REPAIR PAINTING <50%	

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			60.0	
Preparation Main Work Metal		2.10	21.0	88.20
Preparation Comp. Work Plastic		0.50	5.0	21.00
Total	10 WU/h	8.60	86.0	361.20
Total	12 WU/h	8.60	103.2	361.20

Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	78.23
Repair Painting	80.75
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	186.08

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2019-11-11 Price SGD
0283	FRONT BUMPER COVER	USED PART LESS 20%		728.00
0306	R/AIR INTAKE TRIM	51 11 7 231 860		45.00
0336	FRT UPP BUMPER SUPP	USED PART LESS 20%		352.00
0340	FRT UPP IMPACT DAMP	51 11 7 200 707		40.00
0348	R/OUT U-SONIC SENDER	USED PART LESS 20%		152.00
0562	RIGHT HEADLAMP ASSY	USED PART LESS 20%		1,216.00
0634	R/WASHER NOZZLE TRIM	51 11 7 246 870		42.00
0638	R/F FOG LAMP	63 17 7 216 886		155.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			2,730.00
u: Used parts	Fixed Sundry Parts Price			100.00
	Total			2,830.00

Extras

Code	Description	Price SGD
1001	CHK/ERASE FAULT CODE SN	80.00*
	Total Extras	80.00

Code	Description	Price SGD
------	-------------	-----------

Final Calculation

	SGD	SGD
Parts	2,730.00	
Fixed Sundry Parts Price	100.00	
Total Parts		2,830.00
Labour Time Base 12 WU/h		
Total 48.0 WU X 42.00 SGD/h	168.00	
Total of Labour		168.00
Total Of Extras		80.00
Paint Work Time Base 10 WU/h		
Labour Cost 86.0 WU X 42.00 SGD/h	361.20	
Material Cost	186.08	
Total Paint Including Material		547.28
Repair Cost Excludes GST		3,625.28
GST (+7.0%)		253.77
Repair Cost Included GST		3,879.05

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Nov 2019 Sendback Est	08 Nov 2019 11:16 S\$4,523.28	08 Nov 2019 14:18 Edit Adj Rpt	S\$3,625.28 Edit Estimates	S\$3,625.28 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	TEO CHIN CHAI (ZHANG JINCAI), ID: S8133107C, Tel: +6590686133, Email: kelvinteocc@gmail.com			
Vehicle Reg. No.:	SML3282R	Date of Loss:	06/11/2019 11:00 - :59 [101 Months and 3 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / SNM19D205293-SML3282R-CBS	Policy/Cover Note No.:	DMPCSN3041191900 (Comprehensive)	
		Excess:	S\$0.00	
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Alfred Toh - 6389 6183]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 19/11/2019]			
Driver/Custodian:	TEO CHIN CHAI (ZHANG JINCAI) (38 / Male), NRIC: S8133107C, Tel: +6590686133 Email: kelvinteocc@gmail.com			

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

- CHINA_TAIPIING (11/11/2019): Alert - Adj Mandate Approved (S\$4523.28) - SML3282R - Claim Handler: Alfred Toh

ALL ASSOCIATED TASKS View All

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SML3282R (SNM19D205293-SML3282R-CBS)
OD

Nov 6 2019 11:00AM
[TEO CHIN CHAI (ZHANG JINCAI)]
Lai Huat (Meng Kee) Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	07/11/19 11:58	Video - Accident [Linked Accident Report Documents]	Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	08/11/19 11:16	Repairer Estimates	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/11/19 16:21	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	08/11/19 11:16	Front View	Load JPG	☒
2	08/11/19 11:16	Front View Left	Load JPG	☒
3	08/11/19 11:16	Front View Right	Load JPG	☒
4	08/11/19 11:16	Photographs of Damaged Parts	Load JPG	☒
5	08/11/19 11:16	Chassis Number	Load JPG	☒
6	08/11/19 11:16	Photographs of Damaged Parts	Load JPG	☒
7	08/11/19 11:16	Photographs of Damaged Parts	Load JPG	☒
8	08/11/19 11:16	Photographs of Damaged Parts	Load JPG	☒
9	08/11/19 11:16	Photographs of Damaged Parts	Load JPG	☒
10	08/11/19 11:16	Photographs of Damaged Parts	Load JPG	☒
11	08/11/19 11:16	Photographs of Damaged Parts	Load JPG	☒
12	08/11/19 11:16	Photographs of Damaged Parts	Load JPG	☒
13	08/11/19 11:16	Photographs of Damaged Parts	Load JPG	☒
14	08/11/19 11:16	Photographs of Damaged Parts	Load JPG	☒
15	08/11/19 11:16	Photographs of Damaged Parts	Load JPG	☒
16	08/11/19 11:16	Photographs of Damaged Parts	Load JPG	☒
17	08/11/19 11:16	Odometer Reading	Load JPG	☒
18	08/11/19 11:16	Tyre - Continental	Load JPG	☒
19	08/11/19 11:16	Tyre size	Load JPG	☒
20	08/11/19 11:16	Photographs of Damaged Parts	Load JPG	☒
21	08/11/19 11:16	Photographs of Damaged Parts	Load JPG	☒
22	08/11/19 11:16	Photographs of Damaged Parts	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/12/19 15:25	General View	Load JPG	☒
2	11/12/19 15:25	General View	Load JPG	☒
3	11/12/19 15:25	General View	Load JPG	☒
4	11/12/19 15:25	General View	Load JPG	☒
5	11/12/19 15:25	General View	Load JPG	☒
6	11/12/19 15:25	General View	Load JPG	☒
7	11/12/19 15:25	General View	Load JPG	☒
8	11/12/19 15:25	General View	Load JPG	☒
9	11/12/19 15:25	General View	Load JPG	☒
10	11/12/19 15:25	Odometer Reading	Load JPG	☒

Video			1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
11	11/12/19 15:25	Chassis Number	Load JPG	☒
12	11/12/19 15:25	General View	Load JPG	☒
13	11/12/19 15:25	General View	Load JPG	☒
14	11/12/19 15:25	General View	Load JPG	☒
15	11/12/19 15:25	General View	Load JPG	☒
16	11/12/19 15:33	DISMANTLE PHOTOS	Load JPG	☒
17	11/12/19 15:33	DISMANTLE PHOTOS	Load JPG	☒
18	11/12/19 15:33	DISMANTLE PHOTOS	Load JPG	☒
19	11/12/19 15:33	DISMANTLE PHOTOS	Load JPG	☒
20	11/12/19 15:35	BEFORE PAINT PHOTOS	Load JPG	☒
21	11/12/19 15:35	BEFORE PAINT PHOTOS	Load JPG	☒
22	11/12/19 15:35	BEFORE PAINT PHOTOS	Load JPG	☒
23	11/12/19 15:35	BEFORE PAINT PHOTOS	Load JPG	☒
24	11/12/19 15:35	BEFORE PAINT PHOTOS	Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	08/11/19 11:14	E-filed GIA report	Load PDF	
2	08/11/19 11:14	Driver's NRIC & Driving Licence	Load PDF	
3	08/11/19 11:14	Certificate of Insurance	Load PDF	
4	08/11/19 11:14	Enquire PARF / COE Rebate for Registered Vehicle	Load PDF	
5	08/11/19 11:14	Audatex Report	Load PDF	
6	29/11/19 16:59	Supplier Bill	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/11/19 16:23	ESTIMATE	Load PDF	

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	07/11/19 11:58	Video - Accident	Load MP4	

Assessment Reports			1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	06/12/19 19:05	Accident Statement	Load HTM	
2	06/12/19 19:06	Accident Statement	Load HTM	
3	06/12/19 19:08	Accident Statement	Load HTM	
4	06/12/19 19:10	Accident Statement	Load HTM	

Photos/Images			3 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	07/11/19 14:27	Accident Photo	Load JPG	☒
2	07/11/19 14:27	Accident Photo	Load JPG	☒
3	07/11/19 14:27	Accident Photo	Load JPG	☒
4	07/11/19 14:27	CHASSIS NUMBER	Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	07/11/19 14:27	Sketch Plan	Load TIF	
2	07/11/19 14:27	POLICE REPORT	Load TIF	
3	07/11/19 14:27	CERTIFICATE OF INSURANCE	Load TIF	
4	07/11/19 14:27	Driver's Identification Card and Driving Licence	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19019835/KQF3S2

Date: 07/01/2020

REFERENCE

Insured/Claimant: TEO CHIN CHAI (ZHANG JINCAI) Policy No: DMPCSN3041191900
Date of Loss: 06/11/2019 Nature of Claim: OD Claim No: SNM19D205293-SML3282R-CBS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SML3282R Engine No: 10407692N52B25AF
Make & Model: BMW 523i, 2.5 (A) Chassis No: WBAFP32030C864394
Reg. Date: 03/06/2011 (Man. Year: 2011) Odometer: 111510 km
Colour: Metallic Black
Engine Capacity: 2497 cc
Market Value/New Car Price: S\$48,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
Front Left Side: Continental 7 mm Rear Left Side: Continental 7 mm
Front Right Side: Continental 7 mm Rear Right Side: Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,600.00	2,730.00	870.00	24.17
Miscellaneous Items	180.00	180.00	0.00	0.00
Labour	196.00	168.00	28.00	14.29
Paintwork Labour	547.28	547.28	0.00	0.00
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,523.28	3,625.28	898.00	19.85
+ GST 7.00/7.00% (S\$)	316.63	253.77	62.86	19.85
Nett Amount (S\$)	4,839.91	3,879.05	960.86	19.85

INSPECTION

Date of Assignment: 08/11/2019 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected: 08/11/2019 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Estimated Period of Repair: 4.0 days 160 Sin Ming Drive #04-01, Sin Ming AutoCity
Singapore 575722

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Jan 2020)
Parts: 143	BMW 523I 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML3282R)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					3,600.00 F	-
1	1		*SPARE PARTS		-	*728.00 F
2	1		*FRONT BUMPER COVER	Bent	-	*45.00 F
3	1		*R/AIR INTAKE TRIM	Dented	-	*352.00 F
4	1		*FRT UPP BUMPER SUPP	Bent	-	*40.00 F
5	1		*FRT UPP IMPACT UPP	Distorted	-	*152.00 F
6	1		*R/OUT U-SONIC SENDER	Missing	-	*1,216.00 F
7	1		*RIGHT HEADLAMP ASSY	Cracked	-	*42.00 F
8	1		*R/WASHER NOZZLE TRIM	Dented	-	*155.00 F
9	1		*R/F FOG LAMP	Mtg Broken	-	*- F
10	1		*R/F PANEL SUPPORT	Repair	-	*- F
11	1		*R/HEADLAMP NOZZLE	Serviceable	-	*- F
F=Franchise part.						
					Total Parts (S\$)	3,600.00
						2,730.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	CHK/ERASE FAULT CODE	80.00	80.00
2	1	SUNDRY PARTS	100.00	100.00
Sub Total (S\$)			180.00	180.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TOTAL PAINT INCLUDING MATERIAL	New	547.28	-
2	PAINT WORK: LABOUR COST.	New	-	361.20
3	PAINT WORK: MATERIAL COST.	New	-	186.08
<u>Labour Items</u>				
4	TOTAL OF LABOUR	New	196.00	168.00
Gross Labour Cost (S\$)			743.28	715.28

Report was unsubmitted during this print-out.

< END OF ESTIMATES >