

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5991X**AAD1911-034***Not Authored
11 Sep 8 565d*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

07 NOV 2019

SHC 5991X

VF1ABL15AUC280996

RENAULT

LATITUDE

5.11.19

AIG

18/12/2014

PART			LIST		
1	1	BUMPER COVER REAR	\$	<i>As</i> 561.70	✓
2	1	BUMPER LOWER REAR	\$	<i>As 10.1</i> 411.90	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 98.10	} X
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>Sn</i> 82.10	
5	1	BUMPER RETAINER RH REAR	\$	<i>Sn</i> 59.80	
6	1	BUMPER REFLECTOR RH	\$	<i>Sn</i> 16.60	
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>Sn</i> 80.80	
8	1	BUMPER RETAINER LH REAR	\$	<i>Sn</i> 54.20	} X
9	1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 16.60	
10	1	BUMPER BEAM REAR	\$	<i>As</i> 547.80	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>Dis</i> 114.50	✓
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>Dis</i> 100.90	✓
13	1	BUMPER BLOCK LH REAR	\$	<i>Sn</i> 75.70	X
14	1	BUMPER BLOCK RH REAR	\$	<i>Sn</i> 76.50	X
15	1	BUMPER HARNESS REAR	\$	<i>Sn</i> 301.10	X
16	1	BOOT REAR	\$	<i>Bur</i> 1,677.20	✓
17	1	BOOT FINISHER	\$	<i>Sn</i> 344.70	X
18	1	BOOT WHEATERSTRIP	\$	<i>Sn</i> 178.20	X
19	1	BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 277.70	X
20	1	BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 277.70	X
21	1	BOOT BADGE 'RENAULT'	\$	<i>As</i> 82.40	✓
22	1	BOOT BADGE	\$	<i>As</i> 95.80	✓
23	1	BOOT STRUT LH	\$	<i>Sn</i> 145.10	X
24	1	BOOT STRUT RH	\$	<i>Sn</i> 145.10	X
25	1	BOOT HINGE LH	\$	<i>As</i> 254.20	X
26	1	BOOT HINGE RH	\$	<i>As</i> 253.80	X
27	1	BOOT INNER BOARD	\$	<i>Sn</i> 611.00	X

Trans-cab Auto Services Pte Ltd**AAD1911-034**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5991X

28	1	BOOT SWITCH	\$	Sn	113.00	
29	1	BOOT LOCK	\$	R	246.60	
30	1	BOOT LOCK CATCH	\$	R	41.70	
31	2	LICENCE PLATE LAMP	\$	Sn	26.30	
32	2	BOOT RUBBER PLUG	\$	Sn	139.30	
33	2	BOOT BUFFER	\$	Sn	26.80	
34	1	BOOT LOCK LINKAGE	\$	Sn	20.60	
35	1	BOOT LOCK LINKAGE HOLDER	\$	Sn	99.50	
36	1	BOOT TRIM BOARD	\$	Sn	611.00	
37	1	FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45	
38	1	FENDER PANEL REAR LH	\$	R	1,933.20	
39	1	WHEELARCH REAR LH	\$	Sn	181.60	
40	1	FENDER PANEL INNER TRIM REAR RH	\$	R	671.45	
41	1	FENDER PANEL REAR RH	\$	R	1,933.20	
42	1	WHEELARCH REAR RH	\$	Sn	275.40	
43	1	AIR VENT LH	\$	Sn	59.40	
44	1	AIR VENT RH	\$	Sn	59.40	
45	1	TAILLAMP RH	\$	mgm	313.10	✓
43	1	TAILLAMP PANEL RH	\$	R	401.40	X
44	1	TAILLAMP LH	\$	mgm	401.40	✓
45	1	TAILLAMP PANEL LH	\$	R	401.40	X
46	1	OUTER PANEL REAR (End Panel)	\$	R	745.80	✓
47	1	OUTER PANEL REAR (End Panel)TRIM	\$	mgm	404.56	✓
48	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	1,229.40	
49	1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21	
50	1	SPARE TYRE BOARD	\$	Sn	680.90	
51	1	EXHAUST REAR	\$	R	5,263.60	
52	1	EXHAUST CAP REAR	\$	R	125.40	
53	1	FUEL FLAP	\$	Sn	244.70	
TOTAL			\$		24,874.97	
10%			\$		2,487.50	
			\$		22,387.47	

Special Nett

1	1SET PARKING AID	\$	Shen	700.00	400.00
2	1SET REAR BUMPER CLIP	\$	rec	66.00	✓

Trans-cab Auto Services Pte Ltd**AAD1911-034**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5991X

3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	X
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	na	16.00	X
11	1 EXHAUST BRACKET REAR	\$	na	24.80	X
12	1SET BOOT FINISHER CLIP	\$	na	24.20	X
13	1 BOOT STICKER "Trans-cab"	\$	na	30.00	✓
14	1 BOOT STICKER "6555-3333"	\$	na	30.00	✓
15	1 BOOT INNER TRIM CLIP	\$	na	45.00	X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	X
17	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	fin	385.00	X
18	1 SPARE TYRE	\$	fin	330.00	X
19	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X
20	1 TAILLAMP CLIP RH	\$	na	5.00	✓
21	2 REAR WINDSCREEN SEALANT	\$	na	80.00	X
22	1 WINDSCREEN MOULDING	\$	na	100.00	X
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	X
24	1 TAILLAMP CLIP LH	\$	na	5.00	✓
25	1 Rear Bumper Protector	\$	na	100.00	40.00
26	1 REAR LEFT TYRE	\$	fin	300.00	} X
27	1 REAR LEFT TYRE RIM	\$	fin	380.00	
28	1 REAR RIGHT TYRE	\$	fin	300.00	
29	1 REAR RIGHT TYRE RIM	\$	fin	380.00	
30	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
31	1 FENDER INNER TRIM CLIP RH	\$	na	28.00	
32	1SET Rear licence plate with holder	\$	fin	80.00	
TOTAL		\$		3,788.00	

TOTAL PARTS	\$	26,175.47
--------------------	-----------	------------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	6606
---	----	----------	------

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5991X**AAD1911-034**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	6001
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201

Trans-cab Auto Services Pte Ltd**AAD1911-034**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5991X

To transfer of rear bumper fittings, attachment and perform water seepage test.

\$ *nn* 380.00 *X*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 *X*

To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.

\$ *nn* 380.00 *X*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 *X*

TOTAL \$ 19,200.00

Over All Total \$ 45,375.47

(LUMP SUM) Repair Days*25 DAYS**5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: