

INS. CASE OWNER

CC 4/III1901

9845

LKK:
IDAC

Surveyor:

Dylan

DOI:

8/11/2019

Date / Time:

7/11/19

Registered in Merimen:

8/11/19

re-assign / CCU / FTE



Insured Vehicle No.:

SHA 7093B

Name of Insured:

LTP

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A.:

4/11/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

TOM KWEE 41A

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

MIMOUS

TOYOTA

BANGKIE KLEEN KISS YLE

R0

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SJO 9091M



INSRS:

WSP:

Tel:

Liability:

RMKS:

Alfred
Auto

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time	STAGE	DATE / PIC
25/10 - RIA AVP from TP & OI.	Non-Reporting ltr (1st):	
20/11 - OI AVP in merimen. Pending TP AVE. (OLD driving straight, TP turning right). potential rejection	Non-Reporting ltr (2nd):	
19/11 - Pending mv when drop & rian.	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: S\$ 12,700/- (10 days) Reduction: 92% - 80% 45% Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: Confirm with: Email ☐ Call ☐

Final Liability: % (Agreed / Assessed) BOLA S/N No.:

Repair Cost: S\$

Loss of Rental (LOR): S\$ (days)

Loss of Use (LOU): S\$ (\$ x days)

Loss of Income (LOI): S\$ (\$ x days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LO ☐ [Tick only one]

GIA/LTA Search: S\$

Medical: S\$

Disbursement: S\$ (e.g. Tow/ Independent)

Legal Cost: S\$

Total: S\$ Global Sum S\$:

FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐

Payee 1: S\$ Name 1:

Payee 2: (Strike if N.A.) S\$ Name 2:

Payee 3: (Strike if N.A.) S\$ Name 3:


ASSIGNMENT

02E April 2028

2008 April

Vehicle No. SSD 9091 M
 Type M.Cat M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make Honda Fit CC 1339
 Colour Silver A/C Insured / Std / NI / NA
 Up/Booting 164552 (Radio: Insured / Std / NI / NA)
 Log/In L13A4040106
 C/No GE61036250
 Gen. Cond. Good / Fair / Poor / Burnt
 Steering Normal / Jammed / Leaked / Burnt or Swat
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: NA / S/Rim / STD A/Rim or
 Tyre Size: F: 195/50 R15
 R: 11

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.



Est. or Market Value:
 IDAC Accident Report Consistent? : Yes or No
 C/A / PR Score Consistent? : Yes or No
 Est. Repair: 10 days Res.: Yes or No
 Loss Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Bridgestone

Front Rear
 R/Bal. S mm R/Bal. S mm
 L/Bal. S mm L/Bal. S mm

D.O.A. 04/11/2019 D.O.I. 08/11/2019

Survey held at Alfred Auto AMK
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Front 4 N/S Bay 4 N/S Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TH SHA 7053 B</u>
	<u>MV 45K</u>
	<u>VIA 32.5K</u>
	<u>HL 12.5K</u>
	<u>1/5 \$12,300/- (Red- \$9,779.80 / 43.1%)</u>

Date/Time, File Path to: ☐ : Prel. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Insp (\$) ☐ Wash and (\$)

Survey Fee:

Transportation

\$ + H.S. \$

Phone

+ Fax

Other

Total



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391069/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



BATTERY



Reference No: 61119

Date: 6.11.2019

Boh Julie

Blk 922 Hougang St. 91 #07-37

Singapore 530922

Honda Fit 1.3A

Estimated Repair Cost for Vehicle Reg. No: SJD 9091 J

REPLACEMENT OF DAMAGED PANELS / PARTS

N/S	1 Pc. Head Lamp Assy. <i>Painting</i>		685.40	✓
	1 Pc. Front Bumper Cut/attach		598.20	✓
	10 Pcs. Front Bumper Clips New	@ 4.00	40.00	✓ SN 30.00
	2 Pcs. Front Bumper Side Retainer New o/s M/S cut	@ 21.90	43.80	✓ 21.90
	1 Pc. Front Fender LH <i>Bruc</i>		448.90	✓
N/S	1 Pc. Front Fender Dust Garnish <i>detach</i>		83.00	✓
N/S	10 Pcs. Front Fender Dust Garnish Clips New	@ 4.00	40.00	✓ SN
	1 Pc. Front Door (LH) <i>Detach</i>		859.60	✓
N/S	2 Pcs. Front Door Hinger <i>1 pc. LH lower</i>	@ 65.00	130.00	✓ 66.00
	1 Pc. Front Door Stopper <i>1 pc.</i>		59.90	✓ X
	1 Pc. Front Door Lock New		269.70	✓
	2 Pc. Front Door Wind Vesper New		90.00	✓ SN
	1 Pc. Rear Door (LH) <i>Detach</i>		822.00	✓
	2 Pcs. Rear Door Hinger New	@ 65.00	130.00	✓ X
	1 Pc. Rear Door Stopper New		59.90	✓
	1 Pc. Local Panel (LH) <i>Remove</i>		504.00	✓
	1 Pc. 15inch Sport Rim Cut		250.00	✓ SN
	1 Pc. 195 x 50 x 15 Tyre <i>Painted 70%</i>		199.00	✓ SN 139.30
	1 Pc. Front LH Absorber <i>1 pc.</i>		306.00	✓
	1 Pc. Front LH Absorber Mounting <i>1 pc. NN</i>		47.00	✓
	1 Pc. Front LH Absorber Bearing <i>2 pc.</i>		40.80	✓
	1 Pc. Front LH Absorber Mounting Cover New		33.20	✓
	1 Pc. Front LH Hub <i>2 pc.</i>		203.00	✓
	1 Pc. Front LH Hub Bearing <i>2 pc.</i>		41.00	✓
	1 Pc. Front LH Knuckle Arm <i>2 pc. broken</i>		310.00	✓
	1 Pc. Front LH Wheel Housing <i>2 pc. reg.</i>		998.00	✓ X
	1 Pc. Front LH Lower Arm <i>2 pc.</i>		252.00	✓
	1 Pc. Disc Rotor New		228.00	✓
	1 Pc. Steering Rack & Pinion <i>2 pc.</i>		1,677.90	✓

SN 549.30

List 6414.70

\$21,579.80



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
 Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
 Email: alfredauto@hotmail.com

Tyre &
Sports Rim



BATTERY

1 Pc. Steering Tie Rod <i>✓</i> <i>1st</i>	45.90 <i>Z</i> <i>✓</i>
1 Pc. Steering Tie Rod End <i>✓</i> <i>distn</i>	49.20 <i>Z</i> <i>✓</i>
1 Pc. Steering Tie Rod Cover <i>new</i>	20.00 <i>X</i>
1 Pc. Stabilizer Bar <i>✓</i> <i>new</i>	131.00 <i>✓</i> <i>new</i> <i>X</i>
1 Pc. Stabilizer Bar Linkage <i>✓</i> <i>1st</i>	79.30 <i>Z</i> <i>✓</i>
1 Pc. ABS Sensor <i>new</i> <i>form</i>	170.00 <i>Z</i> <i>✓</i>
1 Pc. Drive Shaft <i>✓</i> <i>Don</i> <i>3cm</i>	1,991.00 <i>✓</i> <i>✓</i>
1 Pc. Auto Transmission Oil <i>new</i>	180.00 <i>X</i> <i>SN</i>
1 Pc. Brake Hose <i>✓</i> <i>form</i>	190.00 <i>✓</i> <i>✓</i>
1 Pc. Brake Fluid <i>new</i>	50.00 <i>✓</i> <i>SN</i>

20% disc

Total (Panels / Parts): **12,356.70 (SGD)**

LABOR CHARGES

Towing Fee (2 times)	120.00 <i>new</i>
To check wiring & remove refit wiring.	200.00 <i>30/-</i>
To panel beating, welding, straightening repair & renew All accident damage parts.	1,300.00 <i>1100/-</i>
To remove & refit interior carpet, garnish door board, Cushion & affected parts.	280.00 <i>120/-</i>
To Respray painting on all accident affected area.	1,400.00 <i>1200/-</i>
To rust proof all accident damage parts.	120.00 <i>40/-</i>
To remove & refit renew all undercarriage damage Affected area.	800.00 <i>250/-</i> <i>2850.00</i>
To check & adjust computer wheel alignment & test Drive.	180.00 <i>60/-</i>
To press hup bearing.	120.00 <i>50/-</i>

Total (Labor Charges): **4,520.00 (SGD)**

List 2525.40 SN 50.00



ALFRED AUTO Services & Supplies

Bkk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391069/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



TOTAL COST SUMMARY

PANELS / PARTS	12,356.70
LABOR CHARGES	4,520.00
<hr/>	
Grand Total:	<u>16,876.70 (SGD)</u>

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'Alfred Auto Services and Supplies'

List 14413.20 SW 639.30

200 11530.56 Labor 3250.00

Handwritten signature

ALFRED AUTO SERVICES & SUPPLIES

Total 15419.86

L/S 12300/-

08/11/2019 11:00am

NA Antine

L/S sum 10 days

Handwritten signature: Ryan

LKK Auto

Handwritten signature

Cheque HV

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391069/00-E
Email: alfredauto@hotmail.com



Reference No: 61119

Date: 12.11.2019

Boh Julie

Blk 922 Hougang St. 91 #07-37

Singapore 530922

Honda Fit 1.3A

Supplementary Repair Cost for Vehicle Reg. No: SJD 9091 J

REPLACEMENT OF DAMAGED PANELS / PARTS

1 Pc. Front Quarter Garnish <i>Nec</i>	135.10	✓
1 Pc. Front Windscreen Moulding <i>Nec</i>	258.00	✓
1 Pc. Front Windscreen Sealant & Repair Kit <i>Nec</i>	120.00	✓ 40/- SH
1 Pc. Front Door Pillar LH <i>Dented</i>	1,260.00	✓
1 Pc. Rear Fender LH <i>Dented</i>	1,890.00	✓
2 Set. LH Quatuar Glass Repair Kit <i>Nec</i> @ 120.00	240.00	✓
1 pc cross member distortion 20% disc	1,690.00	✓

Total (Panels / Parts): 3,903.10 (SGD)

List 5473.10 SH 40.00

LABOR CHARGES

To remove dashboard & refit.	380.00	180/-
To remove front windscreen.	180.00	120/- 400.00
To remove & refit quarter glass, front and rear LH side.	240.00	100/-

Total (Labor Charges): 800.00 (SGD)

11/11/2019 @ 1030m

[Signature]
Jack Andy



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4862 Reg. No. 391069/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



BATTERY



TOTAL COST SUMMARY

PANELS / PARTS	3,903.10
LABOR CHARGES	800.00
<hr/>	
Grand Total:	<u>4,703.10 (SGD)</u>

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'Alfred Auto Services and Supplies'

ALFRED AUTO SERVICES & SUPPLIES



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538

Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391069/00-E

Email: alfredauto@hotmail.com

Tyre & Sports Rim



Reference No: 61119

Date: 6.11.2019

Boh Julie

Blk 922 Hougang St. 91 #07-37

Singapore 530922

Honda Fit 1.3A

LKK Auto Centre
the Reparer

- To repair vehicle
- To display damaged parts and survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal (non-accident) is allowed
- Supplemental items must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

Estimated Repair Cost for Vehicle Reg. No: SJD 9091 J

REPLACEMENT OF DAMAGED PANELS / PARTS

1 Pc. Head Lamp Assy. <i>crack</i>		685.40	<i>✓</i>
1 Pc. Front Bumper <i>cut/damaged</i>		598.20	<i>✓</i>
10 Pcs. Front Bumper Clips <i>new</i>	@ 4.00	40.00	<i>✓ SN</i>
2 Pcs. Front Bumper Side Retainer <i>new o/s m/s</i>	@ 21.90	43.80	<i>✓</i>
1 Pc. Front Fender LH <i>new</i>		448.90	<i>✓</i>
1 Pc. Front Fender Dust Garnish <i>detached</i>		83.00	<i>✓</i>
1p Pcs. Front Fender Dust Garnish Clips <i>new</i>	@ 4.00	40.00	<i>✓ SN</i>
1 Pc. Front Door (LH) <i>detached</i>		859.60	<i>✓</i>
2 Pcs. Front Door Hinger <i>1 pc. not lower</i>	@ 65.00	130.00	<i>✓</i>
1 Pc. Front Door Stopper <i>new</i>		59.90	<i>✓</i>
1 Pc. Front Door Lock <i>new</i>		269.70	<i>✓</i>
2 Pc. Front Door Wind Vesper <i>new</i>		90.00	<i>✓ SN</i>
1 Pc. Rear Door (LH) <i>detached</i>		822.00	<i>✓</i>
2 Pcs. Rear Door Hinger <i>new</i>	@ 65.00	130.00	<i>✓</i>
1 Pc. Rear Door Stopper <i>new</i>		59.90	<i>✓</i>
1 Pc. Local Panel (LH) <i>new</i>		504.00	<i>✓</i>
1 Pc. 15inch Sport Rim <i>cut</i>		250.00	<i>✓ SN</i>
1 Pc. 195 x 50 x 15 Tyre <i>punctured 70%</i>		199.00	<i>✓ SN</i>
1 Pc. Front LH Absorber <i>new</i>		306.00	<i>✓</i>
1 Pc. Front LH Absorber Mounting <i>new</i>		47.00	<i>✓</i>
1 Pc. Front LH Absorber Bearing <i>new</i>		40.80	<i>✓</i>
1 Pc. Front LH Absorber Mounting Cover <i>new</i>		33.20	<i>✓</i>
1 Pc. Front LH Hup <i>new</i>		203.00	<i>✓</i>
1 Pc. Front LH Hup Bearing <i>new</i>		41.00	<i>✓</i>
1 Pc. Front LH Knuckle Arm <i>broken</i>		310.00	<i>✓</i>
1 Pc. Front LH Wheel Housing <i>new</i>		998.00	<i>✓</i>
1 Pc. Front LH Lower Arm <i>new</i>		252.00	<i>✓</i>
1 Pc. Disc Rotor <i>new</i>		228.00	<i>✓</i>
1 Pc. Steering Rack & Pinion <i>new</i>		1,677.90	<i>✓</i>



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391069/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



BATTERY

1 Pc. Steering Tie Rod <i>2 Vst</i>	45.90 <i>Z L</i>
1 Pc. Steering Tie Rod End <i>2 dist. n</i>	49.20 <i>Z L</i>
1 Pc. Steering Tie Rod Cover <i>NH</i>	20.00 <i>X</i>
1 Pc. Stabilizer Bar <i>2 NH</i>	131.00 <i>2 NH X</i>
1 Pc. Stabilizer Bar Linkage <i>2 Vst</i>	79.30 <i>Z L</i>
1 Pc. ABS Sensor <i>2 NH</i>	170.00 <i>Z L</i>
1 Pc. Drive Shaft <i>2 Dam. Iron</i>	1,991.00 <i>Z L</i>
1 Pc. Auto Transmission Oil <i>NH</i>	180.00 <i>X SN</i>
1 Pc. Brake Hose <i>2 NH</i>	190.00 <i>Z L</i>
1 Pc. Brake Fluid <i>NH</i>	50.00 <i>Z L SN</i>

20% disc

Total (Panels / Parts): 12,356.70 (SGD)

LABOR CHARGES

Towing Fee (2 times)	120.00 <i>NH</i>
To check wiring & remove refit wiring.	200.00 <i>30/-</i>
To panel beating, welding, straightening repair & renew All accident damage parts.	1,300.00 <i>1000/-</i>
To remove & refit interior carpet, garnish door board, Cushion & affected parts.	280.00 <i>120/-</i>
To Respray painting on all accident affected area.	1,400.00 <i>1200/-</i>
To rust proof all accident damage parts.	120.00 <i>40/-</i>
To remove & refit renew all undercarriage damage Affected area.	800.00 <i>250/-</i>
To check & adjust computer wheel alignment & test Drive.	180.00 <i>60/-</i>
To press hup bearing.	120.00 <i>50/-</i>

Total (Labor Charges): 4,520.00 (SGD)



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



TOTAL COST SUMMARY

PANELS / PARTS	12,356.70
LABOR CHARGES	4,520.00
<hr/>	
Grand Total:	<u>16,876.70 (SGD)</u>

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'Alfred Auto Services and Supplies'

Handwritten signature

ALFRED AUTO SERVICES & SUPPLIES

08/11/2019 11:00am

NA Antine

2/Sum 10 days

Handwritten signature: Ryan

2 KK Auto

Handwritten signature Chee M ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No: 61119

Date: 12.11.2019

Boh Julie

Blk 922 Hougang St. 91 #07-37

Singapore 530922

Honda Fit 1.3A

Supplementary Repair Cost for Vehicle Reg. No: SJD 9091 J

REPLACEMENT OF DAMAGED PANELS / PARTS

1 Pc. Front Quarter Garnish	Nec	135.10	✓
1 Pc. Front Windscreen Moulding	Nec	258.00	✓
1 Pc. Front Windscreen Sealant & Repair Kit	Nec	120.00	✓
1 Pc. Front Door Pillar LH	Dented	1,260.00	✓
1 Pc. Rear Fender LH	Dented	1,890.00	✓
2 Set. LH Quatuar Glass Repair Kit	Nec @ 120.00	240.00	✓
1 pc Cross member distortion	20% disc	1690.00	✓

Total (Panels / Parts): 3,903.10 (SGD)

LABOR CHARGES

To remove dashboard & refit.	380.00	180/-
To remove front windscreen.	180.00	120/-
To remove & refit quarter glass, front and rear LH side.	240.00	100/-

Total (Labor Charges): 800.00 (SGD)

11/11/2019 @ 1030m

Boh Julie
Lee Andy



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



TOTAL COST SUMMARY

PANELS / PARTS	3,903.10
LABOR CHARGES	800.00
<hr/>	
Grand Total:	<u>4,703.10 (SGD)</u>

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'Alfred Auto Services and Supplies'

ALFRED AUTO SERVICES & SUPPLIES

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport /Company Cert No.:	S6849571G
Owner ID Type:	Singapore NRIC
Owner Name:	BOH JULIE
Registered Address:	APT BLK 922 HOUGANG STREET 91 #07-37 SINGAPORE 530922
Mailing Address:	-
Birth Date:	25 Dec 1968

Vehicle Particulars

Vehicle No.:	SJD9091M
Previous Vehicle No.:	-
Effective Date of Ownership:	08 Apr 2008
Original Regn Date:	08 Apr 2008
Registration Date:	08 Apr 2008
Year of Manufacture:	2008
Vehicle Type:	Passenger Motor Car
Vehicle Scheme:	-
Vehicle Attachment 1:	No Attachment
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Silver
Secondary Colour:	-
Passenger Capacity:	4
Chassis No.:	GE61036250
Engine No.:	L13A4040105
Engine Capacity /Power Rating:	1339 cc / -
Maximum Power Output:	73.0 kW (97 bhp)

Max Unladen Weight:	1010 kg
Maximum Laden Weight:	1285 kg
Open Market Value:	\$13,028.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
Minimum PARF Benefit:	-
No. of Transfers:	0
IU Label No.:	1029114335
COE No.:	2008040101003707C
COE Expiry Date:	07 Apr 2028
COE Category:	A - Car (1600cc & below)
COE Registration Category:	A - Car (1600cc & below)
Quota Premium (QP) / Prevailing Quota Premium:	\$15,389.00 / -
PQP Paid:	\$38,655.00
QP (Regn Cat):	\$15,389.00
OPC Cash Rebate Eligibility:	No
QP during COE Bidding Exercise:	\$15,389.00
Additional Registration Fee Rate:	100.00 %
Actual ARF Paid:	\$13,028.00
Vehicle Lifespan Expiry Date:	No Lifespan
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-
Message:	To renew the COE, the Prevailing Quota Premium payable is that of Category A.

MV abt 42k

ofw upstg 10k reg

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, 7 November 2019 3:56 PM
To: Alfred Quah; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Sundari Nagarajan - III
Subject: RE: SJD9091M
Attachments: 9091 - ADD(TMIS).pdf

4-03pm 7/11/19
p: Alfred
Y. In
agreed Sunny on
8/11/2019

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SJD9091M and let us have your report urgently.

- This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street, #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Alfred Quah [mailto:alfredauto@hotmail.com]
Sent: 07 November, 2019 1:06 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: SJD9091M

Lkk ok can in workshop

Alfred Quah
HP: 91454773

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, November 7, 2019 11:59 AM
To: Alfred Quah <alfredauto@hotmail.com>
Subject: RE: SJD9091M

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street, #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Alfred Quah [mailto:alfredauto@hotmail.com]
Sent: 06 November, 2019 6:43 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: SJD9091M

Dear Sir,

Accident involving SJD9091M and SHA7053B, we act for Ms Boh Julie whose vehicle registration number SJD9091M was damaged in the above accident. We are instructed to claim for damages you and/ or your insured. Please arrange for your surveyor to inspect our client's vehicle at the following address

ALFRED AUTO SERVICES & SUPPLIES
BLK 5035 ANG MO KIO IND PK 2
#01-1351 S9569538)

Regards,

Alfred Quah
HP: 91454773

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.
It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be

intercepted, corrupted, lost, delayed or contain viruses.

- Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Print Received Message

This mail is associated with :

***SJD9091M (MCT19110091)**

[SHA7053B]

TP

BOH JULIE

Nov 4 2019 4:00PM

[COMFORT TRANSPORTATION PTE LTD]

Alfred Auto Services & Supplies

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 04/03/2020 09:35 AM.

To LKK_HQ

Subject Alert - Adj Mandate Maintained - SJD9091M - Claim Handler: Sundari Nagarajan

Maintained:agree to reject

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Tuesday, 3 March 2020 12:38 PM
To: Alfred Quah
Subject: RE: YOUR REF: SJD 9091M (OUR REF: CC4/III19019845/Dgb3) *** ACCIDENT INVOLVING SHA 7053B & SJD 9091M ON 04/11/2019 ***
Attachments: Video - Accident-IV (10).MP4

Your Ref: **SJD 9091M** Without Prejudice
Our Ref: CC4/III19019845/Dgb3

Dear Sirs/Madam,

ACCIDENT INVOLVING SHA 7053B & SJD 9091M ON 04/11/2019

We refer to the above matter.

Attached is a copy of our insured car video footage for your easy reference. We have reviewed the matter and we are of the view that our driver is not liable for the accident. The traffic light was green which means our driver has the right of way as he is driving straight along his lane. Your client has make a right turn from the opposite lane without making sure that the road is clear.

In view of the above, we have our principal instruction to deny liability and unable to look into your client's matter.

Thank you.

Note: This video footage is solely for investigation and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Alfred Quah [mailto:alfredautoss@gmail.com]
Sent: Thursday, 26 December 2019 12:23 PM



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4585 Fax: 6483 4882 Reg. No. 391069/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Tax Invoice: 61119

Date: 6.12.2019

India International Insurance Pte Ltd
64 Cecil St #04/05/06-02
IOB Building, Singapore 049711.
Motor Claim Department

Cc:

Boh Julie
Blk 922 Hougang St. 91 #07-37
Singapore 530922
Honda Fit 1.3A

Re: Property Damage Direct Settlement

Attention: Ms. Sundari

Final Repair Cost for Vehicle Reg. No: SJD 9091 J

Lum Sum Repair	12,300.00
----------------	-----------

Grand Total:	<u>12,300.00 (SGD)</u>
---------------------	-------------------------------

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'Alfred Auto Services and Supplies'

ALFRED AUTO SERVICES & SUPPLIES



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



LETTER OF DEMAND

Date: 6.012.2019

Your Ref: SHA 7053 B

Re: Property Damage Direct Settlement Claim

Accident involving SJD 9091 D & SHA 7053 B on 4th November, 2019 at junction of Road 1 Yio Chu Kang & Ang Mo Kio Ave 5.

Cost of Repair	12,300.00
Loss of Usage (16days @ 80.00/day)	1,280.00
Towing Fee	50.00
Search Fee	Waived

Grand Total: **13,630.00 (SGD)**

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'Alfred Auto Services and Supplies'

ALFRED AUTO SERVICES & SUPPLIES

Date: 6/11/2019

To The Motor Claims Manager

M/s India International Insurance Pte Ltd

6A Cecil St #04/05 #06-02

10B Building

Singapore 049711

Dear Sirs,

ACCIDENT ON 04/11/2019 INVOLVING VEHICLES NOS:
SJD9091M AND SHA7053B
ALONG ~~AT~~ Road 1 Yio Chu Kang Road X Ang Mo Kio Ave 5.

I/We, M3 Boh Julie of NRIC NO.: 86849571A
am/are the registered owner of motorcar no: SJD9091M. I/We, hereby
authorised you to release all compensation monies pertaining to the above-mentioned accident,
directly to my repairer, M/s Alfred Auto Services & Supplies.

I/We, hereby authorise the said repairer, M/s Alfred Auto Services & Supplies to collect all
compensation monies due to me from you or any other party, regarding the said accident.

Thank you.



Signature

Owner: Boh Julie

ORIGINAL



Signature

Witness by: Quah Hock Wah

NRIC No: 8174884912

Date: 6/11/2019



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538

Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E

www.yahoo.com.sg id: alfredautoaaa@yahoo.com.sg

Email: alfredauto@hotmail.com

Tyre &
Sports Rim



BATTERY

SATISFACTION AND DISCHARGE FORM

I, Ms Bon Julie I/C NO: 86849571 G

hereby declare that vehicle number 8JD9091M has been repaired

to my satisfaction.

I also declare that I will discharge the Workshop from any further claims.

ORIGINAL

OWNER OF VEHICLE

2/12/19

DATE

2.00pm

TIME

...CLAIM SUBFOLDER...(Pending for Survey Report)
WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Nov 2019 Edit Reg		07 Nov 2019 00:00 Edit Adj Rpt	\$12,300.00 Edit Estimates	\$12,300.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -		
Main Claimant:	BOH JULIE, ID: S6849571G		
Vehicle Reg. No.:	SJD9091M	Date of Loss:	04/11/2019 16:00 - :59 [138 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT19110091	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHA7053B	Policy No. (Claimant):	19-MX002123-R05
		Excess:	
Repairer:	Alfred Auto Services & Supplies (HQ) Blk 5035, Ang Mo Kio Ave 3, #01-351, Ang Mo Kio Industrial Park 2, 569538 Ang Mo Kio - Tel: 64834586/91454773		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari NagaraJan - 6347 6071]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 19/11/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

- III_SG (04/03/2020): Alert - Adj Mandate Maintained - SJD9091M - Claim Handler: Sundari NagaraJan
- III_SG (27/12/2019): Alert - Adj Mandate Approved (\$0.00) - SJD9091M - Claim Handler: Sundari Nagara...
- III_SG (27/12/2019): Alert - Adj Mandate Maintained - SJD9091M - Claim Handler: Sundari NagaraJan

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)
























































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

























































Claim Documents

























































*SJD9091M (MCT19110091)
[SHA7053B]
TP
BOH JULIE
Nov 4 2019 4:00PM
[COMFORT TRANSPORTATION PTE LTD]
Alfred Auto Services & Supplies


































Upload DocumentsUpload PhotosCompose New LetterViewView in Browser

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	27/12/19 09:37	Video - Accident-1V	Load MP4	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
2	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
3	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
4	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
5	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
6	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
7	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
8	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
9	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
10	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
11	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
12	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
13	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
14	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
15	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
16	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
17	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
18	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
19	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
20	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
21	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
22	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
23	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
24	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
25	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
26	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
27	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
28	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
29	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
30	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
31	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
32	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
33	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
34	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
35	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
36	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
37	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
38	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
39	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>
40	19/03/20 16:33	General View	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
42	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
43	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
44	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
45	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
46	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
47	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
48	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
49	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
50	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
51	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
52	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
53	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
54	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
55	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
56	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
57	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
58	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
59	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
60	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
61	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
62	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
63	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
64	19/03/20 16:33	Chassis Number		<input checked="" type="checkbox"/>
65	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
66	19/03/20 16:33	Odometer Reading		<input checked="" type="checkbox"/>
67	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
68	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
69	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
70	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
71	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
72	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
73	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
74	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
75	19/03/20 16:33	General View		<input checked="" type="checkbox"/>
76	19/03/20 16:34	Reinspection Photo		<input checked="" type="checkbox"/>
77	19/03/20 16:34	Reinspection Photo		<input checked="" type="checkbox"/>
78	19/03/20 16:34	Reinspection Photo		<input checked="" type="checkbox"/>
79	19/03/20 16:34	Reinspection Photo		<input checked="" type="checkbox"/>
80	19/03/20 16:34	Reinspection Photo		<input checked="" type="checkbox"/>
81	19/03/20 16:34	Reinspection Photo		<input checked="" type="checkbox"/>
82	19/03/20 16:34	Reinspection Photo		<input checked="" type="checkbox"/>
83	19/03/20 16:34	Reinspection Photo		<input checked="" type="checkbox"/>
84	19/03/20 16:34	Reinspection Photo		<input checked="" type="checkbox"/>
85	19/03/20 16:34	Reinspection Photo		<input checked="" type="checkbox"/>
86	19/03/20 16:34	Reinspection Photo		<input checked="" type="checkbox"/>
87	19/03/20 16:34	Reinspection Photo		<input checked="" type="checkbox"/>
88	19/03/20 16:34	Reinspection Photo		<input checked="" type="checkbox"/>
89	19/03/20 16:34	Reinspection Photo		<input checked="" type="checkbox"/>
90	19/03/20 16:34	Reinspection Photo		<input checked="" type="checkbox"/>
91	19/03/20 16:34	Reinspection Photo		<input checked="" type="checkbox"/>
92	19/03/20 16:34	Reinspection Photo		<input checked="" type="checkbox"/>
93	19/03/20 16:34	Reinspection Photo		<input checked="" type="checkbox"/>
94	19/03/20 16:34	Reinspection Photo		<input checked="" type="checkbox"/>
95	19/03/20 16:34	Reinspection Photo		<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
96	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
152	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
168	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
169	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
170	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
171	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
172	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
173	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
174	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
175	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
176	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
177	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
178	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
179	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
180	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
181	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
182	19/03/20 16:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
183	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
184	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
185	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
186	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
187	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
188	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
189	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
190	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
191	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
192	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
193	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
194	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
195	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
196	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
197	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
198	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
199	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
200	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
201	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
202	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
203	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
204	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
205	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
206	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
207	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
208	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
209	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
210	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
211	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
212	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
213	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
214	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
215	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
216	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
217	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
218	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
219	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
220	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
221	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
222	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
223	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
224	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
225	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
226	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
227	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
228	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
229	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
230	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
231	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
232	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
233	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
234	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
235	19/03/20 16:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/11/19 15:07	EMAIL FROM III DD 07112019	 Load PDF	
2	08/11/19 15:07	TP GIA REPORT	 Load PDF	
3	13/11/19 17:06	TP ESTIMATE- MARKED	 Load PDF	
4	19/03/20 16:32	REJECTION EMAIL TO TP	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	11/11/19 08:37	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19019845/DGA3Q2

Date: 31/03/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No : SJD9091M Insured Vehicle No : SHA7053B
 Date of Loss: 04/11/2019 Nature of Claim: TP Claim No: MCT19110091

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJD9091M Engine No: L13A4040105
 Make & Model: HONDA FIT, 1.3 G (A) Chassis No: GE61036250
 Reg. Date: 08/04/2008 (Man. Year: 2008) Odometer: 164552 km
 Colour: Silver
 Engine Capacity: 1339 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50 R15 Rear Tyre Size: 195/50 R15
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,949.80	12,169.86	5,779.94	32.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,320.00	3,250.00	2,070.00	38.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,269.80	15,419.86	7,849.94	33.73
Approved Total (Overridden) (S\$)		12,300.00		
Nett Amount (S\$)	23,269.80	12,300.00	10,969.80	47.14
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 07/11/2019
 Date Inspected: 08/11/2019 Inspected At: Alfred Auto Services & Supplies (HQ)
 Blk 5035, Ang Mo Kio Ave 3, #01-351,
 Ang Mo Kio Industrial Park 2
 Singapore 569538

Estimated Period of Repair: 10.0 days

Adjuster: BRYAN TANI

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

<https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=g...> 31/3/2020

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Mar 2020)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJD9091M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S HEAD LAMP ASSY	Mtg Cracked	685.40 F	*685.40 FL
2	1		*FRONT BUMPER	Distorted / Cut	598.20 F	*598.20 FL
3	10		*FRONT BUMPER CLIPS	Necessary	40.00 FS	*30.00 FS
4	1		*FRONT BUMPER SIDE RETAINER	O/S Not Necessary /N/S Cracked	43.80 F	*21.90 FL
5	1		*FRONT FENDER LH	Buckled	448.90 F	*448.90 FL
6	1		*N/S FRONT FENDER DUST GARNISH	Deformed	83.00 F	*83.00 FL
7	10		*N/S FRONT FENDER DUST GARNISH CLIPS	Necessary	40.00 FS	*40.00 FS
8	1		*FRONT DOOR (LH)	Dented	859.60 F	*859.60 FL
9	1		*N/S FRONT DOOR HINGER	Lower Bent	130.00 F	*65.00 FL
10	1		*FRONT DOOR STOPPER	Not Necessary	59.90 F	*- FL
11	1		*FRONT DOOR LOCK	Not Necessary	269.70 F	*- FL
12	2		*FRONT DOOR WIND VESER	Necessary	90.00 FS	*90.00 FS
13	1		*REAR DOOR (LH)	Dented	822.00 F	*822.00 FL
14	2		*REAR DOOR HINGER	Not Necessary	130.00 F	*- FL
15	1		*REAR DOOR STOPPER	Not Necessary	59.90 F	*- FL
16	1		*LOCAL PANEL (LH)	Repair	504.00 F	*- FL
17	1		*15INCH SPORT RIM	Cut	250.00 FS	*250.00 FS
18	1		*195X50X15 TYRE (70%)	Punctured	199.00 FS	*139.30 FS
19	1		*FRONT LH ABSORBER	Bent	306.00 F	*306.00 FL
20	1		*FRONT LH ABSORBER MOUNTING	Not Necessary	47.00 F	*- FL
21	1		*FRONT LH ABSORBER BEARING	Damaged	40.80 F	*40.80 FL
22	1		*FRONT LH ABSORBER MOUNTING COVER	Not Necessary	33.20 F	*- FL
23	1		*FRONT LH HUP	Damaged	203.00 F	*203.00 FL
24	1		*FRONT LH HUP BEARING	Damaged	41.00 F	*41.00 FL
25	1		*FRONT LH KNUCKLE ARM	Broken	310.00 F	*310.00 FL
26	1		*FRONT LH WHEEL HOUSING	Repair	998.00 F	*- FL
27	1		*FRONT LH LOWER ARM	Bent	252.00 F	*252.00 FL
28	1		*DISC ROTOR	Not Necessary	228.00 F	*- FL
29	1		*STEERING RACK & PINION	Damaged	1,677.90 F	*1,677.90 FL
30	1		*STEERING TIE ROD	Bent	45.90 F	*45.90 FL
31	1		*STEERING TIE ROD END	Distorted	49.20 F	*49.20 FL
32	1		*STEERING TIE ROD COVER	Not Necessary	20.00 F	*- FL
33	1		*STABILIZER BAR	Not Necessary	131.00 F	*- FL
34	1		*STABILIZER BAR LINKAGE	Bent	79.30 F	*79.30 FL
35	1		*ABS SENSOR	Torn	170.00 F	*170.00 FL
36	1		*DRIVE SHAFT	Damaged / Jammed	1,991.00 F	*1,991.00 FL
37	1		*AUTO TRANSMISSION OIL	Not Necessary	180.00 F	*- FL
38	1		*BRAKE HOSE	Torn	190.00 F	*190.00 FL
39	1		*BRAKE FLUID	Necessary	50.00 FS	*50.00 FS
40	1		*FRONT QUARTER GARNISH	Necessary	135.10 F	*135.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*FRONT WINDSCREEN MOULDING	Necessary	258.00 F	*258.00 FL
42	1		*FRONT WINDSCREEN SEALANT & REPAIR KIT	Necessary	120.00 FS	*40.00 FS
43	1		*FRONT DOOR PILLAR LH	Dented	1,260.00 F	*1,260.00 FL
44	1		*REAR FENDER LH	Dented	1,890.00 F	*1,890.00 FL
45	2		*SET LH QUATUAR GLASS REPAIR KIT	Necessary	240.00 F	*240.00 FL
46	1		*CROSS MEMBER	Distorted	1,690.00 F	*1,690.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	17,949.80	15,052.50
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	2,882.64
Total Parts (S\$)	17,949.80	12,169.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEE (2 TIMES)	New	120.00	0.00
2	TO CHECK WIRING & REMOVE REFIT WIRING	New	200.00	30.00
3	TO PANEL BEATING ,WELDING ,STRAIGHTENING REPAIR & RENEW ALL ACCIDENT DAMAGE PARTS	New	1,300.00	1,100.00
4	TO REMOVE & REFIT INTERIOR CARPET ,GARNISH DOOR BOARD,CUSHION & AFFECTED PARTS	New	280.00	120.00
5	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED AREA	New	1,400.00	1,200.00
6	TO RUST PROOF ALL ACCIDENT DAMAGE PARTS	New	120.00	40.00
7	TO REMOVE & REFIT RENEW ALL UNDERCARRIAGE DAMAGE AFFECTED AREA	New	800.00	250.00
8	TO CHECK & ADJUST COMPUTER WHEEL ALIGNMENT &TEST DRIVE	New	180.00	60.00
9	TO PRESS HUP BEARING	New	120.00	50.00
10	TO REMOVE DASHBOARD & REFIT	New	380.00	180.00
11	TO REMOVE FRONT WINDSCREEN	New	180.00	120.00
12	TO REMOVE & REFIT QUARTER GLASS ,FRONT AND REAR LH SIDE	New	240.00	100.00
Gross Labour Cost (\$\$)			5,320.00	3,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >