



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No: 61119

Date: 6.11.2019

Boh Julie

Blk 922 Hougang St. 91 #07-37

Singapore 530922

Honda Fit 1.3A

Estimated Repair Cost for Vehicle Reg. No: SJD 9091 J

REPLACEMENT OF DAMAGED PANELS / PARTS

1 Pc. Head Lamp Assy. <i>monday crac</i>	685.40	<i>✓</i>
1 Pc. Front Bumper <i>cut/damaged</i>	598.20	<i>✓</i>
10 Pcs. Front Bumper Clips <i>huc</i> @ 4.00	40.00	<i>✓ SN</i>
2 Pcs. Front Bumper Side Retainer <i>huc o/s m/s crac</i> @ 21.90	43.80	<i>✓</i>
1 Pc. Front Fender LH <i>Buc</i>	448.90	<i>✓</i>
1 Pc. Front Fender Dust Garnish <i>defunct</i>	83.00	<i>✓</i>
1p Pcs. Front Fender Dust Garnish Clips <i>huc</i> @ 4.00	40.00	<i>✓ SN</i>
1 Pc. Front Door (LH) <i>Defunct</i>	859.60	<i>✓</i>
2 Pcs. Front Door Hinger <i>1 pc 1st lower</i> @ 65.00	130.00	<i>✓</i>
1 Pc. Front Door Stopper <i>huc</i>	59.90	<i>✓</i>
1 Pc. Front Door Lock <i>huc</i>	269.70	<i>X</i>
2 1 Pc. Front Door Wind Veser <i>huc</i>	90.00	<i>✓ SN</i>
1 Pc. Rear Door (LH) <i>Defunct</i>	822.00	<i>✓</i>
2 Pcs. Rear Door Hinger <i>huc</i> @ 65.00	130.00	<i>X</i>
1 Pc. Rear Door Stopper <i>huc</i>	59.90	<i>X</i>
1 Pc. Local Panel (LH) <i>huc</i>	504.00	<i>X</i>
1 Pc. 15inch Sport Rim <i>cut</i>	250.00	<i>✓ SN</i>
1 Pc. 195 x 50 x 15 Tyre <i>punctured 70%</i>	199.00	<i>✓ SN</i>
1 Pc. Front LH Absorber <i>huc 1st</i>	306.00	<i>✓</i>
1 Pc. Front LH Absorber Mounting <i>huc</i>	47.00	<i>X</i>
1 Pc. Front LH Absorber Bearing <i>huc Dam</i>	40.80	<i>✓</i>
1 Pc. Front LH Absorber Mounting Cover <i>huc</i>	33.20	<i>X</i>
1 Pc. Front LH Hup <i>huc Dam</i>	203.00	<i>✓</i>
1 Pc. Front LH Hup Bearing <i>huc Dam</i>	41.00	<i>✓</i>
1 Pc. Front LH Knuckle Arm <i>huc broken</i>	310.00	<i>✓</i>
1 Pc. Front LH Wheel Housing <i>huc reg</i>	998.00	<i>X</i>
1 Pc. Front LH Lower Arm <i>huc 1st</i>	252.00	<i>✓</i>
1 Pc. Disc Rotor <i>huc</i>	228.00	<i>X</i>
1 Pc. Steering Rack & Pinion <i>huc Dam</i>	1,677.90	<i>✓</i>



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



BATTERY



1 Pc. Steering Tie Rod <i>✓</i> <i>1st</i>	45.90 <i>✓</i> <i>✓</i>
1 Pc. Steering Tie Rod End <i>✓</i> <i>disc</i>	49.20 <i>✓</i> <i>✓</i>
1 Pc. Steering Tie Rod Cover <i>NK</i>	20.00 <i>X</i>
1 Pc. Stabilizer Bar <i>✓</i> <i>NK</i>	131.00 <i>✓</i> <i>disc</i> <i>X</i>
1 Pc. Stabilizer Bar Linkage <i>✓</i> <i>1st</i>	79.30 <i>✓</i> <i>✓</i>
1 Pc. ABS Sensor <i>✓</i> <i>disc</i>	170.00 <i>✓</i> <i>✓</i>
1 Pc. Drive Shaft <i>✓</i> <i>Disc</i> <i>1st</i>	1,991.00 <i>✓</i> <i>✓</i>
1 Pc. Auto Transmission Oil <i>NK</i>	180.00 <i>X</i> <i>SN</i>
1 Pc. Brake Hose <i>✓</i> <i>disc</i>	190.00 <i>✓</i> <i>✓</i>
1 Pc. Brake Fluid <i>NK</i>	50.00 <i>✓</i> <i>SN</i>

Total (Panels / Parts): **12,356.70 (SGD)**

LABOR CHARGES

Towing Fee (2 times)	120.00 <i>NK</i>
To check wiring & remove refit wiring.	200.00 <i>30/-</i>
To panel beating, welding, straightening repair & renew All accident damage parts.	1,300.00 <i>1000/-</i>
To remove & refit interior carpet, garnish door board, Cushion & affected parts.	280.00 <i>120/-</i>
To Respray painting on all accident affected area.	1,400.00 <i>1200/-</i>
To rust proof all accident damage parts.	120.00 <i>40/-</i>
To remove & refit renew all undercarriage damage Affected area.	800.00 <i>250/-</i>
To check & adjust computer wheel alignment & test Drive.	180.00 <i>60/-</i>
To press hup bearing.	120.00 <i>50/-</i>

Total (Labor Charges): **4,520.00 (SGD)**



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



BATTERY



TOTAL COST SUMMARY

PANELS / PARTS	12,356.70
LABOR CHARGES	4,520.00
Grand Total:	<u>16,876.70 (SGD)</u>

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'Alfred Auto Services and Supplies'

Handwritten signature

ALFRED AUTO SERVICES & SUPPLIES

08/11/2019 @ 1100am

NA Antine

2/Sum 10 days

Handwritten signature: Ryan

2 KK Auto

Handwritten signature Check MV

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



BATTERY



Reference No: 61119

Date: 12.11.2019

Boh Julie

Blk 922 Hougang St. 91 #07-37

Singapore 530922

Honda Fit 1.3A

Supplementary Repair Cost for Vehicle Reg. No: SJD 9091 J

REPLACEMENT OF DAMAGED PANELS / PARTS

1 Pc. Front Quarter Garnish <i>Nec</i>	135.10 ✓
1 Pc. Front Windscreen Moulding <i>Nec</i>	258.00 ✓
1 Pc. Front Windscreen Sealant & Repair Kit <i>Nec</i>	120.00 ✓
1 Pc. Front Door Pillar LH <i>Deduct</i>	1,260.00 ✓
1 Pc. Rear Fender LH <i>Deduct</i>	1,890.00 ✓
2 Set. LH Quatuar Glass Repair Kit <i>Nec</i> @ 120.00	240.00 ✓
1pc Cross member dist <i>dist</i> 20% disc	1690.00 ✓

Total (Panels / Parts): **3,903.10 (SGD)**

3903.10
3177.48

LABOR CHARGES

To remove dashboard & refit.	380.00 180/-
To remove front windscreen.	180.00 120/-
To remove & refit quarter glass, front and rear LH side.	240.00 100/-

Total (Labor Charges): **800.00 (SGD)**

11/11/2019 e 1030m
[Signature]
Jkk Ande



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



TOTAL COST SUMMARY

PANELS / PARTS	3,903.10
LABOR CHARGES	800.00
Grand Total:	<u>4,703.10 (SGD)</u>

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'Alfred Auto Services and Supplies'

ALFRED AUTO SERVICES & SUPPLIES