

ASS. REC. BY:

REP:

CS/SMO/19019856/KSD312

Special Instruction:

Surveyor: KennethASSIGNMENT (Office)

From (Person):

Yong kang Melvin

of

SMO

Date/Time:

7/11/19 @ 4:19pm

Estimated Cost:

Bill to:

OD: TP / FWS / TP RES / OD RES / EVA / INV / MV / CG

To Inspect Vehicle No:

GBE 2275 K

Insured:

GBH 7690X

at Workshop n/s

Yee Auto

Tel:

GAST 5768

of

160 Sin Ming Drive # 02-17

Policy No:

Claim No:

CMTD1905182/AGC

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 6/11/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

GBE 2275K

Person Contacted:

Mr. Chan

Vehicle IN/OUT

Date/Time

Action/Instruction

1-shmald ✓

GRE 7690X X

GRE 2275K X

11/11/19

@ 16:43 pm received PA to Melvin via email.

18/11

11 Pm 8490d email & Call

(589750 - 0 - 1 - 1)

REF: SMO

REG. FILE BY

Kenneth

ASSIGNMENT

From

Date

8/11/19

Estimated Cost:

OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No.

GBE 2275K

at Workshop no.

Yee Auto

of

160 Sin Ming Drive # 02-17

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

(up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBE 2275K

Yr Regn:

09 15

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyno

C.C.

2P82

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

161452

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTFA1354XOK205087

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size

F: Yokohama 185R 15X8

R: Austone 155R 12X80

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

6/11/19

D.O.I.

8/11/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 21 NOV 2019

Date/Time, File Pass to/

21/11/19

1)

Typist

Date/Time, File Return to/

2)

☐

: Prelim. Report

☒

: Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Witness (\$)

Survey Fee:

Transportation

S + FS \$

Pins

Others

Total

350

Report Format:

Group 1 (10):

\$ 4,900/- 45



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1905182/AGC

Date: 11 November 2019

Our Ref: CS/SMO19019858/Ksd3

The Motor Claims Department
SOMPO INSURANCE SINGAPORE PL

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBE 2275K .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 08/11/2019 at the premises of M/s Yee Auto Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 13,835.80
Revised Estimate Amount	: S\$ 7,014.45
"Check" Items Amount	: S\$ 890.70
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the n/s front portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 5 days

Yours faithfully

Kenneth Kong
Automotive Assessor

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Monday, 11 November 2019 4:43 pm
To: 'Ye, Yong Kang Melvin'
Cc: 'Chan, Shu Hui Agnes'; 'Henry, Irene James'; SUR; assignments; Admin-D (LKKAuto)
Subject: RE: Urgent: Pre-Repair Inspection: Your Vehicle: GBH 7690 X; Our Ref: YeeAuto-GBE 2275 K; Accident Involving GBE 2275 K & GBH 7690 X on 6 November 2019 Our ref : CMTD1905182/AGC
Attachments: PRELI ADVISE - GBE 2275K.pdf

Dear Melvin,

Enclosed preliminary revised of vehicle GBE 2275K.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Friday, 8 November 2019 10:02 am
To: 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Chan, Shu Hui Agnes' <agnes.chan@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: Urgent: Pre-Repair Inspection: Your Vehicle: GBH 7690 X; Our Ref: YeeAuto-GBE 2275 K; Accident Involving GBE 2275 K & GBH 7690 X on 6 November 2019 Our ref : CMTD1905182/AGC

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Nivitha (LKK Auto)

From: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Sent: Thursday, 7 November 2019 4:19 PM
To: sur@lkkauto.com; assignments@lkkauto.com
Cc: Chan, Shu Hui Agnes; Henry, Irene James; yeeauto pteltd; bonnie kwok
Subject: RE: Urgent: Pre-Repair Inspection: Your Vehicle: GBH 7690 X; Our Ref: YeeAuto-GBE 2275 K; Accident Involving GBE 2275 K & GBH 7690 X on 6 November 2019 Our ref : CMTD1905182/AGC

Hi LKK,

Please make arrangement to conduct the survey for GBE2275K.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Download now @

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: bonnie kwok <litigation@bonniekwok.com>

Sent: Thursday, 7 November, 2019 3:44 PM

To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Cc: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>; yeeauto pteltd <yeeautopteltd@gmail.com>

Subject: Re: Urgent: Pre-Repair Inspection: Your Vehicle: GBH 7690 X; Our Ref: YeeAuto-GBE 2275 K; Accident Involving GBE 2275 K & GBH 7690 X on 6 November 2019 Our ref : CMTD1905182/AGC

Dear Sirs,

Our client agrees to LKK Auto Consultants Pte Ltd as the Single Joint Expert (SJE).

Please let us have their report in due course.

Kindly request for the SJE to contact the repairers, M/s Yee Auto Pte Ltd at 6457 5768 to make the necessary arrangements.

Regards,

ST

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Thu, 7 Nov 2019 at 15:05, Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg> wrote:

Our Reference: CMTD1905182/AGC

Your Reference: YeeAuto-GBE 2275 K

Without Prejudice

Date: 07 November 2019

Attention:

Dear Sir / Mdm,

ACCIDENT INVOLVING GBE2275K & GBH7690X ON 06.10.2019

We refer to your Notice of Accident dated 07/11/2019.

The handler for this case is Ms Agnes Chan.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



or



Download now @

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: bonnie kwok <litigation@bonniekwok.com>

Sent: Thursday, 7 November, 2019 10:33 AM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Subject: Urgent: Pre-Repair Inspection: Your Vehicle: GBH 7690 X; Our Ref: YeeAuto-GBE 2275 K; Accident Involving GBE 2275 K & GBH 7690 X on 6 November 2019

Urgent

Dear Sirs,

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle no. GBE 2275 K at M/s Yee Auto Pte Ltd, Block 160 Sin Ming Drive #02-17 Sin Ming Autocity Singapore 575722.

Regards,

ST

--

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other

defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : Somp Insurance Singapore Pte Ltd
50 Raffles Place
#03-03 Singapore Land Tower
Singapore 048623

Estimate No: ES1900114

Date: 08 Nov 2019

Policy No:

Veh Reg No: GBE2275K

Make/Model: TOYOTA TOYOTA
DYNA 150 MANUAL

Chassis No: JTFAT35YX0K205087

Engine No: 1KD2557751

Reg. Date: 30/09/2015

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 06/11/2019

TP Veh Reg No: GBH7690X

Estimate Repair Cost to Vehicle No :GBE2275K

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
Net Price				
1 FRONT NUMBER PLATE	60.00	1 PC	60.00	60.00
Spare Parts				
2 DASHBOARD	1,867.50	1 PC	1,867.50	X
3 ERP IU BRACKET	40.00	1 PC	40.00	261m
4 FRONT BUMPER	672.80	1 PC	672.80	—
5 FRONT CORNER FENDER - LH	223.90	1 PC	223.90	—
6 FRONT CORNER PANEL TOP GARNISH 'BLACK' - LH	85.10	1 PC	85.10	R
7 FRONT DOOR - LH	1,668.50	1 PC	1,668.50	—
8 FRONT DOOR HINGE BOTTOM	82.50	1 PC	82.50	X
9 FRONT DOOR HINGE TOP	82.50	1 PC	82.50	L
10 FRONT DOOR INNER TRIM - LH	420.00	1 PC	420.00	X
11 FRONT DOOR LOCK - LH	285.00	1 PC	285.00	X
12 FRONT DOOR OUTER MOULDING - LH	152.90	1 PC	152.90	X
13 FRONT DOOR STICKER 'COMPANY' - LH	40.00	1 PC	40.00	255m
14 FRONT DOOR STICKER 'LOGO' - LH	260.00	1 PC	260.00	71501m
15 FRONT DOOR WEATHERSTRIP - LH	125.60	1 PC	125.60	X
16 FRONT GRILLE	380.50	1 PC	380.50	2m
17 FRONT GRILLE 'LOGO'	105.10	1 PC	105.10	2m
18 FRONT HEADLAMP - LH	658.40	1 PC	658.40	—
19 FRONT PANEL	781.20	1 PC	781.20	X
20 FRONT PANEL EMBLEM 'DYNA'	95.10	1 PC	95.10	—
21 FRONT PANEL TOP GARNISH 'BLACK'	185.50	1 PC	185.50	X
22 FRONT SIDE MIRROR 'BIG' - LH	135.90	1 PC	135.90	—
23 FRONT SIDE MIRROR 'SMALL' - LH	165.90	1 PC	165.90	—
24 FRONT SIDE MIRROR BRACKET - LH	195.10	1 PC	195.10	—
25 FRONT SIDE MIRROR COVER 'SILVER' - LH	125.90	1 PC	125.90	X
26 FRONT TOP STEP GARNISH - LH	185.30	1 PC	185.30	X
27 FRONT WINDSCREEN	1,170.10	1 PC	1,170.10	—
28 FRONT WINDSCREEN RUBBER	295.50	1 PC	295.50	509m 147.75
29 FRONT WIPER ARM COVER - LH	30.00	1 PC	30.00	X
30 FRONT WIPER ARM COVER - RH	30.00	1 PC	30.00	X
			10,545.80	10,545.80
Labour				
31 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,200.00	1 JOB	1,200.00	600

Not Notarise

61 Day 8490m

Phony After Rain

5 day

me

258



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : Somp Insurance Singapore Pte Ltd
50 Raffles Place
#03-03 Singapore Land Tower
Singapore 048623

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 06/11/2019
TP Veh Reg No: GBH7690X

Estimate No: ES1900114
Date: 08 Nov 2019
Policy No:
Veh Reg No: GBE2275K
Make/Model: TOYOTA TOYOTA
DYNA 150 MANUAL
Chassis No: JTFAT35YX0K205087
Engine No: 1KD2557751
Reg. Date: 30/09/2015

Estimate Repair Cost to Vehicle No :GBE2275K

Description	U/Price	Quantity	List Price	Amount
32 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,200.00	1 JOB	1,200.00	SS 900
33 TO REMOVE/REPLACE DASHBOARD LABOUR.	480.00	1 JOB	480.00	250
34 TO REMOVE/REFIT FRONT WINDSCREEN TO FACILITATE REPAIRS.	200.00	1 JOB	200.00	60
35 TO CHECK WIRING FUNCTIONS.	150.00	1 JOB	150.00	20
			3,230.00	3,230.00
Total				SS 13,835.80
Add GST @ 7%				968.51
Total Amount Payable				SS 14,804.31

TOTAL: SINGAPORE DOLLAR FOURTEEN THOUSAND EIGHT HUNDRED AND FOUR AND CENTS THIRTY ONE ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

YEE AUTO PTE LTD	160 Sin Ming Drive	#02-17/#07-12 Sin Ming AutoCity	Singapore 575722
Tel: 6457 5768	Fax: 6252 8459	Mobile: 9687 4031	
Email: yeeautopte ltd@gmail.com			
Registration No.: 201719251W	GST No: 201719251W		




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO19019858/Ksd3n2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 25-11-2019	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBH 7690X	Veh. Inspected	GBE 2275K
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1905182/AGC	Excess (\$)	0.00
Assign From	YONG KANG MELVIN	Assign Date	07/11/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTFAT35YX0K205087	Colour	SILVER
Odometer	161452	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15X8	YOKOHAMA	9 mm
L/H Front Tyre	195 R15X8	YOKOHAMA	9 mm
R/H Rear Tyre	155 R12X8 (D)	AUSTONE	9/9 mm
L/H Rear Tyre	155 R12X8 (D)	AUSTONE	9/9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	06/11/2019	Inspection Date	08/11/2019
Survey held at	160 SIN MING DRIVE #02-17		
Repairer	YEE AUTO SERVICE		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 2275K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DASHBOARD	SERVICEABLE	1,867.50	-
1	FRONT BUMPER	BENT	672.80	672.80
1	FRONT CORNER FENDER-LH	BENT	223.90	223.90
1	FRONT CORNER PANEL TOP GARNISH "BLACK"-LH	TO REPAIR SEE LABOUR	85.10	-
1	FRONT DOOR-LH	BENT	1,668.50	1,668.50
1	FRONT DOOR HINGE BOTTOM	TO REPAIR SEE LABOUR	82.50	-
1	FRONT DOOR HINGE TOP	TO REPAIR SEE LABOUR	82.50	-
1	FRONT DOOR INNER TRIM-LH	SERVICEABLE	420.00	-
1	FRONT DOOR LOCK-LH	TO REPAIR SEE LABOUR	285.00	-
1	FRONT DOOR OUTER MOULDING-LH	SERVICEABLE	152.90	-
1	FRONT DOOR WEATHERSTRIP-LH	SERVICEABLE	125.60	-
1	FRONT GRILLE	MTG CRACKED	380.50	380.50
1	FRONT GRILLE "LOGO"	NECESSARY	105.10	105.10
1	FRONT HEADLAMP-LH	CRACKED	658.40	658.40
1	FRONT PANEL	TO REPAIR SEE LABOUR	781.20	-
1	FRONT PANEL EMBLEM "DYNA"	NECESSARY	95.10	95.10
1	FRONT PANEL TOP GARNISH "BLACK"	SERVICEABLE	185.50	-
1	FRONT SIDE MIRROR "BIG"-LH	BROKEN	135.90	135.90
1	FRONT SIDE MIRROR "SMALL"-LH	BROKEN	165.90	165.90
1	FRONT SIDE MIRROR BRACKET-LH	BENT	195.10	195.10
1	FRONT SIDE MIRROR COVER "SILVER"-LH	SERVICEABLE	125.90	-
1	FRONT TOP STEP GARNISH-LH	SERVICEABLE	185.30	-
1	FRONT WINDSCREEN	CRACKED	1,170.10	1,170.10
1	FRONT WIPER ARM COVER-LH	SERVICEABLE	30.00	-
1	FRONT WIPER ARM COVER-RH	SERVICEABLE	30.00	-
	LESS 25% DISCOUNT		-	-1,367.83
			9,910.30	4,103.47

Report Ref No. CS/SMO19019858/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	ERP IU BRACKET (SN)	NECESSARY	40.00	26.00
1	FRONT NUMBER PLATE (SN)	BENT	60.00	25.00
1	FRONT DOOR STICKER "COMPANY"-LH (SN)	NECESSARY	40.00	25.00
1	FRONT DOOR STICKER "LOGO"-LH (SN)	NECESSARY	260.00	150.00
1	FRONT WINDSCREEN RUBBER (50%)(SN)	NECESSARY	295.50	147.75
			695.50	373.75
	LABOUR			
	TO DISMANTLE & REPLACE DAMAGED PARTS,PANEL BEAT WHERE NECESSARY.INCLUSIVE OF THE REPAIR OF FRONT CORNER PANEL TOP GARNISH "BLACK"-LH,FRONT DOOR HINGE BOTTOM,FRONT DOOR HINGE TOP,FRONT DOOR LOCK-LH AND FRONT PANEL.		1,200.00	600.00
	TO PUTTY,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.		1,200.00	900.00
	TO REMOVE/REPLACE DASHBOARD LABOUR.		480.00	250.00
	TO REMOVE/REFIT FRONT WINDSCREEN TO FACILITATE REPAIRS.		200.00	60.00
	TO CHECK WIRING FUNCTIONS.		150.00	20.00
			3,230.00	1,830.00
	GRAND TOTAL		13,835.80	6,307.22
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,900.00

Report Ref No. CS/SMO19019858/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.