

11th November 2019

Quotation No.: Q19-OPS-1614

India International Insurance
IOB Building, 64 Cecil St, #04-05
Singapore 049711

Attn: Claims Department

Dear Sir/Mdm

Estimated Cost of Repair job for PC6808S (Accident on 30/10/2019 In front of Hotel Swissotel Merchant Court involving SHD3082C)

We are pleased to submit herein, our quotation for your consideration.

S/N	Description	Qty.	Unit Price	Total Price
1	Supply skill labour & paint material (paint, thinner, hardener, lacquer, masking paper, masking tape, sandpaper, putty to repair RHS rear Bumper	1 portion	\$ 880.00	\$ 880.00
Total				\$ 880.00
GST				\$ 61.60
Sub-Total				\$ 941.60

700

Terms and Conditions:

Payment Terms : 30 days upon invoice
Quotation Validity : 30 days
Lead-Time : 2 working days
Price quoted subject to 7% GST

Repair days - 2 days

Yours faithfully

Handwritten signature



P/P Repair.
before spray. photo

Sun Pin. CLKK -
12/11/2019.
Sun Pin - 8661 2621.
sunpin@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LexBuild International Pte. Ltd.

2 Woodlands Sector 1, #05-12 (Woodlands Spectrum 1), Singapore 738068.

Tel: (65) 6456 3533, Fax: (65) 6456 3353

Website: www.LexBuild.com, Email: sales@LexBuild.com



ROC / CR / GST Reg No: 200004370R