

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

AIG

Owner : Yew Ah Chye

Accident Date : 25-Oct-19

Vehicle No : FBJ 895 H

Vehicle Model : Yamaha 125

Estimated Repair Costs

Qty	Description	Amount S(\$)
<u>List Items</u>		
2	Front fork tube assy	\$ 800 640.00 X
1	Fork under bracket	\$ 17 185.00 X
1	Front rim shaft	\$ 17 45.00 X
1	Front rim bearing	\$ 17 38.00 X
1	Front brake disc	\$ 17 155.00 X
1	Handle-bar	\$ 88 88.00 ✓
2	Handle-bar ends	\$ 32 0/500 64.00 170
1	Hand grip (1 set)	\$ 55 700 55.00 ✓
1	Handle-bar inner bracket	\$ 17 68.00 X
2	Side mirrors	\$ 55 0/500 110.00 170
1	Clutch lever	\$ 17 30.00 X
1	Brake lever	\$ 32 32.00 ✓
2	Front signals	\$ 17 140.00 X
1	Headlamp	\$ 285 285.00 ✓
1	Fairing assy (1 set)	\$ 580 580.00 ✓
1	Radiator grille cover	\$ 17 125.00 X
1	Rear footrest -R/H	\$ 40 40.00 ✓
1	Exhaust assy	\$ 485 485.00 X
1	Exhaust protector	\$ 60 60.00 ✓
1	Step board panel	\$ 285 285.00 ✓
1	Rear fender	\$ 120 120.00 X
		\$ 3,630.00
Less 10%		\$ 363.00
		\$ 3,267.00

not added
2/5 4000

7/11/19
the photo attached

21512
10%
1360.80

c/f: \$ 3,267.00

Special Nett Items

1	Number plate (1 set)	\$ net	28.00	10
2	Fork oils	\$ 17	30.00	X
2	Fork oil seals	\$ 17	56.00	X
1	Steering cone (1 set)	\$ 17	90.00	X
1	Rear box	\$ 17	250.00	180
1	Rear box bracket	\$ 17	100.00	X
1	ERP IU	\$ 17	175.00	X
1	Sticker (1 set)	\$ net	95.00	✓
1	Delivery bag	\$ 700	600.00	?
		\$	1,424.00	

S/No. Labour

1	To provide towing service.	\$	50.00	35
2	To check wiring and reset headlamp focusing	\$ 17	80.00	X
3	To provide labour.	\$	380.00	280
4	To repair body frame.	\$ 17	350.00	X
		\$	860.00	

Grand Total

\$ 5,551.00

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: