

SM SPRAY PAINTING

ON BEHALF OF OWNER :

Policy Particulars: - THIRD PARTY CLAIM

Insured veh.	SLQ4309C	Excess.	NIL
Policy No.	5113274271	Coverage.	
Claiming Against.			
Insured Under.	NTUC INCOME INSURANCE CO-OPERATIVE LTD		

Vehicle Particulars & Condition

Make & Model	MITSUBISHI ATTRAGE		
Engine No.	3A92UGB5911		
Chassis No.	JHMF46209S200246		
Odometer			
Engine CC.			
Year Of Reg.	2017		
Colour.	SILVER		
Parf/COE Rebate.		MV	

Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

Description Of Damages

REAR PORTION

General Information

Accident Date.	6/11/2019
Survey held at	

Yew Tee Automobile Tech Pte Ltd
SYNERGY@KB 25 KAKI BUKIT ROAD 4 #01-61 S417800

Remarks

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR: 7 Days

*Not Authorised
 make repair
 8/11/19
 Theoph. Attorneys
 6dy.
 L/s #2800*

*P-1714
 102
 9-1542.60
 L-1970.00
 3512.60
 282
 2810.00*

SM SPRAY PAINTING

Qty.	Description Of Parts	Pricing
1	REAR BUMPER Dis ✓	\$ 708.00 ✓
1	REAR BUMPER SIDE RETAINER RH 14 X	\$ 26.00 X
1	REAR BUMPER SIDE RETAINER LH 34 ✓	\$ 26.00 ✓
1	REAR BUMPER LOWER SPOILER NS X	\$ 1,110.00 X
1	REAR BUMPER REFLECTOR RH 17 X	\$ 20.00 X
1	REAR BUMPER REFLECTOR LH 17 ✓	\$ 20.00 ✓
1	REAR END PANEL 34/20 ✓	\$ 402.00 ✓
1	REAR END PANEL TOP GARNISH 11 X	\$ 62.00 X
1	REAR SPARE TYRE PANEL 12 X	\$ 906.00 X
1	REAR LH TAILLAMP 17 ✓	\$ 276.00 ✓
1	REAR RH TAILLAMP 17 X	\$ 276.00 X
1	REAR LH FENDER 12 X	\$ 723.00 X
1	REAR LH FENDER INNER SHIELD 12/17 ✓	\$ 38.00 ✓
1	REAR LH FENDER INNER TRIM 17 ✓	\$ 158.00 ✓
1	REAR LH DOOR 12 X	\$ 1,009.00 X
1	TAIL GATE 12 X	\$ 828.00 X
1	TAIL GATE DAMPER RH 17 X	\$ 192.00 X
1	TAIL GATE DAMPER LH 17 X	\$ 192.00 X
1	TAIL GATE LOCK 17 X	\$ 206.00 X
1	TAIL GATE EMBLEM 17 ✓	\$ 48.00 ✓
1	TAIL GATE ATTRAGE EMBLEM 17 ✓	\$ 38.00 ✓

List items \$ 7,264.00
Less 10% \$ 726.40
Sub Total \$ 6,537.60

2	REAR BUMPER SENSOR 17 X	\$ 180.00 X
1	REAR NUMBER PLATE 17 X	\$ 35.00 X
1	REAR LH FENDER INNER SHILED CLIP 17 X	\$ 60.00 X

S/N \$ 275.00

SM SPRAY PAINTING

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
<u>LABOUR</u>		
	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	11 \$ 150.00 X
	To Remove and Refit Rear Bumper Sensor.	\$ 80.00 50
	To Transfer Rear Tailgate.	11 \$ 80.00 X
	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	\$ 50.00 20
	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	\$ 1,500.00 850
	To Do Up Interior Cleaning and Chemical Wash.	11 \$ 150.00 X
	To Carry-Out Body Cavity Preservation.	\$ 120.00 50
	To Supply Spray Terostat Sealant On The Cutting Areas.	11 \$ 100.00 X
	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	\$ 1,200.00 1000
		1970
	LABOUR	\$ 3,430.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.

Sub Total. \$ 10,242.60
7% GST \$ 716.98
Grand Total \$ 10,959.58