	ASS, REC, BY:		REF: (S 3/AIG 1901990L) 905317 Special Instruction:						
	Court Con				T (Office)				
MiliM	From (Person)	Hor Ymm 1	of	ALG		I	Date/Time: 11.11.19	10560·N	
	EstimatedCos				Bill to:				
	To Inspect Ve	hicle No:	SLU 3236P	MV i CS		Insured:	SI U 8661L 8332 2833		
	at Workshop m/s 833 motor sports					Tel:	8332 2833		
	of 160 SY	my prive	Autocary						
	Policy No:				Claim No:	FIG	12896979861		
	Sum Insured:				Excess:				
	Make of Veh:			D.O.A. 3.11. 2019					
		)   REP. / REV 24  -  -  -  -  -  -  -  -  -  -  -  -  -	HRS (w) Person Cor	ntseted:	e Idnd		H.O.D Endorsement:		
	Date/Time		n(x)Es	timate					
		SLU 8661							
						1			
		Sulant 1	YAR.						

Simeyor AV.	16.
PP5	ASSIGNMENT
From: Date:	Veh No. SUU3236P Yr Regn: 03/11/17
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD (TR/ WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: BMW 218i c.c 1499
at Workshop m/s 833 Motos purts	Colour white A/C: Insured / Std / NI / N
of	Sp.Reading 24796 T/Radio: Insured / Std / NI / N
Insured:	Eng/No:
Policy No.	C/No: WDA2H32010V·B97053
	Gen. Cond: Good / Fair / Poor / Burnt
Claims No  Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
- I	Brake: Ingreer / Jammed / Leaked / Burnt or
(Client's Record)  Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
Make of Ven.	Tyre Size: F: 225/45 R17
and the s	ris old risk
(Policy Condition)  Remark: The veh had commenced its	N/S O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Cartinerta.
	Front Rear
Bal. or Market Value:  UDAC Accident Roort: Consistent? : Yes	/
IDAO Accident ripore.	- M
GIA / PK Geen.	-0-
Lat. Nopella.	
Lum Sum: % 3 Val.: Yes	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS	Vehicle: IN / OUT
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collis
Date / Time   Action / Instruction	
	3
	RECEIVED 2 0 NOV 2019
	/
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
1) 20 1 Miss : Final Report	Resurvey No. of Trip: Survey Fee: 180
. l. b. 44.	Resurvey No. of Trip: Survey Fee: 180
1) 20 1 Miss : Final Report	Resurvey No. of Trip:   Survey Fee:   180
1) 20 1 2054 : Final Report Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee: 180

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

		CKING					1	1-	
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sub	mitted	Ins Auth'ed	Status	
Main	05 Nov 2019 Edit Reg		11 Nov 2019 00:00 Edit Adj Rpt					Report  Cancel Case	Survey
	Main	Re	ference		Claim Details		Docume	nts	Show All
CLAIM SU	BFOLDER DE	TAILS				[Creat	ed by adjuster]		
Insured:	EVERS MA	ARK, ID: S70856	851						
Main Claimant:	-								
Vehicle Reg No.:	9. SLU3236P Date of Loss: 03/11/2019 00:00 - :59								
Claim Type	: <b>TP</b> / 761	2896979SG			Policy/Cover Note No.:				
Vehicle Reg No. (Insured):	SLU8661L		Policy No. (Claimant):	9					
					Excess:				
Repairer:							78 Sin Ming - Tel:		
Handling Insurer:	BernardJiQ	ian.Ler@aig.com					ed by <b>Ler, Berna</b>		
Adjuster:	LKK Auto	<b>Consultants Pte</b>	Ltd (HQ) - Tel:	6256-3561	[Handled by )	KING GU	O QIANG] [Fi	nal Rpt due 20	/11/2019]
ASSOCIA	TED MAIL RE	CEIVED						View All Comp	ose Case Mail
<ul> <li>AIG_SG</li> </ul>	(12/11/2019)	Request To Upl	oad TP GIA Re	port					
ALL ASSO	CIATED TAS	KS⊡				View /	All   Search Tasks	Create New Tas	Complete
Due Dat		Type Task	Group Subj	ject Han	dler Assign	ed By	Completed O	n Created (	n Done

### PRE-REPAIR INSPECTION REQUEST - SLU3236P vs SLU8661L (OI) on D.O.A.: 03/11/2019

To 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)

Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Div

Sent Monday, 11 November, 2019 10:55:37 AM

Hi.

Please refer to the enclosed request fromAdvance Law LLC.

Claim no

: 7612896979SG003 Case Owner : Bernard Ler Ji Qian

If you have any queries/concerns, please let us know.

Thanks & Regards.

Hor Yin Rul (Viviane)

FNOL Adjuster I

Singapore FNOL | Claims Operations - Auto

Tel 8001206556 | Ext 1002208

Yinrul.Hor@aig.com | www.aig.sg

From: jiayun.lee@advlawllc.com [mailto:jiayun.lee@advlawllc.com]

Sent: Thursday, November 07, 2019 12:18 PM

To: Hor, Yinrul

Cc: jiayun.lee@advlawllc.com

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLUB661L AND SLU3236P ON 03/11/2019

Dear Sir / Madam,

We refer to the above matter and to your email dated 7 November 2019.

Please be informed that we have our client's instructions to reject your proposal on your Single Joint Expert.

We propose to use the motor surveyor(s) below to conduct the Joint Pre-Repair Survey as our Single Joint Expert.

Kalvin Ang

LKK Auto Consultants Pte Ltd

Xing Guo Qiang

LKK Auto Consultants Pte Ltd

Marcus Chua

LKK Auto Consultants Pte Ltd

Mohamad Taufikh

LKK Auto Consultants Pte Ltd

Adrian Ling

LKK Auto Consultants Pte Ltd

Mohammed Rasul

LKK Auto Consultants Pte Ltd

Kenneth Kong

LKK Auto Consultants Pte Ltd

Kindly let us hear from you within two (2) working days as per the new NIMA protocol, failing which we will proceed with the necessary.

Thank you.

Best Regards,

lia Yun

From: Hor, Yinrul Sent: Thu, 7 Nov 2019 03:34:33 +0000

To: jiayun.lee@advlawllc.com

Ce: Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur,

Parthiban, Theerthan, Subramaniam, Divyashni

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLU8661L AND SLU3236P ON 03/11/2019

Dear Sir/Madam,

Reminder for pre-repair survey

Kindly response to the email below whether agree to the appointment of any of these motor surveyors below as a single joint expert.

Thanks & Regards,

PRE-REPAIR INSPECTION REQUEST - SLU3236P vs SLU8661L (OI) on D.O.A.:... Page 2 of 3

Hor Yin Rul (Viviane)

AIG

FNOL Adjuster L

Singapore FNOL | Claims Operations - Auto

Tel 8001206556 | Ext 1002208 Yinrul Hori@aig.com | www.aig.sg

T: 10.590.m

From: Hor, Yinrul

Sent: Wednesday, November 06, 2019 10:07 AM

To: jiayun.lee@advlawlic.com

Cc: Fong, Andy-SY; Fan, Winnie-LW; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni

Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLU8661L AND SLU3236P ON 03/11/2019

Without Prejudice

Your Reference Our Reference

: DT/mlc/101214/PD

: 7612896979SG003

Dear Sir/Madam.

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

#### Thanks & Regards.

Hor Yin Rul (Viviane)

FNOL Adjuster I

Singapore FNOL | Claims Operations - Auto

Tel: 8001206556 | Ext: 1002208

Yinrui Hor@aig.com | www.aig.sg

From: Jyl. [mailto:jiayun.lee@advlawlic.com] Sent: Tuesday, November 05, 2019 12:08 PM

To: AIG SGP, Claims-Survey

Cc: Eldred@833motorsports.com; 'Max'; Lynn Wang

Subject: [EXTERNAL] DT/mlc/101214/PD (833) SLU3236P, YOUR INSURED CAR: SLU8661L

This message is from an external sender; be cautious with links and attachments.

Dear Sir/ Ms,

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURUSANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES.

We act for who has been instructed with motorcar no. SLU3236P with instructions to repair the same.

: 03/11/2019 @ 16:40 HRS, ALONG JURONG EAST STREET 21 SLIP ROAD TO TOH GUAN ROAD

Please be informed that the said vehicle can be inspected at:-

Venue 833 MOTORSPORTS

160 SIN MING DRIVE #02-09 SIN MING AUTOCITY SINGAPORE 575722

PIC ELDRED

Contact No 8332 2833 PRE-REPAIR INSPECTION REQUEST - SLU3236P vs SLU8661L (OI) on D.O.A.:... Page 3 of 3

Thank you

Best Regards

Jia Yun



430 Lorong 6 Toa Payoh #11-01 OrangeTee Building Singapore 319402 Tel: (65)6323 5488 | Fax: (65)6258 5521

\*\*WARNING: Computer viruses can and/or may be transmitted via email. Kindly check and ensure that all emails received from our firm ends with the domain @advlawlic.com before acting on them. When and/or if unsure, please contact us to verify. Please note that the company accepts no liability for any damage caused by any

#### STRICTLY CONFIDENTIAL

This message, its contents and any files transmitted with it are intended SOLELY for the addressee(s) and may be legally privileged and/or confidential. Access by any other party is unauthorised without the express written permission of the sender. If you have received this message in error, you may not copy or use the contents, attachments or information in any way. Please destroy it and contact us immediately via e-mail return. This message has been prepared using information believed by the author to be reliable and accurate; we make no warranty as to its accuracy or completeness. We do not accept responsibility for changes made to this

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# > Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle** 

/ehicle Owner Particulars	Singapore NRIC
wner ID Type:	043G
Owner ID:	043G
/ehicle Details	SLU3236P
/ehicle No.:	No
/ehicle to be Exported:	15 Nov 2019
ntended Deregistration Date:	B.M.W.
/ehicle Make:	4
/ehicle Model:	218I COUPE LED NAV SR
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	F1041788B38B15A
Chassis No.:	WBA2H32010VB97053
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$31,335.00
Original Registration Date:	03 Nov 2017
First Registration Date:	03 Nov 2017
Transfer Count:	1
Actual ARF Paid:	\$30,869.00
ntended PARF Rebate Details	<i>ti</i>
ARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Nov 2027
ARF Rebate Amount:	\$23,151.00
ntended COE Rebate Details	
COE Expiry Date:	02 Nov 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$52,000.00
COE Rebate Amount:	\$39,822.00
Total Rebate Amount:	\$62,973.00

The information contained herein is correct as at 15 Nov 2019

# **Enquire Vehicle Transfer Fee**

# **Vehicle Details**

Vehicle No. SLU3236P			
Make / Model			
B.M.W. / 218I COUPE LED NAV SR			
Vehicle Type :			
P10 - Passenger Motor Car			
Vehicle Attachment 1 :			
With Sun Roof			
Vehicle Scheme :			
Normal			
Chassis No.:			
WBA2H32010VB97053			
D			
Propellant : Petrol			
Engine No.: F1041788B38B15A			
F1041700B30B13A			
Motor No.:			
-			
Engine Capacity:			
1499 cc			
Power Rating:			
		4.0	
Maximum Power Output :			
100.0 kW (134 bhp)			

Maximum Laden Weight:		
1870 kg		
Unladen Weight:		
1365 kg	v	
Year Of Manufacture :		
2017		
Original Registration Date :		
03 Nov 2017		
Lifespan Expiry Date :		
/=		
COE Category:		
E - Open - all except motorcycle		
Quota Premium :		
\$52,000.00		
COE Expiry Date :		
02 Nov 2027		
Road Tax Expiry Date :		
02 May 2020		
PARF Eligibility Expiry Date :	W	
02 Nov 2027		
Inspection Due Date :		
02 Nov 2020		
Intended Transfer Date :		
15 Nov 2019		
CO2 Emission :		
129.00 (g/km)		
CEV/VES Rebate Utilised Amount :		
\$5,000.00	¥	
CO Emission :		
-		
HC Emission :		
-		
NO: Frainian		
NOx Emission :		

PM Emission :		
<b>×</b>		

# **Fees To Be Paid For Transfer**

Transfer Fees \$25.00

Print

Save as PDF

Copy as Text

OK →

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

Date Of Driving Pass

**Driving Experience** 

Mobile Number Fax Number Contact Number

**EMail Address** 

Gender

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3, Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT			
Date Of Report	03/11/2019 21:33			
Date Of Accident	03/11/2019 16:40			
Exact Location Of Accident	JURONG EAST ST 21 SLIP RD TO TOH GUAN RD			
Country/State of Loss	SINGAPORE			
	DETAILS OF OWN VEHICLE			
Vehicle Registration Number	SLU3236P			
Insured/Policyholder				
Name Of Registered Owner	LIM LEOK			
NRIC No	S1124043G			
Email Address	LL.AGNES@YAHOO.COM.SG			
Mobile Phone No	(LOCAL) +65-90057648			
Alternative Phone No	OFFICE-90057648			
Vehicle Particulars				
Manufacturer	BMW			
Model	2181			
Exact Purpose for which vehicle was being used ime of accident	t PERSONAL			
Are you claiming under your own insurance polic for repair to your vehicle?	y NO			
f No, Please state action to be taken	THIRD PARTY			
Vehicle Category	PRIVATE CAR			
Insurance Company				
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD			
Type Of Coverage	COMPREHENSIVE			
Fleet Policy	NO			
Policy Number	5108941103			
Cover Note Number				
Driver				
Name of Driver	ONG JUN HONG			
NRIC No	S9007585C			
Date Of Birth	08/02/1990			
Occupation	INDOOR			

16/08/2008

MALE

11 YEARS AND 2 MONTHS

(LOCAL) +65-94389507

JH,ONG@HOTMAIL.COM

Address

BLK 607 SENJA ROAD

#12-02

Postcode

670607

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

CHILDREN

Vehicle Registration Number of Driver's Own

Vehicle

•

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

0

involved in the accident

NO

NO

Was any body injured in the Accident?

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: LIM LEOK

GENDER:

: FEMALE

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

**EMAIL TO MOTOR** 

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

SLU8661L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

**EVERS MARK** 

NRIC/Passport Number

S7085685I

Contact Number

97349055

Address

Postcode

Insurance Company Name

#### Sketch Plan

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts
  may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5 Any false reporting may be referred to the Police for investigation
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknow ledge, agree and consent that
- (a) My insurer, my w orkshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) w ho have insured vehicle(s) involved in this accident (all insurer(s) w ho have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me:
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.

ONG JUN HONG 03/11/2019 18:48

Policyholder's Signature / Date & Time Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

#### Sketch Plan #2

#### Sketch Plan

The sketch plan is based on the closest scenario.

Please refer to "Circumstances of the Accident".



### Describe Circumstances of the Accident

BLACK CAR: SLU8661L

WHITE CAR: SLU3236P

DESCRIPTION:

On 3rd November at Ard 1640HRS, I was traveling from Jurong East St 21 at the silp Rd heading towards Toh Guan Rd. There was a stop sign, so I stopped and check for traffic. When I stopped, suddenly Vehicle(SLU8661L) hit onto my rear.

#### Declaration

I/We declare the foregoing particulars are true in every respect.

ONG JUN HONG 03/11/2019 18:48

Policyholder's Signature / Date & Time Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

# MOTORCAR (Rear)

(1)Replace (√ ) (2)Repair() (3)Check (2) (4)Not Consistent NC)

Vehicle No: SLU3236 P

Rea	r Portion				
NA	C INC	Item	CON	AC	Or
113	993626	Rear Number Plate	Cut	1	X.
113	88 993627	Rear Number Plate Base	-		
113		Rear Number Plate Garnish			
114	10 993632	Rear Number Plate Lamp			
114	992958	Rear Bumper	De	/	
114		Rear Bumper Upper	100		
114	993017	Rear Bumper Lower		$\vdash$	
114	993054	Rear Bumper Side			
114		Rear Bumper Tow Cover	M'S	1	
114	6 992341	Rear Bumper Clips	M	1	
114	7 992976	Rear Bumper Bracket	20	/	
114	8 993068	Rear Bumper Side Retainer	-		
114	9 993045	Rear Bumper Reinforcement	BT	/	
115	0 992970	Rear Bumper Beam			
115	1 993077	Rear Bumper Sponge			
115	2 992999	Rear Bumper Damper			
115	3 993040	Rear Bumper Protector			
115	4 993036	Rear Bumper Pad			
115	5 993026	Rear Bumper Moulding			
115	6 993044	Rear Bumper Reflector			
115	7 993023	Rear Bumper Lower Spoiler			
115	8 994023	Reverse Sensor	DAA	1	
115	9 993327	Rear End Panel	Buc	/	_
116	0 993339	Rear End Panel Top Garnish	1700	-	
116	1 993333	Rear End Panel Inner Trim		$\rightarrow$	
116		Boot Compartment Inner Trim		$\rightarrow$	
116	3 993851	Rear LH Taillamp			
116	4 993853	Rear LH Taillamp Garnish	1	$\rightarrow$	
116	993859	Rear LH Taillamp Panel	_	$\rightarrow$	$\neg$
116	995116	Rear RH Taillamp	CRA	7	$\neg$
116	7 993853	Rear RH Taillamp Garnish	UM	-	$\neg$
1168	993859	Rear RH Taillamp Panel		$\rightarrow$	$\dashv$
1169	993554	Rear Apron Panel		$\rightarrow$	$\dashv$
1170		Bootlid	DD	1	$\dashv$
1171		Bootlid Emblem	m.c		2
1172		Bootlid Handle	W.C.C	4	9
1173		Bootlid Moulding		$\rightarrow$	-
1174	990376	Bootlid Reflector		$\rightarrow$	$\dashv$
1175		Bootlid Lamp LH	1	_	$\dashv$
1176		Bootlid Lamp RH		-	$\dashv$
1177		Bootlid Lock		-	$\dashv$
1178	990377	Bootlid Rubber		$\rightarrow$	$\dashv$
1179		Bootlid Hinge	1	$\rightarrow$	$\dashv$
1180	993877	Bootlid Spoiler		+	$\dashv$
1181	994543	Tailgate	1	-	-+
1182	991328	Tailgate Emblem		$\rightarrow$	$\dashv$
1183	994643	Tailgate Outer Handle	$\vdash$	+	$\dashv$
1184	994640	Tailgate Moulding		+	$\dashv$
1185	994545	Tailgate Garnish		+	
1186	994648	Tailgate Reflector		+	$\dashv$
1187	994549	Tailgate Lamp		$\top$	
1188	994646	Tailgate Protector		+	$\neg$
1189	994676	Tailgate Wiper Arm		+	$\neg$
1190	994677	Tailgate Wiper Blade		+	$\neg$
1191	994679	Tailgate Wiper Nozzle		+	-
1192	994555	Tailgate Wiper Motor		+	-
1193	994602	Tailgate Glass		*	$\dashv$
1194	994606	l'ailgate Glass Rubber		+	$\dashv$
1195	994604	Tailgate Glass Moulding		+	$\dashv$
1196	994607	Tailgate Glass Sealant		1	$\dashv$
1197	994629	Tailgate Lock		+	-
1198	994651	Tailgate Rubber		+	-
1199	994611	Tailgate Hinge		+	$\neg$
1200	994594 7	Tailgate Damper		+	$\dashv$
1201	994613 7	Tailgate Inner Board		+	$\dashv$

		Vehicle No: SUU3	236	6	/
NAC		Item	CON	AC	Qt
1202	993784	Spare Tyre Board			
1203	_	Spare Tyre Panel			
1204		Spare Tyre			
1205	_	Spare Tyre Lock Screw			
1206					
1207		Triangle Breakdown Sign			
1208	99050	CD Changer Assy			
1209		Antenna			
1210		Centre Exhaust Pipe Assy			
1211		Centre Exhaust Mounting	-		
1212	993364	Rear Exhaust Pipe			
1213		Rear Exhaust Chrome Pipe			_
1215	003350	Rear Exhaust Mounting Rear Exhaust Heat Shield	-	_	
1216		Rear LH Chassis Member	Buc	/	_
1217		Rear RH Chassis Member		-	
1218		Rear LH Fender	-	-	_
1219	-	Rear LH Fender Protector	-	-	-
1220		Rear LH Fender Inner Panel	+	-	_
1221	993431	Rear LH Fender Inner Trim		-	_
1222	993415	Rear LH Fender Inner Garnish	+	-	
1223	993425	Rear LH Fender Inner Shield		$\dashv$	_
1224		Rear LH Mudflap		-	
1225	993933	Rear LH Wheel Rim			
1226		Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228		Rear RH Fender			
1229		Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234		Rear RH Mudflap			
1235		Rear RH Wheel Rim			
1237	994025	Rear RH Rim Cover			
1238	005162	Rear RH Tyre		-	
1239	993102	Rear Fender Extension Panel LH Rear Fender Extension Panel RH	-	-	
1240	993430	Rear Fender Inner Top Garnish		+	
1241	993673	Rear Fender 1/4 Glass		+	-
1242		Rear Fender 1/4 Glass Rubber	-	+	-
	993453	Rear Fender 1/4 Glass Sealant		+	=
1244	993949	Rear Windscreen Glass	-	+	
1245	993976	Rear Windscreen Rubber		+	
1246	993961	Rear Windscreen Moulding		1	
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
		Rear Fender Air Grille			
	992167				
		Fuel Neck			
		Fuel Tank			
		Fuel Tank Bracket			
1136	990247	Fuel Tank Float			_
130	770247	SHICKEI			$\perp$
				-	$\dashv$
		(1)20		+	$\dashv$
		SDays.	_	+	$\dashv$
		1		+	$\dashv$
				-	$\dashv$
			-	+	-
				+	
				-	-
				+	$\dashv$
				1	$\dashv$
				_	_

crised com

No of Items:	Assessor:

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

	BFOLDER TRA		A dr Austronia	Adi Dat	Adio	Submitted	Ins Auth'ed	Status	
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj	Submitted	Ins worned	Pending for Survey Report Cancel Case	
Main	05 Nov 2019 Edit Reg		11 Nov 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0	.00 ew Rpt			
	Main	R	eference	Claim De	tails		Documents		Show All
CLAIM S	UBFOLDER DE	ETAILS				[Created	by adjuster]		
Insured:	EVERS M	ARK, ID: S7085	685I						
Main Claimant:	-								
Vehicle Re	g. SLU323	6P		Date o	Loss:		9 00:00 - :59 s From LTA Reg Date	(Man Yr)]	
Claim Typ	e: <b>TP</b> / 761	<b>TP</b> / 7612896979SG			Cover 0.:		(Comprehensive) Coverage: 15/12/2017 - 14/12/2019		
Vehicle Ro No. (Insured)	SLU8661	SLU8661L			No. ant):				
(11130100)				Excess					
Repairer:	833 Moto	orsports (HQ) Bl	k 20 Sin Ming Indust	trial Estate Sector A	#01-1	6, 575678 9	Sin Ming - Tel:		
Handling Insurer:	Bernard3i(	Dian.Ler@aig.com					y Ler, Bernard-JQ]		
Adjuster:	LKK Auto	Consultants Pt	e Ltd (HQ) - Tel: 6	256-3561 [Handle	d by X	ING GUO Q	IANG] [Final R	t due 20/11	/2019]
ASSOCI	ATED MAIL RE	ECEIVED					View A	II Compose	Case Mai
. AIG S	G (12/11/2019)	· Request To Ur	load TP GIA Repo	rt					
• AIG_5	0 (12/11/2015)	. Request 10 c)							
ALL ASS	OCIATED TAS	sks⊟			1	View All	Search Tasks   Crea	te New Task	Complet
Due Da	ate Priority		k Group Subje	ct Handler	Assigr	ned By	Completed On	Created On	Done

#### Claim Documents

\*SLU3236P (7612896979SG) [SLU8661L] TP

> Nov 3 2019 12:00AM [EVERS MARK] 833 Motorsports

Photos/Images			3 per p	age 🔻	V
Vo.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	- Daniel Constant	Thumbnail	-
L	13/11/19 09:25	General View	0	Load JPG	V
2	13/11/19 09:25	General View	0	Load JPG	V
	13/11/19 09:25	General View	0	Load JPG	V
1	13/11/19 09:25	General View	0	Load JPG	2
5	13/11/19 09:25	General View	0	Load JPG	V
	13/11/19 09:25	General View	0	Load JPG	V
0	13/11/19 09:25	General View	0	Load JPG	V
	13/11/19 09:25	General View	0	Load JPG	V
)	13/11/19 09:25	General View	0	Load JPG	V
0	13/11/19 09:25	General View	0	Load JPG	V
11	13/11/19 09:25	General View	0	Load JPG	V
12	13/11/19 09:25	General View	0	Load JPG	V
22		General View	0	Load JPG	2
3	13/11/19 09:25	General View	0	Load JPG	2
-	Principal Control of the Control of	General View	0	Load JPG	8
5	13/11/19 09:25	No Walson	0	Load JPG	6
6	13/11/19 09:25	General View	0	Load JPG	6
7	13/11/19 09:25	General View	0	Load JPG	6
8	13/11/19 09:25	General View	0	Load JPG	6
9	13/11/19 09:25	General View			6
0	13/11/19 09:25	General View	0	Load JPG	1
1	13/11/19 09:25	General View	0	Load JPG	
2	13/11/19 09:25	General View	0	Load JPG	6
3	13/11/19 09:25	General View	0	Load JPG	8
4	13/11/19 09:25	General View	0	Load JPG	6
5	13/11/19 09:25	General View	0	Load JPG	6
6	13/11/19 09:25	General View	0	Load JPG	6
7	13/11/19 09:25	General View	0	Load JPG	8
8	13/11/19 09:25	General View	0	Load JPG	18
9	13/11/19 09:25	General View	0	Load JPG	1 5
0	13/11/19 09:25	General View	0	Load JPG	1
1	13/11/19 09:25	General View	0	Load JPG	6
2	13/11/19 09:25	General View	0	Load JPG	6
13	13/11/19 09:25	General View	6	Load JPG	6
14	13/11/19 09:25	General View	0	Load JPG	6
5	13/11/19 09:25	General View	0	Load JPG	6
6	13/11/19 09:25	General View	0	Load JPG	6
7	13/11/19 09:25	General View	0	Load JPG	6
8	13/11/19 09:25	General View	0	Load JPG	6
9	13/11/19 09:25	General View	0	Load JPG	6
10	13/11/19 09:25	General View	0	Load JPG	6
11	13/11/19 09:25	General View	0	Load JPG	6
42	13/11/19 09:25	General View	0	Load JPG	6
43	13/11/19 09:26	Odometer Reading	0	Load JPG	5

no	tos/Images		3 per	page 🔻	$\overline{\mathbf{V}}$
Vo	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
14	13/11/19 09:26	Chassis Number	0	Load JPG	V
15	13/11/19 09:26	Dismantled Parts	0	Load JPG	V
16	13/11/19 09:26	Dismantled Parts	0	Load JPG	V
17	13/11/19 09:26	Dismantled Parts	0	Load JPG	V
48	13/11/19 09:26	Dismantled Parts	0	Load JPG	V
19	13/11/19 09:26	Dismantled Parts	0	Load JPG	V
50	13/11/19 09:26	Dismantled Parts	0	Load JPG	V
51	13/11/19 09:26	Dismantled Parts	0	Load JPG	$\mathbf{V}$
52	13/11/19 09:26	Dismantled Parts	0	Load JPG	☑
53	13/11/19 09:26	Dismantled Parts	0	Load JPG	$\checkmark$
54	13/11/19 09:26	Dismantled Parts	0	Load JPG	V
55	13/11/19 09:26	Dismantled Parts	0	Load JPG	V
56	13/11/19 09:26	Dismantled Parts	0	Load JPG	V
57	13/11/19 09:26	Dismantled Parts	6	Load JPG	V
58	13/11/19 09:26	Dismantled Parts	0	Load JPG	V
59	13/11/19 09:26	Dismantled Parts	0	Load JPG	V
60	13/11/19 09:26	Dismantled Parts	0	Load JPG	V
61	13/11/19 09:26	Dismantled Parts	0	Load JPG	V
62	13/11/19 09:26	Dismantled Parts	0	Load JPG	V
63	13/11/19 09:26	Dismantled Parts	0	Load JPG	V
64	13/11/19 09:26	Dismantled Parts	0	Load JPG	V
65	13/11/19 09:26	Dismantled Parts	0	Load JPG	V
66	13/11/19 09:26	Dismantled Parts	0	Load JPG	V
67	13/11/19 09:26	Dismantled Parts	0	Load JPG	V
68	13/11/19 09:26	Dismantled Parts	6	Load JPG	V
69	13/11/19 09:26	Dismantled Parts	0	Load JPG	V
70	13/11/19 09:26	Dismantled Parts	0	Load JPG	V
71	20/11/19 09:18	After Repair Photo	0	Load JPG	V
72	20/11/19 09:18	After Repair Photo	0	Load JPG	V
73	20/11/19 09:18	After Repair Photo	0	Load JPG	V
(8)					
Doc	umentation		1 per	page 🔻	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	20/11/19 10:48	TP GIA REPORT	6		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	0	Thumbnail Load PDF	Prin

## **Documents Checklist**

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer  Note: Remarks are private unless you show it to other parties.			

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG19019906/GQF3E2

Date:

21/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

SLU3236P

Insured Vehicle No: SLU8661L

Vehicle No: Date of Loss:

03/11/2019

Nature of Claim:

TP

Claim No: 7612896979SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

**SLU3236P** 

Make & Model:

BMW 218I, 1.5 COUPE HID ABS SR (A)

Engine No:

F1041788B38B15A

Reg. Date:

03/11/2017 (Man. Year: 2017) White

Chassis No: Odometer:

WBA2H32010VB97053 24796 km

Colour: Engine Capacity:

Market Value/New Car

1499 cc

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

225/45 R17

Rear Tyre Size:

225/45 R17

Pre-accident Condition:

Front Tyre Size: Front Left Side:

Continental 6 mm

Rear Left Side:

No

Continental 6 mm

Front Right Side:

Continental 6 mm

Rear Right Side:

Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		0.00	0.00	0.00	
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

11/11/2019

Date Inspected:

11/11/2019 Inspected At:

160 SIN MING DRIVE#02-09 Repairer: 833 Motorsports (HQ)

Estimated Period of Repair:

5.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

# Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR NUMBER PLATE	Cut	0.00 F	*- F
2	1	*REAR BUMPER	Deformed	0.00 F	*-F
3	1	*REAR BUMPER TOW COVER	Missing	0.00 F	*- F
4	1	*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1	*REAR BUMPER BRACKET	Deformed	0.00 F	*- F
6	1	*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
7	1	*REVERSE SENSOR	Damaged	0.00 F	*- F
8	1	*REAR END PANEL	Buckled	0.00 F	*- F
9	1	*REAR RH TAILLAMP	Cracked	0.00 F	*- F
10	1	*BOOTLID	Dented	0.00 F	*- F
11	2	*BOOTLID EMBLEM	Necessary	0.00 F	*- F
12	1	*REAR EXHAUST HEAT SHIELD	Buckled	0.00 F	*- F
F=Fr	anchise part.		Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >