

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19019918/KKA3Q2

Date: 28/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SGY7986U **Insured Vehicle No :** SLA2371T

Date of Loss: 05/11/2019 **Nature of Claim:** TP **Claim No:** 3311410601SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGY7986U		
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Engine No:	1NZX602003
Reg. Date:	09/10/2007 (Man. Year: 2007)	Chassis No:	MR053HY9305019888
Colour:	Metallic Black	Odometer:	0 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Hankook 9 mm	Rear Left Side:	Hankook 9 mm
Front Right Side:	Hankook 9 mm	Rear Right Side:	Hankook 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	0.00	0.00	0.00	
Approved Total (Overridden) (\$\$)		5,363.00		
Nett Amount (\$\$)	0.00	5,363.00	-5,363.00	
+ Car Rental (14.0 x S\$60.00/day) (\$\$)		840.00		
+ Doc/Search Fee (\$\$)		2.00		
+ Other Costs (\$\$)		50.00		
Nett Liability (\$\$)		6,255.00		
Global Sum Settlement (\$\$)		6,255.00		

INSPECTION

Date of Assignment: 11/11/2019

Date Inspected: 12/11/2019 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun
Industrial Park A
Singapore 768761

Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$17,800.00

LTA REIMBURSEMENT VALUE (RV) : \$12,437.00

NETT VALUE : \$5,363.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >