



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 31/10/2019

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,325.00	1060
Total Labour	\$1,325.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$878.00	786
Total Spray Painting & Panel Beating	\$878.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010062	Body	F01001-CW273	COVER:REAR TAIL LAMP,RH,FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	/ DD
6010298	VE	88-25225-6039	LAMP.STOP.LED (MAN BUS)	2.00	\$1,141.70	10.00	\$2,055.06	Replace	/ CRU.
6010064	Body	F01001-CW274	BUMPER:REAR,CENTR E,FOR MAN A22 BUS	1.00	\$1,868.80	100.00	\$0.00	Repair	X R
6009992	BODY RH	A01001-CW564	PANEL.SIDE:R11,FOR MAN A22 BUS	1.00	\$1,782.50	100.00	\$0.00	Repair	X R
6009991	BODY RH	4000F06-ACCE4526	PANEL.SIDE:R10,FOR MAN A22 BUS	1.00	\$192.70	100.00	\$0.00	Repair	X R.
6010299	VE	88-25320-6008	LAMP.INDICATOR:LED (MAN BUS)	1.00	\$1,274.10	10.00	\$1,146.69	Replace	/ SCR.
Total					\$7,234.50		\$4,078.98		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair day - 2 days

Sun Pin (Lkk) sunpin@lkkquto.com

Lumpsum Repair

After paint photo

TP without prejudice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 31/10/2019

User ID : BoonChewTay

Section A - Accident Details

Registration Number	SMB1434K
Case Reference Number	BUS/10/19/1083
Registration Date	24/7/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Suvit Sae-Too
Type of Accident	Head to Rear
Accident Date and Time	30/10/2019 7:58 AM
Accident Reported Date and Time	30/10/2019 9:15 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1434K-REAR RIGHT PORTION SLR4975Z (TP) INSURED WITH AIG
Prepared Date and Time	31/10/2019 2:41 PM
Chassis Number	WMAA22ZZ0E7002151
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$0.00
Total Spray Cost	\$878.00	\$0.00
Total Spare Part Cost	\$3,263.18	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$5,466.18	\$0.00
Lump Sum Total	\$5,450.00	\$0.00
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	31/10/2019 2:49 PM	
Signature		x
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	