



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 35092

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
AIG ASIA PACIFIC INSURANCE PTE LTD

DATE : 07/11/2019
CLAIM NO. : 11454
POLICY NO. : DMMFHQ19-000004

FROM : HASRIANAH

VEHICLE NO. : FBH5129P
MAKE/MODEL : YAM / YBR125

S/N	Description	Action	Qty	Unit Price	Amount
1	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	REPLACE	0.50	\$49.00	20 24.50
2	LAMP SIGNAL REAR LH P/N: 44858	REPLACE	1.00	\$63.00	scribble 63.00 X
3	MUDGUARD FRONT (RED) P/N: 45374	REPLACE	1.00	\$97.00	one 97.00
SUB TOTAL					\$184.50
GST @ 7 %					\$12.92
GRAND TOTAL					\$197.42

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD



Acknowledge & Accepted By

This quotation is sent via email / LAN Fax and will bear a computer generated signature.

*35092 *

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

bizSAFE₃



CERT NO. 2002-1-0363
ISO 9001:2015