

INS. CASE OWNER

CC 4/AIG1901

LKK:
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A:

Nature of Accident:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time	STAGE	DATE / PIC
21/11/19	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	21/11/19
	After call ltr to OI:	
21/11/19	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / CIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
PRELIMINARY ADVICE Date/Time: Sent By: Confirm by:		
FINALIZATION Date/Time: Confirm with: Confirm by:		
Repair Cost: \$5,200.00 (6 days) Reduction: 48 % Email ☒ Call ☐		
FINAL SETTLEMENT Date/Time: 09-03-20 Confirm with: Email ☒ Call ☐		
Final Liability: 100 (Agreed / Assessed) BOLA S/N No.: 27 If NO or B 28, Ass. Lia:		
Repair Cost: \$5,200.00 DND REPAIR ENDED TO		
Loss of Rental (LOR): \$5,200 (8 days) = \$41,600		
Loss of Use (LOU): \$5 (5 x days)		
Loss of Income (LOI): \$5 (5 x days)		
LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LO ☐ [Tick only one]		
GIA/LTA Search \$57.95		
Medical: \$5 -		
Disbursement: \$5 - (e.g. Tow/ Independent)		
Legal Cost \$5 -		
Total: \$52,948.25 Global Sum \$5:		
FINAL PAYMENT Date/Time: 09-03-20 Confirm with: Email ☒ Call ☐		
Payee 1: \$52,948.25 Name 1: SOU MONG AUCX (192 BTH PR 03)		
Payee 2: (Strike if N.A.) \$5 Name 2:		
Payee 3: (Strike if N.A.) \$5 Name 3:		

COPY SENT
12/3/2022

ASS. REC. BY:

REF: A16-1

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Soon:

Consistent? : Yes or No

Est. Repairs:

6 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type:

M.Cs / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal:


L/Bal:

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.



Date / Time

Action / Instruction

File pass to

40,000 (EST: +18,184.32 45%)

MARKET VALUE: 98,000

LTH PREMIUM: 57,616

NET TOTAL: 28,384

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



Sin Ming Autocare BFG Pte Ltd
 176, Sin Ming Drive #02-05
 Sin Ming Autocare Complex
 Singapore 575721
 Tel : (65) 6455 0600
 Fax : (65) 6455 6192
 Website: www.autocare.com.sg
 GST Reg. No: 20-0210033-N

AIG ASIA PACIFIC INSURANCE PTE LTD
 AIG BUILDING
 78 SHENTON WAY #07-16 079120
 SINGAPORE
 Attention : Motor Claim Department
 Contact : 6419 3000 Fax No. : 68357416

Estimate : E19/2522

Date : 11/11/2019
 Vehicle Num. : SLS5613G
 Make/Model : PORSCHE CAYENNE-2011
 Chassis/Eng# : WP1ZZZ92ZBLA33623
 Accident Date : 08/11/2019
 Claim No. : BFG/JH
 Reference : TP CLAIM
 Policy No. : DMPPHQ19-005897

Not Authorized

1st. 11/11/19

6- Jan

11/11/19 820,000

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS:				
1.	1PC	REAR BUMPER		
2.	4PCS	REAR BUMPER SENSOR		
3.	1PC	REAR BUMPER LOWER SPOILER		
4.	1PC	REAR BUMPER COVER INNER SUPPORT		
5.	1PC	REAR BUMPER COVER NUT		
6.	1PC	REAR BUMPER SUPPORT BRACKET		
7.	1PC	REAR BUMPER TOWING COVER		
8.	2PCS	REAR BUMPER TRIM		
9.	2PCS	REAR BUMPER TRIM PANEL SCREW		
10.	2PCS	REAR BUMPER TRIM PANEL NUT		
11.	1PC	REAR BUMPER TRIM COVER		
12.	2PCS	REAR BUMPER TRIM COVER SCREW		
13.	1PC	REAR BUMPER REFLECTOR		
14.	1PC	REAR INNER TRUNK TAIL LIGHT LAMP		
15.	1PC	REAR WINDSCREEN WIPER ARM COVER		
16.	1PC	TAILGATE DOOR LOCK		
17.	1PC	TAILGATE AUTO DOOR LOCK SWITCH		
18.	2PCS	REAR TRUNK HATCH STRUT		
19.	1PC	REAR LID		
20.	1PC	REAR LID HANDLE HOUSING		
21.	1PC	REAR LID CHROME		
22.	1PC	REAR MUFFLER		
23.	2PCS	CLAMPING MUFFLER SLEEVE		
24.	2PCS	MUFFLER SUPPORT WITH RUBBER		
25.	2PCS	TAIL PIPE CLAMP		
26.	2PCS	TAIL EXHAUST TIPS MUFFLER CHROME PIPE		
27.	1PC	REAR MUFFLER HEAT SHEILD COVER		
28.	1PC	REAR STABILIZER BAR		
29.	2PCS	REAR STABILIZER MOUNTING CLAMP		

B11/CM	2,178.00	✓
488.95	1,955.80	✓
CM	653.13	✓
CM	204.05	✓
CM	146.03	✓
CM	89.93	✓
CM	146.02	✓
141.63	283.26	✓
16.50	33.00	✓
16.50	33.00	✓
16.50	141.63	✓
16.50	33.00	✓
16.50	67.65	✓
16.50	1,521.85	✓
16.50	491.15	✓
16.50	1,176.73	✓
16.50	188.10	✓
1,322.48	2,644.96	✓
1,322.48	6,130.03	✓
1,322.48	83.05	✓
1,322.48	482.08	✓
1,322.48	5,610.00	✓
1,322.48	2,739.00	✓
1,322.48	284.36	✓
1,322.48	305.26	✓
1,322.48	2,739.00	✓
1,322.48	929.76	✓
1,322.48	1,316.98	✓
1,322.48	65.46	✓

CONTINUE / ...

LKK Auto Consultants hereby notify the Repairer of the following:

- To remove heliometer spray painting
- To display damaged parts during recovery
- Part prices are subject to confirmation
- Short petty supply item is "Without Frequent" item
- No legal modification is allowed
- Supplemental work must be approved and is subject to final approval from Insurance Company

Authorized to Repair
 Signature
 Date



Sin Ming Autocare BFG Pte Ltd

176, Sin Ming Drive #02-05
Sin Ming Autocare Complex
Singapore 575221
Tel : (65) 6455 0800
Fax : (65) 6455 6192
Website: www.autocare.com.sg
GST Reg. No: 20-0210033-N

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG BUILDING
78 SHENTON WAY #07-16 / 079120
SINGAPORE
Attention : Motor Claim Department
Contact : 6419 3000 Fax No. : 68357416

Estimate : E19/2522

Date : 11/11/2019
Vehicle Num. : SLS5613G
Make/Model : PORSCHE CAYENNE-2011
Chassis/Eng# : WP1ZZZ922BLA33623
Accident Date : 08/11/2019
Claim No. : BFG/JH
Reference : TP CLAIM
Policy No. : DMPPHQ19-005897

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

30.	4PCS	REAR STABILIZER MOUNTING RUBBER	74.80	299.20
-----	------	---------------------------------	-------	--------

List Total S\$:

32,971.47

10.00% Discount S\$:

3,297.15

29,674.32

LABOUR :

TO REMOVE & REINSTALL UNDERCARRIAGE EXHAUST PIPE
TO PANEL BEATING ALL DAMAGES PORTIONS
TO SPRAY PAINT ALL DAMAGES PORTIONS
TO REMOVE & INSTALL REVERSE SENSOR
TO CHECK ALL WIRING
RUST PROOFING ON AFFECTED PORTIONS
TO CHECK BOOTLID WATER SEEPAGE
TO REMOVE & TRANSFER ALL INTERNAL UPHOLSTERY
TO REMOVE & REINSTALL REAR WINDSCREEN GLASS

nn 450.00 X
1000 1,600.00
900 2,000.00
150.00 60
300 200.00
180.00 30
300 120.00
350.00 80
1200 250.00

Labour Total S\$:

5,300.00

E & O.E.

Total S\$: 34,974.32

for Sin Ming Autocare BFG Pte Ltd



Sin Ming Autocare BFG Pte Ltd

176, Sin Ming Drive #02-05
Sin Ming Autocare Complex
Singapore 575721
Tel : (65) 6455 0600
Fax : (65) 6455 6192
Website: www.autocare.com.sg
GST Reg. No: 20-0210033-N

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG BUILDING
78 SHENTON WAY #07-16 079120
SINGAPORE

Attention : Motor Claim Department
Contact : 6419 3000 Fax No. : 68357416

Supplementary Estimate : E19/2524

Date : 11/11/2019
Vehicle Num. : SLS5613G
Make/Model : PORSCHE CAYENNE-2011
Chassis/Eng# : WP1ZZZ92ZBLA33623
Accident Date : 08/11/2019
Claim No. : BFG/JH
Reference : TP CLAIM
Policy No. : DMPPHQ19-005897

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1PC	LIST ITEMS :		
2.	1PC	REAR WINDSCREEN GLASS CUM MOULDING		
		SAFETY BELT		
		List TotalS\$:		3,150.00
		10.00% Discount S\$:		750.00
				3,900.00
				390.00
				3,510.00

E. & O.E.

Total S\$: 3,510.00


for Sin Ming Autocare BFG Pte Ltd



Sin Ming Autocare BFG Pte Ltd

176, Sin Ming Drive #02-05
Sin Ming Autocare Complex
Singapore 575721
Tel : (65) 6455 0600
Fax : (65) 6455 6192
Website: www.autocare.com.sg
GST Reg. No: 20-0210033-N

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG BUILDING
78 SHENTON WAY #07-16 079120
SINGAPORE

Attention : Motor Claim Department

Contact : 6419 3000 Fax No. : 68357416

Estimate : E19/2522

Date : 11/11/2019

Vehicle Num. : SLS5613G

Make/Model : PORSCHE CAYENNE-2011

Chassis/Eng# : WP1ZZZ92ZBLA33623

Accident Date : 08/11/2019

Claim No. : BFG/JH

Reference : TP CLAIM

Policy No. : DMPPHQ19-005897

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1PC	REAR BUMPER	2,178.00	✓
2.	4PCS	REAR BUMPER SENSOR	488.95	✓
3.	1PC	REAR BUMPER LOWER SPOILER	CMY 653.13	✓
4.	1PC	REAR BUMPER COVER INNER SUPPORT	204.05	✓
5.	1PC	REAR BUMPER COVER NUT	RM 146.03	✓
6.	1PC	REAR BUMPER SUPPORT BRACKET	89.93	✓
7.	1PC	REAR BUMPER TOWING COVER	M17 146.02	✓
8.	2PCS	REAR BUMPER TRIM	141.63	✓
9.	2PCS	REAR BUMPER TRIM PANEL SCREW	16.50	✓
10.	2PCS	REAR BUMPER TRIM PANEL NUT	16.50	✓
11.	1PC	REAR BUMPER TRIM COVER	141.63	✓
12.	2PCS	REAR BUMPER TRIM COVER SCREW	16.50	✓
13.	1PC	REAR BUMPER REFLECTOR	M17 67.65	✓
14.	1PC	REAR INNER TRUNK TAIL LIGHT LAMP	ARM 1,521.85	✓
15.	1PC	REAR WINDSCREEN WIPER ARM COVER	491.15	X
16.	1PC	TAILGATE DOOR LOCK	1,176.73	✓
17.	1PC	TAILGATE AUTO DOOR LOCK SWITCH	188.10	✓
18.	2PCS	REAR TRUNK HATCH STRUT	1,322.48	✓
19.	1PC	REAR LID	RM 6,130.03	✓
20.	1PC	REAR LID HANDLE HOUSING	83.05	✓
21.	1PC	REAR LID CHROME	RM 482.08	✓
22.	1PC	REAR MUFFLER	RM 5,610.00	✓
23.	2PCS	CLAMPING MUFFLER SLEEVE	M17 1,369.50	✓
24.	2PCS	MUFFLER SUPPORT WITH RUBBER	142.18	✓
25.	2PCS	TAIL PIPE CLAMP	RM 152.63	✓
26.	2PCS	TAIL EXHAUST TIPS MUFFLER CHROME PIPE	1,369.50	✓
27.	1PC	REAR MUFFLER HEAT SHEILD COVER	929.76	✓
28.	1PC	REAR STABILIZER BAR	RM 1,316.98	X
29.	2PCS	REAR STABILIZER MOUNTING CLAMP	32.73	✓

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To rectify before/after spray painting
- To display damaged part(s) during rectify
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification is allowed
- Supplementary work must be rectified and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



Sin Ming Autocare BFG Pte Ltd

176, Sin Ming Drive #02-05
Sin Ming Autocare Complex
Singapore 575721
Tel : (65) 6455 0600
Fax : (65) 6455 6192
Website: www.autocare.com.sg
GST Reg. No: 20-0210033-N

AIG ASIA PACIFIC INSURANCE PTE LTD

AIG BUILDING
78 SHENTON WAY #07-16 079120
SINGAPORE

Attention : Motor Claim Department

Contact : 6419 3000 Fax No. : 68357416

Estimate : E19/2522

Date : 11/11/2019
Vehicle Num. : SLS5613G
Make/Model : PORSCHE CAYENNE-2011
Chassis/Eng# : WP1ZZZ92ZBLA33623
Accident Date : 08/11/2019
Claim No. : BFG/JH
Reference : TP CLAIM
Policy No. : DMPPHQ19-005897

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

30.	4PCS	REAR STABILIZER MOUNTING RUBBER	74.80	299.20 7
List Total S\$:				32,971.47
10.00% Discount S\$:				3,297.15
				29,674.32

LABOUR :

TO REMOVE & REINSTALL UNDERCARRIAGE EXHAUST PIPE
TO PANEL BEATING ALL DAMAGES PORTIONS
TO SPRAY PAINT ALL DAMAGES PORTIONS
TO REMOVE & INSTALL REVERSE SENSOR
TO CHECK ALL WIRING
RUST PROOFING ON AFFECTED PORTIONS
TO CHECK BOOTLID WATER SEEPAGE
TO REMOVE & TRANSFER ALL INTERNAL UPHOLSTERY
TO REMOVE & REINSTALL REAR WINDSCREEN GLASS

1000l	450.00	7
900l	1,600.00	
	2,000.00	
30l	150.00	60l
	200.00	
30l	180.00	7
	120.00	
120l	350.00	80l
	250.00	
Labour Total S\$:		5,300.00

E. & O.E.

Total S\$: 34,974.32

for Sin Ming Autocare BFG Pte Ltd

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	854W
Vehicle Details	
Vehicle No.:	SL55613G
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Nov 2019
Vehicle Make:	PORSCHE
Vehicle Model:	CAYENNE DIESEL V6
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	CAS154478
Chassis No.:	WP1ZZZ92ZBLA33623
Maximum Power Output:	176.0 kW (236 bhp)
Open Market Value:	\$86,564.00
Original Registration Date:	24 Jun 2011
First Registration Date:	24 Jun 2011
Transfer Count:	5
Actual ARF Paid:	\$86,564.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jun 2021
PARF Rebate Amount:	\$47,610.00
Intended COE Rebate Details	
COE Expiry Date:	23 Jun 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$62,000.00
COE Rebate Amount:	\$10,006.00
Total Rebate Amount:	\$57,616.00

The information contained herein is correct as at 11 Nov 2019

OK

PRE-REPAIR INSPECTION REQUEST – SLS5613G vs SKH4247G (OI) on D.O....

From: Fan, Winnie-LW
To:
Cc: Fong, Andy-SY
Sent: 11/11/2019 12:03:36 PM
Attachments:  [SAS SLS5613G.PDF](#)

Hi LKK,

Kindly assist to survey, vehicle in.

Workshop:

Sin Ming Autocare BFG Pte Ltd

176 Sin Ming Drive #02-05 Singapore 575721

Tel: 6455 0600 Fax: 64556192 Email: motorclaims@autocare.com.sg

12.57pm 11/11/19

V: In

P: Angelen

S: Kenneth

Winnie Fan

AIG

Claims Service Associate

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Thursday, 21 November 2019 3:50 PM
To: Motor Claims
Subject: ACCIDENT INVOLVING SLS 5613G & SKH 4247G ON 07/11/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir/Madam,

ACCIDENT INVOLVING SLS 5613G & SKH 4247G ON 07/11/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us **(LKK)** to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 5(408933)



Your Ref: SKH 42474

Date : 8-11-2019

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG BUILDING
78 SHENTON WAY
#07-16
(S) 079120

LETTER OF AUTHORITY

I/We, MEAGHER DANIEL FRANCIS NRIC NO: S 8368322 H
hereby authorize(s) **Sin Ming Autocare BFG Pte Ltd** to provide further
instructions on my behalf relating to the said claims and as such, all future
correspondence should be addressed to **176 Sin Ming Drive #02-05, Sin
Ming Autocare Complex, Singapore 575721.**

I hereby authorized the cheque payment to be issued in favour of **M/s Sin
Ming Autocare BFG Pte Ltd.**

Claimant's Signature :  
Name : MEAGHER DANIEL FRANCIS
Nric : S 8368322 H
Date : 8/11/2019

Witness By :  
Name : _____
Nric : _____
Date : 8/11/2019

*Please note that it is a condition of any settlement reached that it shall be
without prejudice to any personal injury claim (if any) of the owner/claimant.

Claim Audit

AUDIT TRAIL					
No.	On	Audit	Remarks	By	
1	11 Nov 2019 14:44	Cim Dtl Modified	Claimant's Name: -> ABM LEASING PTE LTD. Claimant's ID: -> 201416854W.	[A] Lau Shu Pei	
2	11 Nov 2019 14:44	Cim Veh Model Changed	(205807) PORSCHE CAYENNE 3.0 (A).	[A] Lau Shu Pei	
3	11 Nov 2019 14:44	Cim Created	Reg No: SLS5613G. Acct Date: 2019/11/07. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. L td. (SG). TP Insurer: EQ Insurance Company Ltd (HQ). Workshop: Sin Ming Autocare BFG Pte Ltd (H Q)	[A] Lau Shu Pei	
4	11 Nov 2019 14:44	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei	
5	11 Nov 2019 14:44	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/11/20	[A] Lau Shu Pei	
6	11 Nov 2019 14:44	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei	
7	11 Nov 2019 14:44	Cim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (E xpress)	[I] Merimen Administrator	
8	11 Nov 2019 14:45	Label Added	(19):Fastlane.	[A] Lau Shu Pei	
9	11 Nov 2019 14:45	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] Lau Shu Pei	
10	30 Jan 2020 16:04	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN	
11	30 Jan 2020 16:04	Cim Dtl Modified	Claim Conclusion: -> 3.	[A] JOANNE LEE KHANG MIN	
12	30 Jan 2020 16:04	Cim Dtl Modified	3PJ Reg. Date: -> 2011/06/24.	[A] JOANNE LEE KHANG MIN	
13	30 Jan 2020 16:04	Cim Details Notified		[A] JOANNE LEE KHANG MIN	
14	17 Feb 2020 16:36	Adj Mandate Request	Cur.Reg:22948.25:LIABILITY: 100% B:27 OID REAR ENDED TP	[A] Asher Sng Rong Yi	

Date From

◀

📅

▶

Date To

◀

📅

▶

Audit Type

None

Go

ACTIVITY
No record

Merimen Billing for this case - Transaction History								
Bill Amt Pay	Bill Date	Bill Type	Accr Type	Accr Issuer	Co-Insurer (Reinsurer)	Ref 1	Ref 2	Amount
2344631	13 Nov 2019 16:58:44	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	AIG Asia Pacific Insurance Pte. Ltd. (Express)	SLS5613G	SKH4247G	11.77
2422057	30 Jan 2020 16:04:54	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLS5613G	SKH4247G	11.77

Print Received Message

This mail is associated with :

***SLS5613G (3182626380SG)**
[SKH4247G]
TP
ABM LEASING PTE LTD
Nov 7 2019 6:00PM
[JOHN PATRICK TANG KOON CHEONG]
Sin Ming Autocare BFG Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 04/03/2020 16:58 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$22948.25) - SLS5613G - Claim Handler: MdNoor, Norsiah

Approved:22948.25.

...CLAIM SUBFOLDER...(Pending for Survey Report)
Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Nov 2019 Edit Reg		11 Nov 2019 00:00 Edit Adj Rpt	\$520,000.00 Edit Estimates	\$520,000.00 View Rpt		Pending for Survey Report Cancel Case

MainReferenceClaim DetailsDocumentsShow All

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	JOHN PATRICK TANG KOON CHEONG, ID: S2563490Z		
Main Claimant:	ABM LEASING PTE LTD, Co. Reg. No.: 201416854W		
Vehicle Reg. No.:	SLS5613G	Date of Loss:	07/11/2019 18:00 - :59 [100 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3182626380SG	Policy/Cover Note No.:	(Comprehensive) Coverage: 07/12/2018 - 06/12/2019
Vehicle Reg. No. (Insured):	SKH4247G	Policy No. (Claimant):	DMPPHQ19-005897
		Excess:	
Repairer:	Sin Ming Autocare BFG Pte Ltd (HQ) 176, Sin Ming Drive #02-05, Sin Ming Autocare Complex, 575721 Sin Ming - Tel: 64550600		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 20/11/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG_EXPRESS (04/03/2020): Alert - Adj Mandate Approved (\$22948.25) - SLS5613G - Claim Handler: MdNoor, No...

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS5613G (31826263805G)
[SKH4247G]
TP
ABM LEASING PTE LTD
Nov 7 2019 6:00PM
[JOHN PATRICK TANG KOON CHEONG]
Sin Ming Autocare BFG Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/01/20 15:57	General View	 Load JPG	☒
2	06/01/20 15:57	General View	 Load JPG	☒
3	06/01/20 15:57	General View	 Load JPG	☒
4	06/01/20 15:57	General View	 Load JPG	☒
5	06/01/20 15:57	General View	 Load JPG	☒
6	06/01/20 15:57	General View	 Load JPG	☒
7	06/01/20 15:57	General View	 Load JPG	☒
8	06/01/20 15:57	General View	 Load JPG	☒
9	06/01/20 15:57	General View	 Load JPG	☒
10	06/01/20 15:57	General View	 Load JPG	☒
11	06/01/20 15:57	General View	 Load JPG	☒
12	06/01/20 15:57	General View	 Load JPG	☒
13	06/01/20 15:57	General View	 Load JPG	☒
14	06/01/20 15:57	General View	 Load JPG	☒
15	06/01/20 15:57	General View	 Load JPG	☒
16	06/01/20 15:57	General View	 Load JPG	☒
17	06/01/20 15:57	General View	 Load JPG	☒
18	06/01/20 15:57	General View	 Load JPG	☒
19	06/01/20 15:57	General View	 Load JPG	☒
20	06/01/20 15:57	General View	 Load JPG	☒
21	06/01/20 15:57	General View	 Load JPG	☒
22	06/01/20 15:57	Odometer Reading	 Load JPG	☒
23	06/01/20 15:57	General View	 Load JPG	☒
24	06/01/20 15:57	Chassis Number	 Load JPG	☒
25	06/01/20 16:00	Reinspection Photo	 Load JPG	☒
26	06/01/20 16:00	Reinspection Photo	 Load JPG	☒
27	06/01/20 16:00	Reinspection Photo	 Load JPG	☒
28	06/01/20 16:00	Reinspection Photo	 Load JPG	☒

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/11/19 14:45	EMAIL FROM AIG DD 11112019.	 Load PDF	
2	11/11/19 14:45	TP GIA REPORT	 Load PDF	
3	12/11/19 16:58	TP ESTIMATE- MARKED	 Load PDF	
4	21/11/19 16:36	LETTER TO OI	 Load PDF	
5	06/01/20 15:56	TP ESTIMATE - MARKED (FINAL)	 Load PDF	
6	30/01/20 17:13	RENTAL RECEIPT	 Load PDF	
7	30/01/20 17:13	LTA SEARCH	 Load PDF	
8	30/01/20 17:13	LOD	 Load PDF	
9	17/03/20 10:55	WORKSHOP INVOICE	 Load PDF	
10	17/03/20 10:55	AUTHORISATION TO ACT FORM	 Load PDF	
11	17/03/20 10:55	Release Voucher	 Load PDF	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail
1	13/11/19 16:57	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKH4247G (Insd veh)	Model:	PORSCHE CAYENNE 3.0 (A)
	SLS5613G (TP veh)		
Date of Accident:	07/11/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	41,178.22
Final Repair Cost	:	\$	21,400.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	1,540.80 8 days
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	22,948.25
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)			
B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____			
BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Sin Ming Autocare BFG Pte Ltd	:	\$ 22,948.25
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

17 Mar
2020

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19019934/KES3Q2

Date: 17/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SLS5613G

Insured Vehicle No : SKH4247G

Date of Loss: 07/11/2019

Nature of Claim: TP

Claim No: 3182626380SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS5613G

Make & Model: PORSCHE CAYENNE, 3.0 (A)

Engine No: CAS154478

Reg. Date: 24/06/2011 (Man. Year: 2011)

Chassis No: WP1ZZZ92ZBLA33623

Colour: Metallic Pearl White

Odometer: 114757 km

Engine Capacity: 2967 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/50 R19

Rear Tyre Size: 265/50 R19

Front Left Side: Pirelli 4 mm

Rear Left Side: Pirelli 5 mm

Front Right Side: Pirelli 4 mm

Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,184.32	22,741.02	10,443.30	31.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,300.00	2,250.00	3,050.00	57.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	38,484.32	24,991.02	13,493.30	35.06
Approved Total (Overridden) (S\$)		20,000.00		
(S\$)	38,484.32	20,000.00	18,484.32	48.03
+ GST 7.00/7.00% (S\$)	2,693.90	1,400.00	1,293.90	48.03
Nett Amount (S\$)	41,178.22	21,400.00	19,778.22	48.03
+ Car Rental (8.0 x S\$180.00/day + 7.00% GST) (S\$)		1,540.80		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		22,948.25		

INSPECTION

Date of Assignment: 11/11/2019

Date Inspected: 11/11/2019 Inspected At:

Sin Ming Autocare BFG Pte Ltd (HQ)
176, Sin Ming Drive #02-05, Sin Ming
Autocare Complex
Singapore 575721

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent / Cracked	2,178.00 FL	*2,178.00 FL
2	4		*REAR BUMPER SENSOR	Serviceable	1,955.80 FL	*- FL
3	1		*REAR BUMPER LOWER SPOILER	Cracked	653.13 FL	*653.13 FL
4	1		*REAR BUMPER COVER INNER SUPPORT	Serviceable	204.05 FL	*- FL
5	1		*REAR BUMPER COVER NUT	Necessary	146.03 FL	*146.03 FL
6	1		*REAR BUMPER SUPPORT BRACKET	Repair	89.93 FL	*- FL
7	1		*REAR BUMPER TOWING COVER	Missing	146.02 FL	*146.02 FL
8	2		*REAR BUMPER TRIM	Serviceable	283.26 FL	*- FL
9	2		*REAR BUMPER TRIM PANEL SCREW	Serviceable	33.00 FL	*- FL
10	2		*REAR BUMPER TRIM PANEL NUT	Serviceable	33.00 FL	*- FL
11	1		*REAR BUMPER TRIM COVER	Distorted	141.63 FL	*141.63 FL
12	2		*REAR BUMPER TRIM COVER SCREW	Necessary	33.00 FL	*33.00 FL
13	1		*REAR BUMPER REFLECTOR	Missing	67.65 FL	*67.65 FL
14	1		*REAR INNER TRUNK TAIL LIGHT LAMP	Broken	1,521.85 FL	*1,521.85 FL
15	1		*REAR WINDSCREEN WIPER ARM COVER	Serviceable	491.15 FL	*- FL
16	1		*TAILGATE DOOR LOCK	Repair	1,176.73 FL	*- FL
17	1		*TAILGATE AUTO DOOR LOCK SWITCH	Repair	188.10 FL	*- FL
18	2		*REAR TRUNK LID HATCH STRUT	Serviceable	2,644.96 FL	*- FL
19	1		*REAR LID	Bent	6,130.03 FL	*6,130.03 FL
20	1		*REAR LID HANLE HOUSING	Serviceable	83.05 FL	*- FL
21	1		*REAR LID CHROME	Bent	482.08 FL	*482.08 FL
22	1		*REAR MUFFLER	Bent	5,610.00 FL	*5,610.00 FL
23	2		*CLAMPING MUFFLER SLEEVE	Missing	2,739.00 FL	*2,739.00 FL
24	2		*MUFLER SUPPORT WITH RUBBER	Torn	284.36 FL	*284.36 FL
25	2		*TAIL PIPE CLAMP	Dented	305.26 FL	*305.26 FL
26	2		*TAIL EXHAUST TIPS MUFFLER CHROME PIPE	Repair	2,739.00 FL	*- FL
27	1		*REAR MUFFLER HEAT SHIELD COVER	Bent	929.76 FL	*929.76 FL
28	1		*REAR STABILIZER BAR	Serviceable	1,316.98 FL	*- FL
29	2		*REAR STABILIZER MOUNTING CLAMP	Serviceable	65.46 FL	*- FL
30	4		*REAR STABILIZER MOUNTING RUBBER	Serviceable	299.20 FL	*- FL
31	1		*REAR WINDSCREEN GLASS CUM MOULDING	Mldg Necessary	3,150.00 FL	*3,150.00 FL
32	1		*SAFETY BELT	Jammed	750.00 FL	*750.00 FL

F=Franchise part. L=ListItemDisc.

	Sub Total (\$\$)	36,871.47	25,267.80
- List Item Discount on L Items 10.00/10.00% (\$\$)		3,687.15	2,526.78
	Total Parts (\$\$)	33,184.32	22,741.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REINSTALL UNDERCARRIAGE EXHAUST PIPE	New	450.00	0.00
2	TO PANEL BEATING ALL DAMAGES PORTIONS	New	1,600.00	1,000.00
3	TO SPRAY PAINT ALL DAMAGES PORTIONS	New	2,000.00	900.00
4	TO REMOVE & INSTALL REVERSE SENSOR	New	150.00	60.00
5	TO CHECK ALL WIRING	New	200.00	30.00
6	RUST PROOFING ON AFFECTED PORTIONS	New	180.00	30.00
7	TO CHECK BOOTLID WATER SEEPAGE	New	120.00	30.00
8	TO REMOVE & TRANSFER ALL INTERNAL UPHOLSTERY	New	350.00	80.00
9	TO REMOVE & REINSTALL REAR WINDSCREEN GLASS	New	250.00	120.00
Gross Labour Cost (\$\$)			5,300.00	2,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >