

Kanchana



TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLT3631L
Date of Accident : 07 November 2019

Mr Nehemiah Sng

Date : 07 November 2019

RASUL - LKA

Estimate To Repair SJW8391D - Perodua Viva Elite EZ AT 2WD 5DR
Chassis No : PM2L251S002101957

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	front bumper <i>de</i>	\$ 450.00
02	1 pc	front bumper side retainer n/s <i>rec</i>	\$ 35.00
03	8 ps	front bumper clips @ \$4.50 <i>rec</i>	\$ 36.00
04	1 pc	headlamp n/s <i>ca</i>	\$ 850.00
05	1 pc	left front fender <i>bus</i>	\$ 650.00
06	1 pc	left front fender inner cowling <i>de</i>	\$ 125.00
07	6 ps	left front fender inner cowling clips @ \$4.50 <i>rec</i>	\$ 27.00
08	1 pc	left front fender signal lamp <i>ca</i>	\$ 65.00
			\$ 2,238.00
		Less 10 %	\$ 223.80
			\$ 2,014.20
		<u>LABOUR & MISC. CHARGES</u>	
01		To check electrical lighting concerned.	\$ 30 60.00
02		To rust-proofing of the affected areas.	\$ 40 120.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 450 600.00
04		Putty and spray painting of the affected portion.	\$ 600 800.00
			\$ 1,580.00
			<i>1,120.00</i>
		Total	\$ 3,594.20
			<i>3,134.20</i>
			- 20%
			<i>\$2,502.36</i>

Form
Hp 90010068
5 days
4/5
07/10/19 @ 1710

Resing after repair

Lump sum \$2,500.00
5 days 18 parts