

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 18926

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1355/2019/NS
Date : 14-Nov-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SHA 6791 K

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Liong Mee Ling
Address : 11 Watton Close
Singapore 287734
Telephone : (HP)+65 93854201
Type of Claim : Third Party Claim
Policy No. : 5086414230-01
Vehicle No : **SDL 3212 A**
Model Code : Q3 1.4 TFSI S tronic
Model / Year : 27/11/2015
Engine No : CZD 217570
Chassis No : WAUZZZ8U6GR042507
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 10-Nov-19
Place of Accident : PIE Towards Tuas

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDL 3212 A

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$	280.00 ✓	
2	To remove and transfer rear lid's convenience lock system, wire harness for tail lights and rear wiper assy.	S/N \$	480.00 ✓	
3	To renew rear windscreen.	S/N \$	480.00 ✓	
4	To install rear windscreen solar film.	S/N \$	400.00 ✓ (SA provide)	
SUB TOTAL LABOUR CHARGES		:	<u><u>\$ 1,640.00</u></u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDL 3212 A

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
5	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$ 480.00 /	
6	To dismantle and renew rear bumper and rear lid. Cut out and reweld end panelling. Re-organise crash management components. Reinstall all parts removed.	\$ 4,800.00	1000
7	To respray rear bumper, rear bumper spoiler, rear lid, spare wheel housing, end panelling and both rear wheel arch trims. To carry out joint sealer works and stone chip treatment.	\$ 5,400.00	2200
8	To carry out diagnostic check.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		: \$ 12,512.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDL 3212 A

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	REAR BUMPER ✓ 00	\$	1,354.00	
2	REAR BUMPER FIXING PARTS ?	\$	112.00	
3	REAR BUMPER SPOILER (Gng) ✓ CM	\$	802.00	
4	REAR DIFFUSER - LH (SIL) ✓ CM	\$	643.00	
5	REAR BUMPER TOWING EYE COVER - LH ✓ CM	\$	39.00	
6	REAR BUMPER TOWING EYE COVER - RH ✓ CM	\$	24.00	
7	TAIL LIGHT - LH / RH CM ✓ 1.2	\$	836.00	
8	LED LICENSE PLATE LIGHT X	2 \$	105.00	
9	REAR BUMPER CARRIER ✓ 00	\$	569.00	
10	REAR BUMPER GUIDE SECTION - LH / RH ?	2 \$	182.00	
11	REAR BUMPER FOAM FILLER PIECE - LH / RH ?	2 \$	156.00	
12	REAR PARKING AID SENSOR ?	2 \$	462.00	
13	REAR BUMPER WIRING SET ?	\$	472.00	
14	REAR LID ✓ 00	\$	3,279.00	
15	REAR LID ATTACHMENT PARTS ?	\$	175.00	
16	REAR LID HINGE - LH / RH X	2 \$	416.00	
17	REAR LID LOCK ?	\$	164.00	
18	LID LOCK ACTUATOR PUSH BUTTON ?	\$	167.00	
19	REAR LID PROTECT CAP ?	\$	14.00	
20	PACKING ADHESIVE ✓ MC	\$	18.00	
SUB TOTAL SPARE PARTS		:	\$ 9,989.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDL 3212 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	FLAP GASKET ?	\$	185.00
22	SPOILER FIXING PARTS ?	\$	70.00
23	AUDI EMBLEM / MC	\$	113.00
24	Q3 INSCRIPTION / MC	\$	87.00
25	TFSI INSCRIPTION / MC	\$	87.00
26	REAR WINDSCREEN / MC	\$	871.00
27	PRIMER / MC	\$	19.00
28	REAR CROSS PANEL ?	\$	284.00
29	CROSS PANEL REINFORCEMENT ?	\$	624.00
30	REAR CROSS PANEL TRIM / CAT	\$	475.00
31	LED TAIL LIGHT - LH / RH X	2 \$	2,434.00
32	REAR WHEEL COVER - LH / RH / MC	2 \$	964.00
33	EXHAUST TAIL PIPES TRIM SET X	\$	218.00
34	REAR LID SPOILER - LH / RH X	2 \$	220.00
35	REAR NO PLATE X	S/N \$	40.00
36	ACRYLIC SEALANT ?	S/N \$	180.00
37	CAVITY WAX ?	S/N \$	140.00
38	STONE CHIP ?	S/N \$	180.00
39	REAR WINDSCREEN SEALANT /	S/N \$	200.00
40	SUNDRIES ?	\$	400.00

TOTAL SPARE PARTS	:	\$ 17,780.00
TOTAL LABOUR CHARGES	:	\$ 12,512.00
GRAND TOTAL	:	\$ 30,292.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Steve (LKK) W/L M/L 15/11/19, 2.20pm
: 5 days
: P/P
: Ry RL Sky
:

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant