

ASSIGNED BY: KABU

REF:


8394

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SHA 95674
 at Workshop m/s DINH ANUO
 of 31, COPPERM 20
 Insured: LONG
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SHA 95674 Yr Regn: 2017 / SGP
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: TOYOTA PRIMS HYBRID 1.8 CVT c.c 1798
 Colour: YELLOW A/C: Insured / Std / NI / NA
 Sp Reading: 278611 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 Cr/No: JTDKB3FU903563271
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Mod: NR / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/65R15
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or TRIANGLE
 Front 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 08/11/19 D.O.I. 11/11/19
 Survey held at DINH ANUO
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or _____
 The UIC / Chassis frame / Body Structure affected due to collision.



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
	P/P - \$4274.95 (Red \$3523.41 / 45Z)

Date/Time, File Pass to? : Prel. Report
 : Final Report

1) _____
 Date/Time, File Return to?
 2) _____
 Report Format: _____
 Lump Sum / LBJ: _____

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: Site Insp (\$) _____
 Interview (\$) _____
 Tech. Invt (\$) _____
 Wash and _____

Survey Fee:	
Transportation:	
_____ \$ + RS _____ \$	
Photos	
Other	
TOTAL	



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC19019941/R1db3

Date: 12.11.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHA9567Y


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11.11.2019 at the premises of M/s Ding Auto Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	6,421.24
Revised Estimate Amount	: S\$	3,603.61
"Check" Items Amount	: S\$	241.34
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

3106

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

08/11/2019 17:40

OWNER'S PARTICULARS

JOB-NO: 50112180

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHA9567Y

TRANS: AUTO

CHASSIS: JTDKB3FU903563271

MAKE / MODEL: TOYOTA / Prius Hybrid 1.8 CVT

ENGINE: 2ZRS081147

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SURDISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,000.00	0.00	1,000.00	Y		500
2 R&R BOOTLID COMPONENTS	1.00	150.00	0.00	150.00	Y		60
3 R&R BOOTLID UPPER WINDSCREEN TO TRANSFER	1.00	150.00	0.00	150.00	Y		120
4 RUST PROOFING	1.00	80.00	0.00	80.00	Y		40
5 SUNDRIES	1.00	60.00	0.00	60.00	Y		20
6 RESPRAY BOOTLID	1.00	250.00	0.00	250.00	Y		200
7 RESPRAY BOOTLID SPOILER	1.00	250.00	0.00	250.00	Y		100
8 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00	Y		200
TOTAL:		2,190.00	0.00	2,190.00			

1240
+
1008

1340

MATERIALS

1 BOOTLID repair <i>bt</i>	1.00	1,113.40	278.35	835.05	L	Y	
2 BOOTLID RUBBER BEADING <i>see</i>	1.00	389.61	97.45	292.16	L	Y	
3 BOOTLID EMBLEM-LOGO <i>see</i>	1.00	58.70	14.18	42.52	L	Y	
4 BOOTLID EMBLEM-PRUIS <i>see</i>	1.00	58.70	14.18	42.52	L	Y	
5 BOOTLID EMBLEM-HYBRID <i>see</i>	1.00	58.70	14.18	42.52	L	Y	
6 BOOTLID SPOILER <i>repair</i>	1.00	1,206.00	301.50	904.50	L	Y	
7 BOOTLID LOCK <i>X SUC</i>	1.00	452.21	113.05	339.16	L	Y	
8 BOOTLID CATCH <i>X SUC</i>	1.00	28.02	7.01	21.01	L	Y	
9 BOOTLID HINGE LHS <i>X SUC</i>	1.00	89.41	22.35	67.06	L	Y	
10 BOOTLID HINGE RHS <i>X SUC</i>	1.00	89.41	22.35	67.06	L	Y	
11 BOOTLID BOARD INNER GARNISH <i>cut</i>	1.00	302.30	75.58	226.72	L	Y	
12 BOOTLID WINDSCREEN BOTTOM <i>bro</i>	1.00	725.90	181.48	544.42	L	Y	
13 BOOTLID WINDSCREEN BOTTOM MLDG <i>see</i>	1.00	85.00	18.25	48.75	L	Y	
14 BOOTLID WINDSCREEN UPPER MLDG <i>see</i>	1.00	85.00	18.25	48.75	L	Y	
15 BOOTLID CARPLATE LAMP LHS <i>3 X SUC</i>	1.00	180.90	40.23	120.67	L	Y	
16 BOOTLID CARPLATE LAMP RHS <i>3 X SUC</i>	1.00	180.90	40.23	120.67	L	Y	
17 ADS STICKER-BOOK NOW <i>see</i>	1.00	80.00	20.00	60.00	L	Y	
18 ADS STICKER-COMFORTDELGRO <i>see</i>	1.00	80.00	20.00	60.00	L	Y	
19 ADS STICKER-65521111 <i>see</i>	1.00	80.00	20.00	60.00	L	Y	
20 REPAIR REAR BUMPER <i>R</i>	1.00	250.00	62.50	187.50	L	Y	
21 BOOTLID WINDSCREEN BOTTOM SEALANT <i>see</i>	1.00	50.00	0.00	50.00	S	Y	
22 BOOTLID WINDSCREEN UPPER SEALANT <i>see</i>	1.00	50.00	0.00	50.00	S	Y	
TOTAL:		5,608.38	377.12	4,231.24			

212364
+
63104 = *supp*
275498
30
30
180

TOTAL PARTS & LABOUR :

7,798.38 1,377.12 6,421.24

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

EXCESS/LOADING:\$\$ 0.00

No. Of Day: 5 days

RE-SURVEY (BEFORE/ ~~AFTER~~ PAINTING)

(PART-BY-PART OR LUMP SUM) \$\$

DATE OF SURVEY: 11 / 11 / 19 @ 1620

SURVEYED BY: RARUL

CONTACT NO: 90010068 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

Insurance policy
the following:
• ... damaged prior to survey
• ... are subject to confirmation
• ... survey is on a "Without Prejudice" basis
• ... (legal modifications) is allowed
• ... must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

DING AUTOMOTIVE PTE LTD

Blk 10, #01-20
 Sin Ming Industrial Est. Sec C
 Singapore 575645
 Tel: 6452 1208
 Fax: 6452 0614

Vehicle:	5HA9567Y
Model:	TOYOTA PRIUS
Chassis:	JTDK83FU903563271

PARTS SUPPLEMENTARY & QUOTATION FORM

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYORS MARKING
1	TAIL GATE REGISTERED GARNISH <i>crn</i>	1	\$ 841.79	25%	\$ 631.34	
PARTS					\$ 631.34	

NO	LABOUR	PRICE	SURVEYOR MARKING
1	RESPRAY TAIL GATE REGISTERED GARNISH	\$ 250.00	<i>100</i>
TOTAL:		\$ 250.00	

PARTS	\$	631.34	
LABOUR	\$	250.00	
TOTAL	\$	881.34	

Part By Part

Labour = \$ 1340

S/M = \$ 180

Parts = \$ 2754.95

LTSP = \$ 4274.95

Final Amount = \$ 4274.95

5 days
P/P

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

08/11/2019 17:40

OWNER'S PARTICULARS

JOB-NO: 50112180

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHA9567Y

TRANS: AUTO

CHASSIS: JTDKB3FU903563271

MAKE / MODEL: TOYOTA / Prius Hybrid 1.8 CVT

ENGINE: 2ZRS061147

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,000.00	0.00	1,000.00		Y	500
2 R&R BOOTLID COMPONENTS	1.00	150.00	0.00	150.00		Y	60
3 R&R BOOTLID UPPER WINDSCREEN TO TRANSFER	1.00	150.00	0.00	150.00		Y	120
4 RUST PROOFING	1.00	80.00	0.00	80.00		Y	40
5 SUNDRIES	1.00	60.00	0.00	60.00		Y	20
6 RESPRAY BOOTLID	1.00	250.00	0.00	250.00		Y	200
7 RESPRAY BOOTLID SPOILER	1.00	250.00	0.00	250.00		Y	100
8 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00		Y	200
TOTAL:		2,190.00	0.00	2,190.00			
MATERIALS							
1 BOOTLID part bt	1.00	1,113.40	278.35	835.05	L	Y	
2 BOOTLID RUBBER BEADING	1.00	389.81	97.45	292.36	L	Y	
3 BOOTLID EMBLEM-LOGO	1.00	56.70	14.18	42.52	L	Y	
4 BOOTLID EMBLEM-PRIUS	1.00	56.70	14.18	42.52	L	Y	
5 BOOTLID EMBLEM-HYBRID	1.00	56.70	14.18	42.52	L	Y	
6 BOOTLID SPOILER	1.00	1,206.00	301.50	904.50	L	Y	
7 BOOTLID LOCK X	1.00	452.21	113.05	339.16	L	Y	
8 BOOTLID CATCH X	1.00	28.02	7.01	21.01	L	Y	
9 BOOTLID HINGE LHS X	1.00	89.41	22.35	67.06	L	Y	
10 BOOTLID HINGE RHS X	1.00	89.41	22.35	67.06	L	Y	
11 BOOTLID BOARD INNER GARNISH	1.00	302.30	75.58	226.72	L	Y	
12 BOOTLID WINDSCREEN BOTTOM	1.00	725.90	181.48	544.42	L	Y	
13 BOOTLID WINDSCREEN BOTTOM MLDG	1.00	65.00	16.25	48.75	L	Y	
14 BOOTLID WINDSCREEN UPPER MLDG	1.00	65.00	16.25	48.75	L	Y	
15 BOOTLID CARPLATE LAMP LHS	1.00	160.90	40.23	120.67	L	Y	
16 BOOTLID CARPLATE LAMP RHS	1.00	160.90	40.23	120.67	L	Y	
17 ADS STICKER-BOOK NOW	1.00	80.00	20.00	60.00	L	Y	
18 ADS STICKER-COMFORTDELGRO	1.00	80.00	20.00	60.00	L	Y	
19 ADS STICKER-65521111	1.00	80.00	20.00	60.00	L	Y	
20 REPAIR REAR BUMPER R	1.00	250.00	62.50	187.50	L	Y	
21 BOOTLID WINDSCREEN BOTTOM SEALANT	1.00	50.00	0.00	50.00	S	Y	
22 BOOTLID WINDSCREEN UPPER SEALANT	1.00	50.00	0.00	50.00	S	Y	
TOTAL:		5,608.36	377.12	4,231.24			
TOTAL PARTS & LABOUR :		7,798.36	1,377.12	6,421.24			

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

EXCESS/LOADING:SS 0.00

No. Of Day: 5 days

RE-SURVEY: BEFORE AFTER PAINTING

PART-BY-PART OR LUMP SUM SS

DATE OF SURVEY: 11, 11, 19 @ 1620

SURVEYED BY: RASUL

CONTACT NO: 90010068 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL: _____ FAX: _____

Nivitha (LKK Auto)


From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 11 November 2019 8:27 AM
To: Taxis Customer Service; CHEW BENG KEE; MT_Claim_SG; assignments@lkkauto.com; Admin-D (LKKAuto)
Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg
Subject: RE: ACCIDENT INVOLVING SHA9567Y AND YN3156U ON 08/11/2019 SURVEYOR ARRANGEMENT Our Ref: 19/19/VC05/022620
Attachments: SAS2699633.pdf; Invoice.html

q. Seung 11/11/19
V: In
S: Perul

Dear Nivitha

Please arrange TP survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Taxis Customer Service [mailto:taxiscs@stengg.com]
Sent: Friday, 8 November 2019 5:18 PM
To: CHEW BENG KEE; MT_Claim_SG
Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg
Subject: RE: ACCIDENT INVOLVING SHA9567Y AND YN3156U ON 08/11/2019 SURVEYOR ARRANGEMENT

Dear Officer,

Please kindly arrange survey for vehicle SHA9567Y. As vehicle is already grounded inside workshop. Survey location will be at 31 Corporation Road.

Best Regards,
Glenn
90295825



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC19019941/R1da3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 17-01-2020	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YN 3156U	Veh. Inspected	SHA 9567Y
Policy No.	Z19VC05002807	Coverage (\$)	0.00
Claim No.	19/19/19/VC05/022620	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	11/11/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS HYBRID 1.8 CVT	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU903563271	Colour	YELLOW
Odometer	278611	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	TRIANGLE	6 mm
L/H Front Tyre	195/65 R15	TRIANGLE	6 mm
R/H Rear Tyre	195/65 R15	TRIANGLE	6 mm
L/H Rear Tyre	195/65 R15	TRIANGLE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/11/2019	Inspection Date	11/11/2019
Survey held at	31 CORPORATION ROAD		
Repairer	DING AUTOMOTIVE PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 9567Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID	BENT	1,113.40	1,113.40
1	BOOTLID RUBBER BEADING	NECESSARY	389.81	389.81
1	BOOTLID EMBLEM-LOGO	NECESSARY	56.70	56.69
1	BOOTLID EMBLEM-PRIUS	NECESSARY	56.70	56.69
1	BOOTLID EMBLEM-HYBRID	NECESSARY	56.70	56.69
1	BOOTLID SPOILER	TO REPAIR SEE LABOUR	1,206.00	-
1	BOOTLID LOCK	SERVICEABLE	452.21	-
1	BOOTLID CATCH	SERVICEABLE	28.02	-
1	BOOTLID HINGE LHS	SERVICEABLE	89.41	-
1	BOOTLID HINGE RHS	SERVICEABLE	89.41	-
1	BOOTLID BOARD INNER GARNISH	CUT	302.30	302.30
1	BOOTLID WINDSCREEN BOTTOM	BROKEN	725.90	725.90
1	BOOTLID WINDSCREEN BOTTOM MLDG	NECESSARY	65.00	65.00
1	BOOTLID WINDSCREEN UPPER MLDG	NECESSARY	65.00	65.00
1	BOOTLID CARPLATE LAMP LHS	SERVICEABLE	160.90	-
1	BOOTLID CARPLATE LAMP RHS	SERVICEABLE	160.90	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	250.00	-
1	TAIL GATE REGISTERED GARNISH (ADDITIONAL)	CRACKED	841.79	841.79
	LESS 25% DISCOUNT		-1,527.54	-918.32
			4,582.61	2,754.95
1	ADS STICKER-BOOK NOW (SN) }	NECESSARY	80.00	120.00
1	ADS STICKER-COMFORTDELGRO (SN) }	NECESSARY	80.00	-
1	ADS STICKER-65521111 (SN) }	NECESSARY	80.00	-
	LESS 25% DISCOUNT		-60.00	-
			180.00	120.00
SPECIAL NETT ITEMS				
1	BOOTLID WINDSCREEN BOTTOM SEALANT (SN)	NECESSARY	50.00	30.00
1	BOOTLID WINDSCREEN UPPER SEALANT (SN)	NECESSARY	50.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	60.00	20.00
			160.00	80.00
	LABOUR			
	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS INCLUSIVE OF THE REPAIR OF BOOTLID SPOILER AND REAR BUMPER.		1,000.00	500.00
	R&R BOOTLID COMPONENTS.		150.00	60.00
	R&R BOOTLID UPPER WINDSCREEN TO TRANSFER.		150.00	120.00
	RUST PROOFING.		80.00	40.00
	RESPRAY BOOTLID.		250.00	200.00
	RESPRAY BOOTLID SPOILER.		250.00	100.00
	RESPRAY REAR BUMPER.		250.00	200.00
	RESPRAY TAIL GATE REGISTERED GARNISH (ADDITIONAL).		250.00	100.00
			2,380.00	1,320.00
	GRAND TOTAL		7,302.61	4,274.95
	RECOMMENDED COST OF REPAIRS			4,274.95

Report Ref No. CC4/LPC19019941/R1da3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.