

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

08/11/2019 17:40

JOB-NO: 50112180

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

CONTACT: 65533880
64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHA9567Y TRANS: AUTO
MAKE / MODEL: TOYOTA / Prius Hybrid 1.8 CVT
OWNER'S INSURER: MS First Capital Insurance Limited
JOB-CODE: TP SA: Ding Auto User 2

CHASSIS: JTDKB3FU903563271
ENGINE: 2ZRS061147

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,000.00	0.00	1,000.00		Y	500
2 R&R BOOTLID COMPONENTS	1.00	150.00	0.00	150.00		Y	60
3 R&R BOOTLID UPPER WINDSCREEN TO TRANSFER	1.00	150.00	0.00	150.00		Y	120
4 RUST PROOFING	1.00	80.00	0.00	80.00		Y	40
5 SUNDRIES	1.00	60.00	0.00	60.00		Y	20
6 RESPRAY BOOTLID	1.00	250.00	0.00	250.00		Y	200
7 RESPRAY BOOTLID SPOILER	1.00	250.00	0.00	250.00		Y	100
8 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00		Y	200
TOTAL:		2,190.00	0.00	2,190.00			

MATERIALS

1 BOOTLID front <i>bt</i>	1.00	1,113.40	278.35	835.05	L	Y	
2 BOOTLID RUBBER BEADING <i>acc</i>	1.00	389.81	97.45	292.36	L	Y	
3 BOOTLID EMBLEM-LOGO <i>rec</i>	1.00	56.70	14.18	42.52	L	Y	
4 BOOTLID EMBLEM-PRIUS <i>rec</i>	1.00	56.70	14.18	42.52	L	Y	
5 BOOTLID EMBLEM-HYBRID <i>rec</i>	1.00	56.70	14.18	42.52	L	Y	
6 BOOTLID SPOILER <i>repair</i>	1.00	1,206.00	301.50	904.50	L	Y	
7 BOOTLID LOCK <i>X</i>	1.00	452.21	113.05	339.16	L	Y	
8 BOOTLID CATCH <i>X</i>	1.00	28.02	7.01	21.01	L	Y	
9 BOOTLID HINGE LHS <i>X</i>	1.00	89.41	22.35	67.06	L	Y	
10 BOOTLID HINGE RHS <i>X</i>	1.00	89.41	22.35	67.06	L	Y	
11 BOOTLID BOARD INNER GARNISH <i>cut</i>	1.00	302.30	75.58	226.72	L	Y	
12 BOOTLID WINDSCREEN BOTTOM <i>bro</i>	1.00	725.90	181.48	544.42	L	Y	
13 BOOTLID WINDSCREEN BOTTOM MLDG <i>rec</i>	1.00	65.00	16.25	48.75	L	Y	
14 BOOTLID WINDSCREEN UPPER MLDG <i>rec</i>	1.00	65.00	16.25	48.75	L	Y	
15 BOOTLID CARPLATE LAMP LHS <i>?</i>	1.00	160.90	40.23	120.67	L	Y	
16 BOOTLID CARPLATE LAMP RHS <i>?</i>	1.00	160.90	40.23	120.67	L	Y	
17 ADS STICKER-BOOK NOW <i>rec</i>	1.00	80.00	20.00	60.00	L	Y	
18 ADS STICKER-COMFORTDELGRO <i>rec</i>	1.00	80.00	20.00	60.00	L	Y	
19 ADS STICKER-65521111 <i>rec</i>	1.00	80.00	20.00	60.00	L	Y	
20 REPAIR REAR BUMPER <i>R</i>	1.00	250.00	62.50	187.50	L	Y	
21 BOOTLID WINDSCREEN BOTTOM SEALANT <i>rec</i>	1.00	50.00	0.00	50.00	S	Y	
22 BOOTLID WINDSCREEN UPPER SEALANT <i>rec</i>	1.00	50.00	0.00	50.00	S	Y	
TOTAL:		5,608.36	377.12	4,231.24			

TOTAL PARTS & LABOUR :

7,798.36 1,377.12 6,421.24

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

EXCESS/LOADING:\$ 0.00

No. Of Day: 5 days

RE-SURVEY: ~~BEFORE~~ AFTER PAINTING

PART-BY-PART OR LUMP SUM \$

DATE OF SURVEY: 11 / 11 / 19 @ 1620

SURVEYED BY: RASUL

CONTACT NO: 90010068 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL: _____ FAX: _____