

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 18273

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1330/2019/NS
Date : 7-Nov-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Eugene Tan Kim Siah
Address : 700 Lorong 1 Toa Payoh
#15-03
Singapore 319773
Telephone : HP +65 96381100
Type of Claim : Own Damage Claims
Policy No. : 1800026555
Vehicle No : **SBD 83 R**
Model Code : Audi A6 1.8 TFSI S -Tronic
Model / Year : 19/3/2018
Engine No : CYG 019196
Chassis No : WAUZZZ4G2HN100282
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Nov-19
Place of Accident : PIE Towards Toa Payoh

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SBD 83 R

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓
2	To dismantle and renew front bumper, bonnet and both headlights, re-organise crash management components. Reinstall all parts removed.	\$ 3,200.00 1600	
3	To respray front bumper and bonnet.	\$ 2,200.00 1100	
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>6,072.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBD 83 R

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER <i>report car</i>	\$	2,787.00	✓ 2229.60
2	FRONT BUMPER FIXING PARTS <i>X nn</i>	\$	491.00	
3	FRONT BUMPER GRILLE - LOWER CENTRE <i>X su</i>	\$	116.00	
4	LOCKING CLIP <i>X nn</i>	14 \$	51.00	
5	FRONT BUMPER ADAPTER - LH / RH <i>X su</i>	2 \$	68.00	
6	FRONT BUMPER CLOSING ELEMENT <i>X su</i>	\$	199.00	
7	FRONT BUMPER SPOILER <i>X su</i>	\$	227.00	
8	FRONT BUMPER COVER MOLDING <i>X su</i>	\$	860.00	
9	RADIATOR GRILLE <i>car</i>	\$	1,766.00	1412.80
10	RADIATOR GRILLE COVER <i>? X su</i>	\$	33.00	X
11	FRONT PARKING AID SENSOR SUPPORT - LH / RH <i>X su</i>	2 \$	122.00	
12	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>X su</i>	2 \$	904.00	
13	FRONT BUMPER COVER - LH / RH <i>X su</i>	2 \$	92.00	
14	FRONT WHEEL SPOILER - LH / RH <i>X su</i>	2 \$	484.00	
15	HEADLIGHT WASHER COVER CAP - LH / RH <i>X su</i>	2 \$	104.00	
16	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>? bt</i>	\$	754.00	✓ 602.80
17	FRONT BUMPER FOAM FILLER PIECE <i>? car</i>	\$	215.00	✓ 172.00
18	FRONT BUMPER COVER <i>X su</i>	\$	112.00	
19	FRONT BUMPER GUIDE PIECE - LH / RH <i>X su</i>	2 \$	68.00	
20	AIRCON STICKER <i>X nn</i>	NEC \$	18.00	
SUB TOTAL SPARE PARTS		:	\$ 9,471.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBD 83 R

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett	Price	
21	CAUTION SIGN STICKER <input checked="" type="checkbox"/>	NEC	\$ 13.00	
22	SIGNAL HORN - LH LOW TONE <input checked="" type="checkbox"/>		\$ 262.00	} m
23	SIGNAL HORN - RH HIGH TONE <input checked="" type="checkbox"/>		\$ 215.00	
24	SPRING SHACKLE - LH / RH <input checked="" type="checkbox"/>	2	\$ 86.00	
25	FRONT PARKING AID SENSOR - INNER <input checked="" type="checkbox"/>	2	\$ 419.00	
26	BONNET <i>repair</i>		\$ 4,965.00	
27	BONNET ATTACHMENT PARTS <input checked="" type="checkbox"/>		\$ 161.00	} s/c
28	BONNET LOCK BAR <input checked="" type="checkbox"/>	2	\$ 90.00	
29	BONNET CATCH HOOK <input checked="" type="checkbox"/>		\$ 127.00	
30	BONNET SAFETY CATCH <input checked="" type="checkbox"/>		\$ 16.00	
31	BONNET LID LOCK <input checked="" type="checkbox"/>	2	\$ 391.00	
32	MICRO SWITCH <input checked="" type="checkbox"/>	2	\$ 133.00	
33	BONNET BOWDEN CABLE <input checked="" type="checkbox"/>		\$ 53.00	
34	HEADLIGHT MOUNTING - LH / RH <input checked="" type="checkbox"/>	2	\$ 214.00	
35	LED HEADLIGHT - LH / RH <input checked="" type="checkbox"/>	2	\$ 17,214.00	
36	LIFT CYLINDER - LH / RH <input checked="" type="checkbox"/>	2	\$ 432.00	
37	HEADLIGHT HOSE <input checked="" type="checkbox"/>		\$ 426.00	
38	EXTERNAL TEMPERATURE SENSOR <input checked="" type="checkbox"/>		\$ 57.00	
39	TEMPERATURE SENSOR BRACKET <input checked="" type="checkbox"/>		\$ 21.00	
40	RADIATOR AIR GUIDE - LH / RH <input checked="" type="checkbox"/>	2	\$ 50.00	
41	RADIATOR COVER - UPPER CENTRE <input checked="" type="checkbox"/>		\$ 27.00	
42	RADIATOR SEALING STRIP <input checked="" type="checkbox"/>		\$ 21.00	
43	FRONT NO PLATE <i>bt</i> ✓	S/N	\$ 40.00	
44	SUNDRIES <i>? neu</i> ✓		\$ 400.00	<i>✓ 75.68</i>

TOTAL SPARE PARTS	\$ 35,304.00
TOTAL LABOUR CHARGES	\$ 6,072.00
GRAND TOTAL	\$ 41,376.00

All charges are not inclusive of GST.
 Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
 Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6641 1183

Telefax

Name : Rasul - Hp 90010068
Surveyed Date : 11/11/19 @ 1540
Authorised Date :
Excess Cost : 4 days
Liability : EXCESS: TBA
Remarks :

Revert
Resurvey before repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant