	19019952/Hed3 Special Instructions
From (Person): Tang Hock lye of	C71 Date/Time: N/11/19@ 2021pm
Estimated Cost: OD FEVWS/TP RES/OD RES/EVA/INV/MV	Bill to:
To Inspect Vehicle No	2821B Insured: GBD 9142U
Policy No: DMCVSN16307619033	Claim No: 2NM 19D 305260
Stun Instituted: 2v of Volt. (Chear's Second)	D.O.A. 4.11.19
CA / REV / REV / REV 24 HRS Person Contact Person Contact	sted: Mr*tey Vekicl IN/OUT
Date/Time / Mon/Instruction Inhumal (2) 91× 8821 B - NA / INC19 CIBD 014U -×	1 4
Diemantle: 12/11/2019. After repair: 16/11/2019	

Birrague H-ANN REF: cti	
	SIGNMENT
From: Date:	Von No: SLX 8821B Yr Regn: 16/04/2018
Estimated Cost:	Type: M.Carl M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD/TP/WS/TP-RES/OD-RES/EVA/INV/MY	Truck / Traller or
To Inspect Vehicle No: SIX P8216	Mako: MITShu Born 112 ATTRAGE //93
at Workshop m/s 25 Kalei Aulist row 4	Colour WAC: Insured / Std / NI / NA
01 #06-8-	Sp.Reading 047 9/7 th T/Redio: Insured / Std / NI / NA
Insured. ,	Eng/No:
Policy No.	CINO: MMBSTABAJHOO1854
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Sleering: norder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: NII SIRIM I STO AIRIM or
AND EXPERIENCES SELECT	Tyre Size: F: 185 /55 /RI5
(Policy Condition)	R: 195/50/115
Remark: The veh had commenced its	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	Τογοίγοκο α
2.1 - 1112-12-12-12-12-12-12-12-12-12-12-12	Eroni Rear FAILEN
Bal, or Market Value: IDAC Accident Roort: Consistent? : Yes or No	R/Bal. 3 mm 155 R/Bal. 4 mpr
iono notional riporti	101 - 1101 4
	D.O.A. 4/11/17 D.O.I. 11/11/19
Est Repairs: 4 days Res.: Yes or No	0-1
Lum Sum: % 3 Val.: Yes or No	
CA / REV / REP. / 24 HRS	Dos. of Damages : Frt / Rear / O/S) / N/S / U/C / Rooftop or
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
Raye - 415-5.5K	SLX BOTIB
Rote > 4 days	Lpri cate.
F7000	
212 - 353/5	and the state of t
NU- 53000 NU- 35.765 NU- 17200	
NCT 1720:	EIVED 0 7 JAN 2020
A Par	
Date/Time, File Pass 107 : Proll. Report	Days Of Repair:
i) : Final Report	Resurvey No. of Trlp: Survey Fee:
Date/Time, File Return to?	II ransportation:
2) Add Fe	: Site insp (\$):s+Rssi
-	Interview (\$.) Pialibe .
Report Format : PRS .	Tech Invs (\$) Others
Lump Sum / I.B.I: (\$: Weekend (\$
	TOTAL

...CLAIM SUBFOLDER...(Pending for Survey Report)

AIM SUB	FOLDER TRA		Adi Assigned	Adj Rpt	Adj Subt	nitted I	ins Auth'ed	Status	
Case	07 Nov 2019	Est Submitted	26 Nov 2019 09:17 Edit Adj Rpt	nuj npt				Pending for Report Cancel Case	141
	Main	Re	eference		Claim Details		Document	s	Show All
CI ATM SI	JBFOLDER DI	ETAILS	AND DESCRIPTION OF THE PARTY OF	Marketin Port deal and	NAME OF TAXABLE PARTY.	[Created	by insurer]		
Insured:									
Main Claimant:	ONG CHO	ON HONG							
Vehicle Reg. SLX8821B		Date of Loss:	04/11/2019 13:00 - :59						
Claim Type	Claim Type: TP / SNM19D205269 //ehicle Reg. GBD9142U		Policy/Cover Note No.: DMCVSN16307619033						
No.				Policy No. (Claimant):					
(Insured):					Excess:	S\$0.00			
Repairer:	Prowerk	z Garage Pte Ltd	(HQ) 25 Kaki B	ukit Road 4,	#06-87 Synergy	@ KB, 417	800 Kaki Bukit - 1	Tel:	
Handling Insurer:	China Ta	iping Insurance	(Singapore) Pt	e. Ltd. (HQ)	- Tel: 6389 611	1 [Handl	ed by Ben Tang	1	/12/20191
Adjuster:	LKK Auto	Consultants Pt	e Ltd (HQ) - Tel	: 6256-3561	[Handled by	LEE HOCK	ANN] [Fillal	KPt due 05	/12/2019]
ASSOCIA	TED MAIL R	ECEIVED						View All Co	mpose Case Mail
There are	no mail for this	s case.					3		
ALL ASS	OCIATED TA	sks⊟				View All	Search Tasks	Create New 1	Control of the Contro
Due Da	te Priority		k Group Sub	oject Han	dler Assign	ned By	Completed On	Create	d On Done

Nivitha (LKK Auto)

From:

Tang Hock Lye <hocklye.tang@sg.cntaiping.com>

Sent:

Monday, 11 November 2019 2:21 PM

To:

prowerkzcar@gmail.com

Cc:

assignments@lkkauto.com

Subject:

RE: OUR REF :SNM19D205269-GBD9142U-THL- Fax Message NO.2130

WITHOUT PREJUDICE

Dear Sirs

We refer to your email of 07.11.19.

We noted that you are not agreeable to our proposed list of surveyors. We will assign our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK.

Please arrange for the survey.

Thank you.

Best Regards Ben Tang Executive Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #XX-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Monday, November 11, 2019 2:01 PM

To: Tang Hock Lye <hocklye.tang@sg.cntaiping.com>

Subject: FW: OUR REF: SNM19D205269-GBD9142U-THL- Fax Message NO.2130

Fya

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Prowerkz Kwang [mailto:prowerkzcar@gmail.com]

Sent: Monday, 11 November, 2019 11:57 AM

To: Claims Dept of CTI < claimsdept@sg.cntaiping.com>

Subject: Re: OUR REF: SNM19D205269-GBD9142U-THL- Fax Message NO.2130

Dear Claims Dept,

Kindly let us know if you agree or disagree to appoint any of the above surveyors within the timeline stipulated.

Thanks, Miss Tay Tel:65436008

Sent from my iPhone

On 7 Nov 2019, at 6:35 PM, Prowerkz Kwang
prowerkzcar@gmail.com
wrote:

Dear Claim Dept,

We regret to inform that our client will not appoint any of the surveyors from your list.

We are pleased to provide below a list of ten surveyors for your consideration.

Gilbert Leow	Impact Analysis Consultant	
Andy Ho	Impact Analysis Consultant	
Shandy Loh	Impact Analysis Consultant	
Michael Yap	Mccoy Pte Ltd	
Joshua Ong	Delta-V Consultant	
James Ong	Delta-V Consultant	
Nick Ng	Delta-V Consultant	
Loo Yee Khang	Cozon Engineers	
Alex Teo	Cozon Engineers	
Denise Yap	Pal's Appraiser Pte Ltd	

Kindly let us know if you agree or disagree to appoint any of the above surveyors within the timeline stipulated.

Thanks,

Miss Tay

On Thu, Nov 7, 2019 at 5:56 PM Claims Dept of CTI < claimsdept@sg.cntaiping.com > wrote:

Dear Ben.

Please conduct PRS for SLX8821B.

Note: officer in charge - Ben Tang 63896175.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: <u>www.sg.cntaiping.com</u> | FB: <u>www.facebook.com/chinataipingsg/</u> | WeChat: 太平 狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

----Original Message----From: FA-X5575C-19A

Sent: Thursday, 7 November, 2019 1:22 PM

To: FA-X5575C-16A-CL <FA-X5575C-16A-CL@sg.cntaiping.com>

Subject: FW: Fax Message NO.2130

Cathryn Chia HR and Administration Dept

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6207 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平

狮城 Taiping SG

----Original Message----

From: FA-RC6004F-16A-FN@sg.cntaiping.com [mailto:FA-RC6004F-16A-

FN@sg.cntaiping.com]

Sent: Thursday, 7 November 2019 12:16 PM

To: FA-X5575C-19A <FA-X5575C-19A@sg.cntaiping.com>

Subject: Fax Message NO.2130

This E-mail was sent from "RC6004F-16A-FN" (MP C6004ex).

Queries to: FA-RC6004F-16A-FN@sg.cntaiping.com

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com



To China Taiping Insurance Singapore Pte. Ltd.

3 Anson Road #16-00 Springleaf Singapore 079909

Attn Motor Claim Officer

Fax: 62221033

07 November 2019

THIRD PARTY CLAIM FOR SLX8821B AGAINST YOUR INSURED GBD9142U

Dear Sir/ Mdm,

We are instructed by Mr Ong Choon Hong (SLX8821B) to notify you of a road traffic accident on 04 November 2019 at about 1.25pm at Tanah Merah Coast Road involving our client's SLX8821B and GBD9142U driven by your insured client at the material time. A copy of the Singapore accident statement/ traffic police report filed is enclosed.


As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, pls let us know within 2 working days of your receipt of this notice whether you or your client would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/ we shall proceed to repair the vehicle without further reference to you.

Yours sincerely,

Miss Tay Administrator enail = proverkzcaragmail.com

encs

25 Kaki Bukit Road 4, #06-87 Synergy@KB, Singapore 417800. Tel: 65436008 Fax: 65436108



MNA119146504 / National Assessment Centre Services - Ubl ENTRY DATE & TIME: 05/11/2019 14:53 SUBMITTED BY: Jackson Ho Zhao Tian

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process,
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	05/11/2019 14:53
Date Of Accident	04/11/2019 13:25
Exact Location Of Accident	TANAH MERAH COAST RD
Country/State of Loss	SINGAPORE
D. D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SLX8821B
Insured/Policyholder	
Name Of Registered Owner	ONG CHOON HONG (WANG JUNFENG)
NRIC No	S8425279D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96268890
Alternative Phone No	OFFICE-96268890
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	ATTRAGE 1.2 CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

5112075783

Cover Note Number

Driver

TAN KIM SOON (CHEN JINSHUN) Name of Driver

S7332046A NRIC No 03/09/1973 Date Of Birth OUTDOOR Occupation 07/01/2008 Date Of Driving Pass

11 YEARS AND 9 MONTHS Driving Experience

MALE Gender

(LOCAL) +65-85117288 Mobile Number

Fax Number

OFFICE-85117288 Contact Number

NOEMAIL EMail Address

83605011

" Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

TAN KIM SOON (CHEN JINSHUN)

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

SLX8821B

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address Postcode

Accident Sketch Plan

THERE I SHOULD SHOULD STORE TO THE HEALT HEALT HEALT HEALT ALC: HELLAN

VEH A SXIZB

WAR GROWNING

relate to place report - thoughts from.	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Policyhocer's senature

Date & Time 5/11/19 145/5 /vr.1 Ottob & Time 5/11/19 145/5 /vr.1

Reporting Centre Fer Plame

NEIC/EN No

Police Report





Police Station Of Origin Nanyang N P C 2 Jurong West Avenue 5 SINGAPORE 649482 Tel No. 1800-7929999 2 of 3 Report No. 1/20191105/2022

CONTINUATION OF REPORT

Driver						
Name	AHMAD NAMBRI BIN TAIB			ID No		S1114286E
Related Vehicle	GBD9142U (Lorry)			Conta	ct No.	83605011
Hospital/Clinic	NIL			Class Drivin Licent Expiry	g	Class NIL Date of Expiry NIL
Date Treatment	NIL		Date Disc	harge	NIL	
No. of Days gran	ted Medical Leave	NIL	Degree o	f Injury	NIL	
Driver						
Name	TAN KIM SOON			ID No		S7332046A
Related Vehicle	SLX8821B (Car)			Contact No.		85117288
Hospital/Clinic	PROHEALTH MEDICAL GROUP @ TAMAN JURONG PTE LTD		UP@	Class Drivin Licen Expin	9	Class NIL Date of Expiry NIL
Date Treatment	04/11/2019		Date Disc	harge	NIL	
The state of the s	ted Medical Leave	05	Degree o	finjury	Sligh	t

Brief Details.

On 04/11/2019 at around 1320hrs, I was driving my car bearing registration plate no SLX8821B along Tanah Merah Coast Road heading towards Tanah Merah Ferry Terminal to drop off my passenger as I was driving GRAB hitch. As I was driving on my lane, a lorry bearing registration plate no GBD9142U hit onto my front right side before speeding off. I then chased the vehicle for several distance before the vehicle came to a stop.

We then alighted from the vehicle and the driver was unhappy. We then exchanged particulars. All the events was witnessed by my passenger. I wish to state that overtaking is not allowed along the road and there were chevron markings in the middle of the road which the driver has crossed the chevron markings. He also did signal of his intention to cut into my lane.

Due to the accident. I sustained pain on my neck and was given 5 days of MC given by Prohealth Medical Group @ Taman Jurong. My passenger did not sustain any injury. My vehicle sustained scratches and dents on the front right side.

That is all

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	279D
Vehicle No.:	SLX8821B
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Nov 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	ATTRAGE 1.2 CVT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	3A92UGS4752
Chassis No.:	MMBSTA13AJH001854
Maximum Power Output:	59.0 kW (79 bhp)
Open Market Value:	\$14,015.00
Original Registration Date:	16 Apr 2018
First Registration Date:	16 Apr 2018
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$5,000.00 - 2506
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Apr 2028
PARF Rebate Amount: Intended COE Rebate Details	\$3,750.00
COE Expiry Date:	15 Apr 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,000.00
COE Rebate Amount:	\$32,015.00
Total Rebate Amount:	\$35,765.00

The information contained herein is correct as at 12 Nov 2019



Mitsubishi Attrage 1.2A

\$53,000

\$5,550 /yr

17-Dec-2018

3 cc 43.0

Sedan

Av

10 Years Manufacturer Engine Warranty, Owner's Third Car, Almost New Condition, Low Maintenance, Low Fuel Consumption.

Posted: 12-Sep-2019

Tags: 2018 Mitsubishi Attrage, 2018 mitsubishi attrage, Mitsubishi Attrage, mitsubishi attrage, Mitsubishi, Attrage, attrage, Used Mitsubishi

Altrage, attrage, Used Mitsubishi

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

_ Sta

For old advertisements, view Expired ads

20 ▼ result

Home New Cars Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpar insurance. Find buy used Mitsubishi Attrage, Mitsubishi Attrage Singapore, used Mitsubishi Attrage, used vehicles Singapore or even buy used 1 Attrage Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial ve

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2019 sgCarMart. All rights reserved,

DOA- 4/11/19

MV - 53000 PU - 35765 NU - 12200 Mme 6000 gm 6000 tn = 500 = 48000 + 2500 + 2500 = 53000

10,

Compare

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj Subr	mitted	Ins Auth'ed	Status		
Main	07 Nov 2019		26 Nov 2019 09:17 Edit Adj Rpt	S\$0.00 Edit Estima	tes	S\$0.00 View Rp	4		Pending f Report Cancel Car	or Survey	
	Main	Re	ference	T (Claim	Details		Docume	nts	Show All	
CLAIM SU	BFOLDER DE	TAILS	and the same of th		Routous		[Created	d by insurer]			
Insured:	-, Co. Re	g. No.: -									
Main Claimant:	ong CHOON HONG										
Vehicle Reg No.:					-	e of Loss:	04/11/2019 13:00 - :59 [18 Months and 19 Days From LTA Reg Date (Man Yr)]				
Claim Type	: TP / SNI	TP / SNM19D205269		Policy/Cover Note No.: DMCVSN16307619033					DMCVSN16307619033		
Vehicle Reg No. (Insured):	GBD9142U (Claimant):										
\$2 3b-					40,110	ess:	S\$0.00				
Repairer:	Prowerkz	Garage Pte Ltd	(HQ) 25 Kaki Bu	ukit Road 4,	#06-8	7 Synergy	@ KB, 417	7800 Kaki Bukit -	Tel:		
Handling Insurer:		ping Insurance								T/42/20403	
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Ha	ndled by L	EE HOCK	ANN] [Fina	Rpt due 0	5/12/2019]	
ASSOCIA'	TED MAIL RE	CEIVED						41	View All C	ompose Case Mail	
There are r	no mail for this	case.									
ALL ASSO	CIATED TAS	sks⊟					View All	Search Tasks	Create New	Task Complete	
Due Dat	e Priority		Group Sub	ject Han	dler	Assign		Completed O	n Create	ed On Done	

Claim Documents

*SLX8821B (SNM19D205269) [GBD9142U] TP ONG CHOON HONG Nov 4 2019 1:00PM [-] Prowerkz Garage Pte Ltd

Pho	tos/Images		3 per page	•	•
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thum	onail	
1	26/11/19 10:33	General View	1 Load	JPG	•
2	26/11/19 10:33	General View	① Load	JPG	•
3	26/11/19 10:33	General View	1 Load	JPG	•
4	26/11/19 10:33	General View	1 Load	JPG	
5	26/11/19 10:33	General View	1 Load	JPG	•
6	26/11/19 10:33	General View	1 Load	JPG	•
7	26/11/19 10:33	General View	1 Load	JPG	•
8	26/11/19 10:33	General View	1 Load	JPG	•
9	26/11/19 10:33	General View	Load	JPG	•
10	26/11/19 10:33	General View	① Load	JPG	•
11	26/11/19 10:33	General View	1 Load	JPG	•
12	26/11/19 10:33	General View	1 Load	JPG	•
13	26/11/19 10:33	General View	1 Load	JPG	•
14	26/11/19 10:33	General View	① Load	JPG	•
15	26/11/19 10:33	General View	1 Load	JPG	•
16	26/11/19 10:33	General View	① Load	JPG	•
17	26/11/19 10:33	General View	1 Load	JPG	•
18	26/11/19 10:33	General View	1 Load	JPG	•
19	26/11/19 10:33	General View	1 Load	JPG	•
20	26/11/19 10:33	General View	1 Load	JPG	•
21	26/11/19 10:33	General View	1 Load	JPG	•
22	26/11/19 10:33	General View	1 Load	JPG	•
23	26/11/19 10:33	General View	3 Load	JPG	•
24	26/11/19 10:33	General View	① Load	JPG	•
25	26/11/19 10:33	General View	① Load	JPG	•
26	26/11/19 10:33	General View	① Load	JPG	•
27	26/11/19 10:33	General View	1 Load	JPG	\checkmark
28	26/11/19 10:33	General View	① Load	JPG	€
29	26/11/19 10:33	General View	1 Load	JPG	\checkmark
30	26/11/19 10:33	General View	① Load	JPG	
31	26/11/19 10:33	General View	1 Load	JPG	€
32	26/11/19 10:33	General View	1 Load	JPG	€
33	26/11/19 10:33	General View	1 Load	JPG	•
34	26/11/19 10:33	General View	① Load	JPG	•
35	26/11/19 10:33	General View	① Load	JPG	•
36	26/11/19 10:33	General View	① Load	JPG	•
37	26/11/19 10:33	General View	① Load	IPG	•
38	26/11/19 10:33	General View	① Load	JPG	
39	26/11/19 10:33	General View	① Load	IPG	•
40	26/11/19 10:33	General View	1 Load	IPG	•

Pho	otos/Images		3 per pa	age ▼	€
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
41	26/11/19 10:33	General View	0	Load JPG	
42	26/11/19 10:33	General View	0	Load JPG	•
43	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
44	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
45	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
46	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
47	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
48	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
49	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
50	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
51	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
52	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
53	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
54	26/11/19 10:34	Photographs of Damaged Parts	ő	Load JPG	•
55	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
56	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
57	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
58	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
59	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
60	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
61	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
62	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
63	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	
64			0		·
65	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	2
66	26/11/19 10:34	Photographs of Damaged Parts		Load JPG	-
70.00		Photographs of Damaged Parts	0	Load JPG	S
67	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
68	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
69	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
70	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
71	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
72	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
73	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	€
74	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	€
75	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	✓
76	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	✓
77	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	
78	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	•
79	26/11/19 10:34	Photographs of Damaged Parts	0	Load JPG	2
80	26/11/19 10:34	Photographs of Damaged Parts		Load JPG	€
81	27/11/19 13:03	After Repair Photo		Load JPG	€
82	27/11/19 13:03	After Repair Photo	0	Load JPG	•
83	27/11/19 13:03	After Repair Photo		Load JPG	•
84	27/11/19 13:03	After Repair Photo	0	Load JPG	•
85	27/11/19 13:03	After Repair Photo	0	Load JPG	•
86	27/11/19 13:03	After Repair Photo		Load JPG	•
87	27/11/19 13:03	After Repair Photo		Load JPG	V
88	27/11/19 13:03	After Repair Photo		Load JPG	•
89	27/11/19 13:03	After Repair Photo		Load JPG	•
90	27/11/19 13:04	After Repair Photo		Load JPG	•
91	27/11/19 13:04	After Repair Photo	0	Load JPG	•
92	27/11/19 13:04	After Repair Photo	0	Load JPG	•
93	27/11/19 13:04	After Repair Photo	6	Load JPG	•

Pho	tos/Images		3 per pa	ge ▼	•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	T	humbnail	Print
94	27/11/19 13:04	After Repair Photo	0	Load JPG	•
95	27/11/19 13:04	After Repair Photo	0	Load JPG	•
96	27/11/19 13:04	After Repair Photo	0	Load JPG	•
97	27/11/19 13:04	After Repair Photo	0	Load JPG	•

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/CTI19019952/HCD3S2

Date:

TP

15/01/2020

REFERENCE

Handling Insurer: Ltd.

China Taiping Insurance (Singapore) Pte.

Policy No:

DMCVSN16307619033

Claimant Vehicle

No:

SLX8821B

Insured Vehicle No GBD9142U

Date of Loss:

04/11/2019

Nature of Claim:

Claim No:

SNM19D205269

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLX8821B

Make & Model:

MITSUBISHI ATTRAGE, 1.2 CVT (A)

Engine No:

3A92UGS4752

Reg. Date:

16/04/2018 (Man. Year: 2018)

Chassis No: Odometer:

MMBSTA13AJH001854

Colour:

White

47919 km

Engine Capacity:

1193 cc

N/A

Market Value/New Car Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good

Steering (Serviceable):

No

Yes Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Yes

Engine Modification:

Front Tyre Size: Front Left Side:

185/55 R15

Rear Tyre Size:

195/50 R15

Front Right Side:

Bridgestone 3 mm Bridgestone 3 mm Rear Left Side: Rear Right Side: Falken 4 mm Falken 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

26/11/2019

Prowerkz Garage Pte Ltd (HQ)

Date Inspected:

11/11/2019 Inspected At:

25 Kaki Bukit Road 4, #06-87 Synergy @ KB

Singapore 417800

Estimated Period of Repair:

4.0 days

LEE HOCK ANN Adjuster:

Manager:

CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
- HE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500.00 \$5,500.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 15 Jan 2020)

Parts: N/A MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLX8821B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >